

## **EQUIPMENT CONDITION REPORT**

Make: Model:	Engine Make: ISM  2002 Engine Model: Cummins ISM  Freightliner Engine SN: 35046633  Columbia 120 series Fuel Type: Diesel  1FUBA6A872LK15236 Fuel Capacity: 160 gallons(80 each tank)	
For Rolling Stock: Transmission: Auto / Standard:	: Speeds:	
Mechanical Condition	Very Good - Starts and operates with no known mechanical defects.  Good - Starts and operates; Some parts may require repair or replacement soon Fair - Starts and operates but some parts require repair or replacement.  Poor - Will not start or operate and is in need of repair.  Yes   No Can the Equipment Be Repaired?  Describe Repairs:	1.
	Yes No Equipment has keys  Yes No Functioning Brake Lights, Head Lights and Turn Signals Not Applicable  Yes No Functioning AC Not Applicable:  Yes No Functioning Heat Not Applicable:  Yes No Service / Repair Records Available  Yes No Any Known Mechanical Issue  Details:	e:
Whe		eeds Repair eeds Repair

Non-	Attachments:  .,  Very Good, Standard Attachments:   GPS Other:	Wear due to use,						
	Oil Leaks:   Yes Fuel Leaks:   Yes Cooling System Leaks:   Yes	No Visible Leaks or Pooling No Visible Leaks or Pooling No Visible Leaks or Pooling						
	Not Applicables 1. I							
Hydraulics	Not Applicable:  ,,  Pumps:   Operational Articulating Cylinders:  ,,  Operational Motors:  ,,  Operational Leaks:   Yes	Wear due to use,   Damage, Needs Repai Wear due to use,   Damage, Needs Repai Wear due to use,   Damage, Needs Repai No Visible Leaks or Pooling						
Interior Condition	<ul> <li>Very Good - No visible signs of damage.</li> <li>Good - Damage is limited to normal wear and minor scratches.</li> <li>Fair - Interior is heavily worn.</li> <li>Poor - Interior has severe damage and/or tears beyond normal wear.</li> </ul>							
Exterior Condition	Very Good - Well maintained   .,  Good - Minor dings and scratches      Fair - Visible dents and scratches    Poor - Major body damage.							
Safety	Mirrors:   ,   Very Good, Horn:   ,   Operational Seat Belts:   ,   Operational Travel Alarm:   ,   Operational Warning Lights:   ,   Operational Gauges:   ,   Operational Safety Manual:     Yes   ,   No							
Equipment Location	Contact: Joe Cappy  Email: N/A  Company Name: Union Beverage Lot  Address: 600 N Union Avenue,  City: Hillside	Phone: N/A  State: NJ Zip: 7205						

	Contact: Joe Cappy			Phone: N/A			
	Email: N/A						
	Buyer Storage Rate:	\$300 per m	nonth				
	Will the Equipment Self Load:						
	Hours of Operation:	24	1/7	Saturday/Sunday Removal:	I.∕ lyes	Ιþ	
Equipment Logistics	Removal Lead Time:	None	_				
	Required Transport Equipment: N/A						
	Is Loading Assistanc	e Available:	NO	Cost: N/A			
	Additional Removal Information: Lot is open 24/7 with guard and guard dog on site. Coordinate with			dinate with Jo			