



Auburn, WA  
206-443-8500  
San Leandro, CA  
510-638-8100

Richmond, VA  
804-271-9356  
North SLC, UT  
801-292-2453

Toll Free  
888-337-2444

## SERVICE REPORT

DATE:

CUSTOMER <u>Malcolm Drilling</u>		TRIP MILEAGE	
CONTACT NAME & NO.			
ADDRESS			
MAKE <u>Crane</u>	MODEL	SERIAL NUMBER	HOURS
			UNIT NUMBER <u>185161</u>

SERVICE REQUESTED <u>LMT Screen is faded &amp; cannot read lower part of screen</u>

REPAIRS MADE <u>led out, ordered a new LCD monitor - customer is going to install</u>

COMMENTS

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED

[Signature]  
TECHNICIAN

\_\_\_\_\_  
CUSTOMER SIGNATURE

**CRANE and RIGGING CO.**

10700 BIGGE AVENUE • P.O. BOX 1657 • SAN LEANDRO CA 94577 • TEL: 510-638-8100  
CONTRACTORS LICENSE NO. 9859 • SOUTH BAY 408-727-5678 • FAX: 510-639-4053

## SERVICE REPORT

Date: 4-24-12

[illegible]

Billy Lee  
SERVICE BY

**CUSTOMER SIGNATURE**



Auburn, WA  
206-443-8500  
San Leandro, CA  
510-638-8100

Richmond, VA  
804-271-9356  
North SLC, UT  
801-292-2453

Houston, TX  
713-434-0995

Toll Free  
888-337-2444

## SERVICE REPORT

DATE 8/18/12

CUSTOMER <u>BECHTEL</u>		TRIP MILEAGE	
CONTACT NAME & NO.			
ADDRESS			
MAKE <u>TEREX</u>	MODEL <u>AC1605</u>	SERIAL NUMBER	HOURS <u>9051</u>
			UNIT NUMBER <u>1605161</u>

SERVICE REQUESTED LOAD PROBLEM, ACB PROBLEM,

REPAIRS MADE 5/0 TO JOB SITE @ 4 1/2 HRS STAND BY TIME TO GET LOAD AND CLEARANCE  
TO ROOM CRANE DOWN ROOMED DOWN CRANE T/S ACB PROBLEM FOUND  
BAD ACB SWITCH ON ~~ACB~~ AUX CHANGED SWITCH & TESTED SET UP CRANE  
AT 74.8" AND CALIBRATED AUX LOAD WITH 16,000 LB RF HAS LOAD  
FLUCTUATING 1,500 LB

### COMMENTS

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED

MIKE  
TECHNICIAN

CUSTOMER SIGNATURE



25 East Pacific Avenue  
North Salt Lake, UT 84054  
Ph. (801) 292-2453 Fax 292-3001

## EQUIPMENT CO.

### SERVICEMAN'S REPORT

Date 10-31-13  
Customer's Name GBI Customer P.O. # \_\_\_\_\_  
Job Location Bartick, NV Make/Model HL165 S/N AC4053 Hour Meter 9412

Describe Defects & Causes of Failure: crane dismantle. and off rent

Describe Work Done: 10-29-13: leave Bigge SL @ 2:00 pm  
Arrive Elko 7:00 pm (5 hr)  
10-30-13 leave hotel @ 5:30 am Arrive onsite 6:30 am  
leave jobsite 7:00 pm Arrive hotel 8:00 pm (14.5 hr)  
10-31-13 leave hotel 6:00 AM Arrive job 7:00 AM  
leave jobsite 2:30. Arrive SL 7:30 pm (13.5 hr)

Job #  
8744

33 hr total

Qty.	Part Number	Description

Other Suggested Repairs: \_\_\_\_\_

Condition of Machine: Good ☒ Fair ☐ Poor ☐

Miles Traveled 660

Labor -Reg. 17

O.T. 16

Bigge's Serviceman [Signature]

Customer's Representative [Signature] Randy Crofts

801-362-3894

Copies: White: Office Pink: Customer on Job Yellow: Equipment File



### SERVICE REPORT

Date: 12/20/13

Customer's Name: AGL

Customer P. O. # \_\_\_\_\_

Job Location: Lewisville TX

M/M/T: \_\_\_\_\_

Hours: 9926

Equipment # BE165161

Serial # AC4053

Describe Defects & Cause of Failure: Service Crane 500hr

Repairs Completed: Replaced oil, oil filter, Fuel filter, Coolant filter, Lubed pennant cables, greased sheaves

Qty	Part Number	Description	Ordered	Installed
1	LF3000	Engine oil filter		
1	FS1022	Fuel filter		
1	WF2072	Coolant filter		
1	AF424	Air filter		

Recommendations: needs extra keys, window

Technician: Eric Wamsby

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete: \_\_\_\_\_

Yes ☐ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

### SERVICE REPORT

Date: 12-26-13

Customer's Name: AGL

Customer P. O. # \_\_\_\_\_

Job Location: Lewisville TX

M/M/T: \_\_\_\_\_

Hours: 9935

Equipment # 165161

Serial # \_\_\_\_\_

Describe Defects & Cause of Failure: Removed Shackle & Installed  
proper connection bracket for becket.

Repairs Completed: Install bracket, New op. Manual & load chart

Next 500hr Service at 10435

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Eric Idornsbay

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete: \_\_\_\_\_

Yes ☐ No ☐

Labor: Reg 2

O.T. \_\_\_\_\_

### SERVICE REPORT

Date: 1-24-14  
Customer's Name: AGL Customer P. O. # \_\_\_\_\_  
Job Location: Lewisville Tx M/M/T: HC165 Terex Hours: 9958  
Equipment # 165161 Serial # AC4053

Describe Defects & Cause of Failure: Door Froze ~~and~~ close & had to jump  
start due to cold, Replaced broken glass. cleaned  
Inside of cab.

Repairs Completed: lubed door & opened jumped off.  
glass Replaced.

Qty	Part Number	Description	Ordered	Installed

Recommendations: next service at 14341

Technician: E. Hensley  
Customer Name: \_\_\_\_\_ Job Complete: \_\_\_\_\_ Labor: Reg \_\_\_\_\_  
Customer Signature: \_\_\_\_\_ Yes ☐ No ☐ O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 4/2/14  
Customer's Name: AGL Constructors Customer P. O. # \_\_\_\_\_  
Job Location: Highland village Tx M/M/T: Terex Hc165 Hours: 10100  
Equipment # 165161 Serial # AC-4053

Describe Defects & Cause of Failure: Dinged lacing on bottom side of  
upper 50 foot boom insert.

Repairs Completed: have welder come to site & Replace lacing  
on 50' Insert.

Qty	Part Number	Description	Ordered	Installed
1	—	Bottom boom lacing		✓

Recommendations: \_\_\_\_\_

Technician: Crick/Amstutz  
Customer Name: \_\_\_\_\_ Job Complete: \_\_\_\_\_ Labor: Reg \_\_\_\_\_  
Customer Signature: \_\_\_\_\_ Yes ☐ No ☐ O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 4/2/14  
 Customer's Name: AGL Constructors Customer P. O. # \_\_\_\_\_  
 Job Location: Highland Village TX M/M/T: Terex HC165 Hours: 10100  
 Equipment # 165161 Serial # AC-4053

Describe Defects & Cause of Failure: Dinged lacing on bottom side of  
upper 50 foot boom insert.

Repairs Completed: have welder come to site & Replace lacing  
on 50' Insert.

Qty	Part Number	Description	Ordered	Installed
1	—	Bottom boom lacing		✓

Recommendations: \_\_\_\_\_

Technician: Eric Hornsby  
 Customer Name: \_\_\_\_\_ Job Complete: \_\_\_\_\_ Labor: Reg \_\_\_\_\_  
 Customer Signature: \_\_\_\_\_ Yes ☐ No ☐ O.T. \_\_\_\_\_

### SERVICE REPORT

Date: 4/25/14  
Customer's Name: AGL Customer P. O. # \_\_\_\_\_  
Job Location: Highland Village Tx M/M/T: Terex HC 165 Hours: 10195  
Equipment # 165161 Serial # AC-4053

Describe Defects & Cause of Failure: Actual wt. not reading on aux line

Repairs Completed: had to calibrate LMI so it would know  
To read for the Aux line.

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Eric Hornsby  
Customer Name: \_\_\_\_\_ Job Complete: \_\_\_\_\_ Labor: Reg \_\_\_\_\_  
Customer \_\_\_\_\_ Yes ☐ No ☐ O.T. \_\_\_\_\_

### SERVICE REPORT

Date: 4/26/14

Customer's Name: AGL

Customer P. O. # \_\_\_\_\_

Job Location: Highland Village M/M/T: Terex HC165 Hours: 10200

Equipment # 165161 Serial # AC-4053

Describe Defects & Cause of Failure: Boom angle & load cells out of calibration

Repairs Completed: Calibrate boom angle & each load cell individually.

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: 

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete: \_\_\_\_\_ Labor: Reg \_\_\_\_\_

Yes ☐ No ☐ O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 5/20/14  
Customer's Name: AGL Customer P. O. # \_\_\_\_\_  
Job Location: Louisville TX M/M/T: Terex HC 165 Hours: 10359  
Equipment # 165161 Serial # AC4053

Describe Defects & Cause of Failure: Roller assembly on door, bent & missing pieces

Repairs Completed: Replaced roller assembly & lubed all moving parts

Qty	Part Number	Description	Ordered	Installed
1		Roller assembly		<input checked="" type="checkbox"/>

Recommendations: Keep door lubed

Technician: Eric Hershby  
Customer Name: \_\_\_\_\_ Job Complete: \_\_\_\_\_ Labor: Reg 1  
Customer Signature: \_\_\_\_\_ Yes ☒ No ☐ O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 5/28/14  
Customer's Name: AGC Constructors Customer P. O. #                       
Job Location: Lewisville TX M/M/T: Terex HC165 Hours: 10,399  
Equipment # 165161 Serial # AC4053  
Describe Defects & Cause of Failure: 500hr Service

Repairs Completed: Replaced engine oil, oil filter, Fuel filter  
Coolant Filter, Air filter,  
Lubed Crane  
& checked all fluid levels.

Qty	Part Number	Description	Ordered	Installed
<u>1</u>		<u>oil filter</u>		<u>✓</u>
<u>2</u>		<u>fuel filter</u>		<u>✓</u>
<u>1</u>		<u>coolant filter</u>		<u>✓</u>
<u>1</u>		<u>air filter</u>		<u>✓</u>

Recommendations: next service 10,900

Technician: Eric Hernsky  
Customer Name:                      Job Complete: Labor: Reg 3  
Customer Signature:                      Yes ☒ No ☐ O.T.

### SERVICE REPORT

Date: \_\_\_\_\_

Customer's Name: AGL Constructors

Customer P. O. # \_\_\_\_\_

Job Location: Lewisville TX

M/M/T: Terex HC165

Hours: 10579

Equipment # 165161

Serial # HC4653

Describe Defects & Cause of Failure: Drum Roll Indicator cuts in & out

Repairs Completed: Replace prox switch for Drum Roll Indicator  
& properly adjust

Qty	Part Number	Description	Ordered	Installed
1		Prox Switch		<input checked="" type="checkbox"/>

Recommendations: \_\_\_\_\_

Technician: Eric Homsby

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete:

Yes ☒ No ☐

Labor: Reg 2 hr

O.T. \_\_\_\_\_

### SERVICE REPORT

Date: 8-18-14

Customer's Name: AGL Constructors

Customer P. O. # \_\_\_\_\_

Job Location: Highland Village Tx. M/M/T: Terex HC-165 Hours: 10642

Equipment # 165161 Serial # 9C-1053

Describe Defects & Cause of Failure: Worn out brake belt for a/compressor

Repairs Completed: Replace belt with new correct V-groove belt

Qty	Part Number	Description	Ordered	Installed
1		<u>fan belt</u>		<input checked="" type="checkbox"/>

Recommendations: \_\_\_\_\_

Technician: Eric Gernsby

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete: Labor: Reg 3

Yes ☒ No ☐ O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 8-22-14  
Customer's Name: AGL Customer P. O. # \_\_\_\_\_  
Job Location: Highland Village, TX M/M/T: Terex HC-165 Hours: 10653  
Equipment # 165161 Serial # AC4053

Describe Defects & Cause of Failure: RPM Gauge, Windmeter, Hourmeter, not  
Working

Repairs Completed: Found blown fuse & replaced

Qty	Part Number	Description	Ordered	Installed
1		20a FUSE		✓

Recommendations: \_\_\_\_\_

Technician: Eric Forness  
Customer Name: \_\_\_\_\_ Job Complete: Labor: Reg 2  
Customer Signature: \_\_\_\_\_ Yes ☒ No ☐ O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 9/12/14  
Customer's Name: AGL Customer P. O. # \_\_\_\_\_  
Job Location: Highland Village, TX M/M/T: Terex HC 165 Hours: 10,782  
Equipment # 165161 Serial # AL-4053  
Describe Defects & Cause of Failure: Bad wiper blades Top & Front

Repairs Completed: Replaced wiper blades

Qty	Part Number	Description	Ordered	Installed
1		12in Wiper Blade		✓
1		19in wiper blade		✓

Recommendations: \_\_\_\_\_

Technician: Ericksonsky  
Customer Name: \_\_\_\_\_ Job Complete: Labor: Reg .5  
Customer Signature: \_\_\_\_\_ Yes ☒ No ☐ O.T. \_\_\_\_\_

# BIGGE

## EQUIPMENT CO.

14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 9-26-14

Customer's Name: AGL

Customer P. O. # \_\_\_\_\_

Job Location: Highland Village

M/M/T: Terex HC-165

Hours: 10874

Equipment # 165161

Serial # AC4053

Describe Defects & Cause of Failure: Service Crane

Repairs Completed:

Changed engine oil and Filter also replaced  
air Filter and Fuel Filter.

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician:

Bryan Venable

Customer  
Name:

Job Complete:

Labor: Reg \_\_\_\_\_

Customer  
Signature:

Yes ☒ No ☐

O.T. \_\_\_\_\_

Copies: White: Office Pink: Customer Yellow: Technician Copy

### SERVICE REPORT

Date: 9-8-15

Customer's Name: AGL

Customer P. O. # \_\_\_\_\_

Job Location: Highland Village

M/M/T: Terex HC 165

Hours: 12417

Equipment # 165161

Serial # \_\_\_\_\_

Describe Defects & Cause of Failure: Remove 50 section of boom

Repairs Completed: \_\_\_\_\_

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Bryan Venable

Customer Name: AGL

Customer Signature: V.R.

Job Complete: \_\_\_\_\_

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 9-9-15

Customer's Name: AGL

Customer P. O. # \_\_\_\_\_

Job Location: Highland Village

M/M/T: Terex 165

Hours: 124/7

Equipment # 165161

Serial # \_\_\_\_\_

Describe Defects & Cause of Failure: 4 part block, Fix A2B, Install rooster Jib

Repairs Completed: Install 4 part block, install rooster Jib and ball.  
A2B would not work found water in all connections.

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Bryan + Tom

Customer Name: AGL

Customer Signature: V.R.

Job Complete: \_\_\_\_\_

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 10-5-15

Customer's Name: AGL

Customer P. O. # \_\_\_\_\_

Job Location: Lewisville Lake

M/M/T: Terex HC 165

Hours: \_\_\_\_\_

Equipment # 165161

Serial # \_\_\_\_\_

Describe Defects & Cause of Failure: Boom lacing, remove block add Ball

Repairs Completed: Disconnect Batterys for welder.  
Boom crane up and down for welder. Remove the  
block and Add the Ball

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Bryan Venase

Customer Name: AGL

Customer Signature: Narcisse Fields

Job Complete: \_\_\_\_\_ Labor: Reg \_\_\_\_\_

Yes ☒ No ☐ O.T. \_\_\_\_\_

### SERVICE REPORT

Date: 2-16-16

Customer's Name: Bigge

Customer P.O. # \_\_\_\_\_

Job Location: Houston Shop

M/M/T: Terex HC 165

Hours: 12768

Equipment # 165 161

Serial # AC - 4053

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: Get unit Rent Ready

Repairs Completed: Change engine oil, change oil filter, change fuel filter, grease crane, change door center roller, fix ATB wire connections, replace boom elec. cable, change key switch, change crane level by OLR control, change Hyd. oil, change Hyd. filter. Change coolant filter

1	0755 130 91	Kit element (Hyd. inline filter)		✓
1	5350 43203	Return filter (Hyd. filter)		✓
1	AF 820	inner Air filter		✓
1	AF 424	outer Air filter		✓
1	P553000	oil filter		✓
1	P552074	coolant filter		✓
Qty	Part Number	Description	Ordered	Installed
1	F35326100	Center roller IHI		✓
1	085830601	Ignition switch IHI		✓
1	093302101	vial, level IHI		✓
1	P558000	Fuel filter		✓

Recommendations: Engine serial number 46396206  
Cummins

Technician: Derrick Wilson / Heriberto De Jesus

Customer Name: \_\_\_\_\_

Job Complete: \_\_\_\_\_

Labor: Reg \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Yes ☒ No ☐

O.T. \_\_\_\_\_

[illegible]

2001

44-38861-101

~~16-00000-1000-1000~~

[illegible][illegible]

2022 P127 - Graham, Brian - 2022-09-08  
2022 P128 - Graham, Brian - 2022-09-08

and all children must attend



### SERVICE REPORT

Date: 2-25-16

Customer's Name: Structural Assurance

Customer P.O. # \_\_\_\_\_

Job Location: New Braunfels, Tx. M/M/T: HC165 Terex

Hours: 12779

Equipment # 165161

Serial # AC 4053

Trip Mileage 340

Describe Defects & Cause of Failure: Boom angle not working, ATB not working

Repairs Completed: T/S and found bad connection in operator cab under moment limiter, repaired and boom angle working.

T/S and found that crane need a dummy plug for 3rd winch, made and dummy plug ATB working properly.

Install ball on rear drum.

add coolant low coolant sensor alarming

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Joel McInerney

Customer Name: \_\_\_\_\_

Customer Signature: Greg C. Brant

Job Complete:

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

### SERVICE REPORT

Date: 04-13-16

Customer's Name: Structural Assurance

Customer P.O. # \_\_\_\_\_

Job Location: New Braunfels, Tx M/M/T: TEREX Hc165

Hours: 12825

Equipment # 165161

Serial # AC 4053

Trip Mileage 185 (one way)

Describe Defects & Cause of Failure: Replace Batteries

Repairs Completed: Arrive to location of crane. Customer had to jump start batteries. Remove and replaced per customer request. Tested charging system on crane, found no issues.

Qty	Part Number	Description	Ordered	Installed
<u>2</u>	<u>4D</u>	<u>12v Battery</u>		<input checked="" type="checkbox"/>

Recommendations: \_\_\_\_\_

Technician: DANIEL C.

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete:

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 6/2/16  
 Customer's Name: \_\_\_\_\_ Customer P.O. # \_\_\_\_\_  
 Job Location: Shop M/M/T: \_\_\_\_\_ Hours: 3  
 Equipment # 165161 Serial # \_\_\_\_\_ Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: damaged door (Hinge mount)

Repairs Completed: metal TORE where hinge mounts on Cab door  
I brought it back TRUE, THEN WELDED it solid

Qty	Part Number	Description	Ordered	Installed

Recommendations: Don't

Technician: Don Milb  
 Customer Name: \_\_\_\_\_  
 Customer Signature: \_\_\_\_\_

Job Complete: Labor: Reg \_\_\_\_\_  
 Yes ☒ No ☐ O.T. \_\_\_\_\_



### SERVICE REPORT

Date: 06/06/16

Customer's Name: Bigge

Customer P.O. # \_\_\_\_\_

Job Location: Houston shop

M/M/T: Terex HC 165

Hours: 12854

Equipment # 165161

Serial # AC-4053

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: Get rent ready

Repairs Completed: Replace A/C air filter.

Replace A/C duct. Replace door stopper.

Replace door rail. Replace door center roller.

Fabricate door bottom rail. Get roof glass reseal.

Fix rear drum wire rope end.

1	F353 261 00	Roller, center		✓
Qty	Part Number	Description	Ordered	Installed
1	085754 722	A/C air filter		✓
1	0857 147 UA	A/C duct		✓
1	4580 799 00	stopper		✓
1	4256 084 00	Rail		✓

Recommendations: \_\_\_\_\_

Technician: Heriberto De Jesus Trejo

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete: \_\_\_\_\_

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_



14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 7-29-16  
 Customer's Name: Bechtel Customer P.O. # \_\_\_\_\_  
 Job Location: Portland TX M/M/T: Trex HC-165 Hours: 13/48  
 Equipment # 165161 Serial # AL-4055 Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: Broke belt

Repairs Completed: Replace belt on Engine

Qty	Part Number	Description	Ordered	Installed
1	4080690HP	Serpentine belt		✓

Recommendations: \_\_\_\_\_

Technician: Eric Thomas  
 Customer Name: Salvas Villarreal Job Complete: Yes ☒ No ☐ Labor: Reg 2  
 Customer Signature: Salvas Villarreal O.T. \_\_\_\_\_





14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 10/5/16  
Customer's Name: Bechtel Customer P.O. # \_\_\_\_\_  
Job Location: Boaland TX M/M/T: American HC165 Hours: 13456  
Equipment # 165161 Serial # \_\_\_\_\_ Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: Brake release hyd cylinders leaking on  
main & aux winches  
Bearings on block sheaves loose.

Repairs Completed: Replaced seals on pistons. Bled cylinders  
Delivered, new block to be installed by customer  
when boom can be layed down.  
New block Manitowoc PN 8013495 SN 0991377

Qty	Part Number	Description	Ordered	Installed
<u>2</u>	<u>456050900</u>	<u>Packing</u>		<u>X</u>

Recommendations: Machine needs new radio

Technician: Austin Buchmayer  
Customer Name: \_\_\_\_\_ Job Complete: \_\_\_\_\_ Labor: Reg \_\_\_\_\_  
Customer Signature: RLA Hagg Yes ☒ No ☐ O.T. \_\_\_\_\_





**SERVICE REPORT**

Date: 8/28/18

Customer's Name: \_\_\_\_\_

Customer P.O. # \_\_\_\_\_

Job Location: Houston Yard M/M/T: TereX HC165 Hours: 16254

Equipment # 165161 Serial # AC4053 Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: \_\_\_\_\_

Repairs Completed: Drain and fill final drive planetaries.  
Adjust one track, other one pending

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Hugo Castillo

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete:

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

# BIGGE

Established 1918  
**CRANE and RIGGING CO.**

10700 BIGGE AVENUE • P.O. BOX 1657 • SAN LEANDRO CA 94577 • TEL: 510-638-8100  
CONTRACTORS LICENSE NO. 9859 • SOUTH BAY 408-727-5678 • FAX: 510-639-4053

## SERVICE REPORT

Date: 3-26-11

Customer's Name & No.

BalFour Bently

W.O. NUMBER

Mileage

Contact Name & Number

SAN FRANCISCO

Beginning

Address

Ending

UNIT NUMBER

MAKE OF EQUIPMENT

MODEL #

SERIAL #

HOUR METER

165161

TEREX

#C165

AC4053

2740

### SERVICE REQUESTED

Job # 51138

### SERVICE PERFORMED & DESCRIPTION OF REPAIRS

Sle Adjust Tracks Install Thrail Hoi st.

### PARTS

INSTALLED

ORDERED

QNTY

PART NUMBER

DESCRIPTION

Bill Finley

SERVICE BY

CUSTOMER SIGNATURE





Auburn, WA  
206-443-8500  
San Leandro, CA  
510-638-8100

Richmond, VA  
804-271-9356  
North SLC, UT  
801-292-2453

Toll Free  
888-337-2444

# SERVICE REPORT

WO 6152

DATE: 9-1-10

CUSTOMER <u>White</u>		TRIP MILEAGE		
CONTACT NAME & NO <u>JBFF</u>				
ADDRESS <u>RIO VISTA CA</u>				
MAKE	MODEL	SERIAL NUMBER	HOURS	UNIT NUMBER
<u>TEREX</u>	<u>HC165</u>		<u>60734</u>	<u>165161</u>

SERVICE REQUESTED HOIST & LMI

REPAIRS MADE 7/3 MAIN HOIST, NOTHOLDING LOAD SINGLE PARTED CRANE  
PICKED 31,000 LBS FOUND BRAKE ALN'T HOLD WASHED OUT BRAKES  
AND ADJUSTED BRAKE. HOOLDING ALN'S FOUND LMI IS READING  
LIGHT BY 10,000 LB RECALIBRATED. SPARTED AND TESTED WITH 31,000  
LB READING IS GOOD WITH THIS WEIGHT.  
ALSO ADJUSTED BOOM KICKOUT WAS SET AT 79° ~~50~~  
SET TO 82° PER LOAD CHART

## COMMENTS

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED

TECHNICIAN

CUSTOMER SIGNATURE