

03/16/16

SERVICE REPORT

Date: 3-16-17

Customer's Name: Bigge 1 yard

Customer P. O. # _____

Job Location: Henderson, CO

M/M/T: Terex RT 345

Hours: 1728

Equipment # 13E4520

Serial # 161145

Describe Defects & Cause of Failure: Need to swap drums l.c.b.k

Repairs Completed: Both lines unspooled and
respoiled on opposite drums so that
rotation resistant rope is on aux line.
Lines were changed by prior customer.
RRL moved to main winch and 4-pulley.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer
Name: _____

Customer
Signature: _____

Job Complete: _____

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 3-16-17

Customer's Name: Bigge 1 yard

Customer P. O. # _____

Job Location: Henderson, CO

M/M/T: Terex RT 345

Hours: 1728

Equipment # 13E4520


Serial # 161145

Describe Defects & Cause of Failure: Need to swap drums l.c.b.k.

Repairs Completed: Both lines unspooled and
re-spooled on opposite drums so that
rotation re-start rope is on aux line.
Lines were changed by prior customer.
RRL moved to main winch and 4-pulley.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: 

Customer
Name: _____

Customer
Signature: _____

Job Complete: _____

Yes ☐ No ☐

Labor: Reg _____

O.T. _____