

	SERVICE REPORT		1
Date: 07/27/2016			
Customer's Name: B TGGE		Customer P.O. #	
Job Location: HOLLTON, TX.			
Equipment # 86150/04	Serial # 23/138	Trip Mileage	
Describe Defects & Cause of Failure:			
5GAL 6829006444 10 L 1 02217118 ARA 1 2255928 MIN	130 MYO. TRANS OFL		Yes Yes Yes
3 95/510293 Louve	TANK GLEMENT ERS - A/C		
1 9258/00173 HYD. 1 AF 26124 PRE	Description FILTER BREATHER AER FELTER AS R FELTER		Installed YES YES YES YES
Technician: KYLE THIS Customer Name: Customer Signature:	Job Comp Yes 🕡	0.77	

Copies: White: Office

Pink: Customer



Date: 09/27/2016		61
Data: 06 /77 /9 //		
		Customer P.O. #
Customer's Name: B #60	MANTE RT9150E	Customer P.O. # Hours:
Job Location: Houston		Trip Mileage
Equipment # BE 15010	9 Serial # 23 (73 8	Trip ivilleage
N - H STANFFER - WILLIAM		*
Describe Defects & Cause of	f Failure:	
		8
CLEAN PUMP AM CONDENSER, AN	FITTINGS AND GREATER BEARING. TEGHTEN HO. ID RECHECK. BLOW OUT A D HYD. COOLER. RESEAL TRANSMISSION, PENOVE B	REAR OUTRIGGER BOX
OF TRANSMITSIO	REMOVE COUNTERWEIGHTS TRATLERS, LOAD CRAME	AND OUTRIGGER BOXES
DEMOVE BALL	N. FILL TRANSMITSION REMOVE COUNTERWEIGHTS TRAILERS, COAD CRAME	AND OUTRIGGER BOXES
DEMOVE BALL	REMOVE COUNTERWEIGHTS TRATICAS, COAD CRAPE	AND OUTRIGGER BOXES
Qty Part Number 1 19561103	Description FUEL TEXTER	AND OUTRIGGER BOXES OUT GREASE BOOM Ordered Installed
Qty Part Number 1 \$755 1103 2 \$165705	Description FUEL TEXTER HYD. FELTER	AND OUTRIGGER BOXES OUT GREASE BOOM Ordered Installed
Qty Part Number 1 19561103	Description FUEL TENER Description FUEL TENER LOOLANT FELTER	AND OUTRIGGER BOXES OUT GREASE BOOM Ordered Installed

Copies: White: Office

Pink: Customer



	SERVICE REPORT		
17-7-16 omer's Name:	Custome #08 M/M/T: <u>GROVE</u> RT 9150	r P.O. # Hours: & &	61_
ocation: Houston St	108 M/M/T: GROVE RT 9130	Mileage	
pment # <u>BE 150104</u>	Serial # 231938 Trip) Mileage	
cribe Defects & Cause of Fail	ure:		
LUID LEVELS.	ACED MIRROR FOR WINCH. OF GREASED ROTEX BEARING OF BOOM SECTIONS. BLEW OUT CONDENSER, & FILTERS. FILTERS. FILTERS. FILTERS. FILTERS.	T RADIAIS	۷.
	LAST P.M. 9-2	7-16 @ 20 Hours	
	LAST P.M. 9-2 79		
Don't Number	Description	7-16 @ CO HOURS Ordered	Installed
Qty Part Number	Description AIR FILTER		
Qty Part Number 1 AFZ6124 1 Z255928			
AF26124 1 2255928 	Description AIR FILTER		Installed

Copies: White: Office

Pink: Customer



Equipment Condition Report

Internal Use Only

	Rough Terrain Crane
Date: 3-1-16 Hours: 7885 Unit #: C1096 BE150104 Crane Serial #: 231938 Crane Make: GROUE Crane Model: RT9150-E	LMI Make & Model: ECOS / EKS5 LMI S/N: Engine Make & Model: CUMMINS Engine S/N: Transmission Make & Model: SPICER / SANA Transmission S/N: PBEA392545 Report Completed by: SAN HISKONOF
Filters and Fluids	
Date/Hours/Miles of Last Service: UNKNOWSA)	
Engine Oil Filter (brand and part#): SEE SPECK SHEET	Transmission Filter (brand and part#):
Engine Oil Level: XOK Requires Attention	Transmission Fluid Level: ✓OK □ Requires Attention
Fuel Filter (brand and part#): 355 Speck Sheet	Coolant Filter (brand and part#):
Fuel Filter (brand and part#): SEE Sheck Sheet	Coolant Level: ÇOK □ Requires Attention
Fuel Level: 1/4 1/2 3/4 Full	Power Steering Fluid Level:
Air Filter (brand and part#): SEE SPECK SHEET	Front Axle Differential Oil Level: 💉 OK 🗆 Requires Attention
Air Filter (brand and part#): SEE Steck Stee7	Front Axle Planetary Oil Level: ★OK □ Requires Attention
Hydraulic Filter (brand and part#): SEE SPeck Sileex	Rear Axle Differential Oil Level:
Hydraulic Fluid Level: ∠OK □ Requires Attention	Rear Axle Planetary Oil Level: 🔀 OK 🗆 Requires Attention
Pre-Inspection Comments:	

Date:

Items	Good	Repair	NA	Comments
Electric Swing Locking Device	ø.			-
Lift Cylinder	×			
Counterweight	×			
Boom	×			
Jib	Z.			
Sheaves	×			
Wire Rope Hoist #1	×			
Wire Rope Hoist #2	×			1
Headache Ball	M			
Hook Block	×			
Hydraulic Swivel	d			
Electrical Swivel	7			
Operators Cab				
Load Chart	×			
Operators Manual	×			
LMI Manual	×			
Service/Maintenance Manual	×			
Safety Manual	×			
Bubble Levels (or equivalent indicator)	×			İ
Safety Decals				
Seat	×			
Glass/Windows	XXXXXXXX			
Window/Door Slides	<i>p</i> °			
Window/Door Handles	8			
Windshield and Wipers				
Skylight Wiper	×			
Controls and Labels	~			
Control Adjustment	by the same of the			
LMI	The state of the s			
ATB	A.			
Gauges	-			
Switches	, <u> </u>			
Horn	AAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAAA			
Warning Buzzers	A			
Heater				
Defroster	7	0		
Air Conditioning				11-70 04 000
Mirrors		×		NEEDS CHARged
Catwalk and/or Handrails (holds)	X	_		
Fire Extinguisher – List Exp. Date				
ATB Lockout Flag	×			
ATB LOCKOUT Flag				
Plant				
ower Plant				
Performance Patteries		×		Engine Has BAD KNOCK (cowoze)
Batteries	×			(*)

Unit #:

Date:

Items	Good	Repair	NA	Comments
Exterior Appearance				
Clean/Degreased	×			
Paint Condition	×			
Operator Cab Panels	M			
Carrier Panels	M			
Decking	×			
Engine cover	THE			
Chassis				
Lights (headlights, marker, tail, stop, etc.)	be			
Hand Signal Decal	N N N			
Electrocution Decal (with clearance distance)	M			
Swing Decal	×			
Tires	J	J	_	
Required Inflation Pressure	×	0		
Excessive Wear	XXXXX			
Sidewall Damage	\$			
Lug Damage	, ra			
Wheel/Rim	3			
Wilcely Mill				
Travel	П			
Steering	~	-		
Brakes	×			
Drive Shaft and U-Joints	×			
Transmission		_ ~		
Transfer Case		×		LOOD VIBRATION DURING TRAVEL
Front Axle	×			
Rear Axle				
Level/Lockout Cylinders	×			
Levely Lockout Cylinders				
Outriggers Cracks	./			
	A			
Bent	XXXXXX			
Leaks	×			
Controls	×			
Locks	X			
Hoses	X			
Cylinder	-			
Superstructure				
Hoist #1	XXXX			
Hoist #2	M			
Swing Bearing	×			
Swing Box	×			
Manual/Pedal Swing Brake	×			
Manual Swing Locking Device	DEK			

Unit #: Date:

Items	Good	Repair	NA	Comments
Oil Pressure		×		1000 / FIRMO RUNCH
Cooling System		×		LOW / ENGINE RNOCK RE-CORE RADIATOR JUSTALLED
Fuel Tank and Cap	×			THE CORE MADE TO SHILLS
Exhaust System	×			
Drive Belts		A		New Belts INSTAILED
Motor Mounts	×			7,000 20012 7,000 4,100
Transmission mounts	×			
Hydraulic System				
Tank	×			
Excessive Heating of Fluid	A			
Pumps and Motors	×			
Leaks at Valve Spools or Joints	×			
Sticking Valve Spools	区			
Leaks	A			
Cylinders				
Drifting	×			
Rod Seal Leakage	×			
Leaks at Welded Joints	×			
Scored, Nicked, or Dented Rods	×			
Air System (If Applicable)				
Compressor	×			
Low Air Warning Device Tanks and Lines	×			
Leaks	×			
Leaks	A			
Mashina Oncretion Comments:				
Machine Operation Comments:	11		.)-	18 20
EDGINE HAS COUL	RWOCK 1	low or	C PR	ressure (SEE ATTACHES Relaid
— • • • • • • • • • • • • • • • • • • •	17.50	1 1 1		7
IKAUSMUSSION HAS	UIBRATIO	WH	en	TRAVELING (SEE ATTACHED ROPALR).
Post-Inspection Comments:				
l ost hispection comments.				

EXACT	Repair sheet	C#: 7 ()	O Date:	Pg. 01
Problem/ Issue/ Diagnosis:		Mechanic:	Scott Mike is	≤ Complete ∠
Inst	alled transmissi	ion and e	True Shafts	
Repair/ Replace:				
Side notes/ Specific Parts:				
Date Started: 4 / 1 / /	Date Finished: 4	111 116	Tota	al Hrs: 4.5
Problem/ Issue/ Diagnosis:		Mechanic: 5	icot, rob, mile 5	Complete X
	79	cation of		transmission
The same of the sa			1	ody BFTance
Repair/ Replace:	amazed transmissi	on to fix	leak on val	is body
Side notes/ Specific Parts:	*			
Date Started: 4/13/1	6 Date Finished: 4	113 116	Tota	al Hrs: <u>**</u> S
Problem/ Issue/ Diagnosis:		Mechanic:	Scott	Complete
Repair/ Replace:	man Mar S	2 installed	trans and	
testa	and on out	-		
	3	30 0		
Side notes/ Specific Parts:				
	The state of the s			2
Date Started: 4/ 4/	Date Finished: 4	11 10		al Hrs:
Problem/ Issue/ Diagnosis:		Mechanic:	Scott	Complete
<u> </u>	A transmission) on and	nd. Same noti	sc as
Repair/ Replace:	fore was hear	101	with trans	
1	1 .	rive Shefrs	noise was s	still there
Removed	trans again	to send b	ack to trav	iny Shop
Side notes/ Specific Parts:	0			
	\.1	S		
Date Started: 126/	Date Finished:	1261/6	Tota	al Hrs:

EXACT	Repair sheet	C#:	Date:	Pg. of
Problem/ Issue/ Diagnosis:		Mechanic: _	Soft	Complete
Repair/ Replace:	sted pulling he amaged piston &	head,	inspect Started	Found Sulling
Side notes/ Specific Parts:				
Date Started: / 25 // (Problem/ Issue/ Diagnosis:	Date Finished:	Mechanic: _	Scott	Total Hrs:Complete
Repair/ Replace: Ma	ming trains su	18	installing lift engi) - 1
Side notes/ Specific Parts: Date Started: // 24/	Jim Zhr	12110		Total Hrs: 9
Problem/ Issue/ Diagnosis:		Mechanic: _	SUN	Complete
Repair/ Replace:	mued pulling s muter mounts	engial,	Osurnect	and herd
Side notes/ Specific Parts:	Rob	1.5	M8	
Date Started: 12711 Problem/ Issue/ Diagnosis:	6 Date Finished: / /	12716 Mechanic: _	Switt	Total Hrs: 8
Repair/ Replace:	ength & herd bulket of took to V	1 from Conted Sytin Law 10	engin 3	TO TO
Date Started: 1/28//	Date Finished: //	>81/6		Total Hrs



Repair Sheet


R79/50 Date:

Pg. of

Make: _____ Crane S# : _____ Hours : _____ Model: ____ Miles: _____

Problem/ Issue/ Diagnosis: Mech	anic: Complete
Set or unit For En	give Repair
Jump Stant Suf or OTR	Swing Frazer
Set up unit For En Tump Start Sut on OTR Repair/Replace: Runard Swing Fr	in Swang unit Tokum
1-20-16	
Side notes/ Specific Parts:	
Date Started: / / Date Finished: /	Total Hrs: 3
Problem/ Issue/ Diagnosis: Mech	nanic:Complete
Repair/ Replace:	
Side notes/ Specific Parts:	
Date Started: / / Date Finished: /	/ Total Hrs:
Problem/ Issue/ Diagnosis: Mech	nanic: Complete
Repair/ Replace:	
Side notes/ Specific Parts:	
Date Started: / / Date Finished: /	Total Hrs:





AMERICAN INDUSTRIAL TRANSMISSION, INC.

20395 HANNAN PKWY WALTON HILLS, OHIO 44146 1.800.588.7515 1.440.232.9545 FAX: 1.440.232.8142

SOLD TO

SHIP TO

EXACT CRANE & EQUIPMENT 28985 AMBINA DR SOLON, OH 44139 EXACT CRANE & EQUIPMENT 28985 AMBINA DR SOLON, OH 44139

ACCOUNT	PURCH	ASE ORDER NO	(SHIP VIA	DATE SHIPPED		TERMS	INVOICE DATE	
E2234	VERBA	L	CUST	PICKUP	03/29/16	ADV	03/30/16		
	QUANTITY ITEM NUMBER				SCRIPTION	UNIT PRICE	EXTENDED PRICE		
1	1	TRANSMISSI	ON	R36000			4,000.00	4,000.00	
						ON 5577	I I I I I I I I I I I I I I I I I I I		
SUB	JECT TO A : RE MUST BE	\$500.00 RESTOCK RETURNED NO LAT	FEE. 'ER THAN .		K FEE. TRANSMISSI				
DAT	E, A 10% LA RESERVE TI	ATE FEE WILL BE CH HE RIGHT TO REFUS THORIZATION IS NE	ARGED. E LATE CO	RE RETURNS.	JRNS.				
DISC	RRANTY CO	IVERAGE BEGINS ON MS DO NOT APPLY	DATE OF TO CORE C	INSTALLATION. HARGES					
	1 j,	n ee vall. DE. Ev.n	t thought i	Maria TEE	*) :)= (}-7°	.21812		
		L		L			SALE AMOUNT	4,000.00	
COMM	ENTS:	J					MISC. CHARGES	0.00	
							SHIPPING	0.00	
							TOTAL	4,000.00	

Page 1

HAWK ENGINE & MACHINE, INC 12166 YORK ROAD. UNIT 1

REPLACE #4 CYL INSTALL HEAD AND ROCKERS ADJUST

NORTH ROYALTON, OH 44133-3602

Telephone 440-582-0900

Invoice # 4494 Invoice Date 3/10/16

Due Date: 3/10/16

Bill To: EXACT CRANE & EQUIP CORP Deliver To: EXACT CRANE & EQUIP CORP

28985 AMBINA DR SOLON, OH 44139

28985 AMBINA DR SOLON, OH 44139

Customer #: 2011012 Your PO: ISC ENG RPR Terms: cod MFR Engine Component Component _____ Item-# Description Qty Unit Price Ext-price CUM 5253887 LEVER, ROCKER 1.00 58.84 58.84 CUM 4944725 GUIDE, TAPPET 3.00 10.50 31.50 CUP 101182 CYLINDER KIT ISC 1.00 177.48 177.48 CUP 131743 GSKT KIT, UPPER 1.00 221.72 221.72 CUP 131746 GSKT KIT, LWR 1.00 141.81 141.81 12.00 3.27 39.24 ROD BRGS C CUP 171816 1.00 318.78 318.78 CUP 191866 CAMSHAFT ASSY CUP 192142 PUSHROD 12.00 13.43 161.16 CUM 3917728-2 CAPSCREW, CYL HD HEX FLN 26.00 5.63 146.38 12.48 24.96 CUM 3975487-2 GASKET, CONNECTION 2.00 CUM 3943445 CROSSHEAD 1.00 13.55 13.55 325.00 325.00 1.00 CORE CHARGE TURBO 26.73 320.76 12.00 CUP 191857 TAPPET, ROLLER 1.00 1837.15 1837.15 Svc # CYL HEAD RECONDITION (DC 323504 1114.41 1114.41 1.00 Svc # REBUILD INJECTOR AS NEEDED TEST 6 RESEAL 4 EXCHANGE 2 1.00 1112.00 1112.00 Svc # TURBO EXCHANGE 1.00 1200.00 1200.00 Svc # #4 CYL BAD DISMANTLE PART'L CLEAN AND INSPECT PARTS INSTALL LIFERS & CAM TIME

** INVOICE ** Page 2

HAWK ENGINE & MACHINE, INC

12166 YORK ROAD. UNIT 1 NORTH ROYALTON, OH

44133-3602

Telephone 440-582-0900

Invoice # 4494 Invoice Date 3/10/16

Due Date: 3/10/16

28985 AMBINA DR

SOLON, OH 44139

Bill To: EXACT CRANE & EQUIP CORP Deliver To: EXACT CRANE & EQUIP CORP

28985 AMBINA DR

SOLON, OH 44139

Customer #: 2011012 Your PO: ISC ENG RPR Terms: cod MFR Engine Component

														_											
_				-										-	-	-	-	-	-	-	-	-	-	_	

Item-#	Description	Qty Unit Price Ext-price
THANK YOU ESN 73266190		Total Parts 1,981.18 Total Labor 5,263.56 EPA & Supplies 50.00 Sales Tax 0.00 Freight 183.49
ver Itt.	J	BALANCE DUE> 7,478.23

Vaud CK 10767

Page: 1 of 1

Printed: 06/26/2015

Work Order: 1502-0003

FEB 2015 - MISC REPAIR

Problem Type:

Call Category:

Repair CMR Misc Repairs

Call Status: CLOSED

Unit Number:

RT-150-151

AVAILABLE

GROVE RT9150E ROUGH TERRAIN 150T

2011 Year: **GROVE**

License:

Serial Number:

Unit Description:

231938

Make:

Location: Status:

Western

ROUGH TERRAIN Model:

Type:

CRANE - ROUGH TERRAIN

KMs:

Hours:

Originator	Technician	Start Date	Completed Date
Natasha McAvoy	(EFT)MEERMAN	Feb-02-2015	May-25-2015
	CONTRACTING LTD.	· · · · · · · · · · · · · · · · · · ·	

Attachments / Instructions

FEB 2015 - MISC REPAIR

FEB 1, 2015 - BOB MEERMAN

-SERVICE CALL TO CHECK BOOM TELI PROBLEM

-FOUND THAT SNOW BUILD UP ON CABLE REEL TOOK BOOM LENGTH OUT OF PERAMETERS

-MANUALLY BRING IN BOOM & RE-ZERO CYL.

Page: 1 of 1

Printed: 06/26/2015

Work Order: 1412-0004

DEC 2014 - MISC REPAIR

Problem Type:

Repair

Call Category:

CMR Misc Repairs

License:

Call Status:

CLOSED

Unit Number: Unit Description: RT-150-151

GROVE RT9150E ROUGH TERRAIN 150T

Serial Number: 231938

Location: Status:

Western **AVAILABLE**

2011 Year:

Make: GROVE

Model: ROUGH TERRAIN

CRANE - ROUGH TERRAIN Type:

KMs: Hours:

Originator	Technician	Start Date	Completed Date
	(EFT)MEERMAN	Dec-01-2014	Mar-23-2015
	CONTRACTING LTD.		

Attachments / Instructions

DEC 2014 - MISC REPAIR

DEC 10, 2014 - BOB MEERMAN

-TROUBLESHOOTING COMPUTER PROBLEMS, A2B & CRANE FUNCTIONS

DEC 13, 2014 - BOB MEERMAN

-WORKING WITH SRONGCO ON A2B & COMPUTER PROBLEMS

DEC 14. 2014 - BOB MEERMAN

-WORKING ON COMPUTER PROBLEMS WITH STRONGCO REP

Page: 1 of 1

Printed: 06/26/2015

Work Order: 1409-0020

SEPT 2014 - MISC REPAIRS

Problem Type:

Repair

Call Category:

CMR Misc Repairs

Call Status:

CLOSED

Unit Number:

RT-150-151

GROVE RT9150E ROUGH TERRAIN 150T

Year: 2011 License:

Unit Description: Serial Number:

231938

Make: **GROVE**

Location:

Western

Model: ROUGH TERRAIN

Status:

AVAILABLE

Type:

CRANE - ROUGH TERRAIN

KMs:

Hours:

Originator	Technician	Start Date	Completed Date	
	UNASSIGNED	Sep-08-2014	Nov-25-2014	
	Attachments / Instru	ctions		

SEPT 2014 - MISC REPAIRS

SEPT 12, 2014 - BOB MEERMAN

-REMOVE COVERS & GUARDS & REPLACE

-MISSING & BROKEN CLAMPS ON MUFFLER

SEPT 22, 2014 - MIKE WOOD

-HYD LEAK AT BASE OF SCOPE CYL

-HYD LEAK AT VALVE AT UPPER CENTER

-REPLACE 2 HYD HOSES FROM PUMP TO SWIVEL & HYD FILTERS BY FUEL TANK

Page: 1 of 1

Printed: 06/26/2015

Work Order: 1408-0006

AUG 2014 - MISC REPAIRS

Problem Type:

Repair

Call Category:

CMR Misc Repairs

License:

Call Status:

CLOSED

Unit Number:

RT-150-151

GROVE RT9150E ROUGH TERRAIN 150T

Unit Description: Serial Number:

231938

Location:

Status:

Western **AVAILABLE** Year: 2011

GROVE

Make: Model: ROUGH TERRAIN

Type:

CRANE - ROUGH TERRAIN

KMs: Hours:

Originator	Technician	Start Date Cor	
	(EFT)MEERMAN	Aug-05-2014	Oct-16-2014
	CONTRACTING LTD.		

Attachments / Instructions

AUG 2014 - MISC REPAIRS

AUG 1 - BOB MEERMAN

ERROR CODES COMING UP ON ECOS. CONTACT STRONGCO & WORKING WITH REP.

AUG 20 - BOB MEERMAN

LOOKING FOR OIL LEAK IN BOOM. REMOVE TOP COVER & GO INSIDE BOOM. SLIGHT OIL LEAK AT ROD HEAD. CAN'T FIND WHERE IT'S COMING FROM. WILL CHECK FURTHER WHEN CRANE IS AVAILABLE.

AUG 30 - BOB MEERMAN **RE-SPOOL HOIST CABLE.**

REPAIR OIL LEAK ON QUICK COUPLER FOR O/R BOX.

Year:

Page: 1 of 1

Printed: 06/26/2015

Work Order: 1407-0069

JULY 2014 - MISC REPAIRS

Problem Type: Repair

2011

Call Category: **CMR Misc Repairs**

License:

Call Status: CLOSED

Unit Number: RT-150-151

Unit Description:

GROVE RT9150E ROUGH TERRAIN 150T Make: **GROVE**

Model: ROUGH TERRAIN Serial Number: 231938 Location: Western Type: **CRANE - ROUGH TERRAIN**

Status: **AVAILABLE** KMs: Hours:

Originator	Technician	Start Date	Completed Date	
	WOOD, MIKE	Jul-21-2014	Sep-09-2014	
	Attachments / Instru	ctions		

JULY 2014 - MISC REPAIRS JULY 18/14 - BOB BMEERMAN

-INSTALL NEW PROX SWITCH FOR REAR STEER CENTERING LIGHT

JULY 19/14 - BOB MEERMAN

-TROUBLESHOOTING NOISY SWING, SEEMS TO BE COMING FROM REAR O/R BOX, BOX NEEDS TO BE REMOVED SO MOUNTING PINS CAN BE LUBED

JULY 23/14 - BOB MEERMAN

-SET UP CRANE & GREASE INNER & OUTER BOOM SLIDES

Page: 1 of 1

Printed: 06/26/2015

Work Order: 1406-0010

JUNE 2014 - MISC REPAIRS

Problem Type:

Repair

Call Category:

CMR Misc Repairs

License:

Call Status:

CLOSED

Unit Number:

Location:

Status:

Unit Description:

RT-150-151

GROVE RT9150E ROUGH TERRAIN 150T

231938

Serial Number:

Western **AVAILABLE** Year: 2011

Make: **GROVE**

Model: **ROUGH TERRAIN** Type: **CRANE - ROUGH TERRAIN**

KMs:

Hours:

Originator	Technician	Start Date	Completed Date
	WOOD, MIKE	Jun-04-2014	Jul-30-2014
			<u> </u>

Attachments / Instructions

June 4/14 - Mike Wood

-Repair engine #1 cylinder, exhaust spring broken. Pull valve cover, replace spring, bridge & rocker.

-Set valves on #1 & reinstall valve cover.

June 6/14 - Mike Wood

-Replace both push tube on #1 cylinder. Tubes were bent from spring failure and straightered, needed to replace.

June 16/14 - Brent Owen

-Error code 1218 coming up on computer screen. The machine had been shut off and restarted - code dropped after a dozen or so off and on.





SERVICE REPOR	RT
Date: 1/6/1/8/17	
Customer's Name: Bigge	Customer P.O. #
Job Location: Hous for TK M/M/T:	_
as the second of	*B Trip Mileage
Describe Defects & Cause of Failure: engine idler pull Squeeking, needs engine service, replace Repairs Completed: engine idler ally remove or ally removed at replaced, all corrected a replaced drained oil to installed engine cover latch	
	* (
Qty Part Number Description	Ordered Installed
1 3697 fuel Eilter (primary) 1 3697 fuel Eilter 1 LF 9009 oil Eilter 1 397 4102 tensioner pulley	
Recommendations:	
Technician: Julian Rios/Goerge Perec	
Customer Job	Complete: Labor: Reg
Customer Signature:	No,□ 0.1

Copies: White: Office

Pink: Customer





SERVI	CE REPORT		
Date: 4-25-2017			
Customer's Name: AGL	Customer	P.O. #	
Job Location: SRT+35 south M/M/T:	Grove RT9150 5	Hours: 84	183
Equipment # BE150104 Serial #			
Describe Defects & Cause of Failure: Reflace	mindron Coble		
	1.	, ,	(+ #
Repairs Completed: Tastalled new cab Black and And two block w	ik on main dron.	Taddled	
Black and And two black w	reight. Test for paper	tunction.	
			1.04
	(4) 4 · ·	· · ·	
	to the	MALL AND THE STREET	
	CV 200	Walter F	
i de la constante de la consta	N. Clare		
15 11 11 11 11 11 11 11 11	the state of the s	14	
Qty Part Number	Description	Ordered	Installed
			17
	,		
Recommendations:	1		
	7000-1-17-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-		
- 2 V//	1		
Technician: By Customer	Inh Commission	Labor: Reg	
Name: FGL	Job Complete:	•	
Customer	Yes 🗸 No 🗅	0	





SERVICE REPORT		
Date: 6/13/17		
Customer's Name: / AMCO Customer P.O.	#	
Job Location: CP Chem M/M/TOROVE 9150E	Hours: 6	697
Equipment # BE1S0104 Serial # Trip Milea	ge	
Describe Defects & Cause of Failure: Active /10,1 error - Swin	ng ang	le
Repairs Completed: Leplaced swing angle MNSON. Wiring for damage- could not see any issue Ron Machine to check for errors- Giffen repair	(heilea - nor) re
		14.90
Qty Part Number Description 1 GK03326912 Agle Sensor assembly	Ordered	Installed
TO RESIDE THE SHIPE SHIPE		
Recommendations:		
A 1 /		
Technician: Austr Bully I laborated	r. Pag	
Customer Name: Systems (1) See No D	or: Reg O.T.	
Customer Signature:	encount is	

Copies: White: Office

Pink: Customer





	SERVICE REPORT	
vate: 7/10/17		
ustomer's Name: Ref. Che	Customer I	2.0.#
b Location: baytown tx	M/M/T: Grove RT 9150 E	Hours: 9065
quipment # BEI50104		Mileage
	e: Grave wont Tele.	
epairs Completed: Crave we was connected correctly. Casing invalid luby. Put in valid luby.	wildn't tele. actu custome evrece y but they now Bailed to k angle net fetting never tele. A angle of clane forctions pro	td jis. jib connect luff Connected luff porly.
Qty Part Number	Description	Ordered Installed
Recommendations:		
Technician: Joseph Oyuz (a Customer Name: L. Mandari Customer Signature: J. Mandari	Job Complete: Yes No D	Labor: RegO.T

Copies: White: Office

Pink: Customer



Copies: White: Office



14800 Jersey Shore Dr. Houston, TX 77047 (713) 434-0995

		SERVICE REPORT	
Customer' Job Locati Equipmen	7-31-17 s Name:Res ton:Bay for t #BE15010	OWN M/M/T: Grove R+9150 E Hours: 9/1 OU Serial # 231938 Trip Mileage 25	m Wa
Describe I	Defects & Cause of F	ailure: Out rigger ads leaking Right	Rear
Repairs C	ompleted: Re	Placed 4 ads + 4 orings	
Qty	Part Number	Description Ordered	Installed
Recomm	endations:		
Technicia Custome Name: Custome Signature	On the Mo	Job Complete: Labor: Reg	

Pink: Customer





	SERVICE REPORT	
Date: 8-24-17		
Customer's Name: REF-Cher	Customer P.O. M/M/T: GROVE RT 9150 E Serial # Trip Milea	#
Job Location: Balton, TX	M/M/T: GROVE RT 9150E	Hours: 9/58
Equipment # <u>BE 150164</u>	Serial # Trip Milea	age
	Boom out of Sync-	
Repairs Completed: Respace Repairs Completed: Repairs Respace Repairs Completed: Repairs	I boom system, customer so move moin block white using 2 test good	id they jib.
Qty Part Number	Description	Ordered Installed
Recommendations:		
Technician: Broduy Liu		
Customer Ref-Chem	Job Complete: Laborate	or: Reg
Customer Name: Customer Signature: Customer Signa	Yes ✓ No □	O.T

Copies: White: Office

Pink: Customer





	SER	VICE RE	PORT			
Date: 0/6/17						
Customer's Name: Rec				ustomer P.O. #		
Job Location: Bayton	M/M/	T: Grove	RT9150		Hours: 90	070
Equipment # <u>BE 150 104</u>	Serial	# 23 193	8	_ Trip Mileag	ge	
Describe Defects & Cause of F	Failure: Cyum	lest boo	m sync.			
Repairs Completed: books Yet and clean of Cleaner out thomas and tested crane ket on tall	tele los	looked looked resynce	lika Klm 1 Loom fol errors Also	corre had ke	en tel	e n kywyteg Ktel
	0					
Qty Part Number		Descript	ion		Ordered	Installed
1 471784	latch lait		ion		Ordered	Mistaned
Recommendations:						
Recommendations.						
Technician: Oscill Or	116					
Customer Frank	Miller		Job Complete:	Labo	r: Reg	
Customer 4 S M	M		Yes No No		O.T	
Signature:	Mul					

Copies: White: Office

Pink: Customer





	SERVICE REPORT
BF 1566	M/M/T: RT9150E Hours: 4301
Repairs Completed: OI Lower State	F. full pm fixed K on Valve Cove/s Reflused F. Xed oil Leak on F. Hel F. Xed HY DWILL Leak PID 300 PE(ty in SPECTION PPer and Lowe/ FCMf Sensor Wire Eleaned With Eletrical Cleane/ With Eletrical Cleane/ Wire on Winch Missor on Oil Cooler HOSE
Technician: 1. The Transcription Customer Name: Customer Signature:	Job Complete: Labor: Reg

Copies: White: Office

Pink: Customer



Richmond, VA 804-271-9356 North SLC, UT 801-292-2453

Houston, TX 713-456-3086 **TOLL FREE** 888-337-2444

CONTACT NAME & NO).					

MAKE		MODEL	SERIAL NUMBER		HOURS	UNIT NUMBER
GROVE		RT9150		231938	1017	75 BE150104
SEDVICE DECLIES			WA HAN WATER			
SERVICE REQUES		AIN AETED DEINIST	ALLING THE CROSS T	ADDET FOR	ALVE BOCKER O	ALCYCLINDED #3
ONLY LASTED 4 HOUR		SAIN AFTER REINST	ALLING THE CROSS T	APPETFOR	VALVE ROCKER C	IN CYCLINDER #2
	-	THE RESERVE OF THE PARTY OF THE				
REPAIRS MADE						
ORDERED AND INSTA	LLED NEW	PUSH RODS, TAPP	ETS, ROCKERS, ADJUS	STING SCRE	WS ON CYLINDER	#2. ADJUSTED ALL VALV
ADJUSTED EXH VALVE						
					101-03001	
COMMENTS					2	
			22.00 20.00 10.			
PART NUMBER	QNTY	DESCRIPTION			INSTALLED	ORDERED





		S	SERVIC	E REPO	RT			
	-25-2017 r's Name: AGL					D.O.	W.	
	tion: SRT+35	71		- 1	Cust	tomer P.O.	#	103
								283
Equipme	nt # <u>BE150104</u>		Serial #	23 938		Trip Milea	ge	
Describe	Defects & Cause of I	Failure: Re	place m	Bindsor	Cable	e)	.05.	-
1/4/2	7	ă .						
Repairs (Completed: Jastal	led new two bloc	cable le weig	OA M	dia droi	a. Jas por fune	daled tion.	
		- 4		Ĭ ^A	Q.K.			ś
			1		Maria Con			
-				Block.		, A.D.		
					- 10			
	Hint:				187			
					34.7			
	All-All In				Marie Comment			
	-							
	-							
				• #				
Qty	Part Number		I	Description			Ordered	Installed
					-1			
					4			
Recomm	endations:		7 -					
< 3		v . e	n				9	
		1			· ·			
Technicia	in: Byan Valla							
Customer	0			Jo	b Complete:	Labo	or: Reg	
Name:	_T6L				s 🗸 No 🗆		O.T	
Customer								. 6

Copies: White: Office

Pink: Customer





SERVICE REPORT 16 14 028 556
Date: 6.18.18
Customer's Name: Customer P.O. #
Job Location: HOUSter Shop M/M/T: Grove BT 9150E Hours: 10, 724
Equipment # BE 150 104 Serial # 73/938 Trip Mileage
Describe Defects & Cause of Failure:
Repairs Completed: Austin and Brad Reliqued Engine- Reliqued Aux Becket - Reliqued uffer cap Mirror Touched uf scars on JiB - Molly Jacks and Center Beering - Dino Reliaced worn out Callars on Jack Pads - Installed Keep in Aux latch - Replaced Keepers and Chains on hock blak - Grease Barn - lube Cables - Checked Speed on main and Aux Windh- Reflaced Aux Cable - Ordered Key for Ign; tion - Tristalled fire ext - Reflaced caps on out rigger Jacks - Replaced Two Batteries - Grease house lock- New Econ on Engine nut working Reflaced it With the old one - Clean JiB holes - Checked all Fluids - Blower out Dirt from Arc Condenser, Filters, and coolers
Qty Part Number Description Ordered Installed
102294477 Mirror
1 90016097 Switch Assy 1 7826000641 3/4" OPEN Wedge
4 7258001543 Cap
4 618400 2997 Cap Bracket
Recommendations: 1# 19 mm Wive Rope /4@+ 6:30 8000 117 = Yoke /4@+
6593000 137 = levers /40+ 983410000 6= Spring Kit
Technician:) U l'an / Creerge
Customer Name: Job Complete: Labor: Reg
Customer Signature: Yes No O.T

Copies: White: Office

Pink: Customer

Eqt.# Model	Serial #	Hours Location:	Last P.M.	Hour	Date	Received	Ready	Delivery	GPS ·
BE150104 RT9150E	231938	11,313 YARD	Service	10,224	6/18/2018				
Make GROVE	0	job#		Customer	ETR	Tech	Status	Repair date	Actual
Off and inspection	Needed repairs			damage	(HOURS)	2000		112/2010	repair time
PM service past due					л	CM/TV	DONE	1/21/2019	
Update 3rd party					1	kempco	DONE	10/8/2019	
No GPS installed					בי				
Front left headlight not working	ot working				1	CM/TV	DONE	4/24/2019	
Need to stamp ball in	Need to stamp ball information onto ball or install new ID tag	stall new ID tag			1	CM/TV	DONE	4/25/2019	
Need keeper pin & touch up paint on ball	uch up paint on ball				1	CM/TV	DONE	4/25/2019	
Hyd level is low					2	CM/KL	DONE	10/11/2019	
Side flow control valv	Side flow control valve is very noisy when operating crane	ating crane			8	CM/TV	DONE	4/29/2019	
Paint on crane is fade	Paint on crane is faded & has some scratches/previous cement splatter	orevious cement s	splatter		5				
Service batteries & ch	Service batteries & check alternator output (light on on display)	ht on on display)			3	CM/TV	DONE	4/24/2019	
Grease drive train					2	CM/TV	DONE	4/25/2019	
Check travel brakes, f	Check travel brakes, feels like a set not releasing all the way	ng all the way			4	CM/TV	DONE	4/24/2019	
Need molly or lube on outrigger jacks	n outrigger jacks				1	CM/TV	DONE	4/25/2019	
Need molly on slew ring bearing	ing bearing				1	CM/TV	DONE	4/24/2019	
Hi speed on both joys	Hi speed on both joysticks doesn't work also with tele	ith tele			3	CM/TV	DONE	4/25/2019	
Blow out radiator, hy	Blow out radiator, hyd cooler, a/c condenser & filters	ι filters			1	CM/TV	DONE	4/26/2019	
Check 134a in a/c system	tem				4	CM/TV	DONE	4/29/2019	
Update fire ext.					1	CM/TV	DONE	4/25/2019	
Replace missing hood latch	latch				1	CM/TV	DONE	4/24/2019	
Wash engine					1	washguys			
Upper T/M needs washing	shing				1	washguys			
Telescope has no fast mode	mode				4	CM/TV	DONE	4/29/2019	
Lube upper/lower tele	Lube upper/lower tele & side pins, very dry				1	CM/TV	DONE	4/24/2019	
Lube cables					2	CM/TV	DONE	4/25/2019	
Rear main seal is leaking	ing				40	CM/KL	Done	10/10/2019	5
Hi speed on winches & tele not working	& tele not working				6	CM/TV	DONE	4/24/2019	•
Grease upper/lower crane	crane				2	CM/TV	DONE	4/25/2019	
Crane needs to be washed	shed				1	washguys			
Replace clamp on exhaust	naust				1	CM/TV	DONE	4/24/2019	
Replace heater valves					2	CM/TV	DONE	4/25/2019	

Tech

16-16-19 Date



Sequence Number 567	
---------------------	--

Information

Information	
Service Type	✓ Maintenance
Maintenance Type	✓ General Repair
	Damage Repair
	Warranty
	Scheduled Maintenance
Equipment Type	R/T
Date/Time:	10-17-2019
Equipment Number:	BE150104
Make:	Grove
Model:	RT9150E
Serial Number:	231938
Customer Name:	Berdal
Jobsite Name:	Waste water
Jobsite Address:	https://www.google.com/maps/search/?query=30.82500,- 97.54585&query_place_id=ChIJd9szop8IRYYRdlfSQ0_dDXE&api=1&hl=en Current Location: Jarrell
Job Number:	ldk

Details of work

Details of Work	
Travel to job by:	Air
	✓ Bigge Vehicle
	Personal Vehicle
	Rental Car
Weather conditions:	✓ Clear
	High Wind
	Rain
	Snow
	Ice
	✓ Excessive Heat
	Excessive Cold
Description of initial call out / reported issue:	Ac belt broke



Work performed:	Changed ac belt
Parts used:	Ac belt
Were there any issues or delays?	No
Follow up work / recommendations:	None
Time arrived on site	02:20 PM (-5 GMT)
Time equipment was back in service (This may differ from time left site)	04:22 PM (-5 GMT)
Hour Meter Reading:	11365
Hour Meter	





Annual Inspection Sticker



Acceptance


Acknowledgment	By my signature below, I certify that all work has been performed to my satisfaction.	
	Thank You	



	1 30.825018, -97.545828
Name:	John Elam
Signature	als
Name:	Travis Vincent
Signature	1/



Form Locations





Sequence Number 621	
---------------------	--

Information

information	
Service Type	✓ Maintenance
Maintenance Type	✓ General Repair
	Damage Repair
	Warranty
	Scheduled Maintenance
Equipment Type	R/T
Date/Time:	10-29-2019
Equipment Number:	BE150104
Make:	Grove
Model:	RT9150E
Serial Number:	231938
Customer Name:	Bernal
Jobsite Name:	Water plant
Jobsite Address:	https://www.google.com/maps/search/?query=30.82497,- 97.54577&query_place_id=ChIJd9szop8IRYYRdlfSQ0_dDXE&api=1&hl=en Current Location: Jarrell
Job Number:	ldk

Details of work

Details of work	
Travel to job by:	Air
	✓ Bigge Vehicle
	Personal Vehicle
	Rental Car
Weather conditions:	Clear
	High Wind
	✓ Rain
	Snow
	Ice
	Excessive Heat
	✓ Excessive Cold
Description of initial call out / reported issue:	Belt is sqeaking and horn don't work



Work performed:	Had to replace the belt and tightened wires on horn
Parts used:	One belt for AC
Were there any issues or delays?	No
Follow up work / recommendations:	No
Time arrived on site	10:00 AM (-5 GMT)
Time equipment was back in service (This may differ from time left site)	12:17 PM (-5 GMT)
Hour Meter Reading:	11456

Hour Meter



Annual Inspection Sticker



Acceptance

Acknowledgment	By my signature below, I certify that all work has been performed to my satisfaction.	
	Thank You	



	1 30.824906, -97.545788
Name:	John Elam
Signature	and
Name:	Travis Vincent
Signature	T/



Form Locations

