

## 2013 Vehicle Maintenance

Vin# 1NP5LBTX57D654375

L-565	2007 PETERBUILT		Steer Tires 425/65R22.5
License		154291	Drive Tires 12R24.5
<u>DATE</u>	<u>Company parts/svcs</u>	<u>Purchased from:</u>	<u>Part #/Description</u>
1/23/13	Cage BILL	2528 hair pin/B145 Zip tie	Tag 295/75R22.5
1/25/13	SHOP		used to adjust cables??? Not on VM log
1/28/13	Peterbilt of WY	R23-6002	Adjusted cables/aux
3/27/13	SENT FROM VERNAL	ATO-1750-4C	Arm Assy Wiper ARC-wiper arm passenger side
3/5/13	Peterbilt of WY	ring lock/washer/clamp	Aux Transmission
3/6/13		3050A	\$ 98.19
		12R24.5 tire	\$ 11.97
		9147	
3/7/13	MPE	90-664 female air fitting	barnes
3/11/13		replaced exhaust minifold gasket and seals	
		1974	\$ 985.14
3/22/13	NAPA	3050A/3050	2" amber (6) 2" red (3) lights
		windshield washer	1 qt washer fluid
		3050	\$ 5.24
		brakeclean 09147	replaced turbo gaskets
		3050	
		2" red light	
		coolant 3200-55	added 1 gal coolant
		90200 & Valve core???	1976
		replaced valve core RRI tire	\$ 11.61
3/25/13	Peterbilt of WY	V1303-01-03653	remove iod brownie/replace with rebuilt from Vernal UT
		PL1066 bushing upper	\$ 75.16
		3050	\$ 16.60
		Light--replaced marker light	
		99060/99782/99763	1976
		Bolts/nuts/washers	\$ 5.03
		3050	\$ 1.18
		replaced marker lights	\$ 15.09
		3050A	\$ 30.18
		11R24.5	
		replaced LRO Tire	
		replaced ujoints in rear driveline	\$ 276.44
3/25/13	MPE	SPL250-3X	
		99060/99782/99763	
		Brakeclean 091314	
		cleared aux trans parts	\$ 2.62
		reinstalled aux transmission	\$ 32.02
		filled aux trans	\$ 70.44
		3 gallons of 50 WT for Brownie	
		3/26/13	
		mpe	\$ 31.85
		54x10 fitting	\$ 1,546.50
		Homax	
		Snatch Block 10"	
		1054009-20 50 WT oil	
		50 Wt	
		LF691A	
		Oil filter	250 hour service
		FF5319	2043
		Fuel Filter	\$ 10.41
		FF105	\$ 8.39
			\$ 3.74

NAPA		Lucas oil treatment	10002	\$ 37.79
Honax	15W40	1056009-1		\$ 102.63
Snow dist		Grease		\$ 7.75
4/23/13	D&H welding	Auxilory trans		
5/1/13	Wy Rigging	1 1/8" Bridle		\$ 6,550.70
5/14/13	MPE	2396808 Clamp		\$ 133.87
5/15/13	MPE	FG9115 Union		\$ 165.38
5/16/13	Peterbilt of WY			\$ 24.75
5/27/13	Barnes			\$ 20.64
NAPA		99108/99763/99724		\$ 73.05
6/6/13	Snow dist	901001 Valve core		\$ 0.79
6/11/13	barnes	02382-120		\$ 0.59
6/12/13	Pacific Steel	81260 glad hand		
6/13/13	barnes	square tube/steel		
		99763 wahser		
		99108 1/2 bolt		
		715--1421 grease fittings (2)		
		1 1/8 bridle		
7/1/13	Wy rigging	new bridle on truck		\$ 165.38
7/9/13	NAPA	replaced grease zerk		\$ 0.73
		7151026 grease zerk		
		02382-209		
7/15/13	MG IL	Greased truck		\$ 8.92
7/15/13	NAPA	reflective sun shade		\$ 6.29
7/16/13	WYO Rigging	new bridle on truck		\$ 165.38
7/19/13	D&H welding	repaired cracks on frame bed and chain hanger		\$ 1,160.25
7/24/13		repaired exhaust leak		
8/6/13	WY rigging	2203		\$ 580.07
8/6/13	Snow dist	02382-120 grease		
NAPA		1/2" helicoil 770 3121		
BARNES		repaired threads in front bumper		
?		replaced grease zerk		
		new bolt for front bumper		
8/27/14		99106 bolt		
		38" tire chain repair links		
		38239 Cotter pin		
		1		
8/28/13	MPE			
		53962 6" oval SST LED light		
		250 hour service		
		B99 oil filter		
		BF1259 Fuel filter		
		BF7587 Fuel filter		
		10529554 15W90 oil		
		02382-120 Grease		
		Greased truck		
		10002 LUCA'S		
		AF25248 air filter		
		adjusted brakes		
		rotated steer tires		

8/30/13	Fleet Pride		EL22040 Junction Box	repaired wiring to lights	1	2264	\$ 17.20
	BARNES		23039 ring terminal				\$ 14.32
9/12/13	NAPA		53962 light				\$ 47.48
	Fleetpride		7151021 Grease Zerk	Replaced dc bad grease zerk			\$ 0.73
10/7/13	Barnes		8260 side fastener	repaired tire chain			\$ 10.70
			23846 connector	repaired wiring to work lights and switch in cab			\$ 0.49
			23849 quick connector				\$ 0.94
			32849-1 QC				\$ 0.38
10/13/13	Wyo Rigging		23823 Ring Terminal	new bridle for Truck			\$ 165.38
10/21/13	MPE		1 1/8" Bridle				
			AC1001 Cartridge	replaced airdryer cartridge			
11/2/13	NAPA		1002 Lucas	200 hour service			
			Homax	1052955 15W40 oil	10 gal		\$ 93.80
			snow dist	02382-120 grease	3		
			MPE	B99 oil filter			
			BF7587 FF				
			BF-1259 Fuel filter				
			WF2017 Water filter				
			TR546D Valve Stem	replaced valve stem right steer tire			
			90180 Valve Cap	replaced missing valve cap RRI			
			Glass cleaner	cleaning supplies for truck			
11/11/13	sams club		F315-800 Battery	replaced batteries warranty			
11/21/13	fleetpride		safety inspection				
12/4/13	UHP inspection		MW1103BK Hub Cap	replaced hub cap on drive axle			
	MPE		MW1209BK Hub Cap				
			2536 cotter pin				
			4651 high beam	replaced driver side high beam			
			425f65R22.5	replaced driver side steer tire 1			
12/6/13	MPE		5632 Brakeline antifreeze	airline antifreeze for truck			
12/9/13	MPE		8025-12 diesel 9-1-1	added to gelled fuel			
12/13/14			wash				
12/26/13	WY Rigging		1 1/8" Bridle	new bridle and spare	2		\$ 418.12
	NAPA		23-2117 floor mat	new floor mat			\$ 10.49

<u>2014</u>	<u>Vehicle Maintenance</u>			Vin# 1NP5LBTX57D654375		
<u>License</u>	<u>Company parts/svcs</u>	<u>Purchased from:</u>	<u>Part #/Description</u>	<u>WORK PERFORMED</u>		
<u>DATE</u>				<u>MILEAGE</u>		
1/10/14	NAPA	Snow Distributing	10002 Lucas Grease	200 Hour Service greased truck	2610	\$ 27.29
		Homax	02382-120 Grease			\$ 11.61
	MPE	B99 OF	1052955-1 15W 40 oil	42 qts		\$ 103.18
		BF1259 FF				\$ 10.22
		BF7587 FF				\$ 9.71
		SPL250 3X u joint		replaced u joints on driveline output side of azu transmission		\$ 8.53
		O rings		repainted hydraulic leaks		\$ 324.51
	NAPA	08880 brakeen			2	
	Barnes	KP86914 Terminal			3	\$ 1.05
	MPE	2352 connector shell		repaired wiring harness to front right turn/marker light		\$ 0.91
		KP81235 seal				\$ 0.50
		H4656 High beam		replaced right high beam headlight		\$ 7.71
		7352 retain male terminal				
		Q276016002 switch		replaced driver side mirror control switch	2713	\$ 144.17
1/27/14	Peterbilt	ubolt for winch				\$ 41.29
2/14/14	CMI Teco	Wash		Truck Wash		\$ 96.00
	GSS	BF1259 Fuel filter		changed fuel filters		\$ 9.71
2/7/14	MPE	BF7587 fuel filter				\$ 8.53
		8080-06		addedPS 911 to gelled fuel		\$ 31.66
		TS21 Tarp Straps		tarp straps for truck		\$ 5.28
		1 1/8" x 175' winch cable		replaced cable winch line		\$ 1,010.63
		u bolt		replaced winch line u bolt		
		1 1/8" osha know and wedges				\$ 78.38
		10352955-1 15W40 oil		200 hour service	2793	\$ 93.80
2/12/14	WY Rigging	10002 Lucas		additive		\$ 27.29
	CMI Teco	B99 Oil filter				
		BF1259 FF				\$ 10.22
		Snow Distributing	02382-120 Grease			\$ 9.71
	fleetcpride	7400 bulb		replaced bulb in beacon light		\$ 0.00
				adjusted clutch		\$ 0.88
	Barnes	33848 self tap screw		repaired winch console		\$ 19.92
2/26/14	Peterbilt	2543376 cap		replaced oil fill cap		\$ 0.22
	Barnes	99027 3/16 bolt		replaced bolts in transmission inspection cover		

	MPE	2415645 cap as		\$ 10.47
3/4/14	GSS	Wash n scrub	Truck Wash	\$ 96.00
4/2/14	NAPA	091847 brakleen		\$ 2.30
4/14/14	Barnes	98106 1/2 bolt	replaced bumper bolt	\$ 0.41
	overall supply	212 nut hole loosener		\$ 10.45
4/23/14	Peterbilt	229635 valve	replaced TW1 valve for location brake	\$ 56.24
	Barnes	10745 ferrule	repaired airline	\$ 0.33
	sutherlands	10853-01 insert		\$ 0.24
		shovel		\$ 9.99
		broom		\$ 15.99
4/27/14	Snow Distributing	02382-120 Grease	Greased and inspected truck	2849
5/16/14	record supply	8600889	24SI pat mt 160 amp dif ALTERNATOR	2927
	NAPA	Switch SW181	replaced battery disconnect switch	\$ 59.52
			swapped out 3 batteries from 540 into 565	\$ 0.00
5/22/14	Peterbilt	13-04711 support	replaced hood bumper stops	\$ 60.40
	Snow Distributing	02382-120 grease	greased truck	\$ 11.61
		sonitomo 425/65R 22.5 tire	replaced left steer tier (used)	
	Peterbilt	2200210 floor mats	replaced floor mats	\$ 30.67
		7/16 x 6 bolt	replaced broken bolt on front of right walking beam	
		Lock nut		
5/23/14	Barnes	10754 1/4 female fitting	repaired grease lines to front spring pins	\$ 7.44
	vernal	1/2" ratchet binder	replaced 3 1/2" ratched binders	
	WYO Rigging	pick up sling	new sling for truck	\$ 90.20
5/28/14	Barnes	2537 hair pin clip	new clip for clevis pin	\$ 1.25
5/29/14	ghosttown	20129LTDC	installed CB radio	\$ 136.49
			nuts for 1 1/8 clevis's	\$ 16.84
5/30/14	Wear parts	1g177949 nut		\$ 119.91
	wyo rigging	g1100 hook	new hooks for chain slings	\$ 3.49
	NAPA Wright	59 x 3 fitting	repair air leak	\$ 3.17
		59 x 4 fitting		
		59 x 5 fitting		\$ 4.97
6/5/14	MPE	TSM4P15W antenna	replaced CB antennas	2949
6/16/14	MPE	D61-6002-004 starter	warranty consideration	\$ 433.19
6/20/14	HOMAX	1052955-1 15W40 oil	200 hour service	3006
	Snow Distributing	02382-120 grease		\$ 89.20
	MPE	1002 Lucas		\$ 11.61
		B99 OF		\$ 27.99
		BF1259 FF		\$ 10.54
		BF7587 FF		\$ 9.91
	NAPA	901001 valve core	replaced valve core LFE LRO	\$ 8.77
	Sams club	washer fluid	filled windshield reservoir	\$ 1.18
	MPE	D61-6002-004 starter	replaced starter waiting on warranty	\$ 1.97
7/11/14	Vernal	TS21 Taip Straps		\$ 433.19
				\$ 2.64

7/24/14	Barnes	99106 1/2 bolt			\$ 0.41
	Vernal	12R24.5 tire	replaced tires on rear drive axle		\$ 990.00
7/30/14	Snow Distributing	00232-120 greas	greased truck	3102	\$ 11.61
8/4/14	WY rigging	sling hooks 1/2"		2	\$ 114.20
8/12/14	ITP		repair drivelines	3128	\$ 2,871.73
	MG Oil	02387-029 grease	grease tube for truck		\$ 4.68
	Barnes	99108 1/2 bolt	new hardware for carrier bearing		\$ 0.84
					\$ 0.72
					\$ 0.20
					\$ 0.34
					\$ 2.62
	NAPA	08880 brakeleen	clean driveline parts		\$ 173.25
8/25/14	WY Rigging	chain sling		3155	\$ 1.19
9/22/14	MPE	11P0436 gasket	repaired fuel leak on primer pump		\$ 217.77
9/24/14	WY Rigging	chain sling		3157	\$ 209.06
9/27/14	WY rigging	1 1/8" bridle	new bridle for truck		\$ 18.09
	Vernal	TS31 tarp strap	new tarp straps for truck		\$ 11.61
	Snow Distributing	02382-120 grease	greased truck		\$ 15.00
	MPE	30-18 wipers	replaced wiper blades		
	Peterbilt	MF0003p mudflap	replaced mudflaps on front fenders	3150	\$ 34.67
10/10/14	MPE	AC1001 cartridge	replaced air dryer cartridge	3157	\$ 21.53
10/27/14	Homax	1052955-1 15W40 oil	200 hour service	3181	\$ 89.20
	MPE	10002 lucas			\$ 27.99
	Snow Distributing	02382-120 grease			\$ 11.61
	MPE	B99 oil filter			\$ 10.54
		BF7587 fuel filter			\$ 8.77
		BF134 coolant filter			\$ 9.91
		3050 A led light	replaced clearance light		\$ 5.96
		4417-1 bulb	replaced work light bulb		\$ 12.07
		BF1259 FF	changed fuel filters		\$ 9.59
12/31/14	MPE	BF7587 FF			\$ 8.86
		1080-06 Power Service	added supplement to fuel		\$ 15.35
12/10/14	dan eldredge	Inspected 12/10/13			\$ 15.00

<u>2015</u>	<u>Vehicle Maintenance</u>	Vin# 1NP5LBTX57D654375	year end	58521	3401
L-565	2007 PETERBUILT	Inspected 12/16/2015	Steer Tires	425/65R22.5	
			Drive Tires	12R24.5	
License	154291		Tag	295/75R22.5	
<u>DATE</u>	<u>Company parts/svcs</u>	<u>Part #/Description</u>	<u>WORK PERFORMED</u>	<u>MILEAGE</u>	<u>HOURS</u>
1/2/15	MPE	BF1259 Fuel filter BF7587 Fuel filter	changed fuel filters	3190	\$ 9.45
1/9/15	Fleetpride	2484-BX switch	replaced master switch		\$ 8.86
3/5/15	Peterbilt	066011A pump	replaced windshield washer pump	3371	\$ 32.27
	Homax	1052955-1 15W40 oil	200 Hour service		\$ 44.72
	Snow dist	02382-120 grease			\$ 93.94
	MPE	10002 Lucas			\$ 11.61
		B99 Oil filter			\$ 27.99
		BF957 fuel filter			\$ 10.64
		BF7587 Fuel filter			\$ 3.82
3/10/15	Fleetpride	3800250 airline	replaced airline to brakecan- left front		\$ 8.86
	glass c solutions	2015 ferrule	drive axle		\$ 2.17
1/12/15	Fleetpride	849-1025-12	2 quarts fuel treatment		\$ 1.66
1/12/15	HOMAX	#1 diesel for winter	110 gallons		\$ 13.83
					\$ 320.44

2016 Vehicle Maintenance		Vin# 1NP5LBTX57D654375		
License	Date Purchased from:	Part #/Description	Work Performed	Mileage Hours Cost
L-565	2007 PETERBUILT	Inspected 12/16/2015	Steer Tires 425/65R22.5 Drive Tires 12R24.5	beginning 58521 3401
1/1/16	Stock	Greast 02382-120 trans 1054009-20	beginning miles grease 565, check bxs 3.87 pounds x 3.5	\$ 5.81 \$ 18.18 \$ 11.85
4/28/16	MPE	1053887-20 JC12000 NAPA	1.5 Qt 75W90 gear oil check all lights fix battery cables accumulator dual pad ester 100 oil/134A coolant 3.25 AC 134A	\$ 48.04
7/11/16	ITP	41528IN Seal 250-70-18X Strap Kit	replaced input seal on Aux Trans replaced u joint strap kit	\$ 20.75 \$ 23.65
	Homax	1053887-20 75W90 oil	filled aux trans 3 QT	\$ 23.70
1/1/16	Peterbilt	192-6000-0718 cable 2335665 bellows	replaced hood safety cables replaced turbo exhaust bellows	\$ 26.39 \$ 25.46
	MPE	AC1001 Cartridge B05134 filter	replaced air dryer cartridge replaced coolant filter	\$ 5.96
		3050 2" LED Light 3050R 2" Led Light	replaced rear marker light replaced left front marker light on bed	\$ 10.06 \$ 5.03
	Class C Solutions	6221 1156 Bulb P037St PAS Clip	replaced bulb 1 Driver side turn signla replaced missing clip on safety cable, checked all fluid levels, inspected drivelines and suspension	\$ 0.26 \$ 0.00 \$ 0.00
12/5/16	dan		vehicle inspection	\$ 15.00

<b>2017</b>	<b>Vehicle Maintenance</b>		Vin# 1NP5LBTX57D654375			
<b>L-565</b>	<b>2007 PETERBUILT</b>	Inspected 12/05/2016	Steer Tires 425/65R22.5	beginning		
<b>License</b>			Drive Tires 12R24.5			
<b>DATE</b>	<b>Company parts/svcs</b>	<b>Purchased from:</b>	<b>Part #/Description</b>	<b>WORK PERFORMED</b>	<b>MILEAGE</b>	<b>HOURS</b>
1/1/17			beginning miles	59747	3549	
2/21/17	Pacific Steel	1 1/2" Round 4140 steel	fabricated new pin for rear sheep foot		\$ 11.45	
	Class C solutions	34272 nyloc nut			\$ 0.05	
		99008 1/4 x 2 bolt			\$ 0.16	
3/17/17	Snow Dist	02382-120Grease	greased truck	3556	\$ 7.74	
	HSC	7124643 cable clamp	fabricated cable for pole risers		\$ 44.68	
	Vernal	7/8" Wire rope				
3/20/17		adjusted bb brakes			3565	\$ 0.00
4/3/17	Peterbilt	250-4-551-1 yoke	output yoke for auxilliary transmission		\$ 381.45	
4/3/17	ITP		Fabricated two drive lines with line saver		\$ 4,722.33	
4/14/17	Midwest hose	2503-10-12-FG fitting	replaced adapter on aux transmission		\$ 3.32	
	Homax	1053887-20	filled Aux Trans		\$ 79.08	
5/1/17	Snow Dist	02382-120 grease	250 HR Service	3620	\$ 7.74	
	Homax	1078334-1 15W40			\$ 88.44	
	MPE	B99 OF			\$ 10.95	
		BF957 FF			\$ 4.11	
		BF7587 Ff			\$ 9.33	
6/13/17	Pacific Steel	2*2 square tubing	replaced broken chain hanger on driver side	3667	\$ 12.18	
	snow dist	02382-120 Grease	greased/adjusted brakes		\$ 7.74	
7/3/17	MPE	243612GK	mud flap 24*36		\$ 18.81	
8/9/17			repaired swamp side chain hanger		\$ 0.00	
	MPE	243612GK Mudflap/frame	replaced swamp side mudflap and antisail arm		\$ 18.81	
		Frame			\$ 16.98	
8/15/17	MPE	243612GK Mudflap/frame	replaced driver side flap/frame	3730	\$ 18.81	
					\$ 16.98	
	snow dist	02382-120 grease	greased/adjusted brakes/cleaned AC Evaporator and filter		\$ 7.74	
	POW	EC00061 Orifice	replaced AC orifice tube recovered vaccummmed and charged AC		\$ 10.64	
		R1340 Refridgerant	checked operation of AC system		\$ 0.00	
8/16/17	Six States	1021 Torque Bolts	replaced driveline and torque bolts			
	class C solutions	99762 washer	hardware for new mudflap		\$ 0.52	
		99058 bolt			\$ 1.08	
		34274 nyloc nut			\$ 0.32	
10/30/17	Casper fire	extinguisher	installed new fire extinguisher	3719	\$ 57.75	
12/6/17	Air Gas	glow light cord			\$ 36.00	

<u>2018</u>	<u>Vehicle Maintenance</u>	<u>Vin#</u> 1NP5LB7X57D654375			
L-565	2007 PETERBUILT	Inspected 12/6/2018	Steer Tires 425/65R22.5 Drive Tires 12R24.5	beginning	
License	154291		Tag 295/75R22.5	end	
<u>DATE</u>	<u>Company parts/svcs Purchased from:</u>	<u>Part #/Description</u>	<u>WORK PERFORMED</u>	<u>MILEAGE</u>	<u>HOURS</u>
1/1/18		beginning miles			
4/18/2018	Shop/stock	replaced plug to block heater	68266	3789	
18-Apr	Shop/stock	inspection	68266	3789	
12/5/2018	Shop/Stock	Flat Tire	Replaced valve stem	60294	3806
10-Dec	Shop	Coolant leak	Added 1 Gallon & Fixed leak	60294	3806
12/6/18	Peterbilt	relay			\$ 10.74
12/19/18	fleetpride	purge valve			\$ 102.33

<u>2019</u>	<u>Vehicle Maintenance</u>		Vin# 1NP5LBTX57D654375			
<u>L-565</u>	<u>2007 PETERBUILT</u>	<u>Inspected 12/6/2018</u>	<u>Steer Tires 425/65R22.5</u>	<u>beginning</u>		
<u>License</u>		<u>154291</u>	<u>Drive Tires 12R24.5</u>	<u>60620</u>	<u>end</u>	
<u>DATE</u>	<u>Company parts/svcs</u>	<u>Purchased from:</u>	<u>Part #/Description</u>	<u>WORK PERFORMED</u>	<u>MILEAGE</u>	<u>HOURS</u> COST
<u>Mileage</u>						
3/7/19	Fleet Pride		FILTERS BD7154, BF7760, BF7766, B252	NOT ON LOG		\$ 78.10
8-Mar				Trouble shoot heater, found melted wiring, rewired		
				Greased		
28-Mar	ATD-374 1-6mm grease zerk		6mm grease zerk	greased-replaced grease zerk removed tail roll side stop(bent) to grease tail roll	61354	39421
22-Apr	Eiko Wire		1" x 4' grommet sling	not on log		\$ 189.60
3-Jun				Check all fluids, greased u joints stalled new mud flap (used)		
06/02/2019				Pulled off yok metal in seal pulling off out		
8-Oct				anti freeze -55 degrees		
7-Oct	DFS Supplement			added to fuel tanks		\$ 16.49
1-Oct				cleaned batteries/spray protectant		
31-Oct	Fleet Pride		brake kit			\$ 262.91
26-Oct	Napa		Filters			\$ 23.39
4-Nov	Best deal		brak reline			\$ 109.33
7-Jan	Freedom Truck		Differential			\$ 12,744.57
			core credit			-\$ 4,598.70
3-Dec	Napa			replaced 4 batteries core parts, wahser for tractor aslo replaced races and bearings on driver 1st drive axel	62173	3989 \$ 479.90
	six states		seals/bearings			\$ 366.05
4-Dec	Peterbilt of WY		U-joint	replaced straps on u-joint purchased for tractor	62173	3989 \$ 20.56
10-Dec	Peterbilt of WY		Bearings	purchased for 1st drive axle	62173	3989 \$ 114.21
12/11/2019	Peterbilt of WY		bearings	purchased for 1st drive axle	62173	3989 \$ 165.89
12/17/19	Vernal Peterbilt		axle shaft			\$ 526.10

2020 Vehicle Maintenance		Vin# 1NP5LB1X57D654375		
L-565	2007 PETERBUILT	Inspected	Steer Tires 425/65R22.5	beginning
License	154291		Drive Tires 12R24.5	62173
			Tag 295/75R22.5	end
Company parts/svcs		Axle Spacing	WORK PERFORMED	MILEAGE HOURS COST
DATE	Purchased from:	Part #/Description		\$ -
2-Jan			sanded bumper for painters	
7-Jan	Homax		3-5 gal buckets of 70/90 gear oil, 2-bucket for truck 1 for shop	62173 3989 309.44
7-Jan	Peterbilt	Nut	1-hub nut	84.84
1/7/2020	Fleet pride		12- wheel nuts, 4- for truck 565, 8 for shop	40.19
1/18/2020	walmart	paint		37.42
1/20/2020	Napa		oil filter, 2 fuel filters	54.72
1/21/2020	Shop		Repaired electrical wires for light, grease job, checked lights, oil levels, checked tire pressure	0
8-Dec	Shop		cleaned air filters	62316 4012