

| 2013 Vehicle Maintenance | | VIN # | | | |
|--------------------------|------------------------------------|--|--|-------|-----------|
| FL-6 | Tires | | | | |
| DATE | Company parts/svcs Purchased From: | Part#Description | WORK PERFORMED | HOURS | COST |
| 1/8/13 | Shop | | all fluids checked & Topped off, heater switch installed, fully greased and interior cleaned | | \$ 12.80 |
| 1/14/13 | Titan Macinery | 84169306 Filters | replaced cab heater temp control | | \$ 134.88 |
| 1/14/13 | Extreme Truck outfitters | 288271 Filters | 84412164 Fuel, 84228510 Eng, 8605140 Air, 87712194 Cab Deflecta Shield Part | | \$ 348.71 |
| 1/15/13 | Titan Macinery | Filters | 84491498 Hyd A 13 filter--replaced transmission filter | | \$ 73.20 |
| 1/18/13 | Homax | 3200-55 Filters | Hyd 84476010 replaced hydraulic filters | | \$ 100.02 |
| 1/23/13 | Titan Macinery | 3200-55 | replaced coolant | | \$ 67.95 |
| 1/29/13 | Titan Macinery | nuts/bolts/washers | replaced heater control valve | | \$ 153.91 |
| 2/22/13 | Titan Macinery | (2) 5/16*18/3 bolts 99637, (4) 5/16 x 18 nuts 99781, (8) 3/8 washers 99571 | | 1710 | \$ 27.80 |
| | | 84412164 Filter 250 HOUR SERVICE | | | |
| | | 84170818 water seporator | | | |
| | | 84228510 oil filter | | | |
| | | 8605139 air filter | | | |
| | | 8605140 inner air filter | | | |
| | | 02382-120 GREASE 2 lbs | | | |
| | | 052955-1 Aw32 | | | |
| 3/20/13 | Stock | hyd oil 2 gallons 1055928-5 | 15W40 oil 4 gallons | | \$ 7.75 |
| 4/10/13 | NAPA Barnes | 87350055 Switch | Windshield washer hose repaired | | \$ 37.34 |
| 4/12/13 | Titan Macinery | 7308 paint for chains 1 can | 20' 3/8 chain replaced bolt in fork attachment | | \$ 1.56 |
| 4/22/13 | Snow dist | 02382-120 Grease | Greased | | \$ 18.59 |
| 4/29/13 | Barnes? | nuts bolts washers | 1/4bolt 40031 W 2 washers and nuts, 1/8 bolt 4008 | | |
| 4/30/13 | | 715-1051 1/4 grease zer | 4 | | |
| 5/28/13 | Titan Macinery | Filters | 250 hour service | | |
| | | 84412164 | | | |
| | | 84170818 | | | |
| | | 84228510 | | | |
| | | Homax | 1052955-1 | | |
| | | Snow dsit | 02382-120 | | |
| | | washer fluid | 15W40 oil | | |
| | | | grease | | |
| | | | 1/2 gal | | |
| 6/24/13 | Snow dsit | 02382-120 Grease | Greased | | |
| | | Titan Machinery | 76303266 | 2025 | \$ 7.74 |
| 7/17/13 | Sams | Glass cleaner | replaced driver side mirror bracket purchased 10/15/2012 | | \$ 162.10 |
| | | | | | \$ 2.00 |

| | | | | | |
|----------|-------------|----------------------------|--|-----------|-----------|
| 8/5/13 | Snow dsit | 02382-120 | Greased | 2040 | \$ 7.74 |
| 8/6/13 | TDS | | rotated and filled tires | 2041 | \$ 329.18 |
| 8/21/13 | Snow dsit | 02387-120 | Greased | 2067 | \$ 7.74 |
| | D&H welding | | repaired hydraulic hard line | | \$ 55.39 |
| | Homax | | filled hydraulic tank 2.5 Gal | | |
| 9/10/13 | | | 1055928-5 Hyd oil | | |
| | | | 21449 clamp | | |
| | | | BT2S-CO BART TIE | 1 | |
| 9/23/13 | Homax | | 15W40 oil | | |
| | | | 250 hour service | 2161 | \$ 36.52 |
| | | | grease | | |
| | Snow dsit | | Greased | | |
| | Titan | 84170818084412164/84228488 | FILTERS | | |
| | | | replaced front windshield wiper | | |
| | NAPA | 76048601 wiper | replaced heater ducting | \$ 119.74 | |
| | TITAN | 7051021 clamp | replaced cab air filter | \$ 2.73 | |
| | Vernal | 87712194 filter | replaced outer air filter used | \$ 48.21 | |
| | Homax | 8605139 filter | hyd oil 1055928-5 hyd oil | | |
| | NAPA | 091314 brakleen | filled hyd tank | \$ 16.62 | |
| 11/10/14 | | | cleaned rotar/caliper on parking brake | | \$ 2.83 |
| | | | nut buster | 1 can | |
| | | | window cleaner | 1 can | |
| 12/9/13 | Barnes | 998193 7.5A Fuse | replaced fuse for engine cover motor | | \$ 0.65 |
| | | | | | |

| 2014 | Vehicle Maintenance | | VIN # | | | |
|-------------|----------------------------|------------------------|-------------------------|---|--------------|----------------|
| FL-6 | Tires | | | | | |
| DATE | Company parts/svcs | Purchased From: | Part#Description | WORK PERFORMED | HOURS | COST |
| 1/24/14 | HOMAX | | 15W40 oil 1052955-1 | 200 hour Service | 14 qt | 2533 \$ 37.52 |
| | Snow Distributing | | 02382-120 | Greased Truck | | \$ 11.61 |
| | Titan Machinery | | 84228488 filter | | | \$ 23.86 |
| | Titan Machinery | | 84348882 filter | | | \$ 29.54 |
| | Barnes | | 99781 5/16 Nut | Repair arm rest | | \$ 0.03 |
| | Titan Machinery | | 84412164 filter | | | \$ 27.79 |
| | Barnes | | 99761 5/16 washer | | | \$ 0.10 |
| 2/5/14 | Barnes | | 998193 fuse | replaced fuse for engine cover | | \$ 0.71 |
| | Fleet Pride | | 8025-12 | added power service 911 to gelled fuel 2 qt | | \$ 19.00 |
| 2/19/14 | NAPA | | Emblem 430 | | | \$ 13.64 |
| 3/6/14 | Barnes | | c703059 5/16 bolt | repaired threads in cab air filter and | | \$ 0.28 |
| | | | 997211lock washer | installed new hardware | | \$ 0.12 |
| | | | 99741 flat washer | | | \$ 0.10 |
| | | | 33831 screw | repaired tool box hinge | | \$ 0.42 |
| | | | 99002 bolt | installed slowing moving vehicle placard | | \$ 0.18 |
| | | | 99740 washer | | | \$ 0.06 |
| | | | 32574 washer | | | \$ 0.34 |
| | | | 34272 nyloc | | | \$ 0.04 |
| | | | 7352 shell | fabricated wiring harness for hood acutator | | \$ 0.91 |
| | | | KP86912 terminal | | | \$ 0.99 |
| | | | KP81235 seal | | | \$ 0.51 |
| | Fleet Pride | | 47406 100 loom | | | \$ 3.00 |
| | Barnes | | 422288 blue wire | | | \$ 2.00 |
| | | | 23449 red wire | replaced hand switch and wiring | | \$ 2.00 |
| 3/11/14 | peterbilt | | cn27250 terminal | | | \$ 7.40 |
| | | | p20-1178 connector | switch | | \$ 17.82 |
| | | | 16-091227b3gmn2d31 | 200 hour service | | \$ 65.44 |
| 3/25/14 | Snow Distributing | | 02382-120 grease | | 2714 | \$ 7.74 |
| | Homax | | 1052955-1 15W40 oil | | | \$ 37.76 |
| | Titan Machinery | | 8422848 | | | \$ 23.86 |
| | | | 84348882 | | | \$ 29.54 |
| | | | 84412164 | | | \$ 27.79 |
| 3/19/14 | wear parts | | ? Parts | | | \$ 5.02 |
| 4/10/14 | Titan Machinery | | 8602475 jack | replaced hood actuator | | 2790 \$ 743.04 |
| | Snow Distributing | | 02382-120 grease | greased loader | | \$ 7.74 |

| | | | | | |
|-------------------|-------------------|--------------------------|---|------|-----------|
| 5/19/14 | Titan Machinery | 76303230 glass | replaced glass in right door | 2980 | \$ 224.70 |
| | | 84228488 | 200 hr service | | \$ 23.89 |
| | | 84348882 | fuel filter | | \$ 29.66 |
| | | 84412164 | | | \$ 27.83 |
| HOMAX | | 1032955-1 15W40 | | | \$ 37.76 |
| Vernal | | air filter | replaced air filter (cleaned) | | \$ 7.74 |
| Snow Distributing | | 02382-120 grease | greased | | \$ 14.70 |
| Titan Machinery | | 87312626 relay | replaced horn relay | | \$ 0.52 |
| NAPA | | tubing | replaced washer tubing on rear wiper | | \$ 165.90 |
| Titan Machinery | | 76303266 mirror | replaced left outside mirror | | |
| | | | tightened connections on lift cylinders | | |
| | | 87696241 wiper arm | replaced front wiper | | \$ 120.75 |
| | | 710043977 wiper blade | | | \$ 78.49 |
| | | 86505868 nut | | | \$ 1.74 |
| 6/3/14 | HOMAX | 1055928-5 | repainted hydraulic tank and filled hydraulics tank | 3000 | \$ 83.80 |
| 6/11/14 | Snow Distributing | 02382-029 greased loader | greased loader | 3091 | \$ 4.68 |
| 6/24/14 | Snow Distributing | 02382-029 | greased loader | | \$ 7.74 |
| 7/10/14 | HOMAX | 1052955-1 15W40 oil | 200 hour service | 3165 | \$ 44.60 |
| | Titan Machinery | 8605139 air filter | | | \$ 71.93 |
| | | 87712194 cab filter | | | \$ 48.30 |
| | | 84228488 oil filter | | | \$ 23.89 |
| | | 84348882 fuel filter | | | \$ 29.66 |
| | | 84412164 fuel filter | | | \$ 27.83 |
| | Snow Distributing | 02382-120 grease | greased | | \$ 7.74 |
| | sams club | 959877 wash fluid | filled reservoir | | \$ 1.97 |
| 8/12/14 | Snow Distributing | 02382-120 | greased loader | 3330 | \$ 7.74 |
| 8/19/14 | Homax | 1052955-1 15W40 oil | 200 hour service | 3362 | \$ 35.68 |
| | Snow Distributing | 02382-120 grease | | | \$ 7.74 |
| | Titan Machinery | 84228488 oil filter | | | \$ 24.15 |
| | Titan Machinery | 84348882 fuel filter | | | \$ 29.93 |
| | | 84412164 FF | | | \$ 28.09 |
| | | 87212194 cab filter | | | \$ 48.30 |
| | | 8605129 AF | | | \$ 71.93 |
| 8/27/14 | Barnes | 6221-1156 bulb | replaced brake light bulb | 3370 | \$ 0.27 |
| 9/18/14 | Snow Distributing | 02382-120 grease | greased | | \$ 7.74 |
| 9/26/14 | Titan Machinery | 84412164 | 200 hr service | 3539 | \$ 28.09 |
| | | 84348882 | | | \$ 29.92 |
| | | 84228488 | | | \$ 24.15 |
| | Snow Distributing | 02382-120 grease | | | \$ 7.74 |
| | Homax | 1052955-1 15W40 oil | | | |

| | | | | |
|----------|-------------------|---------------------|---|---------------|
| 9/27/14 | Peterbilt | 16091227b3gn2d31 | replaced switch for hood actuator | \$ 67.40 |
| | Class C solutions | 6221 1156 bulb | replaced brake light bulb | \$ 0.26 |
| 10/6/14 | Peterbilt | 16091227B3Gmn-2031 | replaced hood actuator switch | \$ 67.40 |
| 10/10/14 | Titan Machinery | | replaced hood actuator | 3542 warranty |
| 10/14/14 | Class C solutions | 38217 cotter pin | chain repair | \$ 0.04 |
| | Sams club | 959877 washer fluid | filled windshield washer res | \$ 1.97 |
| 11/12/14 | wear parts | 16MMbolts | replaced bolts in hood actuator brackets | \$ 6.24 |
| | NAPA | 16MMTAP | repaired threads in hood actuator bracket | \$ 8.70 |
| | Fleet Pride | 413 hook | replaced cross chain hook on tire chain | \$ 3.65 |
| 12/1/14 | HOMAX | 1052955-1 15W40 oil | 2000 HR service | 3788 \$ 35.68 |
| | | 02382-120 grease | | \$ 11.61 |
| | Titan Machinery | 84412164 ff | | \$ 28.09 |
| | | 84348882 ff | | \$ 29.93 |
| | | 84228488 of | | \$ 24.15 |
| | Class c solutions | 6221 1156 bulb | replaced right rear turn bulb | \$ 0.26 |
| 12/22/15 | snow dist | 02382-120 grease | greased loader | 3857 \$ 7.74 |
| 12/29/14 | | | repaired tire chains | |
| 12/31/14 | Class c solutions | 998192 5 amp fuse | spare fuses | \$ 1.42 |
| | | 998193 7.5 amp fues | | \$ 1.42 |
| | | 998194 10 amp fuse | | \$ 1.42 |
| | | 998195 15 amp fuse | | \$ 2.13 |
| | | | | |
| | | | | |

| 2015 Vehicle Maintenance | | VIN # N7F200782 | year end |
|---------------------------------|---|------------------------------------|---|
| FL-6 | Tires | | 4228 |
| DATE | Company parts/svcs Purchased From: | Part#Description | WORK PERFORMED |
| 1/5/15 | Titan Machinery | 504034215 fuel line | replaced fuel line |
| 1/9/15 | HOMAX | 1055298-5 4w30 | filled hydraulic tank |
| 1/12/15 | D&H welding | | repaired cracked hydraulic line |
| | Titan Machinery | 84412164 fuel filter | 200 hr service |
| | | 84348882 fuel filter | |
| | | 84228488 oil filter | |
| | HOMAX | 1052955-1 15W40 | |
| 1/20/15 | Snow Dist | 02382-120 grease | \$ 7.74 |
| | Titan Machinery | 410939A1 bulbq | replaced brake/turn bulbs |
| 1/26/15 | Titan Machinery | High Fuel Pressure Code | new sensor |
| 2/2/15 | Bowden Welding | cut off old eyes on forks | clean up and wend new |
| | century equip,emt | fork eyes | |
| 2/19/15 | HOMAX | 1052955-1 15W40 | 200 Hour Service |
| | Snow Dist | 02382-120 Grease | |
| | Titan Machinery | 84412164 fuel filter | oil clean service done per Monty on SEPT VM LOG |
| | | 84348882 fuel filter | |
| | | 84228488 oil filter | |
| | Titan Machinery | 76303230 glass | |
| | Homax | 3200-55 coolant | spare coolant for loader |
| | Titan Machinery | cas 87715377 park brake pads | replaced park brake pads and adjusted |
| 2/20/15 | century equip,emt | | |
| 3/4/15 | fleetpride | 05089 brakleen | |
| | | 913 hardener | repaired crack in hood |
| | NAPA | | |
| | Sutherlands | sanding blocks | |
| 9/30/15 | | test antifreeze -40F, check fluids | 4224.19 |
| 11/21/15 | fleetpride | PS fuel treatment | \$ 3.45 |

