

Description		Quantity	Rate	Amount
Labor	Correction: CHASSIS TESTED GOOD, PERFORMED COMPRESSION TEST, PASSED TEST, WAITING ON CHASSIS / CHASSIS / 11/19 DISASSY	60.00000	\$137.75	\$8,265.00
	11/22 DISASSY			
	12/1 INSTALLED CRANKSHAFT			
	12/2 ROTATED ENGINE, CLEANED BLOCK, INSTALLED LINERS			
	12/7 WORKED WITH PARTS DEPT TO FIND TOOLS FOR ENGINE BUILD	1.00000	\$825.00	\$825.00
	12/8 DISASSY RODS, NEEDS BEARINGS AND WRISTPINS	1.00000	\$37.09	\$37.09
	1/3 BEGAN ROD REASSY	1.00000	\$15.59	\$15.59
	1/4 REASSY BOTTOM END	1.00000	\$15.35	\$15.35
	1/5 SET BASE ENGINE TIMING	4.00000	\$277.53	\$1,110.12
	1/7 BEGAN CLEANING	5.00000	\$25.01	\$125.05
	1/18 INSTALLED HEAD, FOUND UPPER GEAR TRAIN NEEDS TO BE INSTALLED THROUGH BOTTOM OF THE HEAD, NEED TO REMOVED AND REASSY	1.00000	\$120.00	\$120.00
	1/19 REMOVED HEAD, INSTALLED TIMING GEAR, INSTALLED INTAKE AND OTHER COMPONENTS ON HEAD WHILE WAITING ON GASKET.	2.00000	\$65.58	\$131.16
	1/24 REINSTALLED HEAD, BEGAN REASSY	2.00000	\$14.74	\$29.48
	1/25 CONTINUED REASSY	1.00000	\$30.11	\$30.11
	2/1 CONTINUED REASSY	1.00000	\$234.70	\$234.70
	2/2 CONTINUED REASSY	12.00000	\$2.93	\$35.16
	2/2 COMPLETED REASSY.	6.00000	\$550.00	\$3,300.00
	2/7 HELPED WITH INSTALL	1.00000	\$111.24	\$111.24
	2/16 INSTALLED AND SET BACKLASH ON OIL PUMP, INSTALLED OIL PAN. HELPED BENJAMIN WITH REASSY	2.00000	\$3.50	\$7.00
	2/17 HELPED WITH REASSY	1.00000	\$5.84	\$5.84
	2/23 HELPED WITH REASSY	1.00000	\$11.25	\$11.25
	2/24 DIAG NO START	1.00000	\$2.34	\$2.34
	2/25 CONTINUED DIAG, ATTEMPTED TO MAKE TOOL, COULD NOT FIND LINES IN BONEYARD THAT MATCH, NEED NEW LINE TO MAKE TOOL WITH OLD LINE.	1.00000	\$160.89	\$160.89
	2/28 CONTINUED DIAG	1.00000	\$168.67	\$168.67
	3/1 CONTINUED DIAG	1.00000	\$219.07	\$219.07
	3/2 CONTINUED DIAG	1.00000	\$162.00	\$162.00
	3/10 CONTINUED DIAG	1.00000	\$31.19	\$31.19
	3/11 CONTINUED DIAG, FOUND INJECTORS NEED TO BE TESTED, REMOVED AND GAVE TO PARTS	1.00000	\$39.05	\$39.05