



901 West 94th Street
Minneapolis MN 55420-4236



Minnesota 800-352-2812
Iowa 800-342-7002
Missouri 800-342-7002
Wisconsin 800-342-7002

Service Invoice

Invoice SI000297112
Date 2/24/2023
Call Number SC00347750
Location Rochester
Page 1 / 5

Sold to: ZRS RNTL HEAVY AGRI REPAIR & MAINT
ATTN: CORP HEAVY RENTAL MANAGER
901 W 94TH ST
MINNEAPOLIS, MN 55420-4236

Ship to 6340 HIGHWAY 63 S
ROCHESTER, MN 55904-8414

Invoice Account

I001723

Payment

Internal - No Payment

Due Date

2/24/2023

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-001 Perform Maintenance On - Machine

Customer complaint: Service machine.

Resultant damage: na

Cause of failure: na

Repair process comments: Performed service. Drained and refilled engine oil. Changed engine oil filter and fuel filters.

Drained and refilled both reaction arms. Took engine oil and tras/hyd oil sample. Repair complete.

Quantity	Type	Part Number	Description	Unit Price	Amount
1.00	Parts	V837091117 - 200	FUEL FILTER KIT	147.45	147.45
1.00	Parts	V837081555 - 200	ENG OIL FILTER	118.71	118.71
3.00	Parts	79035353 - 200	OIL-15W40CK4 5G	116.53	349.59
1.00	Parts	79034597 - 200	OIL-15W40CK4 2.5G	61.64	61.64
1.00	Parts	79034867 - 200	OIL-SAE 50 1G	45.18	45.18
	Labor		Labor		803.25
2.00	Misc	SAM	SOS - Oil Sample	16.00	32.00

Credit card payments are only accepted at Point of Sale
A service charge of 1 1/2% per month will be assessed on all past due accounts.

ZRS RNTL HEAVY AGRI REPAIR & MAINT
ATTN: CORP HEAVY RENTAL MANAGER
901 W 94TH ST
MINNEAPOLIS, MN 55420-4236

Invoice
Date
Account

SI000297112
2/24/2023
I001723

Please Remit to:

Ziegler Inc.
SDS 12-0436
PO BOX 86
MINNEAPOLIS,MN 55486-0436

Amount Due:

\$42,811.28

Amount Enclosed:

Parts: 722.57

Labor: 803.25

Misc: 32.00

Segment Subtotal: 1,557.82

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-002 Replace - Track Belt
Replace track belts. On a different service call will align tracks SC00361989.

Quantity	Type	Part Number	Description	Unit Price	Amount
2.00	Parts	581870D1 - 200	TRACK-6500HR 36"	18,450.00	36,900.00
	Labor		Labor		994.50
1.00	Misc	FRT	FREIGHT	250.00	250.00
Parts: 36,900.00		Labor: 994.50		Misc: 250.00	Segment Subtotal: 38,144.50

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-003 Replace - Bogie
Customer complaint: replace left side bogie wheel.
Resultant damage: na
Cause of failure: worn and ripped rubber.
Repair process comments: removed damaged bogie. cleaned surface. installed new bogie. repair complete.

Quantity	Type	Part Number	Description	Unit Price	Amount
1.00	Parts	548350D3 - 200	MID ROLLER WHEEL-POL	599.30	599.30
	Labor		Labor		114.75
Parts: 599.30		Labor: 114.75		Segment Subtotal: 714.05	

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-004 Repair - Exhaust Leak

Customer complaint: repair leaking right side exhaust manifold.
Resultant damage: leaks exhaust.
Cause of failure: idle slobber pushed gasket maker out of manifold.
Repair process comments: removed manifold. cleaned all surfaces. removed all studs. installed new studs. installed manifold with gasket maker. tested operation. repair complete.

Quantity	Type	Part Number	Description	Unit Price	Amount
1.00	Parts	V546801930 - 200	STUD BOLT	5.99	5.99
10.00	Parts	V836667960 - 200	STUD BOLT	9.95	99.50
12.00	Parts	V513601002 - 200	NUT	3.79	45.48
1.00	Parts	V546801910 - 200	STUD BOLT	1.97	1.97
1.00	Parts	V837081786 - 200	GASKET	40.30	40.30
	Labor		Labor		765.00
Parts: 193.24		Labor: 765.00		Segment Subtotal: 958.24	

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-005 Replace Gasket/Reseal - Turbocharger - Line(s)

Customer complaint: turbo drain lines leaking oil.
Resultant damage: leaks oil
Cause of failure: bad gasket.
Repair process comments: removed turbo drain lines. cleaned all gasket material from line and turbo. installed new gasket. tested operation. repair complete.

Quantity	Type	Part Number	Description	Unit Price	Amount
2.00	Parts	V837084638 - 200	GASKET	13.50	27.00
	Labor		Labor		229.50
Parts: 27.00		Labor: 229.50		Segment Subtotal: 256.50	

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-006 Troubleshoot - Oil Leak

Customer complaint: troubleshoot oil leak from turbo boots.
Resultant damage: na
Cause of failure: na
Repair process comments: removed turbo boots. oil was from letting machine idle for to long causing slobber. cleaned all boots. repair complete.

Quantity	Type	Part Number	Description	Unit Price	Amount
	Labor		Labor		382.50
			Labor: 382.50	Segment Subtotal: 382.50	

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-007 Troubleshoot - Fuel Leak

Customer complaint: troubleshoot fuel leak
Resultant damage: na
Cause of failure: na
Repair process comments: found fuel tank was overfilled and had pressure in it causing fuel to come out of breather. cleaned all fuel from breather. repair complete.

Quantity	Type	Part Number	Description	Unit Price	Amount
	Labor		Labor		76.50
			Labor: 76.50	Segment Subtotal: 76.50	

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-008 Replace - V-Belt(S)

Customer complaint: replace belts
Resultant damage: na
Cause of failure: worn belts.
Repair process comments: removed belt guards. removed both belts. installed new belts. tested operation. installed belt guards. repair complete.

Quantity	Type	Part Number	Description	Unit Price	Amount
1.00	Parts	565812D1 - 200	BELT-1917MM 8PK	70.10	70.10
1.00	Parts	578628D1 - 200	FAN BELT-1747MM 12PK	138.00	138.00
	Labor		Labor		76.50
Parts: 208.10		Labor: 76.50		Segment Subtotal: 284.60	

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-009 Repair - Light(S)

Customer complaint: Left hand rear flasher doesn't work.
Resultant damage: .
Cause of failure: The light bulb was burnt out.
Repair process comments: Removed connector and measured for voltage at the connector. removed lens cover and removed bulb. installed a new bulb and installed lens. tested lights.

Quantity	Type	Part Number	Description	Unit Price	Amount
1.00	Parts	7797137 - 200	BULB-12V	1.86	1.86
	Labor		Labor		114.75
Parts: 1.86		Labor: 114.75		Segment Subtotal: 116.61	

Customer PO	Customer EQ	Model	Serial Number	Equipment ID	Segment SMU
		MT875E	AGCC0875VGNLG1008	EQ0044537	4,141

SC00347750-010 Inspect - Transmission Shaft - Seal

Customer complaint: trans input shaft seal wet.
Resultant damage: na
Cause of failure: na
Repair process comments: inspected seal. cleaned seal and ran machine to test for leaks. no leaks found. returned seal. repair complete.

Quantity	Type	Part Number	Description	Unit Price	Amount
	Labor		Labor		153.00
		Labor: 153.00		Segment Subtotal: 153.00	

Subtotal	42,644.32
Shop Supplies and Environmental Fees	166.96
Sales Tax	0.00
Total	\$ 42,811.28