



Established 1916
CRANE and RIGGING CO.

14511 Industry Circle
La Mirada, CA 90638
(714) 670-9525

SERVICE REPORT

Date: 12-18-13

Customer's Name: _____

Customer P. O. # _____

Job Location: Hinkle-/ M/M/T: Liebherr LR1200-Crawler Hours: 6903

Equipment # 250167 Serial # _____

Describe Defects & Cause of Failure: Alarm for fuel Sending unit

Repairs Completed: Removed Cover for sending unit and found Computer Board under water - removed Board Cleaned terminals, removed water, hooked Back up works for a min then alarm goes off again - checked wiring to Sending unit all is good - Needs New sending unit - re sealed

Qty	Part Number	Description	Ordered	Installed
		<u>sending unit</u>		

Recommendations: Make sure to Seal correctly when new unit is installed

Technician: Boye Hulet

Customer Name: _____

Customer Signature: _____

Job Complete: _____ Labor: Reg _____

Yes ☐ No ☒ O.T. _____



Established 1916
CRANE and RIGGING CO.

14511 Industry Circle
La Mirada, CA 90638
(714) 670-9525

SERVICE REPORT

Date: 12-30-2013

Customer's Name: Bigge

Customer P. O. # _____

Job Location: Hinckley

M/M/T: Liebherr LR 1200

Hours: 6984

Equipment # 250167

Serial # 135040

Describe Defects & Cause of Failure: Fault Code

Repairs Completed: Install new circuit board in fuel sender

Qty	Part Number	Description	Ordered	Installed
1	91744014	Circuit Board / fuel sender		12-30-13

Recommendations: _____

Technician: Steve

Customer Name: _____

Customer Signature: _____

Job Complete: _____

Yes ☒ No ☐

Labor: Reg 2

O.T. _____



Established 1916
CRANE and RIGGING CO.

14511 Industry Circle
La Mirada, CA 90638
(714) 670-9525

SERVICE REPORT

Date: 1-5-14

Customer's Name: BIGGE

Customer P. O. # _____

Job Location: HINKLEY

M/M/T: LIEBHERR LR1200

Hours: 7017

Equipment # 250167

Serial # 135021

Describe Defects & Cause of Failure: 500 HR SERVICE

Repairs Completed: 500 HR SERVICE

OIL / FILTER CHANGED

AIR FILTERS

FUEL FILTERS

HYDRAULIC FILTERS

HYD / FUEL BREATHERS

1	7373880	HYDRAULIC FILTER INSERT		✓
1	P777869	AIR FILTER INNER		✓
1	P777868	AIR FILTER INNER OUTER		✓
Qty	Part Number	Description	Ordered	Installed
2	10297295	OIL FILTERS		✓
1	10044303	FUEL FILTER		✓
1	10429946	FUEL FILTER		✓
2	510713814	HYD / FUEL TANK BREATHERS		✓

Recommendations: NEXT SERVICE DUE 7517

Technician: BRUCE / BRIAN

Customer Name: _____

Customer Signature: _____

Job Complete: _____ Labor: Reg _____

Yes ☒ No ☐

O.T. _____



Established 1916
CRANE and RIGGING CO.

14511 Industry Circle
La Mirada, CA 90638
(714) 670-9525

SERVICE REPORT

Date: 1-16-14

Customer's Name: _____

Customer P. O. # _____

Job Location: Hinkley M/M/T: Liebherr 1200 crawler Hours: 7104

Equipment # 250167 Serial # _____

Describe Defects & Cause of Failure: Boom fall back cyl switch faulty

Repairs Completed: checked switches and AdJ Arms All good
set a call later faulted again need to order 2 new switches
intermittant problem

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: Bryce Aulet

Customer Name: _____

Customer Signature: _____

Job Complete: _____ Labor: Reg _____

Yes ☐ No ☒ O.T. _____

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 9-2-15

Customer's Name: Ameco

Customer P.O. # _____

Job Location: CA Chem

M/M/T: LA 1200 SX

Hours: 9828

Equipment # 250167

Serial # 135021

Trip Mileage —

Describe Defects & Cause of Failure: Service Due

Repairs Completed: change engine oil, oil filter, fuel filters, and air filter.

Qty	Part Number	Description	Ordered	Installed
2	oil	oil filters		✓
1	fuel	1 Hyd		✓
1	fuel	1 Hyd		✓
1	air	air		✓
1	air	air		✓

Recommendations: _____

Technician: [Signature]

Customer Name: J.C. Williams

Customer Signature: [Signature]

Job Complete: Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916
CRANE and RIGGING CO.

10700 Bigge Ave.
San Leandro, CA 94577
(510) 638-8100

SERVICE REPORT

10-02-031217

Date: 10/16/14

Customer's Name: Vortex Marine

Customer P. O. # _____

Job Location: _____

M/M/T: _____

Hours: 8,178

Equipment # 250167

Serial # 135-021

Describe Defects & Cause of Failure: _____

Repairs Completed: On 9/22/14 Replaced luffing hoist
fitting on breather, Boom backstop cylinder roller,
4 hours labor x Jared Crowley

On 10/10/14 Replaced sheave in main load block
2 hours labor x Fernando Fernandez
Fernando Fernandez

Qty	Part Number	Description	Ordered	Installed
1	927739401	Fitting	1	1
1	289001714	roller	1	1
1	10503932	sheave	1	1

Recommendations: _____

Technician: Jared Crowley

Customer Name: _____

Job Complete: _____

Labor: Reg 6

Customer Signature: _____

Yes ☒ No ☐

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

SERVICE REPORT

Date: 02-07-2015
 Customer's Name: Shimick Customer P. O. # _____
 Job Location: Gerald Desmond M/M/T: Liebherr 1200 Hours: 8751
 Equipment # 250167 Serial # 135 021
 Describe Defects & Cause of Failure: heater control failure

Repairs Completed: Replaced Actuator, installed relay but control is not responding to potentiometer need PC board.
Replace alt, machine has error code X2-91-5 unequal voltage, need into on module 91.

- ① night switch
- ② PC Board for heater
- ③ Module 91 unequal voltage
- ④ fan belt
- ⑤ Fall back support (check)

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer Name: _____

Customer Signature: _____

Job Complete: Labor: Reg _____

Yes ☐ No ☒ O.T. _____

SERVICE REPORT

Date: 04-22-2015
 Customer's Name: SHIMICK Customer P. O. # _____
 Job Location: Desmond Howard M/M/T: LTC-1200 LIEBHERR Hours: 9149
 Equipment # 25D1167 Serial # 135-021

Describe Defects & Cause of Failure: Scale with empty hook is showing 5T cust as has been with machine for along time, up until today machine always show 15T

Repairs Completed: TAKE Button stuck
Load test with 31,000 scale is accurate. Boom tip 5400
 multi 6600
 Sig 2400

706 keys for box?

Bigge Safety Vest, T shirts XL

Went to safety check in with Joe, Crane IS now off of PEIR D st under bridge

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: B. Matthews

Customer Name: _____
 Customer Signature: _____

Job Complete: Labor: Reg _____
 Yes ☒ No ☐ O.T. _____



LIEBHERR-WERK NENZING GMBH

Dr.-Hans-Liebherr-Straße 1 · A-6710 Nenzing

Kundendienst
Service-Department

Montage/Reparatur Bericht

Assembly/Repair Report

Zum Auftrag
Order

Nr.

684524

Typ type	LR 1200	Werk Nr. works no.	135 012	Betriebsstunden hours run	9717	
Vermerke remarks	Datum date	Std. hours	Pos. item	festgestellter Schaden/Reparatur/Hinweis/Mängel damage found/repair/hints/deficiencies	erled. settled	offen open
	8/7/15			TRAVEL FROM SHOP TO JOBSITE. CRANE WAS BOOMED DOWN, DISCONNECT PENNANTS AND LAY MAST BACK CLOSE TO TRANSPORT AND CRIB MAST WITH WOOD. DISCONNECT 4E-Y11 & 4E-Y12 AND SPOOL OFF A LITTLE BOOM HOIST ROPE FOR SLACK. REMOVE AND REACE ALL SHEVES FOR BOOM HOIST ON SUPERSTRUCTURE. DONE FOR THE DAY. TRAVEL FROM JOB TO KZAGWOOD, TX.		
	8/8/15			TRAVEL FROM KZAGWOOD TO JOB. REMOVE AND REPLACE ALL BOOM HOIST SHEVES ON A-FRAME. DOUBLE CHECK KEEVING, ALL GOOD. HOOK UP PENNANT LINES AND POT BOOM IN THE AIR. TRAVEL FROM JOB TO SHOP.		X

Datum Rep.-Anfang:
Date start of repair:

8/7/15

Datum Rep.-Ende:
Date end of repair:

8/8/15

Ort: SJOIANDER RD, BAYTOWN

Name und Unterschrift Monteur
Name and signature serv. eng.

X [Signature]



Established 1916
CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 8-29-15

Customer's Name: Ameco

Customer P.O. # _____

Job Location: CP Chem

M/M/T: LR1200 SX

Hours: 9800

Equipment # 200707

Serial # 135

Trip Mileage 66

Describe Defects & Cause of Failure: Crane won't start lifting cable rubbing on lugger winch sheave in butt section.

Repairs Completed: Emergency stop button depressed reset e-stop and crane starts.

Adjust lifting cable roller to prevent cable from rubbing in butt section, and grind down bracket

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer Name: J. Cedillo

Customer Signature: [Signature]

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

SERVICE REPORT

Date: 9-15-15

Customer's Name: Ameo

Customer P.O. # _____

Job Location: CP Chem

M/M/T: LR 1200 S&S

Hours: 9875

Equipment # 250167

Serial # 135021

Trip Mileage 44

Describe Defects & Cause of Failure: Crane won't start module 77 + 78 error codes

Repairs Completed: Install new software and replace module 77 (x 23 keyboard)

Qty	Part Number	Description	Ordered	Installed
1		module 77		<input checked="" type="checkbox"/>

Recommendations: _____

Technician: J. Cadillo

Customer Name: J. Cadillo

Customer Signature: [Signature]

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

SERVICE REPORT

Date: 9-24-15

Customer's Name: Ameco

Customer P.O. # _____

Job Location: CPCHM

M/M/T: _____

Hours: 9939

Equipment # 250167

Serial # 135021

Trip Mileage 3 hrs.
~~5 hrs. in all~~

Describe Defects & Cause of Failure: CUSTOMER CALL-OUT TO CHECK CABLE DRUM

Repairs Completed: Cable on Front drum backlash. Tied cable back from obstructions for customer to operate crane. I undid all power to front drum, double checked different modes of operation with the operator, drum will not engage. Cable will be pulled off drum as per customer timeline, will need to check cable for damage. Cable still on drum for now.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer Name: [Signature]

Customer Signature: [Signature]

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 9-30-15

Customer's Name: Ameco

Customer P.O. # _____

Job Location: CD Chem

M/M/T: LR1200SX

Hours: 9945

Equipment # 275167

Serial # 135021

Trip Mileage 66

Describe Defects & Cause of Failure:

Front drum back lashed and bad
Customer did not have button for luffing drum turned on and
luffed down and backlashed front drum.

Repairs Completed:

Remove bad cable from front drum

9-30-15 8.5 hrs.

10-1-15 3 hrs.

Customer to be charged for new cable and man hrs.

New cable not to put on machine by customer's
request.

Cable at yard.

Qty	Part Number	Description	Ordered	Installed
1		from drum cable	✓	

Recommendations: _____

Technician: [Signature]

Customer Name: J. Castillo

Customer Signature: [Signature]

Job Complete: _____

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

SERVICE REPORT

Date: 10-2-15

Customer's Name: Amerio

Customer P.O. # _____

Job Location: CP Chem

M/M/T: LR1200 SX

Hours: 9947

Equipment # 275167

Serial # 135021

Trip Mileage 66

Describe Defects & Cause of Failure: Hyd leak, loose fitting

Repairs Completed: tighten fitting.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: Jack A. Miller

Customer Name: J. Castillo

Customer Signature: J. Castillo

Job Complete: Yes ☒ No ☐

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 11-25-15

Customer's Name: Jacob A. McDonald

Customer P.O. # _____

Job Location: CA Chem

M/M/T: LR1200SX Liebherr

Hours: 10405

Equipment # 275167

Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: Heat not working heater valve broken

Repairs Completed: Replace heater valve under cab

Qty	Part Number	Description	Ordered	Installed
1	10584671	Water valve		X

Recommendations: _____

Technician: [Signature]

Customer Name: _____

Customer Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 12-30-15

Customer's Name: FLour

Customer P.O. # _____

Job Location: C.P. Chem

M/M/T: _____

Hours: 10718

Equipment # 275167

Serial # FK 10223223

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: _____

170429946 Fuel Filter
11004432 Water Sep ~~not~~ installed
17370955 Air ~~not~~ installed

Qty	Part Number	Description	Ordered	Installed
1	14179320	Hydraulic Filter		
2	10297295	Oil Filters		

Recommendations: _____

Technician: Daniel Sweazn

Customer Name: J. Cedillo

Customer Signature: _____

Job Complete:

Yes ☐ No ☐

Labor: Reg _____

O.T. _____



Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 12-31-15

Customer's Name: CP Chem Fluor

Customer P.O. # _____

Job Location: 650 Landall M/M/T: LIEBHERR LR120 Hours: 7 1/2

Equipment # 250167 Serial # 135021 Trip Mileage _____
CHC0043

Describe Defects & Cause of Failure: _____

Repairs Completed: Removed valve Block Solenoid on MAIN
100-54, Removed HOSES, Removed Broken Bolts from
valve Block, Picked up Bolts nuts and washers from
transfomer, Replaced Air Studs, Replaced Breck and
Hoses, Checked for leaks, Tighten cut off valve
fixings on tank hoses, Checked Leaks on Crane CASE
Housing And cleaned old OIL

9:30 - 3:30

Qty	Part Number	Description	Ordered	Installed
<u>4</u>		<u>studs</u>	<u>12</u>	<u>11</u>
<u>4</u>		<u>washers</u>		<u>11</u>
<u>4</u>		<u>nuts</u>		

Recommendations: _____

Technician: [Signature]

Customer Name: J. Carver

Customer Signature: [Signature] 12/31/15

Job Complete:

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

SERVICE REPORT

Date: 2-29-16

Customer's Name: FLour

Customer P.O. # _____

Job Location: CP Chem

M/M/T: LR 1200

Hours: 11225

Equipment # 250167

Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: 500HR Service Change oil Change oil Filter
Fuel Filter Air Filter Grease

<u>2- 10297295</u>		<u>oil Filter</u>		✓
Qty	Part Number	Description	Ordered	Installed
<u>1</u>	<u>10044302</u>	<u>Fuel Filter</u>		✓
<u>1</u>	<u>10429946</u>	<u>Fuel Sep</u>		✓
<u>1</u>	<u>P777869</u>	<u>in Air Filter</u>		
<u>1</u>	<u>P777868</u>	<u>out Air Filter</u>		✓

Recommendations: _____

Technician: Daniel Swezza

Customer Name: J Cordillo

Customer Signature: [Signature]

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____



Established 1916
CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 3-17/14-16

Customer's Name: CP Chem (Fluor)

Customer P.O. # _____

Job Location: STOLANDER

M/M/T: LIBBER

Hours: _____

Equipment # 250167
CHC 0043

Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed:

Replaced Prop Switches on Boom
for Ladder
Replaced Limit Switch on Boom tip
for Ladder
Tommy Barker

3-17-16 - 2:00 - 5:00

3-18-16 - 7:30 - 11:30

Qty	Part Number	Description	Ordered	Installed
<u>2</u>	<u>606060314</u>	<u>Limit Switch</u>		<u>2</u>
<u>2</u>	<u>226519</u>			

Recommendations: _____

Technician: _____

Customer Name: _____

Customer Signature: _____

Laine Celillo

Job Complete: _____

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

3/18/16

Copies: White: Office

Pink: Customer

Yellow: Technician Copy



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 05-21-16

Customer's Name: AMECO

Customer P.O. # _____

Job Location: CP Chem

M/M/T: LR 1200

Hours: 11802

Equipment # 250 167

Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: 500 HR Service Change oil change oil
Filter Fuel Filter Air Filter Cab Filter

4.5 Gal 15W40

1X 7370256 inner air

Qty	Part Number	Description	Ordered	Installed
1	10429949	Fuel Filter		✓
1	10044302	Water Sep		✓
2	10297295	oil Filter		✓
1	AF25454	outer air		✓

Recommendations: _____

Technician: Daniel Sweaza AUSTIN

Customer Name: _____

Job Complete: _____

Labor: Reg _____

Customer Signature: _____

Yes ☒ No ☐

O.T. _____

BIGGE

CRANE and RIGGING CO.

Established 1916

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 8-1-16

Customer's Name: C.P. Chem (flour)

Customer P.O. # _____

Job Location: 550 Lander Rd M/M/T: LIEBHERR LR1200 Hours: _____

Equipment # 2806780167 Serial # 135021 Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: Boom Down Lutter changed Left and Right Transducer
Boom UP Lutter changed codes checked
Kick outs and A2B Switch All OK

Qty	Part Number	Description	Ordered	Installed
<u>2</u>	<u>835C179670</u>	<u>Transducers</u>		<input checked="" type="checkbox"/>

Recommendations: _____

Technician: [Signature]

Customer Name: J. Redello

Customer Signature: [Signature] 8/1/16

Job Complete:

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 8.31-16

Customer's Name: Ameco

Customer P.O. # _____

Job Location: CD Chem

M/M/T: LR 1200

2606

Hours: 12625

Equipment # 250167

Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: 500 HR Service

Repairs Completed: 500HR Service Change oil Change oil Filters
Fuel Filters Air Filter A/C cab Filter

1X 7370956 inner Air Filter
1X 7370955 outer Air Filter

Qty	Part Number	Description	Ordered	Installed
1	10429946	Fuel Filter		✓
1	10044302	water sep		✓
2	10297295	oil Filter		✓
2	592293714	A/C cab Filters		✓

Recommendations: _____

Technician: Daniel And Leroy

Customer Name: J. Cerillo

Customer Signature: [Signature] 8/31/16

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy



10700 Bigge Ave
 San Leandro, CA. 94577
 (510) 638-8100

Service Report

Date : 10/14/2016

Customer's Name : C P CHEM

Customer's P.O. # _____

Job Location : SJOLANDER RD

M/M/T : LIEBHERR LR 1200

Hours : ####

Equipment # _____

250167

Serial # _____

135021

Describe Defects and Cause of Failure :

LIMIT SWITCH ON LUFFER

Repairs Completed: CHECKED CODES ON COMPUTER UPER LIMIT SWITCH NOT WORKING. WENT UP IN
MAN LIFT TO CHECK SWITCH . ROLLER ON UPPER SWITCH IS OFF . CAME DOWN ORDERED ORDERED
UPPER AND LOWER SWITCHES FROM LIEBHERR. PICKED UP SWITCHES AT LIEBHERR WENT UP IN MAN
LIFT . REMOVED UPPER AND LOWER LIMIL SWITCHES AND REPLACED AND ADJUSTED. TESTED SWITCHES
CODES WENT AWAY AND LUFFER HOISTED UP . CAME DOWN IN MAN LIFT . BOOM UP LUFFER , TESTED
A TO B SWITCH AND LUFFER KICK OUT ALL GOOD.

QTY	Part Number	Orderd	Installed	Description
2	606066314		YES	LIMIT SWITCHES

Recommendations :

Technician: LEROY SMITH

Labor : Reg. _____
 O.T. _____

Customer Signature : _____

Job Complete : Yes X
 No _____



10700 Bigge Ave
San Leandro, CA. 94577
(510) 638-8100

Service Report

Date : 10/20/2016

Customer's Name : C.P. CHEM

Customer's P.O. #

Job Location : SJOLANDER RD. M/M/T : LIEBHERR LR1200

Hours : 13300

Equipment # 250167 Serial # 135021

Describe Defects and Cause of Failure : fuel alarm on

Repairs Completed: CHECKED FUEL GAUGE ON TANK REMOVED TOP .ELECTRICAL BOARD SHORTED
WATER IN BOX. REMOVED ALARM WIRES REPLACED TOP AND ORDERED PARTS

PICKED UP PARTS AT LIEBHERR . REPLACED LEVELING STICK AND BOARD ,CHECKED
ALARM AND GAUGE ALL GOOD

10-22-16 RESET LEFT AND RIGHT SWING VALVE IN COMPUTER

10-23-16 FULL SERVICE (SEE SERVICE REPORT) HOURS -1 13329

QTY	Part Number	Orderd	Installed	Description
1	10223876		X	LEVEL SENSOR -SELL
1	917443014		X	ELECTRONIC BOARD

Recommendations :

Technician: LEROY SMITH

Labor : Reg. _____
O.T. _____

Customer Signature : _____

Job Complete : Yes ☒
No _____

White: Office Pink: Customer Yellow : Technician Copy



Auburn, WA
206-443-8500
San Leandro, CA
510-638-8100

Richmond, VA
804-271-9356
North SLC, UT
801-292-2453

Houston, TX
713-456-3086
TOLL FREE
888-337-2444

SERVICE REPORT

DATE:

CUSTOMER		C.P.CHEM (FLUOR)		TRIP MILEAGE		DATE:12/28/16	
CONTACT NAME & NO.							
JAMIE CEDILLO (832-364-5966)							
ADDRESS							
SJOLANDER RD. GATE #6							
MAKE	MODEL	SERIAL NUMBER		HOURS	UNIT NUMBER		
LIEBHERR	LR1300SX	135021		14099	250167		

SERVICE REQUESTED

FULL SERVICE

REPAIRS MADE

CHANGED MOTOR OIL AND FILTERS, CHANGED FUEL FILTERS, CHANGED AIR FILTERS, CHANGED AC CAB FILTERS,
GREASED AND LUBED ALL WIRE ROPE:
TIME:2.5 HOURS

COMMENTS

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED
1044302	1	FUEL FILTER WATER SEPARATOR	X	
10429946	1	FUEL FILRER	X	
592293714	2	CAB AC FILTERS	X	
737095503	1	INTER AIR FILTER	X	
737095603	1	OUTER AIR FILTER	X	
10297295	2	OIL FILTER	X	
15/40	10gals	MOTOR OIL	X	

LEROY SMITH SR. / DANIEL SWEAZA
TECHNICIAN


CUSTOMER SIGNATURE



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 12-28-16

Customer's Name: Ameco

Customer P.O. # _____

Job Location: CP Chem

M/M/T: LR 1200

Hours: 14099

Equipment # 275767 250107 Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: 500HR Service Change oil change
oil Filter Fuel Filter Air Filter Cab A/C Filter

1 x 1044302 Water Sep
1 x 10429946 Fuel Filter
2 x 592293714 Cab A/C Filters

Qty	Part Number	Description	Ordered	Installed
1	737095503	Air Filter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
1	737095603	Air Filter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	10297295	oil Filter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
	10 Gal	15/40 motor oil	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Recommendations: _____

Technician: Leroy Daniel

Customer Name: _____

Customer Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 2/24/17
Customer's Name: Ameco Customer P.O. #
Job Location: CP Chem M/M/T: LR 1200 Hours: 14538
Equipment # 275167 Serial # Trip Mileage

Describe Defects & Cause of Failure: Block twisting when cabling up.
Rope damaged.

Repairs Completed: Spooled off old rope. Spooled on 675m of 26mm
rope onto rear drum.

Qty	Part Number	Description	Ordered	Installed
		<u>675m 26mm rope</u>		<u>X</u>

Recommendations:

Technician: Austin Buchnayer
Customer Name: J. Celis
Customer Signature: J. Celis

Job Complete: Labor: Reg
Yes ☒ No ☐ O.T.



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 3/8/17
 Customer's Name: Amico Customer P.O. # _____
 Job Location: CP Chen M/M/T: LR1200 Hours: 14615
 Equipment # 250167 Serial # _____ Trip Mileage _____

Describe Defects & Cause of Failure: Engine randomly stalling.

Repairs Completed: Replaced del filters. Reprimed fuel system

Qty	Part Number	Description	Ordered	Installed
1	10044302	Water/Fuel separator filter		X
	10429946	Fuel filter		X

Recommendations: _____

Technician: Austin Buchmayr
 Customer Name: J. Celillo Job Complete: ☒ Yes ☐ No Labor: Reg _____
 Customer Signature: [Signature] O.T. _____



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 3-12-17

Customer's Name: AMECO

Customer P.O. # _____

Job Location: CP Chem

M/M/T: LR 1200

Hours: 14646

Equipment # 250167

Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: 500HR Service Change oil change oil Filter
Fuel Filter Air Filter Cab A/C Filter

10 Gal 15/40
1x 7370955 Outer Air

Qty	Part Number	Description	Ordered	Installed
2	10297295	oil Filter	✓	✓
1	10044302	Fuel Water Sep	✓	✓
1	10429946	Fuel Filter	✓	✓
1	7370956	Inner Air Filter	✓	✓

Recommendations: _____

Technician: Daniel Sweaza

Customer Name: J. Cardillo

Customer Signature: [Signature] 3/17/17

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 5-17-17

Customer's Name: Ameco

Customer P.O. # _____

Job Location: CP Chem

M/M/T: LR 1200

Hours: 15259

Equipment # 250167

Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: 500HR Service change oil change
oil Filter Fuel Filter Air Filter
Cab A/C Filter

8 Gal 15/40
1X SKL 46607 Filter mat
2X SKL 46608 Cab A/C Filters
1X 7370955 outer Air Filter

Qty	Part Number	Description	Ordered	Installed
2	LR3749	Lube Filter	✓	✓
1	WK 1156/2	Fuel Filter	✓	✓
1	1009302	Fuel water sep	✓	✓
1	7370956	inner Air	✓	✓

Recommendations: _____

Technician: Amstion & Daniel Swartz

Customer Name: J. Celli

Customer Signature: [Signature]

Job Complete: _____

Yes ☒ No ☐

Labor: Reg _____

O.T. _____



14800 Jersey Shore Dr.
 Houston, TX 77047
 (713) 434-0995

SERVICE REPORT

Date: 5/30/17
 Customer's Name: AMECO Customer P.O. # _____
 Job Location: CP Chem M/M/T: LR 1200 Hours: 15407
 Equipment # 250167 Serial # 135021 Trip Mileage _____

Describe Defects & Cause of Failure: Main boom cable dummy plug
missing.

Repairs Completed: Ordered and installed new dummy plug.

Qty	Part Number	Description	Ordered	Installed
1	11214982	Dummy Plug		X

Recommendations: _____

Technician: Austin Buchmayer
 Customer Name: J. Cel: 110 Job Complete: ☒ Yes ☐ No Labor: Reg _____
 Customer Signature: [Signature] 5/30/17 O.T. _____



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 6-7-17

Customer's Name: A-meco

Customer P.O. # _____

Job Location: West Lake

M/M/T: LR 1200

Hours: 15408

Equipment # 275167

Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: 500HR Service Change oil Change oil Filter
Fuel Filter Air Filter A/C Cab Filter

		10 Gal 15/40		
1 X	7370955	Outer Air Filter		
1 X	7370956	Inner Air Filter		
Qty	Part Number	Description	Ordered	Installed
2	LF 3749	Lube Filter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
1	1004432 10429946	Fuel Filter	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
1	1004432	Fuel Water Sep		
2	SKL 46608	Cab A/C Filters		

Recommendations: _____

NO ONE there to sign

Technician: Daniel Swcazn

Customer Name: _____

Job Complete: _____

Labor: Reg _____

Customer Signature: _____

Yes ☒ No ☐

O.T. _____

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

6-30-17
Date: 7-11/12-17 Per: Brynnce Turner
Customer's Name: Ameco Customer P.O. # _____
Job Location: SASOI M/M/T: LIEBHERR LR1200 Hours: 15431
Equipment # 280167 Serial # 135021 Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed:

6-30-17 - Pul shield on Boom, Pul on
BAD Block Boomup Crane And tested
All KICK on FS
7-10-17 - Checked Plugs on Fall BACK Sinsor And
Switches, checked wires on Fib Ladder Box
Time Checked All Puses, Left Pressure Switch plug
6:00 AM And Link Pressure Sinsor need Dried out And
2:00 PM Replaced ordered Sinsor Barw And Lighting
Stand Down
7-11-17 - Replaced Luffing Fall BACK Sinsor 5
Time - 2:00 PM 3:30 PM
7-12-17 - Reset Three Wap Drum Indicator on Rear
Drum
Time - 10:00 PM 11:30 AM

Qty	Part Number	Description	Ordered	Installed
2	693126214	Pressure Sensor		

Recommendations: _____

Technician: Sergio Smith SR

Customer
Name: _____

Customer
Signature: _____

Job Complete: _____

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 8-3-17

Customer's Name: Performance (Ameco)

Customer P.O. # _____

Job Location: SASO 1

M/M/T: LIEBHERR LR 1200

Hours: 15738

Equipment # 250 167
CAC 0106

Serial # 135-001

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: Checked Luffed winch And Aux Drums And
Refilled with OIL
Checked front And Rear Grease CANS And
Refilled, Checked top wiper Blade And wiper
motor need REPLACED (in deal)

Time 10:00 Am - 12:00 pm

Qty	Part Number	Description	Ordered	Installed
<u>1</u>		<u>wiper Blade And motor</u>	<u>✓</u>	

Recommendations: _____

Technician: Levy Smith Sr.

Customer Name: Josef

Customer Signature: _____

Job Complete:

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 11-18-17

Customer's Name: Amoco

Customer P.O. # _____

Job Location: Westlake

M/M/T: LR 1200

Hours: 16388

Equipment # 275167
CHC 0106

Serial # 135021

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: Install new HORN

Qty	Part Number	Description	Ordered	Installed
<u>1</u>	<u>730-1043</u>	<u>HK9 24V HORN</u>	<u>✓</u>	<u>✓</u>

Recommendations: _____

Technician: Daniel Swartz

Customer Name: _____

Customer Signature: _____

Job Complete: _____

Yes ☐ No ☐

Labor: Reg _____

O.T. _____



Bigge Service Report

Sequence Number	598
-----------------	-----

Information



Service Type	<input checked="" type="checkbox"/> Maintenance
Maintenance Type	<input checked="" type="checkbox"/> General Repair Damage Repair Warranty Scheduled Maintenance
Equipment Type	Crawler
Date/Time:	10-23-2019
Equipment Number:	250167
Make:	Liebherr
Model:	LR1200
Serial Number:	135.021
Customer Name:	BMEI
Jobsite Name:	Garden city wind farm
Jobsite Address:	Garden city wind farm
Job Number:	1234

Details of work

Travel to job by:	Air <input checked="" type="checkbox"/> Bigge Vehicle Personal Vehicle Rental Car
Weather conditions:	<input checked="" type="checkbox"/> Clear High Wind Rain Snow Ice Excessive Heat Excessive Cold
Crew members (List names of all crew members):	Bradley Wick



Bigge Service Report

Description of initial call out / reported issue:	Left track has leak and won't hold tension while cutting.
Work performed:	Checked crane and verified issue. Found damaged and leaking fittings and tension relief valve. Ordered new fittings and valve. Installed new parts and tested crane, all tests and checks good. No leaks.
Parts used:	Pressure limiting valve 592323114 Flange joint 7617461 12s adapter
Were there any issues or delays?	No
Follow up work / recommendations:	None
Time arrived on site	07:00 AM (-5 GMT)
Time equipment was back in service (This may differ from time left site)	09:00 AM (-5 GMT)
Hour Meter Reading:	17709
Hour Meter	
Annual Inspection Sticker	

Acceptance

Acknowledgment	By my signature below, I certify that all work has been performed to my satisfaction. Thank You
	 31.763751, -101.660241
Name:	Dustin
Phone #	1234
Email:	1234



Date Submitted: 10-23-2019 02:53 PM

Submitted By: bwick@bigge.com

Bigge Service Report

Signature	
Name:	Bradley Wick
Signature	



Date Submitted: 10-23-2019 02:53 PM

Submitted By: bwick@bigge.com

Bigge Service Report

Form Locations

