

SERVICE REPORT

Date: 10/15
 Customer's Name: Matrix Customer P.O. # _____
 Job Location: MH 2 Channelview M/M/T: RT670 Hours: 2.79
 Equipment: RT67004 Serial # 161192 Trip Mileage _____
 Describe Defects & Cause of Failure: no A/C

Repairs Completed: R/R Compression, dryer & expansion valve
VAC & charging

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]
 Customer Name: YAC Nery Job Complete: Yes ☐ No ☐ Labor: Reg _____
 Customer Signature: [Signature] O.T. _____

SERVICE REPORT

Date: 12-2-13
 Customer's Name: BERKELEY Customer P. O. # _____
 Job Location: MEMORIAL DR M/M/T: TEREX RT470-1 Hours: 291
 Equipment # _____ Serial # 161192

Describe Defects & Cause of Failure: _____

Repairs Completed: Removed Swing P04 from Computer
PW & ON TANK And Hose for hose

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature] Job Complete: _____ Labor: Reg 3:00 - 5:30
 Customer Name: Tina Roberts Berkeley Co. Yes ☒ No ☐
 Customer Signature: [Signature] O.T. _____

SERVICE REPORT

Date: 02-27-14

Customer's Name: Biggs

Customer P. O. # _____

Job Location: Stop/Vend

M/M/T: _____

Hours: 621.0

Equipment # BE 700X

Serial # 161192

Describe Defects & Cause of Failure: _____

Repairs Completed: Instal Hast Boal Hook on.
Day Before B-Service. Oil Change and Filter.
is OK

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer Name: _____

Customer Signature: _____

Job Complete: _____

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 4-8-14

Customer's Name: Compressor Station

Customer P. O. # _____

Job Location: Bangue et Ty 3612 FM 666

M/M/T: TEREX RT670-1

Hours: 701

Equipment # BE7004

Serial # 1161192

Describe Defects & Cause of Failure: Outriggers will not set on full
outriggers

Repairs Completed: Reset computer, Adjusted Bubble leveler

TO Bangue et Ty Time - 8:41-12:30

miles - 227

ON JOB - 12:30 - 1:15

TO Houston Time - 1:15 - 6:30

miles - 228

(6:30)

Qty	Part Number	Description	Ordered	Installed

Recommendations: CONTACT - DWAYNE HAMILTON 405-694-7827

Technician: [Signature]

Customer Name: _____

Customer Signature: [Signature]

Job Complete: _____

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 5-29-14

Customer's Name: Ranger

Customer P. O. # _____

Job Location: Robstown Tx

M/M/T: Terex RT670-1

Hours: 938

Equipment # BG7004

Serial # 161152

Describe Defects & Cause of Failure: A/C not working

Repairs Completed: T/S A/C, thermostat bad

Need to order parts.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer Name: _____

Customer Signature: Dwayne Hamilton

Job Complete: _____

Yes ☐ No ☒

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 6-3-14

Customer's Name: Barger

Customer P. O. # _____

Job Location: Robstown, Tx

M/M/T: RT670-1

Hours: 948

Equipment # B97004

Serial # 161192

Describe Defects & Cause of Failure: ALC not work

Repairs Completed: order thermostat and replace

*Left front extension cylinder leaking at
valve block on barrel need to be replaced.

Qty	Part Number	Description	Ordered	Installed
1	215841	Thermostat		<input checked="" type="checkbox"/>

Recommendations: _____

Technician: _____

Customer
Name: _____

Customer
Signature: _____

Job Complete: _____

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 8-8-14
 Customer's Name: Ranger Plant Const. Customer P. O. # _____
 Job Location: Banquete, Tx M/M/T: Terex RT 670-1 Hours: 1452
 Equipment # BE7004 Serial # 161192

Describe Defects & Cause of Failure: A/c not working

Repairs Completed: Arrived to location of crane. A/c blower was not working. Remove fan switch and install new switch. Tested fan and not working. Checked fuses and fuse was blown due to fan switch going bad. Installed new fuse and tested a/c, & blower fan & A/c compressor started working, blowing cold.

Warranty - Claim

Qty	Part Number	Description	Ordered	Installed
1		A/c fan switch		✓

Recommendations: _____

Technician: DANIEL CANU
 Customer Name: Jonny Martinez Jr.
 Customer Signature: _____

Job Complete: Labor: Reg _____
 Yes ☒ No ☐ O.T. _____



Date: 11-15-10
Customer's Name: Range Plant Services Customer P. O. # _____
Job Location: 3612 FM 666 M/M/T: TEREX RT 6701 Hours: 1929
Banquet, TX
Equipment # BC7004 Serial # 161192

Describe Defects & Cause of Failure: _____

Repairs Completed: Changed motor oil And filter

Changed fuel filters

Greased under carriage
Greased Block And Boom

Time 1:00 - 1:40
miles to Job - 32 To Job -
miles to Houston 4:00 - 8:00
Time on Job - 1:40 - 4:00

Qty	Part Number	Description	Ordered	Installed
1	7182	OIL filter		1
1	3682 3682	Fuel filter		1
1	FS19132	Water Separator filter		1
				1

Recommendations: _____

Technician: As Above

Customer Name: John Smith

Customer Signature: 

Job Complete: Labor: Reg _____

Yes ☒ No ☐ O.T. _____

Copies: White: Office Pink: Customer Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 1/29/15

Customer's Name: Bigge Crane

Customer P.O. # _____

Job Location: Bigge - Hou. Tx.

M/M/T: Terex RT 670-1

Hours: 2004

Equipment # BE 7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: Tech. Remove + replaced left rear flasher bulb - topped
off wiper fluid - Troubleshoot A/C fan control switch burnt. Remove
replaced A/C ok - Checked ATB checked out ok - Put snap ring
on to block latch - Greased main + Aux wire ropes - Installed
bolts into front engine panel - NO service need at time
last service 1959 hrs. - Blowed out air element - Installed new
propane tank

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: Marcus Pin

Customer Name: _____

Customer Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 3/5/15

Customer's Name: Bigge CRANE

Customer P.O. # _____

Job Location: Bigge-Hou. Tx.

M/M/T: Terex/RT670-1

Hours: 2127

Equipment # BE 7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: Tech H. Removed & replaced propane tank -
Repair leaking left front beam cylinder
Greased boom sections.

Lubed main air wire rope

No service need at time - last svc. at 1929 HRS.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: Marcus Rice

Customer Name: _____

Customer Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 3-6-15

Customer's Name: Berkel Company

Customer P.O. # _____

Job Location: UNDER WED

M/M/T: TERRY RAYMOND

Hours: 10132

Equipment # 161192

Serial # 161192

Trip Mileage 28

Describe Defects & Cause of Failure: _____

Repairs Completed:

Pull on Jib Rephooked A & B
Swapped Jib to Boom Tip

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer Name: Tracy [Signature]

Customer Signature: [Signature]

Job Complete:

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 3-11-15

Customer's Name: BERICI (NRG)

Customer P.O. # _____

Job Location: Underwood

M/M/T: _____

Hours: 2141

Equipment # BE7004

Serial # 161192

Trip Mileage 28

Describe Defects & Cause of Failure: _____

Repairs Completed:

Replaced Swing Lock Hose And
Fixing Air Coupling on cylinder

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer Name: James Cunningham

Customer Signature: [Signature]

Job Complete:

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 3/5/15

Customer's Name: Bigge Crane

Customer P.O. # _____

Job Location: Bigge-Hou. Tx.

M/M/T: Terex/RT670-1

Hours: 2127

Equipment # BE 7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed:

Tech H. Removed & replaced propane tank -
Repair leaking left front beam cylinder
greased boom sections.

lubed main & aux wire rope

NO SERVICE NEEDED AT TIME - LAST SVC. AT 1929 HRS.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician:

Manus Price

Customer
Name: _____

Job Complete:

Labor: Reg _____

Customer
Signature: _____

Yes ☒ No ☐

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 03-23-15

Customer's Name: Berkel

Customer P.O. # _____

Job Location: EN COS

M/M/T: RT 670-1 Terex

Hours: 0205

Equipment # BE7004

Serial # 161152

Trip Mileage 96

Describe Defects & Cause of Failure:

NO boom, tele, or swing, pump shaft and coupler bad.

Repairs Completed:

03-22-15 Travel to Jobsite and T/S no
traction problem. Found that boom, tele, swing pump bad. Remove
pump and coupler.

03-23-15 Install new pump. SAE flange size different
on new pump. Install new hoses on pressure side of pump.

Qty	Part Number	Description	Ordered	Installed
<u>1</u>		<u>Pump</u>		<u>/</u>
<u>1</u>		<u>Coupler</u>		<u>/</u>
<u>2</u>		<u>Hoses</u>		<u>/</u>

Recommendations: _____

Technician: [Signature]

Customer
Name: James Cunningham

Customer
Signature: [Signature]

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

SERVICE REPORT

Date: 4/1/15

Customer's Name: Bigge CRANE

Customer P.O. # _____

Job Location: Bigge-Hou. TX

M/M/T: Terex RT670-1

Hours: 2222

Equipment # BE 7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: A/c Not cooling - MAIN boom weight incorrect

Repairs Completed: Tech - performed resetting transducer & recalibrating system had fault - Tech removed & replaced transducer box - Zero sensor & Reset boom lengths -
- Tech. removed & replace A/c pressure switch & dryer vacuum system & Recharged with R-134

Qty	Part Number	Description	Ordered	Installed
1	403081	pressure Sw. Tech A/c	1	1
1	82-00-001	A/c Dryer	1	1
1	23520100	Transducer Box	1	1

Recommendations: _____

Technician: 

Customer Name: _____

Customer Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 4-20-75

Customer's Name: CPK (FLUOR)

Customer P.O. # _____

Job Location: STOLANDER R M/M/T: TEREX RT670

Hours: 2233

Equipment # BE7004

Serial # 161192

Trip Mileage 28

CHR3607

Describe Defects & Cause of Failure: _____

Repairs Completed: _____

Removed Plugs And Computer BOX
Cover And Dried Out Water

11:30 - 1:30

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: _____

Customer
Name: _____

Customer
Signature: _____

Job Complete: _____

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 5-1-15

Customer's Name: Ameco

Customer P.O. # _____

Job Location: CD Chem

M/M/T: RT670 Terex

Hours: 799

Equipment # BE7004

Serial # 161192

Trip Mileage 66

Describe Defects & Cause of Failure: Computer displaying overload, out of Calibration

Repairs Completed: Flash computer with hex file and calibrate

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer Name: Jaime C. [Signature]

Customer Signature: [Signature]

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

CRANE and RIGGING CO.

Established 1916

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 5-18-15

Customer's Name: Ameco

Job Location: CA Chem

Customer P.O. # _____

Equipment # BE7004

M/M/T: RT670 Terex

Hours: 2312

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: Greer Computer lost communication with display.

Repairs Completed: T/S and found that Computer board bad.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]

Customer Name: Dalton Rowe

Customer Signature: [Signature]

Job Complete:

Yes ☐ No ☒

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 5-19-15

Customer's Name: Ameco

Customer P.O. # _____

Job Location: CA Chem

M/M/T: RT670 Terex

Hours: 2312

Equipment # BE7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure:

Greer computer bad. Communication with main computer failed

Repairs Completed:

Replace greer computer, download Hex file and
Calibrate angle & length. Communication good.

Qty	Part Number	Description	Ordered	Installed
1		Greer computer		X

Recommendations: _____

Technician: Scott McLean

Customer Name: Dalton Rowe

Customer Signature: Dr. R.

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 6-26-15

Customer's Name: _____

Customer P.O. # _____

Job Location: Shop

M/M/T: Terex RT 670-1

Hours: 2450

Equipment # BE 7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: Tint on windows, P.M service, customer
stickers on crane

Repairs Completed: Removed tint on windows, *P.M service completed*
Removed customer stickers

18 quarts " 4.5 gallons " 15/40 engine oil

Qty	Part Number	Description	Ordered	Installed
1	7182	Oil Filter		
1	FS 19732	Fuel water Separator		
1	3682	Fuel Filter		
1	5261249	Air Filter		

Recommendations: _____

Technician: Jason Remy

Customer
Name: _____

Customer
Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg 6

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

SERVICE REPORT

Date: 9/30/15
 Customer's Name: Matrix Customer P.O. # _____
 Job Location: Miller RD 2 M/M/T: RT670-1 Hours: 2727
 Equipment # BE7004 Serial # 1T9RT100 HCW Trip Mileage 161182
 Describe Defects & Cause of Failure: Hyd leak.

Repairs Completed: Loose fitting & bad O-ring on outrigger valve
body test point.

R/R Test point & Replace O-ring.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature]
 Customer Name: ALF AMSON
 Customer Signature: [Signature]

Job Complete: Labor: Reg _____
 Yes ☐ No ☐ O.T. _____



CRANE and RIGGING CO.

Established 1916

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 1-13-16

Customer's Name: Bigge CRANE

Customer P.O. # _____

Job Location: Hou. Tx

M/M/T: Terex / RT 670-1

Hours: 3055

Equipment # BE 7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: Anti-freeze leak at overflow tank - PM SVC.

Repairs Completed: Tech removed engine oil filter - fuel filters T/m filter - Inner + outer Air element - Replaced engine oil and filters

- Removed overflow tank found crack in tank repaired CRACK on tank - Reinstalled tank + reconnected hoses
- Remove + Replace damage hood compartment hinge + door
- Installed correct brake light bulbs + removed + replace diode on left rear
- Installed new latches on block + ball
- Greased upper + lower crane - Greased boom sections
- Removed + Replaced front + upper wipe blades
- Replaced damage A/c louver

1 -	216855	- wiper blade (front)	1	1
1 -	57182	- oil filter	1	1
1 -	FF5612	- fuel filter	1	1

Qty	Part Number	Description	Ordered	Installed
1	FS19732	Fuel/Water Sep	1	1
1	471788	Latch Kit (Block)	1	1
1	471784	" " (Ball)	1	1
1	463402	A/c Louver	1	1
1	AF55014	outer air element	1	1
1	AF55308	Inner "	1	1

Recommendations: _____

Technician: Manus Rice

Customer Name: _____

Customer Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

14940 Jersey Shore Dr
Houston, TX 77041
(713) 494-0998

Parker
pump

Bigge
CRANE AND RIGGING

SEE THE REPORT

3002

10/11/95
10/11/95

BE 10/11
10/11/95

Autogas tank at over-bank -
911 sec.

Removed section tank found block in the repaired
Crank on tank - reinstalled fuel & returned to hoses
Remove - replace damage hood compartment hinge & door
Installed correct chain light balls - remove replaced
block on left knee
Installed new rollers on block & ball
Greased upper - lower crane - Greased lower sections
Removed - replaced float - upper wgs block 2

1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter
1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter
1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter
1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter
1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter
1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter
1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter
1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter
1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter
1 - 21182 - fuel filter	1 - 21182 - wiper blade (front)	1 - 21182 - oil filter	1 - 21182 - fuel filter

Thomson/Fore

SERVICE REPORT

Date: 2/29/16

Customer's Name: Bigge Crane

Customer P.O. # _____

Job Location: Hou. Tx

M/M/T: Tenex / RT670-1

Hours: 3080

Equipment # BE 7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: Turbo making noise

Repairs Completed: Tech. removed engine manifold - DRAIN engine radiator removed Air intake removed engine turbo - Sent turbo out to be rebuild. Reinstall engine Air intake - manifold - turbo

- found wire unplugged on safety lever on left hand side Reconnect wire safety lever working correctly
- lubed Aux wire rope
- removed + replace turn signal flasher
- lubed crane

Qty	Part Number	Description	Ordered	Installed
1	091225	TURN signal flasher	1	1

Recommendations: _____

Technician: Maneus Price

Customer Name: _____

Customer Signature: _____

Job Complete: _____

Yes ☒ No ☐

Labor: Reg _____

O.T. _____



SERVICE REPORT

Date: 1-12-2017

Customer's Name: _____

Customer P.O. # _____

Job Location: _____

M/M/T: _____

Hours: 3/37

Equipment # DE 7004

Serial # 161192

Trip Mileage 10

Describe Defects & Cause of Failure: _____

Repairs Completed: put new oil pan gasket on Eng
New Crank Case filter Fix other Eng oil Leaks +
Tran Leaks Greased, mach. Replaced Cover on
Out Rigger SW, welded in new Bolts for Cover
Painted Ball

Qty	Part Number	Description	Ordered	Installed
1	12455192	Tran p6i SW,		✓
1		oil pan Gasket		✓
1	CV52001	Crank Case Filter		✓

Recommendations: _____

Technician: Wayne + Mike

Customer Name: _____

Customer Signature: _____

Job Complete: _____

Yes ☐ No ☐

Labor: Reg _____

O.T. _____



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 3-6-17

Customer's Name: _____

Customer P.O. # _____

Job Location: HOUSTON SHOP M/M/T: TEREX RT 670-1 Hours: 3282

Equipment # BE7004 Serial # 161192 Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: LUBE WIRE ROPE. BRAZE END CABLE. TOUCH UP PAINT ON LADDER. GREASED BOOM SECTIONS & LUBE BOOM CHAIN. GREASE UPPER & LOWER CRANE. CHECKED ALL FLUID LEVELS. BLEW DIRT FROM RADIATOR, A/C CONDENSOR, & FILTERS. SERVICED BATTERIES. CRANE WAS WASHED & DETAILED.

LAST P.M. 1-8-17 @
3085 HOURS.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: C. MADDEN

Customer Name: _____

Customer Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____



10-14-028282

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 1-10-18

Customer's Name: Bigge

Customer P.O. # _____

Job Location: Houston, TX

M/M/T: Terex 670-1

Hours: 4378

Equipment # BE 7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: replaced front Headlight & turn signal bulbs, cleaned out outrigger beams, replaced reflector tape on jack's, 3rd party inspection passed, replaced propane tank with a full one, replaced fire ext., painted Ball & Block, greased boom, installed snap ring & keepers on Block & Ball, topped off Hyd oil, coolant & washer fluid, replaced both batteries w/new, blew clean all coolers, tightened hoses & clamp for pump leak, leveled axles, troubleshoot & repaired horn, fueled

Customer damage repairs: replaced outrigger pad keepers X4, replaced main cable w 3/4" X 600ft, front cover of deck straighten as best as possible, replaced latch on Aux. ball, replaced prox switch & cover, replaced A/C knob

Qty	Part Number	Description	Ordered	Installed
1	T120217	Prox switch (billable)		
1	T120594	Sensor cover (billable)		
600ft		3/4" hoist cable (billable)		
1		A/C knob (billable)		

Recommendations: _____

Technician: Julian Rios, George P

Customer Name: _____

Customer Signature: _____


Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

10-00-10-01



Form header section with fields for name, address, and other identifying information.

Main body of the document containing several paragraphs of handwritten text.

10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01
10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01
10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01
10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01
10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01	10-00-10-01

Form footer section with additional fields and stamps.



SERVICE REPORT

Date: 05.17.2019

Customer's Name: BENGAL

Customer P.O. # _____

Job Location: PASADENA

M/M/T: TEREX RT670-1

Hours: 4537

Equipment # BE7004

Serial # 161192

Trip Mileage _____

Describe Defects & Cause of Failure: FAN HUB/PULLEY SPLIT 10-TRON
CAUSING BELT FAILURE.

Repairs Completed: REMOVED ENGINE COWLING. DRAINED
COOLANT. REMOVED BROKEN FAN HUB, TENSIONER
AND WATER PUMP.

INSTALLED NEW: WATER PUMP, FAN PULLEY W/SUPPORT
SERPENTINE V-BELT AND BELT TENSIONER.

FILL SYSTEM WITH COOLANT - 8 GALLONS.

TEST. ALL GOOD. - REINSTALL COWLING.

Qty	Part Number	Description	Ordered	Installed
1	5260996	SUPPORT, FAN		
1	5282158	PULLEY, FAN		
1	3289952	BELT V, RIBBED		
1	5473237	KIT, WATER PUMP		
1	5256546	TENSIONER, BELT.		

Recommendations: _____

Technician: A. BRANDON

Customer Name: _____

Job Complete: _____

Labor: Reg _____

Customer Signature: [Signature]

Yes ☐ No ☐

O.T. _____