



Auburn, WA  
206-443-8500  
San Leandro, CA  
510-638-8100

Richmond, VA  
804-271-9356  
North SLC, UT  
801-292-2453

Houston, TX  
713-434-0995

Toll Free  
888-337-2444

41-01-56386

## SERVICE REPORT

DATE: 6-12-13

CUSTOMER <i>Michels</i>		TRIP MILEAGE <i>366</i>	
CONTACT NAME & NO. <i>Spencer</i>			
ADDRESS			
MAKE <i>Grove</i>	MODEL <i>RTB90E</i>	SERIAL NUMBER <i>223308</i>	UNIT NUMBER <i>BE9057</i>

SERVICE REQUESTED <i>Teardown Crane &amp; move to Different Jobsite and build</i>

REPAIRS MADE <i>Transducer on boom cylinder leaking</i> <i>computer not reading Actual weight on main &amp; Aux</i> <i>reading -3.4 need to order transducers</i>

COMMENTS <i>Drove from Houston yard to Wells TX P.O. 39. 138 miles</i> <i>Remove Cwt. and load out. Drove from Wells, TX. to</i> <i>Bennington Ok. P.O. and install Cwt.</i> <i>228 miles.</i>

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED

TECHNICIAN

*Patrick J. Lasato*  
CUSTOMER SIGNATURE





Auburn, WA  
206-443-8500  
San Leandro, CA  
510-638-8100

Richmond, VA  
804-271-9356  
North SLC, UT  
801-292-2453

Houston, TX  
713-434-0995

Toll Free  
888-337-2444

## SERVICE REPORT

DATE: 9-5-13

CUSTOMER <i>Michels</i>		TRIP MILEAGE <i>360</i>	
CONTACT NAME & NO. <i>Spencer</i>			
ADDRESS <i>Bennington OK.</i>			
MAKE <i>Grove</i>	MODEL <i>RT890E</i>	SERIAL NUMBER	HOURS <i>1782</i>
			UNIT NUMBER <i>BE9057</i>

### SERVICE REQUESTED

*load-out cut. & crane*

### REPAIRS MADE

*Travel to jobsite, remove cut. load-out.*

### COMMENTS

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED

TECHNICIAN

CUSTOMER SIGNATURE



Established 1916  
**CRANE and RIGGING CO.**

14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 8-13-15

Customer's Name: Ameo

Customer P.O. # \_\_\_\_\_

Job Location: CP Chem

M/M/T: RT890E Crane

Hours: 3871

Equipment # BE9057

Serial # 232208

Trip Mileage 66

Describe Defects & Cause of Failure:

Hyd leak, bad oring @ swivel  
A/C not cooling

Repairs Completed:

Replace o-ring, and charge A/C

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: \_\_\_\_\_

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

J. Cavillo  
8/13/15

Job Complete: \_\_\_\_\_

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

Copies: White: Office

Pink: Customer

Yellow: Technician Copy





Established 1916  
**CRANE and RIGGING CO.**

14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 9-17-15

Customer's Name: Ameco

Customer P.O. # \_\_\_\_\_

Job Location: CP Chem

M/M/T: RT890 Grove

Hours: 4086

Equipment # BE9057

Serial # 232218

Trip Mileage 66

Describe Defects & Cause of Failure: Service due, rotation indicator on main not working, A/C not blowing, grease boom (dry boom). O/R pads want stay on.

Repairs Completed: change engine oil, oil filter, Air filters and fuel filters. T/S thumper and replace proximity switch on drum. Pull A/C blower unit out and clean coils. Grease boom. Replace cups and spring kits on R/R O/R pad.

3 - roll pins  
3 - spring k.its  
1 - pad finger  
1 - proximity switch

Qty	Part Number	Description	Ordered	Installed
1		oil		✓
1		Air		✓
1		Air		✓
1		fuel		✓
1		fuel sep		✓

Recommendations: \_\_\_\_\_

Technician: David A. McDonald

Customer Name: J. Casilla

Customer Signature: [Signature]

Job Complete: \_\_\_\_\_

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

# BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

## SERVICE REPORT

Date: 9/10  
11-9-15

Customer's Name: CPK (FLUOR)

Customer P.O. # \_\_\_\_\_

Job Location: STOLANDER RD M/M/T: GROVE RT 890E Hours: 4377

Equipment # BE9057 Serial # 232280 Trip Mileage \_\_\_\_\_  
BE8061, 150320, TV-011

Describe Defects & Cause of Failure: \_\_\_\_\_

Repairs Completed: Checked out Rigger PAD Pins And  
BE9057  
11-9-15 Clups And Ordered 10:00-12:30

BE957  
11-10-15- Replaced Right front out Rigger PAD clump  
And Spring And Pin 10:00-10:30

11-10-15-BE8061- Replaced Left Rear out Rigger clump And Pin  
Hours-1437 Time-10:30-11:00

11-10-15-150320-Boom down Crane changed wind meter Battery  
Hours-4791 Time 11:00-12:00

11-10-15-Repairs HD LEAKON swing motor, Replaced Hour Meter-12:00-12:30  
TV-011 Hours-0 - COAK - Pick up meter-7:00-9:30 Hour meter

Qty	Part Number	Description	Ordered	Installed
2	9-834-100006	Out Rigger PAD Springs & P.W. Set (BE9057)		✓
2	042715/1	Out Rigger clump (BE8061)		✓
1	ER34615	3.6V wind meter Battery (-150320)		✓
1	100222-0	Hour meter TV-011		✓

Recommendations: \_\_\_\_\_

Technician: Benjamin

Customer Name: J. Cellio

Customer Signature: Benjamin 11/10/15-

Job Complete: \_\_\_\_\_ Labor: Reg \_\_\_\_\_

Yes ☐ No ☐ O.T. \_\_\_\_\_

Copies: White: Office

Pink: Customer

Yellow: Technician Copy





Established 1916  
**CRANE and RIGGING CO.**

14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 11-20-15

Customer's Name: C P Chem Elevator

Customer P.O. # \_\_\_\_\_

Job Location: \_\_\_\_\_

M/M/T: \_\_\_\_\_

Manidoc 777  
Grove 8905

Hours: \_\_\_\_\_

Equipment # 200317  
Manidoc 777

Serial #

7771093

Trip Mileage \_\_\_\_\_

Grove 8905-BE9057

Describe Defects & Cause of Failure: \_\_\_\_\_

Repairs Completed:

200317-Hours 5956 SH 7771093

Removed Hoses from Hoses in cab cut off  
Hydro valves, and replaced hoses, checked hydro line  
on boom hoist motor removed hydro line had Rema. R  
and replaced, refilled radiator wash water checked  
hydro oil in tank 7:00 - 10:00

BE9057-Hours.

SH 232208 - checked hydro line on leak  
front steering cylinder, removed hydro hose  
had Rema. R WAPA Auto Parts replaced  
hose and checked hydro tank level  
10:00 - 12:00

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: \_\_\_\_\_

Customer  
Name: \_\_\_\_\_

Customer  
Signature: \_\_\_\_\_

J. C. Williams 11/20/15

Job Complete: \_\_\_\_\_

Yes ☐ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

### SERVICE REPORT

Date: 12-23-15

Customer's Name: Flour

Customer P.O. # \_\_\_\_\_

Job Location: C.P. Chem

M/M/T: \_\_\_\_\_

Hours: 4703

Equipment # BE 9057

Serial # 232208

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: \_\_\_\_\_

Repairs Completed: Servica Grease Boom

(Needs cable lube. And Grease cut Fix on Ball)

Qty	Part Number	Description	Ordered	Installed
1	FF 5632	Fuel Filter		
1	LF 3970	Oil Filter		
1	33965	Water Sep		
1	AF 55015	outer Air		

Recommendations: \_\_\_\_\_

Technician: Daniel Sweaza

Customer Name: J. Ceballos

Customer Signature: \_\_\_\_\_

Job Complete:

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

12/23/15

H&E Equipment Services, Inc.  
1700 South Sam Houston Parkway West  
Houston TX 77047-6312  
Tel No. (877) 321-5249  
Fax No. (713) 433-3981

Regional Credit Office  
Phone (866) 322-6577  
Fax (972) 606-1011

## Invoice Preview

<b>Bill-To-Party</b> BIGGE CRANE AND RIGGING COMPANY ACCOUNTS PAYABLE PO Box 1657 SAN LEANDRO CA 94577	<b>Information</b> Invoice Preview No. 70342391 Order No. 41801998 Customer No. 1014390 PO No. PO date Currency USD Make GV - GROVE CRANE Model RT880E RT890E Serial No. 232208 Customer Eq No. BE9057 H&E Eq No. 10115684 Customer Contact Rick Rumrey Contact Phone 832-405-4153 Meter 6077 hrs 0 mile
<b>Ship-To-Party</b> BIGGE CRANE AND RIGGING COMPANY PO Box 1657 BayTown TX 77520	
<b>Complaints</b>	
<b>Complaint Details</b>	
Start having problems after working the machine half a day	
<b>Causes</b>	
<b>Cause Details</b>	
<b>Corrections</b>	
<b>Correction Details</b>	
02/12 Travel to the job. Checked and found a canbus error. Checked the CAN line in the display. Lost all CANS except display and central unit showing error codes. Unplugged the central unit and display from the CAN hub and got green light on CAN line. Plugged back into the CAN hub and removed the swing pot. CAN board and transducer block. Plugged one in at a time to the hub and all went green. Went to the working screen and found the wind speed was at 35.7 MPH with no transmitter. Called the factory for the file to turn off the wind speed. Flashed the central unit. Checked the wind speed and turned off. Found no CAN errors. Travel from the job.	



**H&E Equipment Services, Inc.**  
**1700 South Sam Houston Parkway West**  
**Houston TX 77047-6312**  
**Tel No. (877) 321-5249**  
**Fax No. (713) 433-3981**

**Regional Credit Office**  
**Phone (866) 322-6577**  
**Fax (972) 606-1011**

# Invoice Preview

Material	Description	Quantity	Unit Price	Amount
Truck Mileage				270.00
Environmental				16.25
Shop Supplies				32.50
	Miscellaneous Total			318.75
Service Labor				630.00
Subtotal				948.75
Tax				78.27
Total Amount				1,027.02
<b>Conditions</b> This is SAMPLE INVOICE only. Do not pay.				
Customer Signature _____ Date _____				
Title _____ PO Number _____				

### SERVICE REPORT

Date: 03-23-16

Customer's Name: Flour

Customer P.O. # \_\_\_\_\_

Job Location: CP Chem

M/M/T: Grove Rt 890E

Hours: 5445

Equipment # BE 9057

Serial # 232208

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: \_\_\_\_\_

Repairs Completed: 500 HR Service Change oil Change  
oil Fuel Air Filters Grease

<u>1X AF 55309</u>		<u>Air Filter</u>		<input checked="" type="checkbox"/>
Qty	Part Number	Description	Ordered	Installed
<u>1</u>	<u>LF 3970</u>	<u>oil Filter</u>		<input checked="" type="checkbox"/>
<u>1</u>	<u>FF 63009</u>	<u>Fuel Filter</u>		<input checked="" type="checkbox"/>
<u>1</u>	<u>FS 1098</u>	<u>Water Sep</u>		<input checked="" type="checkbox"/>
<u>1</u>	<u>AF 55015</u>	<u>Air Filter</u>		

Recommendations: \_\_\_\_\_

Technician: Daniel Sweaze

Customer Name: J. Cejillo

Customer Signature: [Signature]

Job Complete:

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

3/23/16





14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 5-19-16

Customer's Name: Bigge Crane Houston TX

Customer P.O. # \_\_\_\_\_

Job Location: HOUSTON SHOP

M/M/T: \_\_\_\_\_

Hours: 5856

Equipment # BE 9057

Serial # 232208

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: \_\_\_\_\_

Repairs Completed:

PM Service on Machine  
Remove Customizer decals, Replaced top Wiper blade,  
and Adjusted Wiper Arm, Replaced FUSE EXT,  
Remove and press Wash Arm Rest, Removed tint  
From Windows, Replaced pin on Ball Safety Latch  
Removed and Replaced Transducer box Reset Computer up,  
Replaced O Rings on big Black Valve on the  
Side of the Machine, Repaired elec in the dash  
Wires Had A bad plug on it Repaired Right Power  
Steps on Machine

Qty	Part Number	Description	Ordered	Installed
1		Pressure Transducer BOX		—
1		Oil		—
1		Fuel		—
1		Fuel		—
1		Inlet Air		—
1		Outlet Air		—

Recommendations: \_\_\_\_\_

Technician: Paul

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete:

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

### SERVICE REPORT

Date: 5/20/16

Customer's Name: \_\_\_\_\_

Customer P.O. # \_\_\_\_\_

Job Location: Shop

M/M/T: \_\_\_\_\_

Hours: \_\_\_\_\_

Equipment # BE9057

Serial # \_\_\_\_\_

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: damaged STEPS

Repairs Completed: Cut off damaged STEP, cut new to fit,  
Weld BACK ON

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: DON Miller

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete:

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_



# H&E EQUIPMENT SERVICES.

H&E Equipment Services, Inc.  
1700 South Sam Houston Parkway West  
Houston TX 77047-6312  
Tel No. (877) 321-5249  
Fax No. (713) 433-3981

Regional Credit Office  
Phone (866) 322-6577  
Fax (972) 606-1011

SERVICE REPORT BE9057

Page 1 of 2

## Invoice Preview

**Bill-To-Party**  
BIGGE CRANE AND RIGGING COMPANY  
ACCOUNTS PAYABLE  
PO Box 1657  
SAN LEANDRO CA 94577

**Ship-To-Party**  
BIGGE CRANE AND RIGGING COMPANY  
PO Box 1657  
Houston TX 77047

### Information

Invoice Preview No.	70362119	
Order No.	41940876	
Customer No.	1014390	
PO No.	14-1753	PO date
Currency	USD	
Make	GV - GROVE - CRANE	
Model	RT890E-4	
Serial No.	232808	
Customer Eq No.	BE9057	
H&E Eq No.	10120109	
Customer Contact		
Contact Phone		
Meter	3949 hrs	
	0 mile	

### Complaints

#### Complaint Details

Module light is on

#### Causes

#### Cause Details

#### Corrections

#### Correction Details

05/31

Travel to the job. Checked and found the electrical diagnostic light was on. Connected the laptop and checked module, inputs and outputs. Removed and replaced the washer fluid tank. Tested, checked ok. Travel from the job.

H&E Equipment Services, Inc.  
1700 South Sam Houston Parkway West  
Houston TX 77047-6312  
Tel No. (877) 321-5249  
Fax No. (713) 433-3981

Regional Credit Office  
Phone (866) 322-6577  
Fax (972) 606-1011

# Invoice Preview

Material	Description	Quantity	Unit Price	Amount
Truck Mileage				18.00
Environmental				4.50
Shop Supplies				9.00
	Miscellaneous Total			31.50
Service Labor				180.00
Subtotal				211.50
Tax				17.45
Total Amount				228.95
<b>Conditions</b> This is SAMPLE INVOICE only. Do not pay.				
Customer Signature _____ Date _____				
Title _____ PO Number _____				





### SERVICE REPORT

Date: 7-18-16

Customer's Name: Fagioli

Customer P.O. # \_\_\_\_\_

Job Location: Corpus Christi

M/M/T: Grove 890 E

Hours: 6228

Equipment # BE9057

Serial # 232208

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: 500hr Service windmeter not working

Repairs Completed: Replace the following:

Lube Filter: LF 3970

Fuel: FS1065 / 5612

Air: AF55015 / AF55309

Cabin Air:

Aprox: 6 gal 15W-40 mobil oil

grease crane

Replaced batteries in Anemometer & recalibrated (OK)

Qty	Part Number	Description	Ordered	Installed

Recommendations: Next service @ 6728

Technician: Eric Hornsby

Customer Name: Clifford Gill

Customer Signature: Clifford Gill

Job Complete:

Yes ☒ No ☐

Labor: Reg 2

O.T. \_\_\_\_\_



14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 8-30-16

Customer's Name: Bigge

Customer P.O. # \_\_\_\_\_

Job Location: Morgan Corp TX M/M/T: Grove RT 890E

Hours: 6319

Equipment # BE 9057

Serial # \_\_\_\_\_

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: batteries dead, crane won't start

Repairs Completed: Checked battery voltage & found 2 volts on all batteries. Bought new batteries & replaced old ones. Tested crane. Starts & runs fine.

Qty	Part Number	Description	Ordered	Installed
3		Interstate 930 CCA batteries		2

Recommendations: \_\_\_\_\_

Technician: Bradley Wick

Customer Name: Bigge.

Customer Signature: \_\_\_\_\_

Job Complete:

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_





### SERVICE REPORT

Date: 9-9-16

Customer's Name: \_\_\_\_\_

Customer P.O. # \_\_\_\_\_

Job Location: HOUSTON SHOP

M/M/T: GROVE RT 890E

Hours: 6321

Equipment # BE 9057

Serial # 232208

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: \_\_\_\_\_

Repairs Completed: PUT DRY MOLLY ON OUTRIGGER JACKS & CENTER BEARING. LUBE ON BOTH WIRE ROPE. REPLACED LATCH ON BALL. CHECKED ALL FLUIDS, TOPPED OFF WIPER FLUID, GREASE UPPER, LOWER CRANE & BOOM SECTIONS. BLEW DIRT FROM RADIATOR, HYD. COOLER, A/C CONDENSOR, & FILTERS. SERVICED BATTERIES. PUT MAIN WIRE ROPE UNDER BAR ON TOP OF BOOM. REMOVED TRASH FROM OUTRIGGER BEAMS. CHECK HOSE REEL BRAKE FOR LEAKS TIGHTEN FLANGE. 3RD PARTY INSPECTION DONE 9-7-16. CRANE WAS WASHED & DETAILED.

LAST PM = 7-17-16

6228 HOURS

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: CHARLES MADDEN

Customer Name: \_\_\_\_\_

Job Complete:

Labor: Reg \_\_\_\_\_

Yes ☒ No ☐

O.T. \_\_\_\_\_

Customer Signature: \_\_\_\_\_





14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 9/20/16  
 Customer's Name: Biggie Crane Customer P.O. # \_\_\_\_\_  
 Job Location: yard M/M/T: \_\_\_\_\_ Hours: \_\_\_\_\_  
 Equipment # BE 9057 Serial # \_\_\_\_\_ Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: \_\_\_\_\_

Repairs Completed: Pull Hose Reel Pump Reseal  
Pump and put ~~new~~ pump  
Back on and tested for leaks

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Michael Parker  
 Customer Name: \_\_\_\_\_  
 Customer Signature: \_\_\_\_\_

Job Complete:  
 Yes ☒ No ☐

Labor: Reg \_\_\_\_\_  
 O.T. \_\_\_\_\_



**SERVICE REPORT**

Date: 4-11-17

Customer's Name: Bigge

Customer P.O. # \_\_\_\_\_

Job Location: Houston Shop M/M/T: Grove RT890 E

Hours: 6570

Equipment # BE 9057

Serial # 232208

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: Hose Reel Fitting Leaking

Repairs Completed: Replaced 360 swivel fitting  
(Leaking due to wear and tear)

Qty	Part Number	Description	Ordered	Installed
1	80019669	360 Swivel Joint		

Recommendations: Properly Grease fittings

Technician: Tony G.

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete:

Yes ☒ No ☐

Labor: Reg 3.5 hrs

O.T. \_\_\_\_\_





**SERVICE REPORT**

Date: 7-29-17

Customer's Name: Lauren En.

Customer P.O. # \_\_\_\_\_

Job Location: Victoria Tx M/M/T: R+890E

Hours: 6914

Equipment # BE9057

Serial # \_\_\_\_\_

Trip Mileage 138 (1 way)

Describe Defects & Cause of Failure: Outrigger Jack leaking

Repairs Completed: installed new Jack

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Kory Hernandez

Customer Name: \_\_\_\_\_

Customer Signature: Joe Legala

Job Complete:

Yes ☐ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_



10-14-028382

# BIGGE

Established 1916

## CRANE and RIGGING CO.



14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

Date: 4-3-18

Customer's Name: Bigge Crane

Customer P.O. # \_\_\_\_\_

Job Location: HOUSTON yard

M/M/T: Crane RT 890-IE

Hours: 7563

Equipment # BE 9057

Serial # 232208

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: OFF Rent Repairs

Repairs Completed: Get 3rd Party done, Repaired damaged steps  
Welders Replaced All outrigger pad collars and Arms  
PM Eng Oil Air Fuel, Replaced Main Winch Mixer,  
Replaced Aux ball spring latch and Pin, Replaced Keeper  
on Main Latch Pin, Replaced Sheave on Main boom Top,  
Repaired parking brake, Replaced Fine EXT, Paint bull  
and Main block, Adjusted Park brake, Grease Cable and,  
brake Cables Greased boom, Check Eng Rear Seal Ok,  
Checked and Recharge AC System, Replaced High  
Filter and Crank Case Filter, Remould and Replaced  
Left two Sides,

Qty	Part Number	Description	Ordered	Installed

Recommendations: \_\_\_\_\_

Technician: Carl Dargatzis

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete: \_\_\_\_\_

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

Copies: White: Office

Pink: Customer

Yellow: Technician Copy



### SERVICE REPORT

Date: 7 MAY 19

Customer's Name: BIGGE CRANE AND RIGGING CO

Customer P.O. # \_\_\_\_\_

Job Location: GONZALES, LA

M/M/T: GROVE RT890E

Hours: 8394

Equipment # BE9057

Serial # 232208

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: AUX BALL MISSING ID PLATE / LEAKING TRANSMISSION FILTER / WASHER NOZZLE INSTALLED INCORRECTLY / AC INOP / ~~WASHER NOZZLE~~ OFF RENT SERVICES AND REPAIRS / AUX CABLE FRAYING

Repairs Completed: CUT AND BRAZED AUX CABLE / PAINTED BLOCK AND BALL / INSTALLED MAIN LATCH KEEPER PIN / SECURED REAVE BARS TO BLOCK / STAMPED AUX BALL WITH CRANE SERIAL NUMBER AND WEIGHT / SECURED SIDE PANEL CLEANED AND SERVICED BATTERIES / REPLACED TRANSMISSION FILTER / MOLLIED JACK CYLINDERS AND BEAMS / SECURED WIPER SPRAYER PROPERLY TO ARM / REPAIRED AC / REPLACED FIRE EXTINGUISHER / CHECKED AND TOPPED OFF FLUIDS / GREASED CARRIER, SUPER, BOOM SECTIONS AND TOPPED OFF LUBED CABLES

Qty	Part Number	Description	Ordered	Installed
1	57129 NAPA	HYDRAULIC ELEMENT (XMSN) (HF28996)	✓	✓
1	7690225600	CLEVIS PIN	✓	✓

Recommendations: NO GPS INSTALLED / CLEANED AND MONITORED REAR MAIN SEAL LEAK, NO DRIPS / NO JIB / CRANE

Technician: J. RIOS / T. WILLIAMS / T. SONNIER

Customer Name: \_\_\_\_\_

Customer Signature: \_\_\_\_\_

Job Complete: \_\_\_\_\_

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_





### SERVICE REPORT

Date: 7 MAY 19

Customer's Name: BIGGE CRANE AND RIGGING CO

Customer P.O. # \_\_\_\_\_

Job Location: GONZALES, LA M/M/T: GROVE RT890E

Hours: 8394

Equipment # BE9057

Serial # 232208

Trip Mileage \_\_\_\_\_

Describe Defects & Cause of Failure: CUSTOMER DAMAGES / MISSING REAR CAB COVER / BENT RF BEAM LOCK / MISSING SPRING ON JACK FLOAT / MISSING SPOT MIRROR ARM / DAMAGED CABLE TENSIONER / BENT KEY / CABLE KINKED

Repairs Completed: INSTALLED REAR CAB COVER / REPAIRED BENT BEAM LOCK FOR OPERATION / INSTALLED SPRING ON JACK FLOAT / INSTALLED MIRROR TO MISPLACED ARM ASSEMBLY / REPLACED DAMAGED CABLE TENSIONER / STRAIGHTEN BENT OVERRIDE KEY / CUT AND BRAZE MAIN CABLE 10 FT TO REMOVE KINK

Qty	Part Number	Description	Ordered	Installed
1	80012661	COVER	✓	✓
1	9834100006	SPRING KIT	✓	✓
1	9974103040	ROLLER	✓	✓
1	CL070	SPOT MIRROR	✓	✓

Recommendations: 70 GALLONS OF FUEL ADDED / STILL HAS BENT ROOSTER SHEAVE PIN /

Technician: J. RIOS / T. WILLIAMS

Customer Name: \_\_\_\_\_

Job Complete: \_\_\_\_\_

Labor: Reg \_\_\_\_\_

Yes ☒ No ☐

O.T. \_\_\_\_\_

Customer Signature: \_\_\_\_\_