



Auburn, WA
206-443-8500
San Leandro, CA
510-638-8100

Richmond, VA
804-271-9356
North SLC, UT
801-292-2453

Houston, TX
713-434-0995

Toll Free
888-337-2444

SERVICE REPORT

DATE:

CUSTOMER <i>Odebrecht</i>				TRIP MILEAGE	
CONTACT NAME & NO.					
ADDRESS					
MAKE	MODEL	SERIAL NUMBER	HOURS		UNIT NUMBER
<i>Grove</i>	<i>RT700E</i>	<i>227258</i>	<i>8</i>		<i>RE6028</i>

SERVICE REQUESTED

REPAIRS MADE

<i>Repair O/R pads and T/S engine light and replace engine coolant sensor</i>

COMMENTS

PART NUMBER	QNTY	DESCRIPTION	INSTALLED		ORDERED
	<i>1</i>	<i>Coolant level sensor</i>	<i>✓</i>		

Jack Amick
TECHNICIAN

CUSTOMER SIGNATURE



Auburn, WA
206-443-8500
San Leandro, CA
510-638-8100

Richmond, VA
804-271-9356
North SLC, UT
801-292-2453

Houston, TX
713-434-0995

Toll Free
888-337-2444

SERVICE REPORT

DATE: 8-20-12

CUSTOMER <i>Odebrechts</i>		TRIP MILEAGE <i>8</i>		
CONTACT NAME & NO.				
ADDRESS				
MAKE	MODEL	SERIAL NUMBER	HOURS	UNIT NUMBER
<i>Grove</i>	<i>RT760E</i>	<i>227258</i>	<i>4107</i>	<i>BE6028</i>

SERVICE REQUESTED

Hyd leak

REPAIRS MADE

Drive to job site, remove hose. Have hose made and replaced

12:30 PM to 1:30 PM

COMMENTS

need to fill w/ hyd oil

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED
	<i>1</i>	<i>Hose</i>		

TECHNICIAN

CUSTOMER SIGNATURE

JOE Bellow
Odebrechts



Auburn, WA
206-443-8500
San Leandro, CA
510-638-8100

Richmond, VA
804-271-9356
North SLC, UT
801-292-2453

Houston, TX
713-434-0995

Toll Free
888-337-2444

SERVICE REPORT

DATE: 8-23-12

CUSTOMER <i>Odebrecht</i>			TRIP MILEAGE		
CONTACT NAME & NO.					
ADDRESS					
MAKE <i>Grove</i>	MODEL <i>RT760E</i>	SERIAL NUMBER <i>227258</i>	HOURS		UNIT NUMBER <i>BE6028</i>

SERVICE REQUESTED
<i>Change Aux cable</i>
<i>Aux cable bad</i>

REPAIRS MADE
<i>2:00 PM to 5:00 PM 3hrs. X 2 mechanics</i>
<i>Remove and replace cable on Aux drum</i>

COMMENTS

PART NUMBER	QNTY	DESCRIPTION	INSTALLED		ORDERED

TECHNICIAN

CUSTOMER SIGNATURE



Auburn, WA
206-443-8500
San Leandro, CA
510-638-8100

Richmond, VA
804-271-9356
North SLC, UT
801-292-2453

Houston, TX
713-434-0995

Toll Free
888-337-2444

SERVICE REPORT

DATE: 10-12-12

CUSTOMER <i>Odebrechts</i>		TRIP MILEAGE <i>6</i>	
CONTACT NAME & NO.			
ADDRESS			
MAKE <i>Grove</i>	MODEL <i>AT760</i>	SERIAL NUMBER	HOURS <i>4262</i>
		UNIT NUMBER <i>BE6028</i>	

SERVICE REQUESTED <i>engine service service</i>

REPAIRS MADE <i>change engine oil, oil filter, fuel filter + trans filter</i>
<i>2 hr</i>

COMMENTS <i>need to repair all O/R Pad, also need to grease boom and under carriage.</i>

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED

TECHNICIAN *[Signature]*

CUSTOMER SIGNATURE



Auburn, WA
206-443-8500
San Leandro, CA
510-638-8100

Richmond, VA
804-271-9356
North SLC, UT
801-292-2453

Houston, TX
713-434-0995

Toll Free
888-337-2444

SERVICE REPORT

DATE: 10-12-12

CUSTOMER <i>Odebrechts</i>		TRIP MILEAGE <i>6</i>	
CONTACT NAME & NO.			
ADDRESS			
MAKE <i>Grove</i>	MODEL <i>AT760</i>	SERIAL NUMBER <i>227258</i>	HOURS <i>4262</i>
			UNIT NUMBER <i>DE6028</i>

SERVICE REQUESTED

engine service

REPAIRS MADE

change engine oil, oil filter, fuel filter & trans filter

2 hr

COMMENTS

*need to repair all O/R Pad, also need to
grease boom and under carriage.*

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED

TECHNICIAN

CUSTOMER SIGNATURE

SERVICE REPORT

Date: 11-16/11-17

Customer's Name: _____

Customer P. O. # _____

Job Location: _____

M/M/T: _____

Hours: 5225

Equipment # BE 6028

Serial # _____

Describe Defects & Cause of Failure: Crane needs to be serviced & greased

Repairs Completed: 11/14 Greased all sheaves, block, ball, Rotect, under carriage and greased Boom

11/17 / changed oil, oil filter, fuel filters & Air

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: Rafael Lopez

Customer Name: _____

Customer Signature: _____

Job Complete: _____ Labor: Reg _____

Yes ☐ No ☐ O.T. _____

SERVICE REPORT

Date: 07-04-14

Customer's Name: Bigge

Customer P. O. # _____

Job Location: Yard

M/M/T: _____

Hours: 5591.0

Equipment # BE6028

Serial # 227258

Describe Defects & Cause of Failure: _____

Repairs Completed: Diagnosed the a Road Call and Goert To End the work
Instal on Change 2 Fuel Filter and Foll up the Engine with 5W40
Motor Oil Heavy Duty Diesel Eng. Check All is worky Ok and Instal
One Right Side Cover is Ok

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: Chris M. [Signature]

Customer Name: _____

Customer Signature: _____

Job Complete: _____

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 10-14-14
Customer's Name: LPR Construction Customer P. O. # _____
Job Location: Bay City, Tx M/M/T: Grove RT 760E Hours: 6000
Equipment # BE6028 Serial # 827258

Describe Defects & Cause of Failure: Service

Repairs Completed: Arrived to location of crane, serviced engine, drained engine oil, removed fuel, air, oil filters and replaced with new filters.
Had to replace right front outrigger latches due to being broken.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: DANIEL CANTU
Customer Name: Joshua Cable LPR Const.
Customer Signature: _____

Job Complete: Labor: Reg _____
Yes ☒ No ☐ O.T. _____

SERVICE REPORT

Date: 2/12/15
 Customer's Name: Bigge Crane Customer P.O. # _____
 Job Location: Bigge - Hou Tx. M/M/T: GAUGE RT 760E Hours: 6000
 Equipment # BE 6028 Serial # 227258 Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: Tech. Installed NEW hr meter 6000 hr already-lubed MAIN + AUX wire Rope - Greased upper + lower crane - Installed front mirror on right front fender - Updated fire ext. - Replace wiper switch on steering column - Installed new fuel tank cap - 3rd party inspection - Installed sun visor in cab. - last svc. at 6000 hrs none needed at time - Installed new hr. meter start hrs. at 6000*

Qty	Part Number	Description	Ordered	Installed

Recommendations: start hrs. at 6000 install new hr. meter

Technician: Manous Price
 Customer Name: _____ Job Complete: _____ Labor: Reg _____
 Customer Signature: _____ Yes ☒ No ☐ O.T. _____

BIGGE

Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 3/25/15

Customer's Name: Bigge CRANE

Customer P.O. # _____

Job Location: Bigge - Hou. Tx.

M/M/T: Grove RT 760 E

Hours: 6156

Equipment # BE6028

Serial # 227258

Trip Mileage _____

Describe Defects & Cause of Failure: engine hr. meter has water inside sight glass - parking brake need adjusting

Repairs Completed: No service need last sec. at 6000 hrs.
- Install new engine hr. meter Add 6156 to hrs. on meter
- lube upper swing bearing
- readjusted parking brake

Qty	Part Number	Description	Ordered	Installed
1	7486002973	engine hr. meter	1	1

Recommendations: _____

Technician: Marcus Rice

Customer Name: _____

Customer Signature: _____

Job Complete: _____

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

SERVICE REPORT

Date: 7-18-15
 Customer's Name: Lane Construction Customer P.O. #
 Job Location: San Antonio M/M/T: Gore RT 760E Hours: 308
 Equipment # BE 6028 Serial # 22725 Trip Mileage

Describe Defects & Cause of Failure: need to pull left side outrigger
jacks

Repairs Completed: pulled and replaced left side outrigger
jacks

Qty	Part Number	Description	Ordered	Installed

Recommendations:

Technician: Adam Moore / [Signature]
 Customer Name: Job C
 Customer Signature: Yes ☒

Copies: White: Office Pink: Customer

NON-BILLABLE
REPAIRS

SERVICE REPORT

Date: 7-22-15

Customer's Name: LANE Construction

Customer P.O. # _____

Job Location: 355+410 N

M/M/T: Grove

Hours: 331

Equipment # BE6028

Serial # 227258

Trip Mileage 362

Describe Defects & Cause of Failure: _____

Repairs Completed:

Removed Length Reel and Replaced
Adjusted Boom Length and Checked Andge
And wight All OK
Tighten AC Belts

to SAN ANTONIO - 2:30 - 5:00
on Job 5:00 - 7:45

to Houston 7:45 - 10:15

Qty	Part Number	Description	Ordered	Installed
1		Cable Reel		<input checked="" type="checkbox"/>

Recommendations: _____

Technician:

Customer Name:

Customer Signature:

Bergman

Job Complete:

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 8-7-15

Customer's Name: LANE Construction

Customer P.O. # _____

Job Location: San Antonio, Tx M/M/T: Grove RT 760E

Hours: 351

Equipment # BE 6028

Serial # _____

Trip Mileage 200 (one way)

Describe Defects & Cause of Failure: Replace solenoid

Repairs Completed: Arrive to location of crane, find hydraulic boost solenoid burned. Remove solenoid and replace with new.

Qty	Part Number	Description	Ordered	Installed
<u>1</u>		<u>12V Solenoid</u>		<u>✓</u>

Recommendations: _____

Technician: DANIEL CANTU

Customer Name: _____

Customer Signature: G.M.R.

Job Complete: _____

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

BIGGE

Established 1916
CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 8-12-15
Customer's Name: Lane Construction Customer P.O. # _____
Job Location: San Antonio M/M/T: Grove RT 760E Hours: 383
Equipment # BE6028 Serial # 227255 Trip Mileage _____

Describe Defects & Cause of Failure: A.C. not blowing cold,
air compressor needs to be replaced

Repairs Completed: _____

Qty	Part Number	Description	Ordered	Installed

Recommendations: Replace air compressor

Technician: Adam Moore
Customer Name: Felix M. Ramirez
Customer Signature: [Signature]

Job Complete:
Yes ☐ No ☐

Labor: Reg 2
O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy



Established 1916
CRANE and RIGGING CO.

14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 10-15-15

Customer's Name: LANE Construction

Customer P.O. # _____

Job Location: San Antonio, Tx

M/M/T: Grove RT 760E

Hours: 580

Equipment # BE 602B

Serial # 227258

Trip Mileage 200 (one way)

Describe Defects & Cause of Failure: Damage Aux cable, A2B

Repairs Completed: Arrive to location of crane found cable on aux fraying apart. Cut 10ft off from ball. A2B weight was missing. Customer stated that they will order new weight and install it themselves.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: Daniel Carr

Customer Name: _____

Customer Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

SERVICE REPORT

Date: 5-14-16

Customer's Name: _____

Customer P.O. # _____

Job Location: _____

M/M/T: _____

Hours: 776

Equipment # BE6028

Serial # 227258

Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: PM SERVICE, LUBE CABLE, GREASE BOOM
UPPER AND LOWER CRANE. LUBE CENTER ROTEX BEARING.
LUBE OUTRIGGER JACKS. PUT UPDATED FIRE EXTINGUISHER. CRANE
WAS WASHED & DETAILED. CLEANED SIB HOLES AND PINS. PUT
SAFETY DECALS ON OUTRIGGER JACKS. FIXED DOOR LATCH
ON CAB. PUT VACUUM ON A/C IT WAS GOOD SO CHARGED SYSTEM.
PUT KNOB ON FAN CONTROL SWITCH. GOT 3RD PARTY INSPECTION
EXPIRES 5-13-17. PAINT BALL, BLOCK, A2 BLOCKS, A/C COVER
& MINOR RUST SPOTS ON FRONT & BACK BUMPERS. BATTERIES
CLEANED AND TESTED GOOD. CHECKED ALL FUNCTIONS.

Qty	Part Number	Description	Ordered	Installed
1	BF7922	FUEL FILTER	✓	✓
1	BF1385-SP5	FUEL SEP FILTER	✓	✓
1	RS 3506	HYD FILTER	✓	✓
1	B 7177	OIL FILTER	✓	✓
1	BTB426-M78	AIR FILTER	✓	✓

Recommendations: _____

Technician: CHARLES MADDEN

Customer Name: _____

Customer Signature: _____

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

SERVICE REPORT

Date: 7-9-2016
 Customer's Name: _____ Customer P.O. # _____
 Job Location: Tulsa, OK M/M/T: Grove RT 760E Hours: 809
 Equipment # BE 6028 Serial # 227258 Trip Mileage _____
 Describe Defects & Cause of Failure: A2B cutting in and out

Repairs Completed: Found A2B cutting in and out.
Found Aux A2B wire pinched. Replaced A2B switch.
Found cable reel wires loose in junction box. Reattached
wires. Test machine. Found Boom length off. Calibrated
boom length sensor.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: [Signature] Job Complete: _____ Labor: Reg _____
 Customer Name: _____ Yes ☐ No ☐ O.T. _____
 Customer Signature: _____



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 10-21-16
Customer's Name: Peppers Welding Customer P.O. # _____
Job Location: Corrigan TX M/M/T: Grove RT 7605 Hours: 861
Equipment # BE 6028 Serial # _____ Trip Mileage _____

Describe Defects & Cause of Failure: A/C belts Slipping, Top wiper not working.

Repairs Completed: Found the A/C belts loose. Tried to adjust but was at Adjustment. Replaced both A/C belts and adjusted. Top wiper was not working. Found power wire grounded out on side of cab. Repaired wiring and replaced 10amp fuse. Wiper is working. Found hyd hose rubbing on cab frame wrapped hyd hoses with protect rubber.

Qty	Part Number	Description	Ordered	Installed
2	XL 25,7450	Napa V-belt	2	2

Recommendations: _____

Technician: Bryan Venable
Customer Name: Peppers Welding Job Complete: _____ Labor: Reg _____
Customer Signature: Kevin Rushing Yes ☒ No ☐ O.T. _____



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT

Date: 4-4-17

Customer's Name: _____

Customer P.O. # _____

Job Location: Houston Tx

M/M/T: Grove/RT760E

Hours: 1218

Equipment # BE6028

Serial # 227258

Trip Mileage _____

Describe Defects & Cause of Failure: Needs 500 Hr PM

Repairs Completed: Performed 500 HR PM - changed engine oil and filter, fuel filters and air filters

5gals 10W-40

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: Wayne & Mike

Customer Name: _____

Job Complete: _____

Labor: Reg _____

Customer Signature: _____

Yes ☐ No ☐

O.T. _____



SERVICE REPORT

Date: 7-15-17

Customer's Name: _____

Customer P.O. # _____

Job Location: HOUSTON SHOP M/M/T: GROVE RT 760E Hours: 1278

Equipment # BE6028 Serial # 227258 Trip Mileage _____

Describe Defects & Cause of Failure: _____

Repairs Completed: PM'ed engine, replaced Aux sheave, topped off A/C Freon & replaced fuse, brazed both cables, installed proper pin into front of jib storage, installed new latch pins on main & Aux, blew out all coolers, load tested & serviced battery's, updated fire ext., checked all fluid levels, molly'd crane, PAINT BALL & BLOCK. GREASE BOOM SECTIONS, UPPER & LOWER CRANE. LUBE CABLES. TOP OFF OIL IN WINCH. CHECKED FOR LEAKS. REPLACED WINCH MIRROR. FIXED CAB MIRROR. 3RD PARTY INSPECTED. FIXED MAIN THUMPER. CHANGED HYD. FILTERS. PUT FUEL. CRANE WAS WASHED & DETAILED.

Qty	Part Number	Description	Ordered	Installed
1	7689000059	PIN-LOCK, HITCH PIN	✓	✓
1	9515102926	A/C VENT	✓	✓
1	6718000580	SHEAVE ASSEMBLY	✓	✓
1	LF3970	OIL FILTER	✓	✓

Recommendations: FF5612 - FUEL FILTER; HF28996 - HYD. FILTER; FS19732 - FUEL SEP. FILTER; AF2513000M - INNER AIR FILTER; AF25129M - OUTER AIR FILTER

Technician: C. MADDEN, J. RIOS

Customer Name: _____

Customer Signature: _____

Job Complete: _____

Yes ☒ No ☐

Labor: Reg _____

O.T. _____

CUSTOMER SIGNATURE



14800 Jersey Shore Dr.
Houston, TX 77047
(713) 434-0995

SERVICE REPORT 10-14-028925

Date: 10-31-18

Customer's Name: Bigge

Customer P.O. #

Job Location: Bigge

M/M/T: Grave RT760E

Hours: 1857

Equipment # BE6028

Serial # 227258

Trip Mileage

Describe Defects & Cause of Failure: Off rent crane repairs

Repairs Completed: Installed new a/c compressor, vacuumed a/c system and recharged with freon. Installed new a/c dryer. Replaced top wiper motor with new. Installed new wiper blades for front and top glass. Replaced front right fender and left side cab mirrors. Installed new roll pin and keeper for aux latch. Installed new info tag on aux ball. Pry moly on center bearing and outrigger jacks. Placed safety tape of outrigger jacks. Replaced cracked wiper container with new. Lubed both aux and main wire rope. Placed new keeper on main block. Removed fire ext. bracket from behind cab. Serviced batteries and tested alternator. Checked all ATB connections. Added 10 gallons of hydraulic oil. *CUSTOMER DAMAGES* Dirty cab clean up FEE. Installed new cab fan. Repaired 3 broken outrigger float levers. Welded new collars on 3 outrigger float pins.

Qty	Part Number	Description	Ordered	Installed
1	7632000943	Wiper motor top glass		
1	10426	Aux latch		
1	7184001014	Mirror arm		
1	7425000659	Cab fan 12V		
1	7083000600	Wiper blade		

Recommendations: (1) 7576000320 - pump and conistar (2) Round mirrors, (1) 26" wiper blade, (4) float levers, (4) Roll pins, (4) Outrigger float collars, (4) Outrigger float springs, (1) A/C compressor 20-10246 (1) A/C dryer. (1) Information tag on Aux ball.

Technician: Juan E.

Customer Name:

Job Complete:

Labor: Reg

Customer Signature:

Yes ☐ No ☐

O.T.



SERVICE REPORT

Date: 5.7.19

Customer's Name: _____

Customer P.O. # _____

Job Location: Houston Shop

M/M/T: Crane RT-760E

Hours: 8,606

Equipment # BE6028

Serial # 227258

Trip Mileage _____

Describe Defects & Cause of Failure: * Customer damage * Sib lacing was replaced. Removed glue and tape of cab windows. Added 62 gallons of fuel.*

Repairs Completed: 3rd Party is up to date. Installed new grease fitting on rooster sheave. Cleaned Sib pins and Sib holes. Pressed upper and lower. Checked Azb and They work. Replaced damaged decals. Service batteries and tested good. dry molly Sacks and Center bearing. Arc is blowing cold. Blew out Coolers and filters. Added 1qt of oil to Engine. Crane got a full detail. Replaced leaking hoses. grease boom. lube main and Aux cable. Replaced fuel pump. Replaced Sight glass on Main and Aux winch. Replaced main mirror Arm bracket. Checked all fluid levels.

Qty	Part Number	Description	Ordered	Installed
1	6184100065	Mirror bracket	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	9974102701	Sight glass	<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
1	098643731	Fuel pump		

Recommendations: _____

Technician: [Signature]

Customer Name: _____

Customer Signature: _____

Job Complete: ☒

Yes ☒ No ☐

Labor: Reg _____

O.T. _____



SERVICE REPORT

Date: 6-10-19

Customer's Name: Jacobs

Customer P.O. # _____

Job Location: Willing Tx

M/M/T: Grove Rt 760 E

Hours: _____

Equipment # Be 6028

Serial # _____

Trip Mileage 354 (1 way)

Describe Defects & Cause of Failure: No throttle

Repairs Completed: found bad ground / throttle works.

Qty	Part Number	Description	Ordered	Installed

Recommendations: _____

Technician: Kerry A

Customer Name: _____

Job Complete:

Yes ☐ No ☐

Labor: Reg _____

O.T. _____

Customer Signature: [Signature]