

		SE	ERVICE R	EPORT			
Customer Job Loca Equipmer Describe	r's Name: Ametion: Elberado tion: Elberado Defects & Cause of Completed: Ro	olo3 significant cy le	laulen M/M/T: Grou erial # 236 Vaulic	je RT91. 1961 Icak	at g	ick co	87 onnect
—————	completed	iaca c	24 113	of you	n covice		
					1011101100000 W		
Qty	Part Number		Descr	iption		Ordered	Installed
Recomm	endations:						
·							
-	00	111 0	7				
Technicia		Moore	/	Job Complé	te: Labo	or: Reg	1
Customer Name:	0.12008	on	-	Yes I No	ic.	O.T	
Customer Signature							

Copies: White: Office

Pink: Customer



CRANE and RIGGING CO.

	SERVICE REPORT	
Date: 6-9-15 Customer's Name: (CWS)	en Customer P.O. #	
	do KS M/M/T: Grove Pt 91505 Hou	
	Serial # 23296/ Trip Mileage	
Equipment #	Zenar # Imp Mileage	-
Describe Defects & Cause of F	ailure: 500hr Service & GPS Ins	stall
Whe Filter: C		
Water Separator: to Coolent filter: W		
Install GPS		
Qty Part Number	D	
Qty Fait Number	Description Ord	dered Installed
Recommendations:	Sorvice @ 990hrs	
8.11	do	
Technician: Customer Way 1. 1. 6	Job Complete: Labor: Re	g 4
Name: Customer Signature:	Yes No O.T	

Copies: White: Office

Pink: Customer



Copies:

White: Office

14800 Jersey Shore Dr. Houston, TX 77047 (713) 434-0995

SERVICE REPORT		
Date: 4-18-15		
1 - 2 2 2 4	O.#	
Job Location: El Dorado, KS M/M/T: Grove 9150E Equipment # BE150103 Serial # 232961	Hours: 3	03
Describe Defects & Cause of Failure: Blown Fuse for outrigger on two broke outrigger latches:	ns Systen	
Repairs Completed: Replace Fuse, Replace broke outrigo	ger latch	rs
	4	2
Qty Part Number Description 1 Sampfuse 2 outrigger latcher	Ordered	Installed
Recommendations:		
Technician: Enologymish		
	abor: Reg O.T	*

Pink: Customer



Established 1916

CRANE and RIGGING CO.

14800 Jersey Shore Dr. Houston, TX 77047 (713) 434-0995

	SERVICE REPORT	
Date: 9-18-15		
Customer's Name: LAUREIU	Customer P.O. #	
Job Location: ELDORADO KS		
Equipment # BE150103	Serial # 2 32% Trip Mileage _	
Describe Defects & Cause of Failure:		
Repairs Completed: Poplaced Luge filter: LF 9! Fuel: FF5636 W/S: FS1065 Har: AF55015/AF55 Coolont: WFZ074		
Boom needs greasi	ag but Crare is in hole Contact plant under lightning tos	of get out
Qty Part Number	Description Ord	dered Installed
Recommendations: Next Service	ee @ 1,592	
^		
Technician: Eric Hornsh	1	
Customer Jason Batson	Job Complete: Labor: Re	g_2
Customer Signature: Just 18	Yes No O.T	·

Copies: White: Office

Pink: Customer



S	ERVICE REPORT	
Date: 1-21-16		
Customer's Name: Bigge Chane	Customer	r P.O. #
Job Location: Hou. Tx.	M/M/T: GROVE/RT9150	Hours: 1785
Equipment # BE150103		
-		
Describe Defects & Cause of Failure:	sue	
<u> </u>	-	
Panaira Completed Tea. H. Out	Cornit + neva outrice	on boxes on
Repairs Completed: Tech. put of No problems found with fut countenweights on	Assembly,	
Aut countenweights on	, NO phoblem found	
Daylor and dillocate		
blow dint shorn engine lubed uppen fonce cus Installed pam minno	e RANIATOR- Hofo. 0:1000	Peu - Me Condinsor
Taraland Damy minne	n or his wind H	TENG
. Add a day Vala - and		
Removed - Replace co	ollar on damaged or plan for pad ide minnon Assy (wince fank cle	utrigger pro
2 - 6308000 /17 - 00	MAR for pad	2 2
1-16/703/ - 1ett 5	de minnon Assy (winc	(4) (1)
1- AF 55015 - A:1	ele.	1 1
1- AF 55015 - AIR 0	"	1/
2- P165705 - Hyd.	f.11 ex	22
Qty Part Number	Description	Ordered Installed
1 FS 1065 flw sep	24	
	enther	1 1
1 FF 5636 fuel fi	Iter	1 /
1 WF 2074 WATE	1.1ten	1 /
Recommendations:		
. 1		
Technician: MANCUS Phile		
Customer	Job Complete:	Labor: Reg
Name:	Yes No 🔾	O.T
Customer Signature:	105 = 110 =	

Copies: White: Office

Pink: Customer





SERVICE REPORT		
Date: 7-20-16		
Customer's Name: Customer P.O. #		
ob Location: Hous TON SHOP M/M/T: GROVE RT 9150 E H	ours: <u>24</u>	13
Equipment # BE 150103 Serial # 232961 Trip Mileage		
Authority 2000 100 100 100 100 100 100 100 100 10		
Describe Defects & Cause of Failure:		
Repairs Completed: BLEW OUT RADIATOR, HYD. COOLER, A/C	COND	ENSOR.
COMPLET HOUSE LANGE E BOOM SECTIONS, ES	00 10	120
acta Deby Acta Ally PADIE T DECKET. MAL	16 -71	-
ALL FUNCTIONS WORKED, CHECKED FOR LEAKS, MADE	RIE	
ALL FLUIDE LEVELS WHERE GOOD. PUT FUEL. CA. INSPECTIONS ON BOTH MAIN & AUX. CABLES.	PRAN	F
WAS' WASHED & DETAILED, CRANE DECALS "BIGGE	" PUT	ON
		11.5
CRANE.		
		W 1
		7.74
Qty Part Number Description	Ordered	Installed
1 (Amm) 3/4" WIRE ROPE	/	
1 782600641 BELKET 1 80026851 BAR	1	1
1 80026851 BAR		
Recommendations:		
MARINE DRIVE PHARIES MANNEN		
	or: Reg	18
Customer Name: Yes 2 No 2	O.T	
Customer		

Copies: White: Office

Pink: Customer

BIGGE Established 1916 CRANE and RIGGING CO.



14800 Jersey Shore Dr. Houston, TX 77047 (713) 434-0995

	SERVICE REPORT		
Date: 8/10/16			
Customer's Name: JV	ind, /Lyandell Customer	P.O. #	
Job Location: Lyondell	1, Corpus christimmit: Grove RT9150	Hours: 24	119
	03 Serial # 23296) Trip	Mileage 12	The second second
Describe Defects & Cause	of Failure:		
a lift pla the count Storted to be writter to getter Customer is Cutting	Travel to job. Unloaded from to Subsite, had to wait on Certified in to be written for own a weights, seembled crene. Swing the Jib a proper for that as well, put and found bad spot in he off 30' of sope so crane come on rent.	00	
Qty Part Number	Description	Ordered	Installed
Recommendations:			
Technician: Customer LEE Customer Customer Customer Customer	UBr~so~ JV Job Complete: Yes No 🗆	Labor: RegO.T	





Customer's Name: Job Location: Job Location: M/M/T: Equipment # 150103 Serial # 23296 Describe Defects & Cause of Failure:	O. # Hours: 2	547
		· ·
Repairs Completed: Dingnose of Found All not cooling. Gressine of Found have gressine uny high. Funther Inspection found Condenser from not appendix Miplace Condenser Paga. Tist Vinity Appin. All Cooling of 390 F.	g proper	<i>y</i>
Description	Ordered	Installed
Qty Part Number Description 1 910 188 43 FAM & Motor ASSY 24V.		
1 1000000000000000000000000000000000000		
Recommendations: Technician: Customer Name: Yes No	Labor: Reg	





SERVICE REPORT		
Date: 8/25/16		
Customer's Name: $50IC/MAKIM$ Customer P.O.	#	
Job Location: LBC Coxpus M/M/T: 1879150	Hours:	655
Equipment # 150 63 Serial # 23296/ Trip Milea	ge	
Describe Defects & Cause of Failure: 5/19/19 under 10192.		
Change oil, oil filten, Air Filten X2, Fuel filten Spaintan	S .	
a de la como de la com	1 P	/2
Spainfor	<i>4</i> //	
		,
		•
1 AF 55015 Aire Filtsu		
1 AF55308 AIN FILTER		
Qty Part Number Photoscription Description	Ordered	Installed
1 LF954B Gil Filter		
7 15-40g GA/ 01/ 15W-40		
Recommendations:		
Technician:	D	
Customer Name: Job Complete: Labor Yes \(\bar{\pi} \) No \(\bar{\pi} \)		
Customer Signature:		

Copies: White: Office

Pink: Customer



Richmond, VA 804-271-9356 North SLC, UT 801-292-2453

Houston, TX 713-456-3086 TOLL FREE 888-337-2444

CUSTOMER CONTACT NAME & NO. ADDRESS		ERIC SPARKS 9/20		IP MILEAGE		
ADDRESS		ERIC SPARKS 9/20	· second			
			/16			
			,,,,			
MAKE	MODEL	SERIAL NUMBER	000001	HOURS	UNIT NUMBER	
GROVE	RT9150		232961	2940		15010
SERVICE REQUEST	ED					
SERVICE REQUEST	EU					
REPAIRS MADE	SSEMBLED CRANE AND	LOADED OUT				THE POPULATION
raveled to jobsite. DISAS	SSEMBLED CRANE AND	LOADED OUT				
						
						1
					· · · · · · · · · · · · · · · · · · ·	
COMMENTS		HEADOWN TO SEASON TO SEASO				
		Million and the second		And the second second	100000000000000000000000000000000000000	
PART NUMBER	QNTY DESCRIPTION	N		INSTALLED	ORDERED	
					2	



Richmond, VA 804-271-9356 North SLC, UT 801-292-2453

Houston, TX 713-456-3086 **TOLL FREE** 888-337-2444

CUSTOMER	EPORT		DATE:	被 表现是一个
			TRIP MILEAGE	
CONTACT NAME & N	NO.	ERIC SPARKS 9/20	1/16	
ADDRESS		LINIO OF AINIO 9/20	1110	
MAKE	MODEL	SERIAL NUMBER	HOURS	UNIT NUMBER
GROVE	RT9150		232961	2940 15
SERVICE REQUE	STED			
REPAIRS MADE				
raveled to jobsite. DI	SASSEMBLED CRANE A	ND LOADED OUT		
COMMENTS				
OMMENTS				
COMMENTS				
	QNTY DESCRIPT	ION	[INSTALLED	ORDERED
	QNTY DESCRIPT	ION	INSTALLED	ORDERED
	QNTY DESCRIPT	ON	INSTALLED	ORDERED
	QNTY DESCRIPT	ION	INSTALLED	ORDERED
	QNTY DESCRIPT	ION	INSTALLED	ORDERED
PART NUMBER	QNTY DESCRIPT	ON	INSTALLED	ORDERED
	QNTY DESCRIPT	ION	INSTALLED	ORDERED
	QNTY DESCRIPT	ION	INSTALLED	ORDERED





	SERVICE REPORT	
ate: 1-3-17		PO #
ustomer's Name: Buyer	Cauno	er P.O. #
ob Location: Houston, SHo	M/M/T: Grove R19180E	
Equipment # <u>BE 150 103</u>		p Mileage
Describe Defects & Cause of Failure	e: things ON OFF Rept	hist
Somewied ena PM	Mucroe ON Frank Winds	
Out Malla on a	enter bearing and outrigg	oc JACKS
	As Continue and Route	and Heel Calles
Blow Dut From	AC Condenser and Renter	
Grased Machine	e and Boom	
0 /	4 9	
top OFF Coolun		
Braze Cable e	mls on Main and Aux	O. L. J. Justelled
Braze Cable & Put A2B Weight Oty Part Number	to me the Right Seile, Description	Ordered Installed
Rut A2B Weight Qty Part Number	to on the Right Side, Description	Ordered Installed
Rut A2B Weight Qty Part Number	to me the Right Seile, Description	
Rut A2B Weight Qty Part Number 1 F-5636 F- 1 W-2074 F- 1 4-55309 A	to on Main and Aux Description The Feltre, Sept Rates, Filter	
Rut A2B Weight Qty Part Number 1 F-5636 F 1 W-2074 F 1 4-F9548 C 1 AF-55309 A	to on Main and Aux Description The Feltre, Sept Rates, Filter	
Rut A2B Weight Qty Part Number 1 F-5636 F- 1 W-2074 F- 1 4-55309 A	Description The Right Stile, Description The Villey The Villey The Filter The Filter The Filter The Filter	
Rut A2B Weish Qty Part Number 1 F-5636 F 1 W-2074 F 1 4-755309 A 1 AF 55015	Description The Right Stile, Description The Villey The Villey The Filter The Filter The Filter The Filter	
Rut A2B Weight Qty Part Number 1 FF5636 F 1 WF2074 F 1 FF9548 C 1 MF55309 A 1 AF55015 A Recommendations 128	Description John States, John Sept Rates, John Filter, Mirror	72.24./6
Rut A2B Weish Qty Part Number 1 F-5636 F 1 W-2074 F 1 4-755309 A 1 AF 55015	Description John States, John Sept Rates, John Filter, Mirror	

Pink: Customer

Copies: White: Office

and the second of the second o The state of the state of And the street, the same of the same entre de la companya of the first of the second A CANADA CAN the second of th The second of th



TECHNICIAN

Richmond, VA 804-271-9356 North SLC, UT 801-292-2453

CUSTOMER SIGNATURE

Houston, TX 713-456-3086 **TOLL FREE** 888-337-2444

SERVICE RE	PORT				DA	TE:	
CUSTOMER					TRI	P MILEAGE	4/00/0047
Hunter							1/30/2017
CONTACT NAME & NO.							
DDRESS							
		MODEL		Bishop, Tx. SERIAL NUMBER		HOURS	UNIT NUMBER
MAKE		MODEL		SERIAL NUMBER		HOOKS	
Grove			9150	and the second s			BE150103
SERVICE REQUES	TED					and ad position all d	lav
Customer reported prob	lem that cra	ne would not t	elescop	e bac in after it was sittin	g in an exte	ended position all d	lay.
Vaited until the shift was	!:	tanded position	n rovos	led that the automatic fu	nction of te	lescoping did not v	vork properly. The 1st
		-acition propo	why but	when it retracted the pro	ogram would	n not exteria trie bo	JOHN PHI III to its nois. Aito
nanually selecting the to	elescope cyl	linder or boom	pin to r	etract or extend. Watchi	ng the pred	ision reel lengurre	ading, and comparing it
REPAIRS MADE							
the published pin pos	ition lengths	we descover	ed that	the extended lengths we	re off up 4 t	enths of a foot whi	ile the retracted lengths were o
- f b also alsba of	a foot I cuo	racet that we h	ave the	nin positions reset to the	air brober bi	aces.	
Automotic toloscoping a	nneare to sl	but off after a r	oredetei	mined time length if prop	er pinning	does not take plac	e. Restarting the
	-flar manii	ally cotting the	nrohla	m nin We tound no onvi	ous nyaraui	ic leaks in the book	111.
Customer can continue	to use the c	rane and prog	rammin	g repairs must be coordi	nated with t	ne customer so tha	at there is minimal downtime o
the machine.	1 0	Sunday.					
No work is allowed in th	e plant on S	sunday.	_				
COMMENTS							
COMMENTS			-				
PART NUMBER	IQNTY	DESCRIPTION	ON			INSTALLED	ORDERED
att ttombert					-		
				Tom Akey			



Page 1 of 2



H&E Equipment Services, Inc. 1700 South Sam Houston Parkway West Houston TX 77047-6312 Tel No. (877) 321-5249 Fax No. (713) 433-3981

Regional Credit Office Phone (866) 322-6577 Fax (972) 606-1011

Invoice Preview

Bill-To-Party Information BIGGE CRANE AND RIGGING COMPANY Invoice Preview No. 70409650 ACCOUNTS PAYABLE Order No. 42180744 PO Box 1657 Customer No. 1014390 SAN LEANDRO CA 94577 PO No. PO date Currency USD Ship-To-Party Make GV-GROVE CRANE BIGGE CRANE AND RIGGING COMPANY Model RT9150E Bishop TX 78343 Serial No. 232961 BE150103 Customer Eq No. 10098063 H&E Eq No. **Customer Contact** Contact Phone Meter 3621 hrs Complaints Complaint Details Telescope issue. Causes Cause Details Corrections Correction Details 02/01 Travel to the job. Checked outer and inner length pots and adjusted the inner to 0. Ran the telescope in and out several times and checked ok.



H&E Equipment Services, Inc. 1700 South Sam Houston Parkway West Houston TX 77047-6312 Tel No. (877) 321-5249 Fax No. (713) 433-3981

Regional Credit Office Phone (866) 322-6577 Fax (972) 606-1011

Invoice Preview

Description	Quantity	
	Quantity Unit Pr	rice Amou
		1,422.
		36.0
	Miscellaneous Total	72.
		1,530.
		1,387.5
		.,
į		
		6)
	Subtotal	2,917.69
	Tax	240.71
	Total Amount	3,158.40
poly Do and		3,100.40
	Date	
PO Number		1
	only. Do not pay.	Subtotal Tax Total Amount



TECHNICIAN

Richmond, VA 804-271-9356 North SLC, UT 801-292-2453

CUSTOMER SIGNATURE

Houston, TX 713-456-3086 **TOLL FREE** 888-337-2444

SERVICE R	EPORT		DATE:	
CUSTOMER			TRIP MILEAGE	
CONTACT NAME & I	NO.			2/10/2017
ADDRESS A	1.			
Bis	shop TX			
MAKE	MODEL	SERIAL NUMBER	HOURS	UNIT NUMBER
Grove	RT 150		3	3718 ₽€ 150103
SERVICE REQUE				
Breakdown call with b	oom telescoped out and in e	rror and not retractable. Plant do	es not aloow the boom to s	tay extended over night.
boom and had the cyli	inder in the wrong place and	oing functions in computor genera the boom locking pins disengage	ated lock out. Someone wa	s manually retracting the
Got the boom to lock it	by increasing the boom angle	. THIS CONTINUES TO BE A P	ROBLEM FOR THIS CUST	TOMER AS THE OPERATORS
ARE TRYING TO TEL	ESCOPE THE BOOM WITH	AN ANGLE BELOW 70 DEGRE	FS	
After getting the boom	pin engaged the RKS fault v	vent away. The telescop cylinder	was locked in to the wron b	boom section and when I
DEDAIDS MADE				
REPAIRS MADE	Luca ablata and			
fault is. The top left ni	n position light was red until	ct the other boom sections. Their	e was an ECOS fault 26.16	6.2.3 and I am not sure what that
problem.	in position light was red until	I retrived the last section, then it	went green, which may be a	a target or proximity switch
	would not allow me to re-ente	er the telescope status and I will o	n hack over there tomorrow	v to see if I can get tele-automatic
to function properly.		water to	o back over there tomorrow	vio see ii i can get tele-automatic
COMMENTS				
PART NUMBER	ONEY DESCRIPTION			
PART NUMBER	QNTY DESCRIPTION		INSTALLED	ORDERED
		Λ.,		
	1	. 4keu		
	101	n /1 · · ·		
	The Late of the Control of the Contr			



Copies: White: Office



14800 Jersey Shore Dr. Houston, TX 77047 (713) 434-0995

SERVICE REPORT	г
Date: 12-15-17	
Customer's Name: Bigge Crane	Customer P.O. #
Job Location: Howston, TX M/M/T: Grove RT	9150 E Hours: 5740
Equipment # BF 150103 Serial # 232961	Trip Mileage
Describe Defects & Cause of Failure: Make Crane Re	ent ready
Repairs Completed: Bioge decels installed open operation checked all greased counter painted ball & block & b load test & serviced batterys installed for main & Aux Costumer damage (costumer damage) topped off wipe brake cylinder mollyed crane installed down latch put in wash installed down 1 01677031 mirror arm left 1 07217118 mirror arm right 2 0 22 55928 outside mirror con 1 919 8101078 kit seal 1 758 1000 186 down light Description	h + (costumer dan)
	4.50
Name:	omplete: Labor: Reg O.T.

Pink: Customer

10:10021232 Garage and a soft of the second of the secon andrika nakvikor 1.4.6.1.1 不成的相同的 语 Consider the state of the second of the seco LithAP consuct f L SASS 1990 Contract this STA Secret TYANG LICE CONTRACT CONTRACT 1.38-383 + kings _____ Followell de din a mongange, e politicalisti di included as a contraction of relative and the contraction of the contr Francisco de la companya del companya del companya de la companya h Sand at Market of the Market of the Market Market h man & A & Close for demand) is included that an Sint was in Transfer of the Mone of the Man 1





SE	ERVICE REPORT	
Date: 1/14/18		
Customer's Name: Zacky	Customer P.C	O.#
Job Location: Change Vicio X M	M/M/T: Grave RTALFOE	Hours: 5154
Equipment # BE156163 S		
Describe Defects & Cause of Failure:	nunication Eyyeus.	
Repairs Completed: CVAN MS CO NOT STONE ON COMPLEX WON YORANGE WINNERS WAREN	Importe (OMM. Brows Cray No toot of Troublished To No Troublished of the length properly.	Neguis,
O. Dert Neuroban	Description	Ordered Installed
Qty Part Number	Description	Ordered Installed
D		
Recommendations:		
Technician: JISIA (VVZ CV		
Customer NAVIN IJANAIS	Job Complete: L	abor: Reg
Customer Signature:	Yes 🗗 No 🗆	O.T
orginature.		

Copies: White: Office

Pink: Customer





	SERVICE REPORT	
Date: 2/10/18		
Customer's Name: Zachwy	Customer P.O. #	#
Job Location: Novstan	M/M/T: Grove RT 950 E	Hours: <u>5205</u>
Equipment # <u>BE 150 103</u>	Serial # 232 X G b Trip Milea	ge
Describe Defects & Cause of Failure:	efe inop.	
Repairs Completed: book tele. (Ustime was able to 3 side vert have come lowhout, veryners verys Inspected latch kit on had to update tele po now running properly. To issues occurs	inop. Got truck completely precision out or sync. Causing error Loom real had to mano all tele the damage, none. After sition is location on displayers the thoroughly to ensure	length real is and function by he most very respect s. Cran is no more
Qty Part Number	Description	Ordered Installed
20) Americanoei	Decempan	- Albumou
		-
Recommendations:		
Technician: Joseph Oprio		
Customer Name: DASIN ISAKISO	v	O.T
Customer Signature:	Yes No D	0.1.

Copies: White: Office

Pink: Customer





SERVICE REPORT
Date: 5/21/18
Customer's Name: TPS Construction Customer P.O. #
Job Location: Monghans M/M/T: Grave 9150E Hours: 5914
Equipment # BE 150103 Serial # Trip Mileage
Describe Defects & Cause of Failure: Hyd leak at quick councet titing to boom.
Repairs Completed: Replaced leaking quick connect & o-ring. Ran machine - no leaks after spair
Kar machine - no leaks after sepair
Qty Part Number Description Ordered Installed
Recommendations:
Accommendations.
Technician:fustin buchnayi/
Customer Robert Kidd Job Complete: Labor: Reg
Customer Signature: Yes No O.T.

Copies: White: Office

Pink: Customer





	SERVICE RE	EPORT	
Date: 7/13/18			
Customer's Name: TURN REL	ROCESSING	Z Custo	mer P.O. #
Job Location: MONOHANS			
Equipment # <u>BE150103</u>	Serial #	Т	rip Mileage
Describe Defects & Cause of Failure:	PIVI SCI	EVICE	
Repairs Completed: PM SE	RUICE, RE	PLACED 2	NG DIL,
1 (es			
T	V		
	æ		
Qty Part Number 1 FF5636FL6 Fix	Descrip		Ordered Installed
1 AF55309 FLG AIR			
1 AFS5015 FLG ALE	2 FILTER		
9 GALLONS ISH	2-40 61L)		
Recommendations:			
Technician: J. GRIMM			
Customer Name:		Job Complete:	Labor: Reg
Customer Signature:		Yes No 🗆	O.T

Copies: White: Office

Pink: Customer





	SERVICE REPORT			
Job Location: LAMESA,	PIAL CONST. / U.S. SILICA TX M/M/T: GROVE RT9150 O3 Serial # 232961	DE	Hours: 6	501
Describe Defects & Cause of NOT RETRACTION	Failure: TELESCOPIC SENISOR	REEL A	fANGIA	16.
THE TIME I AR REEL. SPRING - REELS ON UNIT. UNIT STILL ONLY FULL EXTENT. C	PECT REEL. THE REEL HAR RIVED ON LOCATION. CHE TENSION IS ADEQUATE. CHEC REMOVED LOMMUNICATION OPERATIONAL IN BYPASS. TO LIEARED ISSUE. RETRACT. A TET TELESCOPIC SYSTEM. A	ECKED TO KED OUT LINE A ELES COP ILL REE	ENSION FOTHER ND RE LD FO LS PER	ORMED
Qty Part Number	Description		Ordered	Installed
Recommendations:				
Technician: 4, BROA.	DWAY Job Comple	ete: Lab	or: Reg	
Customer Signature:	Yes 🔼 No		O.T	

Copies: White: Office Pink: Customer Yellow: Technician Copy





	SERVICE REPORT	10 14028 790
Date: 8-30-18		, , , , , , , , , , , , , , , , , , , ,
Customer's Name:		Customer P.O. #
Job Location: 1 a mesa Plan	M/M/T:	Hours:
Equipment # <u>B £ 150 103</u>	Serial #	Trip Mileage
Describe Defects & Cause of Failure:	2 lacing had	dents.
Repairs Completed:	2 side di	agnals on jib
Qty Part Number 2 02210387 Tube	Description	Ordered Installed
2 Vaarusot Tube	38 × 3:2 en long 2 m	30
	7	
Recommendations:		
	a \	
Technician: Daniel R.	·:_	
Customer 1	Job Comple	ete: Labor: Reg
Name:	Yes □ No	0.5
Signature: Kenneth Wirk	wty	

Copies: White: Office

Pink: Customer





SERVICE REPORT	
Date: 12-17-18	
Customer's Name: Bisse Customer P.O.	#
Job Location: Shop M/M/T: KolBeleo CK27505	2 _{Hours: 2385}
Equipment # \$275435 Serial # 7806-04022 Trip Mile	age
Describe Defects & Cause of Failure:	
Repairs Completed: Full 2,000HR Servece Change oil and all Filters Listed	Below
1-R36PGOIG Filter ELEMENT Hydraulie 1 C194600Z0000S000 Hydraulie Filter Spin 1 CS10300A018B Hydraulie Filter Spin 1-YN50Y01006PIP A/C Fabine Filter 1-AR2S437 - A/C FILTES 2 GB50Y000045001 Strainer Baskets 6 YN52Y01021PI Hydraulie Elements 1-YN21P01068R100 Fuel Filter	0~
YN2 Polo68 R100 Fue Filter Qty Part Number Description VM 523 4011640 Fue Filter VM 1560 Eco70 Oil Filter VH 1560 Eco80 Oil Filter VT2 0m0000 45050 Cabin Filter	Ordered Installed
Recommendations:	
Technician: Daniel Sweeze	oor: Reg
Name:	O.T
Customer Signature:	

Copies: White: Office Pink: Customer Yellow: Technician Copy



Est 2000-000 (600)

		r and a transplantation of the contract of the
The second of th		Description of the Control of the Co
	`	्रे <u>क</u> ्ष्या स्थापन के स
THE STATE OF THE S	Beller Water	or . I declaration . Side at
A temperatural in the contract of the contract	6-104032 1-04	OCH 2008 TOWNER LA CONSERVA
ar African Contact to the Action Co.		traving the Law O. A. stocked with 1986 G .
		The control of the co
1. Amerika 1.2.16.512.	7.	
المتحدامها	المرد المراد الم	5 1/2 have 210 server
	Control Aus	Laste Start Block Eller
	Lie Friedlich	1 200 4 COOLO DE LA COEFFE DE 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1
12 22		<u>Links is a solution of the contract of the co</u>
an en 190 <mark>0 de mariamento de m</mark>	Astronom a Missa.	- 4205 W 410 F. 100 F. 100 F.
The same the second sec		Property of the season of the
	24,000 m	5-18452 12 19 12 19 12 19 18 18 18 18 18 18 18 18 18 18 18 18 18
betan LjuturoliO; (*)		the street is to see a second to a second of second
	7.24 7.34	
		Si Maria de
		Arovi Ar
		Control of the contro

West Texas Crane Techs, Inc.

BE150103

6003 East Cottonwood Rd. Gardendale, Texas 79758 (432) 307-8053

PO#:

	Unit #: 8 = 150103							
Customer:	Dissie				Date:	2-18-19		
Make: Grace	Model:	9150 E	_ Serial#: 2	32961	Upper:	Lower:		
Mileage:	3							
Work Descript								
DIT	- 75	Read	Idress /	Incle A	s Ans	le & Calos.		
cost	· Nepla	acad	Fond in	ines f.	inched &	in CAID BY		
Cover	len.	rived	Rest	Adolean	20 5	calibrate		
Len	the Ans	Le Ve	pfiel	jest.				
15.						Koset Pinning		
	7		Jo1.					
Ker	et E	Hard	Rac (easth .	settling			
						PO #'s Used		
1								
· ·		*						
☐ Job Comple	ete							
DATE	MILE	AGE	HOI	JRS	MA	TERIALS USED		
	Begin	End	Begin	End	-			
Sunday								
Monday	52300		8:30 A-		1			
Tuesday								
Wednesday		,			☐ PM Trailer			
Thursday					☐ Welding Trailer			
Friday					☐ Special Equip/Tools			
Saturday					☐ Hazard	ous Road		
Tech:	2	Date 7	8 / Signatu	ure: A	- L.	Date:		

West Texas Crane Techs, Inc.

6003 East Cottonwood Rd.
Gardendale, Texas 79758

BE	150103
----	--------

Invoice Number: _

(432) 307-805	3		PO#: _	PO#:						
			Unit #: BE 150103							
Customer:	Dissie			Date: 2 - 18 - 19						
Make: Grace	Model:	9150 E	Serial#: 2	32961	Upper:Lower:					
Mileage:	L	ocation:	Amesa	Te,	Contact:					
Work Descript	tion:									
DIJ	To	Read	dies !	Prole A	is Angle & Caros.					
cost	· Repla	red	fond n	ines for	Packed in CAID &					
Cover	Regio	inel	Rest	Addless.	us & calibrate					
Len	th Ans	le Ver	a fiel	jest.						
Reg	placed	no cis	ion long	th 14	cel , Keset Pinning					
J'A	in cheis		101.							
	et E	stand.	hal (ength.	se though					
					PO #'s Used					
-										
1										
☐ Job Comple	ete.									
DATE	1	AGE	НО	JRS	MATERIALS USED					
	Begin	End	Begin	End	HERETER HELEVIOLE					
Sunday										
Monday	52300		8:30A-							
Tuesday										
Wednesday					☐ PM Trailer					
Thursday					☐ Welding Trailer					
Friday					☐ Special Equip/Tools					
Saturday					☐ Hazardous Road					
Tech:	A	_Date	8 / Signate	ure:	Date:					





SERVICE REPORT									
Date: 1-21-19									
Customer's Name:		Custon	ner P.O. #	ŧ					
Job Location: Lamesa, 7	M/M/T: Grow	e RT 9150 €		Hours: 7	633				
Customer's Name: Customer P.O. # Job Location: Lamesa, TX M/M/T: Grove RT 9150 E Hours: 7633 Equipment # BE150103 Serial # Trip Mileage									
	Failure: O Crove hos								
Repairs Completed: Checked Crone & Verifited issue. Found small hose running from Engine diven hyd. Pump teaking. Hole rughed is in it from clamp. Removed oid hose of replaced with new one. Checked of fested crone, all fests & Checks good.									
Qty Part Number	Descrip	tion		Ordered	Installed				
1	hyd those			J	J				
Recommendations: Technician: Customer Name: Customer Signature:	Mok	Job Complete:	Labo						

Copies: White: Office

Pink: Customer

	Shore Un Tokk Swell with	XXF.III.	Belte A		emous are						
073.4 6	014808	rayuntah sahalih Materialik tida taha perimum musit	१४को अञ्चलका संदर्भन स्थानस्य हेर्ने स्थानको स्थान	TMOSS	S JON	ANE	i ga agenera in cui Ti ga Ti	en europe en european	tu angaganak tibun a aganga	ecu no de rezola e esta e en espaso B	egerige istansiya egeri ili il
							48.04.85		6: -: 2	Date: 🔿	
	The second secon		s a supra turiene.				<u>.</u>		्राध्नाक्ष्मी र	ະເທດະນຸລິ	
	1 25.63.23	Largetti.	<u> </u>		Miss or	SANG		<u>.</u> 	n Same	japalidoj Papalidoj	
			MgMT	erewk <u>ele</u>	\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	MarioR		ा. ्रि≎ृः	120 44	លេខទទាំក្រុងដី រុំ	ten o e
			A Company of the Comp			10 m					
	And the second second second second						क्रेम्स्ट्र इ	i tg wuşi,),श्रीताक्ष्मीकः	indiaeti. I	
**************************************	en e	tion the this transfer of the section of the sectio	e com e man e man e man e man e e e e e e e e e e e e e e e e e e e	**************************************		· · · · · · · · · · · · · · · · · · ·					
							i yang d				
· · · · · · · · · · · · · · · · · · ·								121 (2) 2 - 2) (i iprijajak en G	Q.M. 49X	
							45				
* ***	Constitute methodic constitution of						ig mann ganann ganann				
	33	NO 122			55.44		•				المحدد والمراجعة الأساس المحدد الم
	ka samua sama	and the second of the terminal and the second of	ationisms for MAC and a magaziness	e de contracte de la fina de la f			;		***		
			na ang antanan kantawang menghantan dalah sebagai kendalah sebagai sebagai kendalah sebagai sebagai sebagai se	tomanada teknatura arangan							
		de raise de la companya de la compa		at academic at a record			; ?				12.
		da giradag daga liga i gada kabandan dadi da da da kaga ing gar	يالمنسون والمارية	na thursdannia (d. 1905). T			• }			· · · · · · · · · · · · · · · · · · ·	
		agency (1960) is the consequence of the consequence	and a management of the second states of the second states of the second	gui esta como esta que como esta como es Como esta como							
		en emergen kalandar (n. 1921). Inganis	n i o stagen for the bigaries on in Assessor	e s un recursión de la company. La companya de la co	<u>.</u>		<u>-</u>	******		·	<u>-</u>
	le llugal	Ordered	in and and an area of the second and area of) boloud	ironoCi			i norig	miki-nof		general en
			and the transfer of the second	ندرست با المحاسب. أناراً			<u></u>		eman jan san in ana esab		
			anak (ku alimin) ya Nesi alimin (hi ir an makasik (ku alimin) harin ka ili maka						tu ming sa mult sa ti sanakangan		
		ة يون الله الخاصف المؤسسة (و الميك والمحمول الم	name description of the description of the	. Parista it Parista		and the second and the second		1			
	} 	Maria de Composito	and the state of t			<u>.</u> 	<u>.</u>		rejatjonst	aring ak	
	The second secon	والمحارب المحاربية المهموم فالحداثين	معيلات ميجيد المعاد يوديونين	en e			ļ				
• • • • • • • • • • • • • • • • • • • •		and the part of the second state of the second	and the same of the same of	s and the second		52 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 - 1 -			.		<u>.</u>
ui.		quá noch.				<i>y</i> (*)		10		usipininali 	
en e		<u></u>	,	and ded		· ·	<u>.</u>			าร์สหาร์แลว เหตุนาร์	Compressor a
		•		t Ter Militar (ay, a gamera a street or age over a	A			ote i degla Mitalina e i	And the
in the common series of the co	Been street comment street was treet.	ar Copy	e commente commente Bont Bothista	e se nt e anesentas elemen. M	en e	a na sa sa sa sa a Sa Militar Sa	Briedstein WW	. 2910(G)	T à Sharen Traction	e meneral meneral Mila Berlingspilis	e postava se po Na sektore