

DATE	Part #/description	WORK PERFORMED	MILEAGE	HOURS	COST
2013	Vehicle Maintenance				
L-527	1990 Peterbilt		Vin# 1XP5D29X8LD285662		
License	Z020029		ESN \$MG86518		
	EXPIRES DEC		Steer Tires 12R22.5		
	Company parts/svcs		Drive Tires 11R24.5		
1/2/13	Peterbilt of WY	806962, 02-01375-100, mis crosslink assy, U Bolt-Front Axle and nuts/washers ect.			\$ 535.32
1/3/13	Peterbilt of WY	CREDIT			-\$ 117.66
1/2/13	SHOP	REPLACED TIE ROD per Casper VM LOG			\$ 0.00
2/5/13	Midwest Hose	replaced transmission coller lines		5543	\$ 122.26
2/5/13	Peterbilt of WY	replaced PTO shims/gaskets, replaced brake air line			\$ 65.71
		u bolt replaced spring center			\$ 104.91
		center pin & Ubolts Left side			\$ 2.78
		Nuts (8)			\$ 5.12
		washer			\$ 2.32
2/5/13	Parts ckout bill	91847 Brake clean (1)			\$ 2.30
2/6/13	Peterbilt of WY	replaced steer axle brakes, wheel seals and cam busings			\$ 106.82
		Seal/Camshaft kit bracket			\$ 0.00
		05-10197/GR1308EG/GR1 Front shoes/core charge			\$ 108.57
		10C02			\$ 2.33
		725-10-10sdy			\$ 46.91
2/6/13	Parts ckout Kelly	213-10-250HSE/13-03510 Hyd hose and bumper rubber hood bumpers replaced			\$ 52.12
	Parts Ckout BILL	99780/99720/99007/BT3S-8 nuts, 4 lock washers, 4 bolts 4 plastic ties BARNES			\$ 5.50
		(2) 3009			\$ 2.78
		BT2S-CO/BT3S-CO			\$ 1.27
2/1/13	Parts ckout bill	Zip ties... 6 each size			\$ 2.25
		99004 1/4 x 1 bolts (4) BARNES			\$ 2.25
		99765 9/16 flat washers 4 BARNES			\$ 2.25
		99726 5/8 lock washers 4 BARNES			\$ 2.25
		23845 butt connector 1 BARNES			\$ 10.94
2/12/13	Peterbilt of WY	replaced rear motor mount rubbers and repaired brackets			\$ 154.64
	SHOP BILL	inspected and adjusted clutch		5569	\$ 0.00
2/15/13		repaired height control valve and set suspension height			\$ 0.00
2/15/13	Parts check out Glenn	Window washer/paper towels			\$ 3.50
		4656 Headlight low beam (1)			\$ 8.49
	Parts ckout bill	oil filter 1 NAPA			\$ 6.53
		1372 oil filter			
		75-150 5W/20 motor oil (4)			
2/17/13	Shop bill	replaced valve stem LFT Tire			\$ 3.67
	NAPA	replaced both low beam headlights (1)		5604	\$ 8.49
1/22/13	Parts check out Glenn				
1/22/13	parts ckout stuart	1 broom handle			\$ 10.82
2/26/13	NAPA	replaced turn signal flasher, repaired wirign to 2 way radio			\$ 33.19
		3050A			
		EP50			

2/26/13	Parts check out Glenn	H82260511	links (2)						\$ 4.16
3/3/13	stock	99054 (2),99722(2),99782(2)	3/8x1 bolts, lock washer, nut						
3/4/13	MPE Casper	PA2729JAB	250 hour service replaced air filter				5695	\$ 134.67	
		LF691A oil filter						\$ 10.40	
		FF5319						\$ 8.39	
		15W/40 032995-1	Oil 10 Gallons					\$ 92.30	
			Lucas oil					\$ 37.79	
			2 lbs					\$ 7.75	
3/4/13	stock potter	Grease 02382-120	tire valve core						
3/4/13	MPE Casper	90-100-1 (2)	gaskets/seals/locknuts/washers, bolts, studs ect2 invoices					\$ 235.16	
3/5/13	MPE Casper	Misc	replaced air chamber					\$ 70.15	
		SC30 Chamber	space adjusters and hardware					\$ 42.06	
		KN4700M1D						\$ 13.07	
	Peterbilt	Lock Ring R627012							
		Washer 1229B1848							
		clamp CM4402	replaced air to air clamp						
	MPE Casper	clamps ec50PLA	repaired exhaust					\$ 101.58	
		pipe EF50300S						\$ 221.37	
	ITP	7500HP kit	replaced turbo/exhaust gasket--rebuild fan clutch					\$ 367.50	
	stock		2 air fresheners						
3/8/13	stock Kelly	0-91847	1 can ????						
3/11/13	Peterbilt	4735-44003-12	replaced engine fan					\$ 181.01	
	peterbilt	99054 bolt	replaced hardware in mudflap						
3/11/13	stock Kelly	99780(4)	1/4" nut						
3/19/13	Barnes	99054,99727,99782,MP382	bolt, washer, nut, cotterpin--repair chain						
3/20/13		MP38237 (3)	cotter pins 5/32x1						
3/28/13	shop	1 gallon used oil	oiled winch line, repaired fan clutch					5701	
4/9/13		715-2002	1 grease zerk						
	Peterbilt	16-07571 Cover	replaced wiring harness cover					5730	\$ 20.88
	Barnes	32572 washer	1/4" fender washer (1)						\$ 0.80
		90180 valve cap	replaced missing valve cap						
4/25/13	Motor Power	SC30 air chamber	replaced brake can/left rear drive axle					5771	\$ 34.99
	NAPA	7443 oil seal	replaced seals in PTO shift shaft						\$ 10.48
	Barnes	99002 Bolt	fabricated wiring harness & Retainer (2)						\$ 0.18
		99780 Nut						2	\$ 0.08
		99720 Lock Washer						2	\$ 0.10
		BT25-CO Zipite						3	\$ 0.36
		MP32604 Cable Clamp						2	\$ 2.40
	ITP	Quik valve	replaced quick release valve for service brakes						
	MPE Casper	Wire Loom 1/2"	repaired wiring harness (3)						\$ 1.14
4/24/13	NAPA	4800 Brake Clean	Cleaned front differential (4)						\$ 8.36
4/29/13	NAPA	H8226-0511 quick link							\$ 2.19
4/30/13	Barnes	MP3827	cotter pins 5/32x1						



6/4/13	Snow Distributing	02382-120 grease	adjusted clutch/greased driveline and clutch linkage cleaned and greased 5th wheel plate						\$ 3.87
6/5/13			repaired wiring to wipers						\$ 9.36
7/19/13	MG Oil	02382-029	2 tubes grease for grease gun						\$ 19.40
8/12/13	ITP		replaced leveling rod for suspension						\$ 19.23
			48100225 kit						\$ 107.42
8/24/13	VVY rigging	1 " Bridle	new bridle for truck						\$ 37.05
9/13/13	Peterbilt	Air Switch	R&R Airswitch fifth wheel slide						\$ 66.75
9/18/13	NAPA	2 prong relay	R&R in dash relay						\$ 17.32
9/30/13	Commercial Tire	1 drain cox	R&R drain cox in the air tank						\$ 497.23
10/1/13	Wheeler	11R24.5 Steer	R&R Left steer tire						\$ 18.88
10/2/13	13-03593	2 oring 2N-3350 1 seal 5P-5846	R&R Oring on injection pump oil side						\$ 51.86
10/3/13	05-03331	roller hood							\$ 31.73
		tube radiator--bushing hood	guleds Rollers						
10/25/13	ITP	48100367 Road Kit	repaired leveling valve & Bracket-replaced rod kit. Repaired dump valve switch						\$ 17.60
10/23/13	Peterbilt	TL10750 switch	replaced turn signal switch					6019	\$ 91.42
10/8/13	Fleetpride	AV107794	dryer cartridge						\$ 28.18
10/9/13	Vernal Stock	AC2001 Cartridge	replaced dryer cartridge						\$ 1.20
10/25/13	MPE Casper	LB73 bulb	replaced bulbs in dash (2)						\$ 57.88
10/17/13	Six States	PTO Seal							\$ 53.66
10/17/13	Six States	PTO Seal							\$ 0.12
11/13/13	BARNES	99721 Lockwasher	replaced missing bolt in deck	2					\$ 0.22
		99027 3/16 bolt							\$ 1.95
11/22/13		998186 20A fuse	replaced missing fuses						\$ 4.51
		81260 gladhand	replaced service glad hand blue						\$ 21.96
	Homax	103051 Howes	howes fuel treatment for truck 1 gal						

2014	Vehicle Maintenance		Vin# 1XP5D29X8LD285662						
L-527	1990 Peterbilt		SAFETY INSPECTION	11/20/2014					
License	Z020029		Steer Tires 12R22.5						
	EXPIRES DEC		Drive Tires 11R24.5						
	Company parts/svcs								
<b>DATE</b>	<b>Part #/description</b>	<b>WORK PERFORMED</b>	<b>MILAGE</b>	<b>HOURS</b>	<b>COST</b>				
1/13/14	Stock	SCB200 Clutch Brake	R&R Clutch Brake						
	Basin Auto	seals 2-2287 1-470954	R&R Seals in PTO						\$ 16.10
	Morcon	20' 4csc hose	R&R Governor Air Lines						\$ 63.10
1/16/13	Fleet Pride	LV90054007	R&R Height Control Valve						\$ 73.42
2/12/14	Vernal Shop	Safety Inspection				205722	6039		\$ 15.00
2/14/14	Fleet Pride	Marker Light Lens							\$ 3.85
2/20/14	Fleet Pride	920049 Lens	Replaced lens covers on headache rack				6048		\$ 3.51
	Barnes	11083-4 pipe plug	fabricate plugs for air fitting quick connects						\$ 6.14
	NAPA	90668 adapter							\$ 10.48
	Barnes	81261	replaced emergency glad hand						\$ 4.70
2/22/14	Barnes	998186 20 amp fuse	replaced blown fuse for gauges				6082		\$ 0.65
	MPE	EC50PLA Clamp	repaired exhaust leak						\$ 9.30
3/1/14	MPE	4302809	removed PTO & Installed transmission cover				6080		\$ 10.05
	Barnes	99081-1 7/16 bolt							\$ 2.88
		99743 7/16 flat washer							\$ 0.48
		99723 2/16 lockwasher							\$ 0.96
3/3/14	Snow Distributing	02382-120 Grease	greased truck						\$ 7.74
		35P15-1 gasket	gasket for transmission cover						\$ 0.91
3/18/14		BT25-CO Ziptie	repaired wiring to wiper motor				6129		
			repaired linkage to wiper arms and adjusted						
3/22/14	NAPA	7443 oil seal	installed shift rail and oil seals						\$ 10.90
	Six States	RT34814 Shaft							\$ 176.30
3/28/14	MPE	35P15-s gasket	reinstalled PTO						\$ 2.14
			welded crack in bed						\$ 0.00
	Snow Distributing	02382-120 Grease	greased truck						\$ 7.74
	CMI TECO	7753 28T34746 Eye bolt							\$ 10.99
3/30/14	Peterbilt	P54-6063	replaced broker turn signal assembly				6131		\$ 108.00
4/9/14	NAPA	90180 Valve Cap	Replaced missing valve caps						
	Sams Club		Filled washer fluid reservoir						\$ 1.97
	NAPA	7151053 Grease zerks	replaced grease zerk						\$ 0.73
	Snow Distributing	02382-120 Grease	greased truck						\$ 7.74
	Barnes	998186 20A fuse	spare fuses for truck						\$ 3.90
4/29/14	MPE	30-18 wiper blade	SERVICE						\$ 7.51

	MPE	B99	Oil filter						\$ 10.64
		BF7587	FF						\$ 8.86
	Homax	1052955-1	Buld 15W40 engine oil						\$ 94.40
	Snow Distributing	02382-120	Buld Grease						\$ 7.74
	MPE	10002	LUCAS						\$ 27.99
	Vernal Shop	AF4664	refurb filter X 2						\$ 46.80
	MPE	30-18 wiper blac=de							\$ 7.51
5/2/14		99722	lock washer						
5/5/14	Sams club	glass cleaner M5702	glass cleaner for truck						\$ 2.10
5/19/14	MPE	B99	SERVICE TRUCK				6347		\$ 10.64
		BF7587 FF							\$ 8.86
	HOMAX	1052995-1 oil	15W40						\$ 94.90
		02382-120 grease	grease truck						\$ 7.74
		AF4664	Clean air filter						
5/20/14	Barnes	998186 20A Fuse	replaced brake light fuse						\$ 0.65
	Sams club	959887 washer fluid	filled windshield washer res						\$ 1.97
	MPE	10002 Lucas							\$ 27.99
	Homax	3200-53 coolant	filled radiator						\$ 7.12
	ITP		replaced carrier bearing and u joint straps on front driveline						\$ 215.76
	NAPA	7443 Seal	replaced shift shaft seals in PTO						\$ 10.90
			Tightened winch chains						\$ 0.00
5/2-1/14	Barnes	38241 Cotter pin	repaired chian hook						\$ 0.12
		2156 Seals	replaced glad hand seal-emergency air line						\$ 2.00
5/26/14	Barnes	MP38229 cotter pin	repaired chain hook						\$ 0.05
5/30/14			repaired wiring to engine fan						\$ 0.00
	ITP	DRIVELINE	FABRICATE NEW DRIVELINE						\$ 589.60
	NAPA WRIGHT		Bolts for fan clutch						\$ 4.98
	ITP	7500HP Clutch kit	reult fan clutch						\$ 439.37
	NAPA	7701305 grommet	grommets for CB coaxial cable						\$ 3.72
6/4/14			ADJUSTED BRAKES				3420		\$ 0.00
6/1-1/14	Barnes	23846 connector	repaired pinched wires				6537		\$ 2.32
		23849-1 terminal	repaired wiring to turn signal flasher						\$ 0.94
		38239 cotter pin	repair chain hooks						\$ 0.16
	Homax	3200-55 coolant	added coolant						\$ 7.12
6/14/14	MPE	D61-6002004 starter	replaced starter				6517		\$ 422.69
			adjusted clutch						\$ 0.00
6/14/14	Homax	1052955-1 15W40 oil	200 hour service						\$ 89.20
	Snow Distributing	02382-120 Grease							\$ 7.74
	MPE	10002 Lucas							\$ 27.99
		B99 Filter							\$ 10.54
		BF7587 Filter							\$ 8.77

				repaired headached rack/winich mount					\$ 0.00
	HOMAX	1053887-20 75W90		filled front differential					\$ 63.20
	NAPA	IN910 plug		repaired tire RRI drive axle					\$ 0.28
		RA010 patch							\$ 1.24
	BARNES	998186 20A fuse		repaired clearance lights/turn signals					\$ 1.30
		67 bulb							
6/24/14	VVO Rigging	1" bridle		new bridle for truck					\$ 178.76
6/30/14	MPE	CB12050		replaced turn signal flasher					\$ 22.11
7/1/14				repaired leak on power divider					\$ 0.00
	VVO Rigging	1" * 165' wire rope		replaced winch line			6588		\$ 759.00
	NAPA	1462*4 fitting		replaced broken air fitting on winch					\$ 7.65
	Vernal Shop	rod chain lube							
	Overall supply	212 nut/bolt loosener							\$ 10.65
7/2/14	CMI TECO		21163	winch u bolt					\$ 18.56
7/16/14	VERNAL STOCK	8- NEW 11R24.5		Firestone FD 663 Drive tires R&R					\$ 1,918.80
		8 - 1202 Counteract beads							
7/17/14	Stewart Wholesale	PINS 20517		dowl pins REBUSH WINCH					\$ 2,712.35
		Collar		""					
		Set Screws		""					
		Gear box bushings		""					
		Drum bushings		""					
		End Bracket Bushings		""					
		Freight		""					
7/17/14	NAPA	2 u joints		R&R u joints in PTD Driveline					\$ 40.90
	Basin Auto	Gasket Sheet		for gear end gasket (winch)					\$ 11.01
	Stock	75-90 W Gear Oil		1 gal for winch		215934		6629	
7/18/14	Bowden welding	fix battery box/cracks/headache							\$ 455.00
7/22/14	Peterbilt	MF0011P-F-G mudflap		replaced mudflaps on toolbos and battery box					\$ 44.04
7/29/14	peterbilt	507162 breather		replaced breather on front differential					\$ 11.99
	Barnes	23449 red wire		repaired wiring to strobe lights					\$ 0.60
		23847 connector							\$ 0.60
		23846 connector							\$ 0.43
8/1/14	Snow Distributing	02382-120 grease		200 hour service			6709		\$ 7.74
	homax	1052955-1 15W40 oil							\$ 89.20
	MPE	B99 oil filter							\$ 10.54
		BF7587 fuel filter							\$ 8.77
		10002 Lucas							\$ 27.99
				repaired fan clutch					\$ 0.00
		4709 brake kit		replaced brakes on rear drive axle					\$ 109.16
		SL50PLA clamp		replaced exhaust clamp					\$ 8.26
	BARNES	6223 1157 bulb		replaced bulb in S/T/T					\$ 0.38





2019	Vehicle Maintenance		Vin# 1XP5D29X8LD285662						
L-527	1 990 Peterbilt		SAFETY INSPECTION						
License	Z020029		Steer Tires 12R22.5						
	EXPIRES DEC		Drive Tires 11R24.5						
	Company parts/svcs								
<b>DATE</b>	<b>purchased from</b>	<b>Part #/description</b>	<b>WORK PERFORMED</b>	<b>MILEAGE</b>	<b>HOURS</b>	<b>COST</b>			
5/28/19	Fleetpride	250-70-18X u joint retainer kit	? NOT ON LOG from CASPER? GET READY TO SEND TO CASPER	?	?	\$ 43.70			
7/29/19	Peterbilt	4 batteries	R&R Batteries						
7/30/19	Fleetpride	filters/cartridge/wipers	also air dryer/split loom change motor oil and filter/wiper blades	219438	6918	\$ 346.78			
	stock	oil 15-40 delo	10 gallon			\$ 93.20			
7/30/19	Peterbilt	front windshields	installed by a nu view 8/1/2019			\$ 85.25			
	A Nu view		installed windshield			\$ 256.08			
7/31/19	Six States	Seal	pinion seal for rear drive axle			\$ 80.85			
8/1/19	Shop	50 W Trans oil	R&R Air dryer cartridge purchased above						
	Stock	Pinion Seal Read/D	5 gal change trans oil						
	Six States	air spring 6069	R&R Pinnion seal rear drive axle						
8/2/19	Peterbilt	5 gal 75W-90W	R/F/D Air spring replaced			\$ 132.64			
	Stock	5 gal 75W-90W	change oil rear drive axle			\$ 126.36			
8/5/19	Fleetpride	marker light	change oil in front drive axle			\$ 126.36			
8/6/19	Fleetpride	fan clutch kit	R&R marker light driver side BED			\$ 34.90			
8/15/19	Fleetpride		rebuild fan hub and clutch assembly			\$ 394.46			
8/15/19	safety inspection					\$ 15.00			
9/2/19	Flying J	CB radio	sent to casper	219,438	6918	\$ 0.00			
9/7/20	billy curtis	labor on fan clutch				\$ 136.49			
7-Sep	Fleetpride	Fan-Clutch Tires	Replace clutch on fan	221311		\$ 150.00			
16-Sep	GCR Tires	Tires	Tire was fixed on truck			\$ 377.79			
16-Sep	Peterbilt of WY	Temp Sensor	replaced temp sensor			\$ 64.03			
23-Sep	back up light switch	light switch	greased tractor and trailer replaced light switch			\$ 70.31			
4-Oct	oil filter/ fuel filter	filters	replaced oil/fuel filter/grease tractor change engine oil	225333	71868	\$ 41.60			
4-Oct	Wheeler	Gasket	replace pump	225333	71868	\$ 117.84			
5-Oct	Napa	u joint kit	replaced 1st axle/input/output u-joints	225333	71868	\$ 100.74			
8-Oct			anti-freeze -23 degrees	225333	71868	\$ 34.64			
7-Oct	DFS Supplement		added to fuel tanks	225333	71868	\$ 34.64			
8-Oct	Shop		cleaned batteries/spray protectant	225333	71868	\$ 34.64			
17-Oct	NAPA	Adapter	replaced	227467	7243	\$ 12.58			
17-Oct	napa	air brake chamber	replaced	227467	7243	\$ 54.76			
17-Oct						7276			
26-Oct	tail light/bulb driver	Shop	replaced	227602	7276				



