

2013	Vehicle Maintenance		Vin# 1NP5DB0X61D568114				
L-528							
License	2001 Peterbuilt Z022842 EXPIRES DEC		Steer tires 425/65R 22.5 Drive Tires 11R 24.5				
	Company parts/svcs						
DATE	Purchased from:	Part #/Description	WORK PERFORMED	MILEAGE	HOURS	COST	
1/3/13	Peterbilt of WY	20-17150-002	Window Slider W Screen-Replaced REAR window			\$ 504.16	
1/10/13	MPE Casper	53-123537	Brake Drums - X30			\$ 389.17	
1/10/13	Peterbilt of WY	810456/810457, R615002	Camshafts and repair kit-Scams and bushings on front drive		6026	\$ 162.48	
1/11/13	Shop	Greased	2 LBS			\$ 7.38	
1/18/13	MPE Casper	30-18	Winter Wiper Blade			\$ 15.02	
1/17/13	Shop	Greased	2 lbs			\$ 7.38	
1/28/13	Cage Bill	1106 light sockets (2)	NOT ON VM LOG--replaced wiring in bumper guides				
	Barnes	99780 1/4" Nut (2)	NOT ON VM LOG replaced hardware in heache rack				
	Barnes	99720 1/4" Lock Washer (2)	NOT ON VM LOG for expanded metal				
	Barnes	99002 1/4 & 3.4 Bolt (2)	NOT ON VM LOG more hardware for above				
2/14/13	Casper Shop	Yokohama 11R24.5 used	replaced LRD Drive Tire			\$ 174.05	
		LF691A	Oil filter 250 hour service		6149	\$ 10.40	
		FF5319	Fuel Filter			\$ 8.39	
		FS1000	Separator			\$ 10.52	
		Lucas Oil	Treatment 1 gal			\$ 37.79	
		15W40D	OIL 10 Gal			\$ 92.30	
		02382-120 Grease	2 lbs			\$ 7.75	
2/14/13	Parts Ckout DT	50/50 Antifreeze	coolant 3200-55 1.5 gallons			\$ 10.78	
2/15/13	Parts Ckout DT	Howes 103051 .5 Gallon	Deisel Treatment			\$ 6.32	
2/16/13	Eastgate Travel Plaza	Antifreeze	2 gallons 50/50 ANIT FRZ ELC			\$ 25.98	
2/22/13	Parts Ckout DT	50/50 AF	2 gallons antifreeze			\$ 14.38	
2/26/13	Parts Ckout bill	1/2" union FG3987	1 MPE			\$ 12.20	
2/27/13	Peterbilt of WY	LB73	Bulb--repaired lights in warning panel		6283	\$ 1.71	
2/28/13	Peterbilt of WY	822680180001.00	Socket Panel			\$ 5.30	
2/28/13	MPE Casper	4050SIG	Replaced taillights and repaired wiring(2)			\$ 32.96	
		mirror SH716S	replaced driver side mirror			\$ 21.80	
		070R	Pogo stick spring ass			\$ 29.43	
		MD1185	Hose tender kit			\$ 36.82	
2/28/13	MPE Casper	29PLX CB Cobra				\$ 134.40	
2/28/13	Parts Ckout bill	99761	5/16 flat washer 4	BARNES			
		99721	5/16 lock washer 2	BARNES			
		99781	5/16 nut 2	BARNES			
2/28/13	Parts Ckout bill	50/50/coolant	2 gallons			\$ 14.38	

		4050 91740 67090	4" S/T/T Light 2 fleet pride Grommets 2 MPE 4.06 Light Harness (2) MPE 3.56 Replaced mudflaps 2 Loom						\$ 30.88 \$ 8.12 \$ 7.12 \$ 30.84 \$ 8.35 \$ 2.80 \$ 21.86 \$ 0.96 \$ 113.40 \$ 3.86 \$ 2.16 \$ 32.88 \$ 2.20 \$ 3.06
3/1/13	MPE Casper	243012GK Mudflap 5-025 5-030 99029.MP34274,99762	Replaced mudflaps 2						
	Stock BARNES	A25RL200	bolt nut washer to replace mudflaps 3/8" 8 each						
	MPE Casper	2523 hairpin	Hanger--replaced mudflap hangers and retaining pins						
	Stock Barnes	29PLX Radio	Replaced CB radio serial # w212122087						
	MPE Casper	kp81235, kp86912, kp86914	seal and connectors--replace taillights and repaired wiring (7.6.6)						
	Stock BARNES	725441 seal	4 blue seals						
	NAPA	4050A	4" S/T/T light						
	Stock MPE	LL09211D	Grommet						
	Stock MPE	LL091810 pigtail							
	Stock MPE	2523 hairpin							
3/2/13		1 gal washer fluid							
3/4/13	MPE	pin and bushings kit	RK04413						
3/1/13	NAPA	194 bulb	replaced bulb in bumper guide						
3/14/13		413 clamp	replace air charge cooler clamp						
	Mountain west truck		replaced radiator core						
	MPE Casper	HE2788	3" hose replaced lower radiator hose						
		HE2650	2.5" hose replaced upper radiator hose						
		99724/99058/99783	washer/bolt/nut						
	homax	3200-55	replaced coolant						
	Peterbilt of WY	L9260000718	cable-replaced hood safety cables(2)						
	Peterbilt of WY	RC0730	replaced radiator cap						
3/13/13	ASAP Radiator	nuts n bolts	radiator tank bolts						
	barnes stock	BT25-co zipties	secure wiring 2						
3/18/13	Two way radio		trouble shoot and repair company radio						
3/19/13	NAPA	715-1021/51 grease zerk	replaced broken grease zerks 4/1						
		90-674 fitting	replaced air fittings on tank						
	Shop	labor	rotated steer axle tires						
	MPE Casper	Wire end K333-67	repaired wiring to rear diff and enging oil temp sensors						
	Decker Glass	glass	replaced passenger windshield						
	stock	greased							
	NAPA	fiberglass kit	repaired fan shroud 765-1281						
	MPE Casper	Cap/MW1209BK	replaced center caps on steer axle wheels						
			repaired wiring and replaced both tail lights						
	MPE	4050 light							
	MPE	94922 pigtail							

	sams	washer fluid	filled windshield washer			\$ 1.87
	NAPA	Bulls 194	replaced bumper guide lights			\$ 0.35
	Stock	413 clamp	replaced clamp on air cooler			
4/3/13	Wyoming Rigging	1" Bridle	replaced bridle			\$ 107.42
4/5/13	Peterbilt of WY	K3963 Cooler	replaced transmission cooler		6342	\$ 386.61
4/8/13	Homax	coolant	filled radiator			\$ 22.65
		50WT	filled transmission			\$ 81.13
4/10/13	NAPA	777-1039 Wire brush	tools for truck			
		cross link chain	11 links (2)			
4/19/13	MPE	17591BLT V belt	replaced both sets of v belts			\$ 31.14
		22550 BLT2 V belt				\$ 36.88
	Peterbilt of WY	1cc4696 compressor	replaced A/C Compressor			\$ 254.00
		LM11400	castrol AC			\$ 15.15
	Barnes	10747 ferrule	repaired airlines			\$ 0.46
		10856 Insert				\$ 0.44
		194 bulb	replaced bumper guide bulbs			\$ 0.68
4/23/13	Peterbilt of WY	LF691A	Oil filter 250 hour service		6448	\$ 10.41
		FF5319	Fuel Filter			\$ 8.39
		FS1000	Fuel Filter			\$ 10.52
	NAPA	10002 Lucas				\$ 37.79
	snow dist	02382-120 GREASE	Greased truck			\$ 11.61
4/24/13	WY Machinery	1375541 PUMP	replaced primer pump			\$ 27.57
4/29/13	Peterbilt of WY	17591BLT V Belt	replaced alternator belts			\$ 0.21
	Barnes	99763 Washer	installed flat washer and lock nut on alternator adjusting rod			\$ 0.48
	BARNES	BT3S-co	secured wiring 4			\$ 0.73
5/17/13	NAPA	715-1021	Replaced Grease Zerk 1			\$ 264.74
5/8/13	upholstry	seat cover	replaced driver seat 5/21 installed in casper		6551	\$ 0.00
5/22/13	Casper Shop	02382-120	Adjust clutch and winch chains/inspect suspension and front end		6500	\$ 7.74
5/23/13	snow dist	R10429/6220	Greased truck chassis			\$ 9.94
5/13/13	NAPA	30/30 type maxi brake can	Spray paint and Bulb --replaced in roof light			
5/28/13		6220.00	mini wedge bulb			
6/5/13	snow dist	02382-120 Grease	Greased Truck			\$ 7.74
	Barnes	10747 Ferrule	repaired air line			\$ 0.46
6/12/13	Barnes	99106 Bolt				\$ 0.40
		99764 Washer				\$ 0.08
		99784 Nut				\$ 0.18
		MP38237 cotter pin				\$ 0.59
		99055 bolt				\$ 0.64
		99722 washer				\$ 0.52

	MPE	99782 Nut 2523 Hair Pin clip 243102GK mudflap A25RL200 Hanger					\$ 0.24 \$ 0.47 \$ 15.42 \$ 10.93
6/14/13	Barnes Barnes	21260 Blue Glad Hand 21621 red glad hands	replaced broker glad hands				\$ 4.51 \$ 4.51
6/24/143	Tire Rama		Flat Repair LRI				\$ 36.75
6/25/13	MPE	B99 oil filter BF7587 Fuel filter BF1259 fuel filter 10002 Lucas 1052955-1 15W40	250 hr service	284445	6702		\$ 10.22 \$ 8.53 \$ 9.70 \$ 37.79 \$ 89.20
	NAPA Homax	greased					\$ 7.74
	snow dist						\$ 19.08
6/27/13	MPE	70-70-18X Bearing Kit	.5 gal				\$ 256.03
6/28/13	stock	210456 50WT trans fluid	replaced input yoke/rear differential				\$ 103.93
	ITP	170-4-381-1X Yoke/NUT	replaced u joint to input yoke				\$ 15.67
	MPE	SPL 170-4X u joint					\$ 45.23
	ITP	128049 yoke nut					
		210724 seal					
	VERNAL	25247 aire filter 2	replaced air filter (used)				\$ 0.73
	NAPA	7151026 grease zerk	replaced bad grease zerk				\$ 0.05
	Barnes	MP38229 cotter pin	repaired load chain				\$ 11.74
	Homax	1054009-20 50 wt	filled transmission				
		28P218 seal	repalced shift shaft seal on PTO				
	Vernal	Ratchet Strap	new ratchet straps for truck				
72/2013	snow dist	GREASE 105667-14	1 tube				
7/5/13	Barnes	Hose 9931N	replaced water pump and bad hoses		6711		\$ 66.08
	MPE	Water Pump 10R0494					\$ 760.61
	Homax	50/50 mix antifreeze	refilled coolant 3 gallons extended life coolant				\$ 90.60
7/10/13	Tire Rama		Flat Repair RRI				\$ 36.75
7/15/13	MPE	Service Dept	Check Engine				\$ 116.48
7/19/13	Dans Tire	8 MTR remove and replace	Head ruined				\$ 127.62
7/22/13	MPE	engine diagnostic	clamp exhaust				\$ 116.48
7/25/13	Kenworth	ED50PLS					\$ 32.58
		Oil Temp sensor					\$ 80.29
7/26/13	Rush Truck	16"-5" exhaust flex pipe Overhaul engin/Calibrate cam shaft oil cooler turbo	ENGINE OVERHAUL				\$ 18,338.19 \$ 0.00 \$ 0.00 \$ 0.00 \$ 0.00

DATE	DESCRIPTION	QUANTITY	UNIT PRICE	TOTAL
7/29/13	STOCK			\$ 0.00
7/30/13	rocker 10 gal antifreeze			
7/30/13	clutch 10 gal Delo 15-40			
7/30/13	surface flywheel Motor Mounts			
7/30/13	TLCS00A/FLX500S-60 6 GAL			
7/31/13	clutch assy/bearing/brake/shaft			
7/31/13	MM75-62372 /PL1013			
7/31/13	lap joint and tubing			
7/31/13	SH Spirax S6 GME 50 P5			
7/31/13	u joint retainer kit and radiator hose			
8/1/13	6 gal			
8/1/13	traction tire			
8/1/13	285017			
8/1/13	6735			
8/1/13	\$ 94.11			
8/1/13	\$ 18.72			
8/1/13	\$ 5.08			
8/1/13	\$ 256.68			
8/1/13	\$ 15.00			
8/1/13	\$ 36.75			
8/1/13	\$ 213.60			
8/1/13	\$ 86.80			
8/1/13	hardener			
8/1/13	service glad hand 21260			
8/1/13	service glad hand 21261			
8/1/13	thinner			
8/1/13	1190036 screw			
8/1/13	tool box			
8/1/13	6223 1157 bulb			
8/1/13	998184 10A fuse			
8/1/13	3050A Light			
8/1/13	02382-120 grease			
8/1/13	30700 grommet			
8/1/13	11096-2 nipple			
8/1/13	2102 connector			
8/1/13	13-04727 sleeve			
8/1/13	HWC07084 nut			
8/1/13	13-04726 bushing			
8/1/13	7151021 grease zerk			
8/1/13	M5702 glass cleaner			
8/1/13	EC50PLA Clamps			
8/1/13	1052955-1 15W40			
8/1/13	1" bridle			
8/1/13	5632.00			
8/1/13	3200-55 coolant			
8/1/13	1280334 hose			
8/1/13	repaired rt marker light			
8/1/13	repaires strobe lights			
8/1/13	replaced clearance light			
8/1/13	greased truck			
8/1/13	repaires airline to emergency glad hand			
8/1/13	replaced bolt and bushings in hood hinges			
8/1/13	replaced grease zerk			
8/1/13	spare oil for engine 1 gal			
8/1/13	spare oil for engine 2 gal			
8/1/13	brake line antifreeze 2 gal			
8/1/13	replaced coolant hose and refilled radiator			
8/1/13	7			
8/1/13	6835			
8/1/13	\$ 3.54			
8/1/13	\$ 53.55			
8/1/13	\$ 8.30			
8/1/13	\$ 107.42			
8/1/13	\$ 9.13			
8/1/13	\$ 18.60			
8/1/13	\$ 39.48			
8/1/13	\$ 9.16			
8/1/13	\$ 39.10			
8/1/13	\$ 1.46			
8/1/13	\$ 2.20			
8/1/13	\$ 18.60			
8/1/13	\$ 9.13			
8/1/13	\$ 107.42			
8/1/13	\$ 8.30			
8/1/13	\$ 53.55			
8/1/13	\$ 3.54			

	Barnes	24114 hose clamp 99106 1/2" bolt 99724 lock washer 99764 flat washer 1052955-1 15W40 M5702 Glass Cleaner 212 Nut/bolt loosener MP38237 cotter keys	replaced missing hardware in bumper					\$ 0.84 \$ 0.40 \$ 0.17 \$ 0.09 \$ 18.26 \$ 2.10 \$ 10.45
9/27/13	Homax		extra oil for engine 2 gal					
10/11/13	Sams club Oreilly Supply		Glass Cleaner for truck/paper towels loosener for truck					
10/15/13	NAPA MPE	10002 Lucas B99 Oil Filter BF1259 Fuel filter BF7587 Fuel filter 1052955-1 15W40 oil 02382-120 Grease	200 Hour service			6931		\$ 37.79 \$ 10.22 \$ 9.71 \$ 8.53 \$ 91.30 \$ 7.74 \$ 0.00 \$ 15.02 \$ 0.00
	Homax Snow distributing		repaired Aux Lights --shop replaced windshield wipers rotated steer tires					
10/17/13	MPE Shop	30-18 wiper blade nut buster						
	WRIS	1" Bridle						\$ 107.42
10/22/13	MPE MPE Barnes	TSM4PKW antenna AC2001 cartridge 99761 Lockwasher P007931B spo	replaced broker/missing CB antennas replaced air dryer cartridge replaced missing hardward on air dryer RETURNED---TOO LATE - BUMPER GUIDES			6938		\$ 17.39 \$ 26.25 \$ 0.05 \$ 0.00
10/23/13	MPE							
11/10/13	Vernal	3/8 Ratchet binder	replaced broker binder					
11/12/13	Snow Distributing Homax	02382-120 Greast 3200-55 coolant 7151021 grease fitting LFW4685 Filter	greased truck filled radiator					\$ 7.74 \$ 7.55
11/14/13	WY Machinery	155-2270 connector 264-4297 sensor 2165455 receptacle 71415F connector BT25-co zipite	changed coolant filter repaired wiring to temp sensor replaced temp sensor replaced power outlet in dash and repaired wiring			7009		\$ 5.94 \$ 35.45 \$ 4.94 \$ 0.48
11/18/13		10856 insert 10747 ferrule 90-662 fitting 90-668 fitting 9L8925 bolt TAS000001TRW 1262702 seal				3		\$ 1.26
11/20/13	MPE		replaced bolt in rocker box			2		\$ 0.15
11/22/13	MPE MPE		Repaired power steering leak repaired oil leak on turbo oil return line			2 2		\$ 27.40 \$ 7.13

		6v5266 oring 1142687 o ring 4p3977 gasket 32-20539 invoice #	repaired oil leak on air compressor repaired pto driveline replaced heater core, heater hose adapters				\$ 7.55 \$ 3.41 \$ 7.65 \$ 377.67
11/23/13	ITP peterbilt peterbilt	3x011018 core E38-6085 adapter 9930N 5/8 hose					\$ 0.00 \$ 370.30 \$ 7.40
	Barnes NAPA	4800 brakleen 10742 ferrule	cleaned parts repaired airline				\$ 4.19 \$ 0.92 \$ 0.88
	NAPA	10856 inserts 90662 coupler 90668 adapter	repaired quick connects and airlines				\$ 51.94 \$ 15.72 \$ 0.52
	Barnes NAPA MPE	99722 Lock washer 7151021 Grease Zerk 236577 Gasket	replaced hardware on PTO Driveline 4 replaced broken grease zerk Replaced gasket for air governor				\$ 0.73 \$ 1.09 \$ 36.70
12/10/13	car tunes						\$ 6.14
12/2/13	Barnes	MP11083-4 pipe plug 1" Bridle	repaired glad hands new bridle for truck	2			\$ 178.76
12/9/13	WY Rriging Homax Barnes Peterbilt	1052955-1 15W40 BT4LH-LO zipite HE2277 hose wire loom	replaced oil return line to power steering resevoir	2			\$ 9.38 \$ 0.44 \$ 9.08
		15W40			1		
12/12/13	MPE	4305294 gasket	replaced shift tower gasket inspected and cleaned detent? Ballsn and springs				\$ 4.30 \$ 0.00 \$ 34.48
12/17/13	Barnes	2252-2d divider 81260 blue glad hand 81261 red glad hand	replaced fuel return crossover valve replaced missing airline adapters				\$ 4.52 \$ 4.52 \$ 2.88
	NAPA	11096-2 1/2" nipple 90662 coupler 90664 coupler					\$ 17.32 \$ 17.32 \$ 17.32
12/23/13	Homax	3200-55 coolant 1052955-1 15W40	added coolant added engine oil	1 1.5			\$ 7.64 \$ 9.38

L-528			SAFETY INSPECTION	10/28/2014			
	2001 Peterbuilt		Steer tires 425/65R 22.5				
License	Z022842		Drive Tires 11R 24.5				
2014	Vehicle Maintenance		VIN# 1NP5DB0X61D568114				
I-528	2001 Peterbilt		esn: 6NZ42955				
			STEER TIRES 425-65R 22.5				
	EXPIRES DEC		Drive Tires 11R 24.5				
	Company parts/svcs		SAFETY INSPECTION	10/28/2014			
DATE	Purchased from:	Part #/Description	WORK PERFORMED		MILEAGE	HOURS	COST
1/9/14	Vernal	30' tape measure	tape measure for truck				\$ 10.00
		100' tape measure					\$ 20.00
	WYO rigging	1 1/8" Bridle	Spare bridle for Truck				\$ 209.06
1/11/14		385/65R27.5 Used	replaced left steer tire				
1/13/14	NAPA	1002 Lucas	200 Hour Service			7170	\$ 27.29
	Homax	1052955-1	15W40 Oil				\$ 93.80
	Snow Distributing	02382-120 Grease					\$ 7.74
	MPE	B99 Oil filter					\$ 10.22
		BF 7587 Fuel filter					\$ 9.71
		BF 1259					\$ 8.53
1/22/14	Pacific Steel	3/16 x 2 x 10 flat steel	fabricate new septs / driver side				\$ 16.33
	Barnes	99722 Lock Washer				3	\$ 0.39
		99054 3/8 bolt				2	\$ 0.34
		99055 3/8 bolt				1	\$ 0.16
		99004 1/4 bolt				6	\$ 0.60
		99760 1/4 washer				6	\$ 0.54
		34272 nyloc nut				6	\$ 0.48
	NAPA	R10429 Paint	9213 aluminum paint				\$ 18.65
		RTA9200 Paint	1694 red primer				\$ 11.95
	MPE	560/550M	center mo 6" convex				\$ 29.23
	Vernal		New OSL Sign				
			2536 pin 2				
1/24/14	MPE	MW1209BK	hub cap c				\$ 4.33
2/13/14	Sutherlands	Hub Cap					\$ 10.23
		? Returned some hubcaps					-\$ 18.19
		Hub caps					\$ 24.16
2/5/14	MPE	8080-06	added power service 911 to fuel				\$ 15.83
2/6/14	MPE	PC1479 Starter	replaced starter				\$ 398.95
2/14/14	NAPA	10002 Lucas	200Hour service			7353	\$ 27.29

	Homax	1052955-1 15W40						\$ 93.80
	Snow Distributing	02382-120 Grease						\$ 7.74
	MPE	B99 Oil Filter						\$ 10.22
		BF1259 fuel filter						\$ 9.71
		BF7587 fuel filter						\$ 8.53
		AF25247 Air Filter						
	MPE	873316 Bolt	Replaced damaged bolts in driveline					\$ 8.16
	NAPA	IN910 Plug	repaired flat tire LRI					\$ 0.28
		RA010100 Patch						\$ 1.24
		901001 valve core	replaced core right steer tire					\$ 0.59
	MPE	0R7923 Turbo	replaced turbo charger					\$ 2,443.46
		1262704 seal						\$ 7.20
		1262702 seal						\$ 7.28
		2N2765 bolt						\$ 20.24
		2N2766 Nut						\$ 18.19
		154259 Gasker						\$ 5.93
2/23/14	Sams Club	Washer fluid	filled windshield washer resevoit					\$ 1.87
3/2/14	Snow distributing	02382-120 Grease	greased Truck			7466		\$ 7.74
3/7/14			replaced osha knot and wedges					\$ 75.38
3/10/14	ITP	DRIVELINE FIX	replaced and installed driveline					\$ 1,440.71
			repaired wiring/heated mirror LEFT					\$ 0.00
3/11/14	Barnes	C99562 Fender Washer	repaired passenger door panel					\$ 0.36
4/16/14	Milis Ace	radip stuff?						\$ 64.83
	Stock	3 385-65R-22.5 steer tires	double coin					
		2 counteract balance beads	R&R Steer tires					\$ 984.42
	howard Supply	3/4 winchline 100'						inc
		3/4 tail chain						inc
		3/4 dog knot	#2 winch line	302012		7493	inc	
		1 6" tail board block	put on bed				inc	
4/15/14	Fleet pride	spring hanger for mud flap	for bed truck					\$ 7.72
		6 pin male plug	R&R bed to truck light cord					\$ 7.89
	Basin Auto	AM/FM Antenna	R&R AM/FM antenna					\$ 15.27
		2 5/8 cable clamps	for #2 winch	302012		7493		\$ 3.45
4/18/14	Snow Distributing	02382-120 Grease	200 Hour Service			7501		\$ 7.74
	Homax	1052955-1 15W40 oil						\$ 94.40
	MPE	10002 Lucas						\$ 27.99
		B99 O F						\$ 10.64
		BF957 FF						\$ 3.84
		BF7587 FF						\$ 8.86
	NAPA	7151033 Grease Fitting	replaced greast fitting					\$ 0.73

4/21/14	MPE	K333-67	replaced wiring to temp sender	7503	
			adjusted brakes		\$ 0.00
4/24/14	Vernal stock	30-18	wiper blades		
		TS31	tarp strap for truck		\$ 8.04
4/29/20014	Peterbilt	CVM104 OSL sign	OSL sign for truck		
	MPE	PB22 bolt kit	replaced suspension bolts - rear diff left side	7584	\$ 9.68
		H4656 low beam	replaced driver side low beam		\$ 7.71
5/20/14	MPE	B99	200 Hour SERVICE	7676	\$ 10.64
		BF7587 FF			\$ 8.86
		BF1259 fuel filter			\$ 10.24
		RS3539 Air Filt			\$ 94.82
		10002 Lucas			\$ 27.99
	Homax	1052955-1 15W40			\$ 94.40
	Snow Distributing	02382-120	Greased truck		\$ 11.61
	MPE	392-9131 Hub Seal	replaced hub seal in right front drive axle		\$ 40.43
		4709 brake shoe kit			\$ 54.58
		03-01568 gasket			\$ 4.78
	NAPA	091314 brakeleen	cleaned parts		\$ 2.82
6/17/14			repaired screen in rear window		\$ 0.00
7/17/14	Homax	1052955-1 15W40 oil	added engine oil		\$ 8.92
7/21/14	Vernal stock	OSL sign			
	Barnes	6220 921 bulb	replaced bulbs in roof lights		\$ 1.24
8/11/14	HOMAX	1052955-1 15W40	extra engine oil		\$ 8.92
	overall supply	212 nut/bolt loosener			\$ 10.48
8/18/14			rebuilt air valve #1 winch dogs	7755	
	NAPA	7308 spray paint	painted chains and binders		\$ 11.95
	MPE	37025 protector	corner protector and load straps		\$ 9.00
	Barnes	MP38229 cotter pin	repaired chain hook		\$ 0.05
8/27/14	Snow Distributing	200 silver streak	chain lube for winches		
	NAPA	7703143 helicoil	repaired stripped threads in engine		\$ 3.95
	MPE	FG3168 jig fitting	replaced clutch fan air hose		\$ 9.35
		HE21711 hose			\$ 32.79
	Barnes	BT25-CO Zip tie			\$ 0.84
9/3/14	Peterbilt	20-14898-20L	windshield		\$ 87.60
9/5/14	Class C solutions	10856 insert	repaired airline		\$ 0.44
		10747 ferrule			\$ 0.46
9/5/14	D&H WELDING	FIX CRACKS			
9/8/14	wyo rigging	1" bridle	new bridle for truck		\$ 78.75
9/12/14	mpe	30-18 wiper blades	replaced wiper blades	7850	\$ 178.76
9/17/14	homax	1052955-1 15w40 oil	200 Hour Service	7892	\$ 15.02
					\$ 89.20

	Snow Distributing	02382-120 grease						\$ 7.74
	homax	3200-55 coolant						\$ 14.24
	mpe	10002 lucas						\$ 27.99
		B99 oil filter						\$ 10.54
		BF7587 fuel filter						\$ 8.77
		BF1259 fuel filter						\$ 9.91
	Vernal stock	R53539 air filter	replaced air filters with refurbished ones					
9/19/14	wyo rigging	1" * 180' wire rope	replaced #1 winch line					\$ 828.00
9/21/14	Tire Rama		changed drive tire RRO					\$ 215.25
10/10/14	MPE	AC1002 cartridge	replaced air dryer cartridge				7968	\$ 25.73
10/21/14	Snow Distributing	02382-120 grease	greased truck				7974	\$ 7.74
11/17/14	Fleetpride	1080-06 power service	antigel supplement					\$ 11.51
11/20/14	Class c solutions	C9952 fender washer	repaired driver door panel					\$ 0.27
		6215 194 bulb	replaced bulb in water temp guage					\$ 0.35
	MPE	3050A LED Light	replaced marker lights					\$ 10.06

L-528			SAFETY INSPECTION	10/28/2014				
	2001 Peterbuilt		Steer tires 425/65R 22.5					
License	Z022842		Drive Tires 11R 24.5					
2015	Vehicle Maintenance		VIN# 1NP5DB0X61D568114					
	2001 Peterbilt		esn: 6NZ42955		year end			
I-528			STEER TIRES 425-65R 22.5		327666	8614		
	EXPIRES DEC		Drive Tires 11R 24.5					
	Company parts/svcs		SAFETY INSPECTION	10/06/2015				
DATE	Purchased from:	Part #/Description	WORK PERFORMED		MILEAGE	HOURS	COST	
1/13/15	Homax	1052955-1 15W40	200 Hr service			8113	\$ 89.20	
	Snow Dist	02382-120 grease					\$ 7.74	
	MPE	10002 Lucas					\$ 27.99	
		B99 oil filter					\$ 10.14	
		BF1259 Fuel filter					\$ 9.45	
		BF7587 Fuel filter					\$ 8.86	
	MPE	5632 Airline Antifreeze	air line antifreeze for truck					
2/1/15	Class C Solutions	Nyloc Nut 34274	replaced missing nut/straightened right quarter fender			8160	\$ 0.08	
2/1/15	ghostown	osl sign	new osl sign (2)			8160	\$ 46.18	
2/17/15	WYO Rigging	1" Bridle (2)	new bridle for truck @ 179.21 each				\$ 358.42	
	Class C Solutions	6223 1157 bulb	replaced bulb in right front turn/tightened alternator belts				\$ 0.38	
			repaired swamp side door panel swamp side lowbeam light				\$ 0.00	
2/27/15	MPE	PE27200 receptacle	replaced plug for trailer lights				\$ 7.04	
3/3/15	HOMAX	1052955-1 15W40	200 Hour Service			8293	\$ 85.40	
	Snow Dist	02382-120 Grease					\$ 7.74	
	MPE	10002 Lucas					\$ 27.99	
		B99 oil filter					\$ 10.14	
		B1259 Fuel filter					\$ 9.45	
		BF7587 Fuel filter					\$ 8.86	
3/5/15	MPE	4719 Brake shoe kit	replacedsteer axle brake shoes and drums				\$ 114.12	
		DB1655B Brake Drum					\$ 292.34	
4/27/15		10740 1/4" airline jam nut	airline to fifth wheel missing--replaced		318607	8322	\$ 1.40	
		10745 1/4" compression sleeve					\$ 0.65	
		10853 1 1/4" insert 1/4" airline					\$ 0.24	
		5" 14" airline HE 22051					\$ 2.65	
6/10/15	Stock	11R24.5 Recap	Traction tires 6				\$ 1,360.78	
	Dans tire	2 11r 22.5 recap tires	R&R ALL driver tires				\$ 701.97	
	Peterbilt	2 quarter fenders	R&R Quarte fenders				\$ 114.85	
		mount fenders					\$ 0.00	
6/11/15	Kenworth	water filter head	R&R coolant filter head		319057	8337	\$ 33.94	
6/23/15	Peterbilt	D9027-2830	hardline hose AC				\$ 0.00	

		1917004	Receiver dryer AC				\$ 352.59
	stock	134A refrigerant charge AC	4.302LB 134A				\$ 11.35
		Ester oil	12 oz ac-oil		319992	8360	\$ 8.69
6/27/15	NAPA	25-9490 HD	AC Compressor froxe up, bypass new belts				\$ 39.88
7/6/15	Peterbilt	1CC4696	AC Compressor froxe up, bypass new belts				
		FG2618 o ring HNBR					
		VH11600	o ring kit				
		1917004	Receiver dryer AC				\$ 317.76
		17590 BLT	v Belt				\$ 23.76
		806-0146	Heater & AC control				\$ 365.99
	Vernal		Make repair to AC		321667	8409	
7/15/15	Basin Auto	798857 Seal					\$ 79.72
	Kenworth	heads/injection kit/gasket kit	see invoice copy		322920	8455	\$ 6,499.13
7/16/15	Wheeler	Plate Spacer					\$ 451.49
		paint top coat					\$ 35.65
	kenworth	rod bearings/seals	see invoice copy				\$ 1,690.02
	pilot	solvent			21777		\$ 40.16
7/17/15	Kenworth	orings/oil pump					\$ 575.10
7/17/15	Wheeler	Liner and ORING set	160-9874/177-7496/176-5749/189-9771				\$ 38.18
			177-7496/176-5749/189-9771				\$ 97.76
7/21/15	Wheeler	thermostats	5E-8771/247-7133 oring and regulator				\$ 106.20
7/22/15	Six States	oil seals	CH2-P-207 Shaft Rail Seal, CH28-P-219 PTO seals				\$ 126.51
	Kenworth	SEAL 5P5678					\$ 35.54
	shop	fs1000	SERVICE DUE AT 8493		?		
		fs319					
		lf691A					
		rs3539					
		15-40 oil					
		antifreeze					
7/21/15	Kenworth	Manual					\$ 737.42
7/23/15	Kenworth	solenoid 993296	replae 2 of 6 cylindersR&R engine fan				\$ 123.24
7/29/15	Fleetpride	Strap Winder	tie down strap winder				\$ 7.32
7/6/15	Fleetpride	4" x 30' Winch Strap W flat Ho			10		\$ 130.28
7/31/15	Peterbilt	BS1989 bugscreen	bug screen				\$ 42.09
		S2129 Assy Tower	R&R Shift tower assy				\$ 197.50
8/17/15	Peterbilt	Mudflap A35RL200 arm					\$ 41.91
		A25RL00	mudflap hanger arm				
	stock	10R24.5	1 recap traction tire				
8/6/15	Dans Tire	tire repair					\$ 42.54
8/28/15	Anderson Service	Tire repair					\$ 15.89

8/14/15	RJ's tire	wheel assembly					\$ 40.00
8/8/15	Main Street Auto	taps					\$ 46.47
9/17/15	Kenworth	Battery bt31591	R&R battery			8607	\$ 97.36
10/13/15	Basin Auto	primer gray/TAP 5/16-18	paint headache screen/tap screen holes				\$ 20.75
	Stock	10 5/16x1 bolts	attach screen to headache				
10/6/15	vernal	safety inspection					\$ 15.00

L-528			SAFETY INSPECTION	10/28/2014				
	2001 Peterbuilt		Steer tires 425/65R 22.5					
License	Z022842		Drive Tires 11R 24.5					
2017	Vehicle Maintenance		VIN# 1NP5DB0X61D568114					
	2001 Peterbilt		esn: 6NZ42955			beginning		
L-528			STEER TIRES 425-65R 22.5					
	EXPIRES DEC		Drive Tires 11R 24.5			end		
	Company parts/svcs		SAFETY INSPECTION	2/21/2017				
DATE	Purchased from:	Part #/Description	WORK PERFORMED		MILEAGE	HOURS	COST	
1/1/17			beginning miles					
2/2 1/17	Inspection				327683			\$ 15.00
3/1 1/17	Rush Truck Center		Cooler charge Air/Cooler charge air core/chg air 4x6					\$ 1,622.29
		core credit						-\$ 283.29
3/3/17			tested batteries				8630	\$ 0.00
	snow Dist	02382-120 grease	greased truck					\$ 7.74
			replaced buibs in both front turn signals					\$ 0.00
			repaired light in drivr door					\$ 0.00
		3704 orange flag	flags for oversize loads					\$ 7.80
3/1 1/17	Fleetpride	F166000031B4136	replaced pump hose clamp				8682	\$ 7.11
	Rush Truck Center	087923 turbo charger	replaced turbo charger, attaching hardware and gaskets					\$ 2,600.47
	MPE	1262702 seal						\$ 8.16
		1986068 seal						\$ 7.71
		154295 gasket						\$ 6.80
		2N2766 nut						\$ 20.79
		5H7704 seal						\$ 20.20
		2N2765 bolt						\$ 36.79
	Rush Truck Center	F31-6049 cac	replaced charge air cooler and hump hoses					\$ 1,228.93
		7715-0002 hose						\$ 110.08
3/14/17	MPE	4656 low beam	replaced swamp side headlight				8707	\$ 7.71
3/16/17	snow Dist	02382-120 grease	250 hour service				8745	\$ 7.74
	Homax	1078334-1 15W40						\$ 88.44
	MPE	B5134 coolant filter						\$ 6.30
		B99 oil filter						\$ 10.96
		BF7587 fuel filter						\$ 9.32
		BF1259 fuel filter						\$ 10.69
		1002 Lucas	Tightened yoke on #2 carrier bearing					
3/23/17	Phillips 66 longmont CO	2 tail lights and 1 external CB speaker						\$ 44.97
4/4/17	Kenworth	Clutch rebuild	clutch assy, cross shaft bushings, bearing, clutch brake ect					\$ 805.08
	six states	transmission	replaced transmission					
	MPE		resurface flywheel					\$ 65.10

		250-70-18X kit bearing							\$ 19.45
		EC50PLA	exhaust clamp						\$ 37.21
	advanced hydraulics	328170-76X stud kit							\$ 5.95
	MPE	4305310-09 gaskets							\$ 24.34
	kenworth VERNAL	pilot bearing/flex pipe							
	Homax	1054003-20 50 Wt oil	filled transmission with oil						\$ 121.20
	Class C sol	10745 ferrule	repaired airline						\$ 0.32
		99027 5/16 bolt	replaced bolts						\$ 0.32
	fleetpride	misc parts	shut off cock, flag magnet, hose extension, warning flag						\$ 80.58
5/4/17	snow Dist	02382-120 grease	greased tricl/adjusted brakes						\$ 3.87
	MPE	SPL250-3x u joint	replaced u-joint and strap kit on front of input				8924		\$ 197.15
		250-70 strap kit							\$ 19.44
6/13/17	class C sol	6223 1157 bulbs	replace right front turn signal bulb and adjustee belts						\$ 0.38
6/14/17	Snow dist	22382-120 grease	greased truck and adjusted brakes						\$ 7.74
	MPE	AC1002 cartridge	changed air dryer cartridge						
6/16/17	snow Dist	02382-120 Grease	greased truck and adjusted brakes				8951		\$ 3.87
	NAPA	901001 valve core	replaced valve core RFI drive tire						\$ 0.62
	class C sol	6220 921 bulb	replaced roof light bulb						\$ 0.62
6/27/17	Homax	1078334-1 15W40	250 hour service				9016		\$ 83.00
	snow Dist	02382-120 grease							\$ 7.74
	MPE	1002 Lucas							\$ 29.40
		B99 Oil Filter							\$ 10.95
		BF7587 fuel filter							\$ 9.33
		BF1259 fuel filter							\$ 10.69
7/3/17	snow Dist	02382-120 grease	greased truck and adjusted brakes						\$ 3.87
	MPE	3651898 wiper	replaced wiper blades						\$ 12.35
7/17/17			repaired air cylinder for grill guard				9117		\$ 0.00
	MPE	A25RL200 ARM	replaced mud flaps and hangres						\$ 23.86
		2430-2GK mudflap							\$ 35.26
	class C sol	2522 hairpin clip							\$ 0.86
7/27/17		11R24.5 run out	replace tire LRO						
	Vernal		1/2 ratcher biner for truck						
		1" * 175 wire rope	replaced winch line						
			replace 5th wheel plate						
8/2/17	MPE	VL2443 valve	replaced leasing coolant valve				9230		\$ 26.54
	Homax	3200-5 coolant							\$ 8.18
	vernal	385-65R22.5 tire	replaced steer tires			344122			
	snow Dist	02382-120 Grease	greased truck and adjusted brakes/repaiared tailboard						\$ 3.87
8/10/17	Homax	1078334-1 15W40	250 hour service				9274		\$ 83.00
	snow Dist	02382-120 Grease							\$ 3.87

	MPE	1002 Lucas						\$ 29.40
		B99 Oil filter						\$ 10.95
		BF7587 Fuel filter						\$ 9.33
		BF1259 fuel filter						\$ 10.69
	NAPA	97618 mirror	replaced driver side convex mirror					\$ 14.02
8/16/17	Fleetpride	15-720 7 pin receptacle						\$ 6.69
	MPE	AP2157 adapter	replaced secondary air glad hands w/quick connects					\$ 10.88
		FG24481 ferrule						\$ 1.20
		HE2260 3/8 airline						\$ 5.50
	NAPA	90-664 coupler						\$ 34.63
8/26/17	snow Dist	02382-120 grease	greased truck and adjusted brakes					\$ 3.87
9/1/17	VERNAL	11R24.5 RECAP	replaced 4 tires on front drive axle					
	Big Horn Tire	11R24.5 REACP	2 of the 4					\$ 1,032.88
9/3/17	snow Dist	02382-120 Grease	Greased/Adjusted brakes, rotated new tires to REAR Drive Axle			9351		\$ 3.87
			repaired quarter fenders					\$ 0.00
9/8/17			test batteries, starting/charging system			9404		\$ 0.00
	Snow	02382-120 Grease	grease/adjusted brakes					\$ 3.87
	class C sol	71415F conector	repaired wiring to front diff temp sensor					\$ 0.48
	MPE	AS7004 Seal	Replaced front diff input seal					\$ 32.92
	Fleetpride	Battery	Replaced two batteries					\$ 194.96
	MPE	4651 high bean	replaced swamp side headlight					\$ 10.57
		4656 low beam	replaced driver side headlight					\$ 7.71
9/13/17	Clacc C	6220 921 bulb	replaced map light bulbs			9420		\$ 1.24
		6223 1157 bulbs	replaced left front marker/turn light					\$ 0.38
	NAPA	7 A Fuse 782-1044	replaced CB fuse					\$ 0.63
	Fleetpride	15-720receptacle	Replaced 7 pin trailer receptacle					\$ 6.75
	class C sol	34272 1/4 nyloc	installed 7 pin trailer recept					\$ 0.08
		99004 1/4 bolt	installed lock bolts w mudflap hangers					\$ 0.18
	MPE	243012GK mudflap	replaced left rear muflap and hangr					\$ 17.63
		A25RL200 hanger						\$ 11.93
		99056 3/8 bolt						\$ 0.92
		34274 3/8 nuloc						\$ 0.20
9/18/17	Snow	02382-120 grease	greased/adjusted brakes			9420		\$ 3.87
10/6/17	MPE	243012GH Mudflap	replace left rear mudflap					\$ 17.63
10/10/17	NAPA	90-664 coupler	replaced quick coupler and glad hand			9488		\$ 17.32
	class C sol	81261 glad hand	emergency airline					\$ 4.70
		2015 ferrule	repaired trailer cord plug					\$ 2.32
10/17/17	Homax	1078334-1 15W40	250 Hour service			9515		\$ 83.00
	Snow	02382-120 Grease						\$ 3.87
	MPE	10002 Lucas						\$ 27.93

		B99 OF						\$ 10.95
		CBF 1259 FF						\$ 10.69
		BF7587 FF						\$ 9.33
	class C sol	6220 921 bulb	replaced roof light bulbs (2)					\$ 1.24
11/13/17			tested batteries and alternator			9526		\$ 0.00
	MPE	8600064 alternator	replaced alternator					\$ 398.73
11/16/18	MPE	FG2429 fitting	replaced hoseend fittings on emergency & service airlined			9536		\$ 15.62
	Fleetpride	15-730 7 pin	replaced pluc on trailer cord					\$ 7.93
11/28/17	MPE	PAC24X30-9	mudflap					\$ 146.92
		A25RL200	mudflap arm				inc	
		513020PCR	ratchet straps				inc	
12/14/17	Peterbilt	905200-32 FAN	Engine fann					\$ 198.75
12/18/17	Peterbilt	D01H02905200-32	replace engine cooling fan					\$ 198.75
12/18/17	stock	2.5" silicone hose 8"	Replace upper radiator hose segment					\$ 13.06

2018	Vehicle Maintenance		VIN# 1NP5DB0X61D568114				
	2001 Peterbilt		esn: 6NZ42955	beginning			
L-528	EXPIRES DEC		STEER TIRES 425-65R 22.5				
	Company parts/svcs		Drive Tires 11R 24.5	end			
			SAFETY INSPECTION 12/6/2018				
DATE	Purchased from:	Part #/Description	WORK PERFORMED	MILAGE	HOURS	COST	
1/1/18			beginning miles				
12/18/17	peterbilt	Fan D01 H02 905200-32	Replace engine cooling Fan			\$ 198.75	
12/18/17	Stock	2.5in silicone hose	Replaced upper radiator hoses				
1/19/18	Peterbilt	PE13050 hose/cord combo	Assemble extra airline/light cord			\$ 148.99	
1/19/18	Peterbilt	IMX-5331A gladhand red (1)				\$ 3.79	
1/19/18	Peterbilt	IMX-5332A gladhand blue (1)				\$ 3.79	
		PE13050 15 Ft Hose	NOT ON VM LOG from Bubba! Invoice CP390689			\$ 148.99	
1/19/18	stock	90-668 air quick coupler (4)				\$ 4.29	
1/19/18	stock	90-664 air quick coupler (2)				\$ 5.24	
1/23/18	stock	washer fluid (1) gal					
1/29/18	stock	WD-40 (1) can				\$ 6.49	
1/29/18	stock	(6) bungee straps					
2/1/18	NAPA	LED S/T/T Grommet	Not on VM???			\$ 21.42	
2/7/18	MPE	BK313 Brake clutch	not on VM???			\$ 23.76	
2/12/18	Peterbilt	Toggle Switch 577.75611				\$ 24.08	
2/21/18	Justin Phillips	Clutch Adjustment	paid cash by Scotty			\$ 150.00	
21-Feb	Stock/Shop	Pigtail plug	wired in new pigtail	360941	9897		
21-Feb	None	N/A	weld broken fender brackets	360941	9897		
21-Feb	Vernal stock	CB radio	install new CB radio	360941	9897	In stock	
6-Mar	shop	tail roll seized	freed tail role	361388	9911		
6-Mar	shop	broken air valve	removed air valve to quick connects	361388	9911		
6-Mar	shop		new license plate bracket (welded on)	361388	9911		
6-Mar	Motor Power	aluminum oversize load sign	mounted new oversize load sign	361388	9911	\$186.43	
6-Mar	Napa	wing nuts	wing nuts to hold sign	361388	9911	\$9.04	
3/20/2018	Fleet Pride	convex mirror & extensions	replaced mirrors and extensions	362964	9962	\$76.45	
3/20/2018	Shop		adjusted braks	362964	9962	\$0.00	
3/20/2018	Shop		greased winch	362964	9962	\$0.00	
3/23/2018	walmart	am/fm radio				\$93.45	
3/27/2018	Shop	Broken wiper blade	tightened bolt to wiper blade	363404	9982		
18-Apr	DTI	alt pully	replaced alt. pulley	365957	10004	\$98.49	
18-Apr	Shop		Adjuste brakes	365957	10004		
18-Apr	Shop		Checked fluid levels	365957	10004		
27-Apr	Shop	Turbo is out	Checked tubo	365957	10004		

30-Apr	Kenworth VERNAL	Turbo fix		fixed Turbo				\$3,412.37
1-May				turbo core return				-\$1,186.60
2-May	midwest hose	Turbo		Changed turbo	364254	10018		\$333.00
2-May	midwest hose	fuel line		changed fuel lines				\$45.80
2-May	Kenworth (vernal)	hose fittings		Jic hose fittings				\$2,015.79
2-May	Kenworth (vernal)	Turbo		replaced turbo				\$33.52
2-May	Kenworth (vernal)	Turbo Bolts		replaced turbo				\$18.96
2-May	Kenworth (vernal)	Turbo Nuts		replaced turbo				\$7.44
2-May	Kenworth (vernal)	oil seal		replaced turbo				\$7.03
2-May	Kenworth (vernal)	seal		replaced turbo				\$6.20
30-May	Kenworth (vernal)	Turbo Gasket		replaced turbo				
4-Jun	Shop	Tail lights		fixed tail light issues				
4-Jun	shop	door handle		replaced missing bolts				
5-Jun	peterbuilt	hood hinge		replaced hood hinge bolt				\$27.54
19-Jun	shop/stock	air filter		changed both engine air filters RS 3539	366207	92		
19-Jun	shop/stock	waiste gate		freed up waiste gate from sticking	366207	92		
19-Jun	shop/stock	oil filter B 99		250 hour service	366207	92		
19-Jun	shop/stock	fuel filter BF 1259		250 hour service	366207	92		
19-Jun	shop/stock	Fuel Filter BF 7587		250 hour service	366207	92		
19-Jun	shop/stock	10 gallons 15-40		250 hour service	366207	92		
19-Jun	shop/stock	checked fluid levels	250 hour service added transmission oil 1/2 gallon 50 UT		366207	92		
19-Jun	shop/stock	marker lights		fixed short	366207	92		
19-Jun	shop/stock	grease		greased truck	366207	92		
19-Jun	shop	brakes		adjusted brakes	366207	92		
26-Jun	DTI	Front shocks		replaced front shocks	366207	92		130.66
26-Jun	shop	brakes		adjusted brakes	366207	92		
28-Jun	peterbuilt of wyoming	A.C Line		replaced A.C line	366207	92		191.4
28-Jun	Shop	Charged A.C		Charged A.C	366207	92		
14-Aug	Shop/Stock	11 R 24.5 Drive Tire		Changed Rear, Right inside tire	367038	O147		
14-Aug	Shop/Stock	Greased 2 Tubes		Greased Truck	367038	O147		
14-Aug	Shop	Inspected		Checked fluid levels, drive lines & suspension	367038	O147		
14-Aug	Shop	A/C		Charged A/C	367038	O147		
4-Sep	Shop/Stock	11 Gallons 15/40		Changed oil	369400	10227		
12-Sep	Vernal Wheeler Machinery	230-3726 Seal 6 each		replaced seal and orings in injectors	369400	10227		\$7.12 each
12-Sep	Vernal Wheeler Machinery	230-3775 Seal 6 each		replaced seal and orings in injectors	369400	10227		\$9.29 each
12-Sep	Vernal Wheeler Machinery	9x-7317 o-ring 6 each		replaced seal and orings in injectors	369400	10227		\$3.67 each

12-Sep	Shop/Stock	oil filters LFP-4005	Replaced oil filter	369400	10227	
12-Sep	Shop/Stock	11 Gallons 15/40	changed oil	369400	10227	
12-Sep	Shop	adjusted valves	ran over head	369400	10227	
13-Sep	Shop	1.5 Can grease	Greased truck	369400	10227	
13-Sep	Peterbuilt of Wyoming	Radiator Rubber Bushings	Replaced radiator right side rubber bushings	369400	10227	\$25.52
13-Sep	Peterbuilt of Wyoming	Hood pivot bushing kit	replaced hood pivot bushings on left side	369400	10227	\$12.48
25-Sep	Peterbuilt of Wyoming	Pressure Valve & oring	return line pressure valve and oring replaced	364642	10240	\$ 36.42
26-Sep	Vernal Wheeler Machinery	230-3726 Seal 6 each	removed & replaced injector seals	369642	10240	\$ 42.76
26-Sep	Vernal Wheeler Machinery	230-3775 Seal 6 each	removed & replaced injector seals	369642	10240	\$ 56.74
26-Sep	Vernal Wheeler Machinery	9x 7317 o-ring 6 each	removed & replaced o-rings in injectors	369642	10240	\$ 22.02
26-Sep	Midwest hose	return hose	replace return fuel line from filter house	369642	10240	\$ 15.93
26-Sep	Peterbuilt of Wyoming	Pressure Valve to return fuel	replaced fuel pressure valve & o-ring filter housing	369642	10240	\$ 36.42
9/5/18	Fleet Pride	7way zinc plug				\$ 8.09
10/17/18	MPE	Injector Cup	replaced injector cups	370351	10276	\$ 1,740.21
10/31/18	Peterbilt	lift pump	replaced lift pump			\$ 182.77
1-Nov	Motor Power Kenworth	Oil Filter B99	Changed oil filter	370351	O275	\$11.07
1-Nov	Shop/Stock	11 Gallon 15/40	Changed Oil	370351	O275	
4-Dec	Shop	Annual Inspection	Performed annual inspection	372043	O330	
4-Dec	Shop/Stock	Marker Light	Replaced marker light bulbs	372043	O330	
4-Dec	Shop/Stock	Blinker Light	Replaced left front blinker bulb	372043	O330	
4-Dec	Shop/Stock	Marker Light	Replaced marker light on headache rack	372043	O330	
11/12/20189	VERNAL SHOP					
	Wheeler	10R8501/10R8501 injectors	R&R #2 and 4 injectors			\$ 554.52
						\$ 554.52
		Bolt	injector hold down bolt			\$ 1.36
11/16/18	fleet pride	B-99 oil filter/fuel/separator	oil filter	370827		\$ 31.25
11/19/18	Stock	15-40 oil	11 gal motor oil			
11/12/18	691A STOCK	LF691A Oil Filter				
11/12/18	Stock	15-40 motoroil	11 gal motor oil			
11/20/18	Kenworth	Set new injectors-codes	trim codes #2&4 injectors	370877	292	\$ 112.83
11/26/19	Stock	471231V seal	2 seals #1 winch PTO shift rail seals			
11/26/19	Fleelpride	Air Dryer Cartridge	R&R Air Dryer Cartridge			\$ 41.58
12/3/18	Fleelpride	ratchet straps				\$ 31.94
11/15/18	Wheeler	Injectors				\$ 800.04
		injectors				\$ 798.59
11/26/18	elko wire rope	ratchet binder/leg chain/grab hooks				?
11/14/18	main street	leak detect dye oil				\$ 7.93

11/8/18	main street	leak detector kit/dye						\$ 36.96
11/15/18	Oreilly	dye cleaner						\$ 15.53
10/29/18	Main street	leak dye detect						\$ 7.93
12/26/18	Six Robles	Ratchet Straps						\$ 86.00

2019	Vehicle Maintenance	VIN# 1NP5DB0X61D568114				
	2001 Peterbilt	esn: 6NZ42965	beginning			
L-528		STEER TIRES 425-65R 22.5	373745			
	EXPIRES DEC	Drive Tires 11R 24.5	end			
	Company parts/svcs	SAFETY INSPECTION 12/6/2018	401871			
	DATE Purchased from:	WORK PERFORMED	MILEAGE	HOURS	COST	
MILEAGE			373745	10437		
10-Jan	Shop	Winch Shift Cable	373745	10437	\$0.00	
10-Jan	Shop	Winch Chain	373745	10437	\$	
10-Jan	Shop	Winch Chain tensioner bushings	373745	10437	-	
10-Jan	Shop	Spot Mirrors	373745	10437	\$0.00	
21-Jan	Shop	Tool Box Door	374573	10466	\$0.00	
22-Jan	Shop	Winch Chain tensioner	374573	10466		
23-Jan	Shop	Brakes	374573	10466	\$0.00	
23-Jan	Shop	Greased	374573	10466	\$0.00	
30-Jan	Shop	filters	374573	10466		
1/25/19	ITP	BUSHING			\$ 17.87	
2/12/18	Hat Six Travel	Airlines	NOT ON LOG		\$ 119.66	
2/18/19	Fleet Pride	Halogen bulb/Convex Mirror	NOT ON LOG		\$ 31.07	
2/22/19	Fleet pride	flag magnets - 4/ orange flags-	NOT ON LOG		\$ 44.78	
2/23/19	Napa	GD BOOT	NOT ON LOG		\$ 4.58	
3-Mar		Grease	Grease tail role cleaned 5th wheel plate and greased			
	used plug in for trailer shop stock		Replaced upper female electric plugin			
8-Mar			adjusted brakes, greased			
4/3/19		? No parts listed	fabricated PTO cable, mounting brackets to install new cable			
			installed new cable. Greased. Repaired fuel leak on top			
			of transmission. Cleaned all battery terminals. Repaired			
			grease zerks that wouldn't take grease.			
4/29/19	Fleet Pride	Poly guard and spring hanger	? Not on VM Log		\$ 43.40	
5/17/19	Six States	PTO CONTROL CABLE	NOT ON VM LOG		\$ 178.52	
5/20/19	NAPA	FILTER-- WHAT Part #	Service and Greased	384100?	8656	\$ 138.11
28-May	Fleetpride	250-70-18X U joint retainer kit	?		43.7	
		SPL250-3X U joint	not on maintenance?		151.14	
	SHOP	Brass 4 Fitting-no part # to look up	fan clutch stuck on		?	
	Peterbilt WY	Assy wiper arc	fixed wiper arm		132.29	

	ITP	Nut M48 1.5-6H	nut yoke				\$41.94
29-May	SHOP	no parts listed	Fixed hanging lights and wiring hanging on door				\$0.00
20-May	Napa	Filter	Serviced and greased	3841100	O8656		\$138.11
28-May	Fleetpride	U-joint stap kits	Strap kits 864 250-20-18X				\$ 43.70
28-May	Shop	Brass 4 Fitting	Fan Clutch stuck on				
28-May	R23-6002	Wiper Arm	Wiper Arm Fix				\$132.29
28-May	M481-5-6H	inland truk	nut yoke				\$39.43
29-May	Shop	Shop	Fixed hanging lights				
29-May	Shop	Shop	Wiring hanging on door				
18-Jul	Shop	Shop	Charged the A/C				
6/24/0018	MPE	Antenna CB					\$137.82
	fleet	flags/magnets					\$27.35
26-Jun	Napa	filters					\$36.51
6.27/2019	Midwest hose	Hydraulic hose	return fuel line on motor				\$28.65
13-Aug	Napa	Fuel filter					\$13.84
20-Aug	Fleetpride	cotitech air spring					\$135.33
26-Aug	Napa	Slack Adjuster					\$104.99
30-Aug	Peterbilt	Fuel cap					\$90.88
20-Sep	DRB Welding	Welding	5" Exhaust stacks @ 40 degree angle and labor				\$52.50
23-Sep	Greased Tractor	Greased	Greased tractor balanced tires	395551	13345		shop
23-Sep	2 light bulbs		replaced light bulbs	395551	13345		shop
24-Sep	2 hoses midwest hoses	1/2 and 3/4 hoses	replaced power steering hoses	395551	13345		\$46.20
24-Sep	MPE Motor Power Fenders	Axel Fenders	Axel Fenders	395551	13345		\$73.49
24-Sep	MPE Motor Power	6" oval amber PFT lighting	amber lights	395551	13345		\$21.24
24-Sep	Six Robbles	flag magnets					\$95.66
26-Sep	Air Back	Air back	Rear airbag replaced very rear driver side	395551	13345		\$136.24
20-Sep	5" Exhaust	5" exhaust	replaced exhaust stacks	395551	13345		\$52.50
24-Sep	u-joint seal	u-joint seal	replaced seal, u-joint	395551	13345		\$179.76
24-Sep	seal-oil nut-yoke	oil back up light, nut	replaced seal, u-joint	395551	13345		\$129.48
11-Sep	Napa	Wiper Blades	Replaced window wipers				\$23.94
13-Sep	Motor Power	Marker Lights	Replaced marker lights				\$ 39.29
9-Feb	Shop		Change fuel, oil, and air filters grease tractors	396456	1384		
8-Oct	Shop		Antifreeze test -20 degrees	396456	1384		
7-Oct	DFS Supplement	fleet pride	added to fuel tanks	396456	1384		\$34.64
8-Oct	Shop		Cleaned batteries/spray protectant	196456	1384		
11-Oct	steer axel/slack adjuster	M807002 slack adjuster	replace slack adjuster driver side steer axel	196456	1384		\$91.11
31-Oct	Shop		Grease tractor, check oil/fluids, tire pressure	397325	1433		
1-Nov	Napa	batteries	check tire pressure/oil/fluids and replace batteries	397325	1433		\$367.46
7-Nov	Shop		Greased tractor checked oil/fluids and tire pressure	398427	1471		

8-Nov	Shop	CD Player	Replaced CD Player in tractor			
13-Nov	Shop		Greased tractor checked oil/fluids and tire pressure	400371	1522	
13-Nov	Shop	Quick Connect	Replaced service quick connect			
14-Nov	Peterbilt Vernal	fender quarter	installed to save back windows			\$83.65
4-Dec	Peterbilt of WY	993272 seloniod	Replaced valve solenoid	401851	1600	\$149.09
5-Dec	Peterbilt of WY	Sensor temp/seal	replaced temp sensor and seal on tractor also greased	401581	1600	\$ 44.15
19-Dec	Fleet Pride	Diesel clean, signal, red lamp	greased, change rear right turn signal light, checked lights	401870	1608	\$31.85

2020	Vehicle Maintenance		VIN# 1NP5DB0X61D568114			
	2001 Peterbilt		esn: 6NZ42955	beginning		
L-528			STEER TIRES 425-65R 22.5	401870		
	EXPIRES DEC		Drive Tires 11R 24.5	end		
License			SAFETY INSPECTION			
	Company parts/svcs		Axle Spacing			
DATE	Purchased from:	Part #/Description	WORK PERFORMED	MILEAGE	HOURS	COST
20-Jan	Shop		grease job, checked lights, checked fluid levels and checked tire pressure	402239	1629	\$0.00
27-Jan	Napa	filters	oil change, grease job, checked lights, tire pressure and fluid levels	404656	1703	\$ 54.72
27-Jan	Shop	homax	11 gallons of oil used			\$102.52
1/31/20	wear parts	pb blaster	2 cans			\$ 10.98
2/15/20	Dans	10 tires	8 11R24.5 tires/ 2 275/70R22.5 tires			\$ 3,052.00
21-Feb	Napa		Fastened 2 mud flaps	405001	1727	\$35.68
21-Feb	Shop	Shop Stock	removed and replaced 8 tires			
21-Feb	Shop	Shop Stock	8 bolts and nuts, 16 washers and 2 mud flaps hanger			
27-Feb	Napa		1 box of dust mask and sanded bumper			\$8.49
1-May	Shop Stock	wheel seal kit	removed and replaced wheel seal on rear axle passenger side	405219	1740	
1-May	Napa		2 cans of braklen, 1 oil gun and 1 silicone tube			\$ 31.35
13-May	Fleetpride		1 air bag			\$120.50
13-May	Shop		removed and replaced air bag on middle axle passenger side			
23-Dec	Shop		cleaned air filters	407943	1831	

