

2013	Vehicle Maintenance	Vin# 1NP5LBEX05D843607			
L-532 License	2005 Peterbuilt Z020026	Steer Tires 425/65R22.5 Drive Tires 295/75/22.5 Tag Tires 12R24.5			
DATE	Company parts/svcs purchased from	Part #/Description	WORK PERFORMED	MILEAGE	HOURS
1/30/13	MPE	FG3976 1/2" union	repair air leak		COST \$ 10.21
1/30/13	MPE	LABOR	checked suspension for noise...N/A, inspected king pins, spring pins and shackles		\$ 586.69
1/30/13	MPE	recommendations	RECOMMENDS GREASING MORE OFTEN		Inc
2/14/13	Shop	LABOR	inspected shift assembly --wrong position		Inc
		Grease 02382-120	inspect vehicle and make ready for new driver		\$ 0.00
		R955342 sensor	Grease Truck		\$ 12.25
		BT4LH-CO, BT4s-CO, BT25-CO	replaced ABS sensor on right rear drive axle		\$ 77.27
			Zipties (2,1,3)		\$ 0.50
2/18/13			Checked Tire pressure		\$ 0.00
	MPE	Sensor 2244535	Replace OSHA Knot (1) and Wedges(1 #8 4076282 \$41.50 Bishop) on #1 Winch		
		seal 5P7814	replaced sensor/intake valve oil pressure		8793 \$ 179.39
	Shop		" " "		inc
		11R22.5 runout	1" Shackle		
3/6/13	MPE	MW1103BK/MW1209BK	repaired wiring for AC		\$ 0.00
		KO22105BXW	replaced RRO Tire		\$ 195.43
		2 osl signs	replaced hub cap on steet and drive axles		\$ 26.25
3/18/13		10 amp ato fuse 7558-A	replaced purge valve	2	\$ 109.18
3/18/13	MPE	5004049BXW			
		1 roll duct tape	replaced governor and checked valve		\$ 74.22
3/21/13	ITP	98-09227			
	Tire Rama	flat repair	PADS- replaced brake pads on #1 winch back up brake		\$ 96.00
	Barnes	99031 99781	repaired L tire		\$ 36.75
	NAPA	90-100-1	replaced bolt 99031 and nut 99781 on mudflap 2 each		\$ 0.86
	Barnes		replaced valve core on LRO Trie		\$ 0.59
4/1/13	Wyoming Rigging	1" OSH knot	replaced mudflap hardware		
	Wyoming Rigging	1" Bridle	replaced bridle and OSHA knot (2)		\$ 107.42
4/5/13	ITP	28P218 Seal	repaired leaks on PTO (2)	86764	\$ 75.38
	ITP	ECB200	replaced clutch brake		8854 \$ 17.46
					\$ 29.45

		MP38239 cotter pin	1			
4/10/13	Peterbilt	LF691A	250 HR service		8878	\$ 10.41
		FF105				\$ 3.74
		FF5319				\$ 8.39
	NAPA	Lucas 10002				\$ 37.79
		air brake antifreeze	1			
	HOMAX	15W40	10 gal			\$ 93.30
	Snow Distributing	Grease 02382-120				\$ 15.48
	Peterbilt	14-14656-4 bushing	replaced upper exhaust mounts on driver side			\$ 67.24
	Fleetpride	7400Bulb	replaced bulbs in beacons(2)			\$ 23.75
4/11/13	Barnes	KP81235/KP86914 Seals	repaired wiring to power divider 2 each			\$ 1.20
	NAPA	DA1620 Spray paint	paint chasis and binders			\$ 11.95
	Barnes		fender washer 4			
	MPE		airline antifreeze			
	Barnes		replace hardware on exhaust	2		\$ 1.36
	Barnes	99060 BOLT		2		\$ 0.64
		99722 lock washer		2		\$ 0.28
		99782 Nut		3		\$ 0.12
4/11/13	Wyoming Rigging	1/2" X 15'-3.5" C	Chain Sling			\$ 585.00
4/21/13			Repaired tire cahins 9' square link tire chain			
4/22/13	two way radio	labor	trouble shoot radio --checked out fine could not duplicate problem			\$ 44.63
4/23/13		chain sling		1		
4/29/13	MPE	AS1033	slack adjuster---replaced adjustor and clevis		8973	\$ 86.84
	MPE	Clevis	right rear drive axle			\$ 11.19
4/29/13	Wyoming Rigging	5724815 1/2" Hook	repaired lifting sling--campbell clevis grab hook grade 100			\$ 53.70
		KHSW13610 1/2 hooks	Pewag clevis sling hooks(2)			\$ 127.25
		Winch Line	1" X 175' replaced #2 Winch line			\$ 863.63
	Barnes	MP38239 Cotter Pin	replaced cotter pin in P70 linkage			\$ 0.81
5/1/13	D&H Welding		fabricatd d bar			\$ 385.88
5/7/13	shop		adjusted clutch			\$ 0.00
	NAPA	90180 CAP	replaced valve cap LRI & LRO 2			
6/6/13	Snow Distributing	Grease 02382-120				
6/16/13		Chain sling	Put 1/2" chain sling on truck			\$ 221.03
7/2/13	Wy rigging	1" Bridle	new bridle for truck			\$ 107.42
7/10/13	MG Oil	02382-029 grease	Grease Truck 2 tubes			\$ 8.92

7/15/13	NAPA	Sun Shade						\$ 10.19
7/30/14	BARNES	MP38226 Cotter Pin				2		
7/31/13	WRIS		ferrule/wedge/tail chain					\$ 488.72
8/6/13	Snow Distributing		Grease Truck					\$ 11.81
9/9/13	Sams Club	glass cleaner						9066 \$ 220.00
	MPE	B99 filter	250 hour service					9084 \$ 10.22
		BF957						\$ 3.77
		BF7587 filter						\$ 8.52
	Homax	1052955-1 15W40 oil						\$ 91.30
	NAPA	10002 Lucas	38 Pts					\$ 37.79
	Snow Distributing	Grease 02302-120	grease truck					\$ 7.74
	Peterbilt	WF2077 Filter	changed coolant filter					\$ 5.94
	Homax	1054009-20 50W+	filled aux trans					
10/10/13	Wyo Machinery	5L25952 oil cap	replaced oil fill cap					9058 \$ 22.50
	NAPA	90180 Valve cap	replaced missing valve caps	2				
10/21/13	MPE	AC1001 cartridge	replaced air dryer cartridge					9093 \$ 18.43
	Barnes	34274 nyloc	retaining hardware for gin pole pins	2				\$ 0.16
	Barnes	99060 3/8 bolt		2				\$ 0.64
10/22/13	MPE	2201206 hose	replaced oil return line on compressor					9093 \$ 26.66
11/1/13	Auto Glass Pro	rear sliding windows						\$ 115.50
11/4/13	WV Rigging	1 1/8" Bridle	new bridle for truck					\$ 165.38
11/11/13								
11/13/13	MPE	H4656 Headlight	replaced low beam headlights					\$ 15.41
11/29/13	NAPA	091842 Brakelee	cleaned hub and spindle--right rear drive					\$ 2.30
	Vernal	370120A Seal	replaced wheel seal					
	ITP	BN3-4708PC Brake Shoe	replaced brake shoes					
		60202C Light	replaced right rear S/T/T Light brake light					
12/3/13	uhp inspection	safety inspection						88767 \$ 15.00
			rotated steer tires					88767 \$ 0.00
	NAPA	DE1601 ford blue	painted chains and binders					9139 \$ 12.58
	NAPA	DAP1692 primer	primed repairs on bed					\$ 5.98
	Barnes	MP38232 cotter pin	repaired chain hook					\$ 0.16
12/6/13	MPE	8075-12 does 9-1-1	added to gelled fuel					\$ 18.80
12/9/13	WYO rigging	1" bridle	replaced bridle on truck					\$ 178.76
12/11/13		911 fuel treatment				2		

2014 Vehicle Maintenance		Vin# 1NP5LBEX05D843607	10/22/2014			
L-532	2005 Peterbuilt	Safety Inspection				
License	Z020026	Steer Tires 425/65R22.5				
		Drive Tires 295/75/22.5				
		Tag Tires 12R24.5				
DATE	Company parts/svcs purchased from	Part #/Description	WORK PERFORMED	MILAGE	HOURS	COST
1/14/14	Barnes	2156 Seal	Replaced gland hand seals	4		\$ 3.84
1/16/14	Peterbilt	D84-1000-3061340	replaced AC Belt			\$ 17.15
	MPE	5-280X U Joint	replaced U Joint Rear diff input			\$ 50.79
1/17/14		370120A wheel seal				
1/24/14	Homax	1052955- 15W40 oil	200 Hr Service	10 gal		\$ 93.80
	Snow Distributing	02382-120Grease				\$ 11.61
	MPE	B99 OF				\$ 10.22
		BF7587 FF				\$ 8.53
		BF957 FF				\$ 3.76
	NAPA	715-1021 Grease Fitting	replaced bad grease fitting			\$ 0.75
		1002 Lucas				\$ 27.79
1/27/14	Stewart Machine & Weld	labor	straighten gin poles			\$ 212.70
?	D&H Welding	labor	straighten gin poles			\$ 491.40
2/10/14	Barnes	99002 1/4 Bolt	repaired tool box door			\$ 0.45
		34272 1/4 nyloc				\$ 0.20
	ITP	28P218 seal	repaired leak on PTO			\$ 19.13
		210736 seal	replaced input seal on front drive axle			\$ 37.09
		5003326 bearing				\$ 106.72
		u joint	replaced carrier bearing and u joints			\$ 331.41
		LABOR	on drive line			\$ 233.69
	MPE	ec50pla clamp	repaired exhaust leak			\$ 18.61
2/17/14	Snow Distributing	02382-120 Grease	greased truck		9348	\$ 11.61
	MPE	HE22221 nylon airline	cleaned fuel tank vents and installed ven tubes			\$ 3.09
	Barnes	10745 ferrule	repaired grease line			\$ 0.32
3/4/14	Fleet pride	60602r light	replaced right S/T/T lights in tailboard			\$ 12.66
	Barnes	23541 heat shrink	repaired wiring to s/t/t lights in tailboard			\$ 0.10
3/5/14	Snow Distributing	02382-120 grease	greased truck			\$ 11.61
	NAPA	4421340 quick link	repaired tire chain			\$ 2.09
	Barnes	38/217 cotter pin				\$ 0.04
3/18/14	WYO Rigging	wire rope sling	new rope sling			\$ 221.03
4/3/14	BARNES	9930N 3/8 hose	replaced heater hose and clamp		9517	\$ 10.23
		24112 clamp				\$ 0.44
	NAPA	091847 brakleen				\$ 2.30
	Homax	3200-55 coolant				\$ 22.92
	Overall supply	212 nut bolt loosener	nut/bolt loosener for truck			\$ 10.45

4/8/14	Vernal	3/8 chain	replaced missing chains from truck		9551	
			lubed winch chains			
		sams club	filled windshield washer reservoir			\$ 1.97
	NAPA	2151053 grease fitting	replaced grease fitting			\$ 1.46
		DA1600, DE1601	black/blue paint			\$ 36.79
	Barnes	998188 30A fuse				\$ 0.65
		998183 20 a fuse				\$ 0.65
		BT35-co zip tie				\$ 0.60
	MPE	B99 oil filter	200 Hr Service 10 gal			\$ 10.64
		BF957 fuel filter				\$ 3.84
		BF7587 fuel filter				\$ 8.86
	Hornax	1052955-1 15W/40				\$ 94.40
	Snow Distributing	02382-120 Grease				\$ 11.61
	MPE	10002 Lucas				\$ 27.99
4/21/14	Stock	2 5/8 x 2 bolts				
		4 5/8 flatwashers				
		2 5/8 lock nuts				
		2 pl1066 aux tran mounts				
		2 PL1064	R&R bushings an dbolts			
		1 87904M ps filter	power steering filter			
		2 qt 15-40 oil	PS Leak and service			
		1 gal elec coolant	top off coolant			
		5 gal 50W tran soil	oil trans leak and change trans oil	42323	9564	
		Adjust clutch				\$ 0.00
4/22/14	Basin	PLA T235	gray sanding primer			\$ 41.22
		PLA 21953	gray primer			\$ 49.13
4/28/14	fastenal	6 x 1/2 x 1 bolts	mount air bags			\$ 6.00
		10 - 3/4 nuts				\$ 13.30
5/3/14	Bowden / PDM steel	gin poles for truck	steel and labor			\$ 7,579.88
5/2/20014	Illove drilling	seat cover	re upolster seat			\$ 126.56
5/1/14	Peterbilt	turn signal switch	TL30350			\$ 146.23
5/6/14	auto paint spec	blue paint/epoxy and thinner	paint for poles			\$ 248.85
5/14/14	auto paint spec	2 qt silver	paint			\$ 132.72
5/15/14	freedom truck	air spring	1T19L12 air spring TAG AXLE			\$ 493.06
7/21/14	STOCK	2/12V batteries				\$ 132.72
8/22/14	Idans	flat fix				\$ 47.86
8/21/14	NAPA	radiator cap				\$ 4.32
8/25/14	cardwell	50Wtrans 75-90 gear oil	change oil diffs/ change oil trans and aux trans			\$ 1,144.31
8/26/14	MVTC	AC condensor	R&R ac condensor	92405	9586	\$ 270.00
	peterbilt	accumulator f31-6063	R&R accumulator receiver dryer			\$ 77.21
10/8/14	kenworth	ac1001 cartridges	r&r air dryer cartridges	92405	9588	\$ 22.30

2015	Vehicle Maintenance		Vin# 1NP5LBEX05D843607				
			Safety Inspection	10/1/2015	Year end		
L-532	2005 Peterbuilt		Steer Tires 425/65R22.5		92652	9621	
License	2020026		Drive Tires 295/75/22.5				
	Company parts/svcs		Tag Tires 12R24.5				
DATE	Company parts/svcs purchased from	Part #/Description	WORK PERFORMED		MILAGE	HOURS	COST
5/15/15	Fastenal	2115205/1136466	mounts for airbags				\$ 19.30
			AirBogs				\$ 45.54
10/1/15	vernal shop	safety inspection					\$ 15.00

[illegible]