

2013	Vehicle Maintenance								
L-537	VIN #228951								
	EXPIRES DEC								
License	A010276								
	Parts from								
	Company parts/svcs								
<u>DATE</u>	<u>Purchased from</u>	<u>Part#/Description</u>	<u>WORK PERFORMED</u>	<u>MILEAGE</u>	<u>HOURS</u>	<u>COST</u>			
1/5/13	NAPA- Wright Auto	1DEX	NAPA Dex Cool (4)			\$61.85			
1/9/13	Cage JR	MPE 5632	Line antifreeze (1)			\$4.14			
1/15/13	FleetPride	F315-800	Replaced 4 batteries (kenworth batteries went bad while still under warranty)		9275	\$351.12			
1/18/13	MPE	211-2Bulb	Light bulbs (2)--replaced dome light bulbs			\$2.12			
1/18/13	250 hour SERVICE	SERVICE	LF691 A Oil filter		9275	\$10.41			
			FF5319 Fuel filter			\$10.52			
			FF105 Fuel filter			\$3.74			
	NAPA- Wright Auto	Homax	Lucas oil treatment 1			\$37.79			
			Grease 2 LBS			\$7.38			
			15W40 oil 10 gallons			\$93.35			
			1/4" ferrule 1			\$0.17			
1/18/13	Cage Bill(peterbilt?)	60NTA4FTG	Steer Axle						
1/29/13	Stock DAN Vernal	2-hub caps	Toggle Switch						
2/1/13	cage jr	K301-270	mudflaps --replaced flaps and hardware						
2/2/13	MPE	243612GK	mudflaps --replaced flaps and hardware						
		243012GK	Washer						
		HWCO5782	Spare belts for engine						
2/4/13	MPE		checked for coolant leak, tightened all hose clamps. DID NOT FIND LEAK						
2/11/13	Shop								
2/21/13	Cage- Phil	1" Bridle							
		2 knots Wy Rigging	no idea what size.... So went with 1" to match bridle for price						
3/4/13		243012GK	replaced 1 mudflap						
		99031/99761/99721/9978	bolts/washers/nuts (3/8/4/4)						
		99033 (7)/ 67090 (3)	bolts and pigtails for tail lights						
		H8226-0511 (4)	5/16" add a links						
3/5/13		90-668 air fitting			4				
		261-49-1	extension cord						
		12-008/12-006	1 each gladhand connection emergency side service						
		90-664	female airline fittings (2)						
3/5/13	Freedom Truck & Trailer	M85615R	4 led back up lights						
3/6/13	NAPA- Wright Auto	82343	Machine Screws						
3/6/13	MPE	several invoices mixed	replaced brake shoe kits/brake drums/s cams and bushing kits on both drive axles						
3/6/13	NAPA- Wright Auto	Paint supplies	misc paint supplies						
	Wy Rigging???	4076282	Pair of #8 wedges---repair bridle						
		MP38239	cotter pins 4						

3/7/13	Peterbilt	91847	brake clean 2 (3/6,3/7)						
3/8/13		timset 429/430	replaced hub bearing & races in in front drive axle						\$ 328.56
		1 gal washer fluid							
		2506-2	2 cotter pins						
3/11/13		105667-14	1 tube of grease						
		75-200	2 aft						
		99780	2 nuts						
3/14/13	MPE	air freshener							
3/20/13	MPE	MF185/FL18L/1X5LL/223	Mflags/magnets/tarp/sign	2					\$ 122.26
	MPE	ard head, sensors & hardware							\$ 1,421.51
		2893107	Gasket						\$ 4.50
3/21/13	MPE	ATF 75-200	2 qts						
	MPE	labor/service call	computer time- call out to shop					95.11	\$ 232.96
	BARNES	243012GK	replaced mud flap and mounting hardware						
	NAPA- Wright Auto	bolts washers and nuts	99031/99781/99721/99781/99033						\$ 2.12
	Barnes	H226-0511	Quick links from when chain broke						\$ 0.84
	NAPA- Wright Auto	81260/61	Blue/red glad hand to repair airlines						\$ 4.38
	Barnes	90-664	air fitting						\$ 4.71
	NAPA- Wright Auto	MP38239	cotter pin to repair rear fender						\$ 0.16
	NAPA- Wright Auto	ATF 75-200	repaired power steering leak						\$ 7.74
	NAPA- Wright Auto	90-100-1	valve core--repaired valve stem						\$ 3.87
	BARNES	Zip tie BT25-CO	secured ramp sensor wiring 4						\$ 1.08
	MPE	Pigtail LL091810	Repaired blue lights						\$ 0.48
	NAPA- Wright Auto	90668 fitting	repaired airlines						\$ 4.59
	WY rigging	#8 wedges	4076282 repaired osh knot						\$ 21.96
	Barnes	MP38239	cotter pinn-replaed pins in flip fenders and mudflaps						\$ 3.04
	HOMAX	1056667-14	Tube Grease for truck						\$ 7.74
	NAPA- Wright Auto	75-200 ATF							
3/20/13	SST	FREIGHT	Trans and Clutch Freight from Six States						\$ 138.75
3/30/13	Auto Paint Specialists		silver paint/spray can/blue paint, wet look acrylic hardener/reducer						\$ 68.50
3/25/13	Six States	FRO 18210C Transmissio	Transmission						\$ 3,728.23
3/26/13	Kenworth Vernal	15 1/2 clutch	R&R Clutch and Trans New Cross Shaft						
		1 speed sensor	clutch fork/speed sensor flywheel						\$ 139.84
		flywheel surface/2 exhaust clamp surface, pilot brg, throw out grease hose							\$ 95.16
		grease hose	grease hose and throw out bearing						\$ 12.74
3/26/13	Freedom Truck & Trailer	Bumper guides	bushing cross, clutch fork, pilot brg, clutch shaft						\$ 101.62
	Basin Auto	Exhaust Flex conn	R&R bumper guide post						\$ 62.16
		Radiator Hose	repair exhaust leak						\$ 40.38
		White strip adhesive	R&R upper radiator hose						\$ 41.44
3/27/13	Stock DAN Vernal	trans oil	fill up trans oil. 20? 60W oil?						\$ 12.74

3/27/13	Kenworth Vernal	nylon ties 12 11"	tie back lines						\$ 62.74
		V Band Calmp	exhaust V Band clamp						
		2 gaskets DPF	Gasket for DPF						\$ 43.76
3/28/13	Six States	clutch brake							
3/28/13	Stock DAN Vernal	antifreeze	refill antifreeze 14 QT						
4/1/13	Elite Diesel	ECM	R&R ECM						\$ 3,998.20
		spool (exhaust)							Inc
		8 11" nylon ties							
4/4/13	Stock DAN Vernal	2 gal ELC Coolant				317913	9522		\$ 32.61
4/4/13	Basin Auto	Coolant sensor	R&R low coolant sensor						\$ 182.26
4/4/13	Peterbilt	connector(1)/terminals (5)	R&R Connector plug and terminals						\$ 14.85
4/5/13	Peterbilt	Coolant surge Tank	R&R Coolant surge tank						\$ 584.29
4/9/13	Kenworth Vernal	air brake antifreeze							
4/15/13	Fastenal	2 bolts HCSS/16-68x4							\$ 1.75
4/11/13	MPE	59-13	replaced wiper blades						\$ 18.56
4/11/13	Peterbilt	LF691A	Oil filter 250 hour service						\$ 10.41
	Peterbilt	FF105	Fuel filter						\$ 3.74
	Peterbilt	FF5319	Fuel filter						\$ 8.39
	Hommax	15W40	10 gal						\$ 93.30
	Snow Dist	grease hose							\$ 7.74
		2523	hair pin clips (2)						
	MPE	5/767X U joint	replaced two u joints--rear driveline						\$ 183.54
	ITP	673209 BOLT	replaced cap bolts						\$ 8.15
	NAPA- Wright Auto	10002 LUCAS	oil treatment						\$ 37.79
	NAPA- Wright Auto	90180 Valve Cap	missing valve caps						
	MPE	05532 Aireline antifreeze							\$ 4.15
	NAPA- Wright Auto	7703045	Helicoil-repaired threads in body/deck bolts						\$ 30.44
	NAPA- Wright Auto	1805	yellow paint for chains and binders						\$ 11.95
	NAPA- Wright Auto	RTA 9210	red paint for chains and binders						\$ 11.95
4/16/13	Barnes	99004 1/4" bolt	replaced deck plate hardware 4						\$ 0.40
	Barnes	MP34272 Lock Nut					4		\$ 0.32
	Fastenal	110120337					2		\$ 1.76
	MPE	59-13 winter blade	replaced windshield wipers						\$ 18.56
4/20/13	MPE	380-5840 Filter	replaced crankcase filter/seals/oil pan set/sleeves				9636		\$ 254.91
4/18/13	Wyoming Rigging	1" Bridle							\$ 107.42
4/19/13	MPE	Safety cable hood							\$ 26.26
4/29/13		1" bridle							
4/30/13	Barnes	998182 5 Amp fuse	spare for truck 2						\$ 1.30
		998186 20 A Fuse	spare for truck 2						\$ 1.30
		998188 30 aFuse	spare for truck--replaced fuses for trailer marker lights 3						\$ 1.95
	WY Rigging???		1" bridle on truck						\$ 107.42

4/30/13	Two Way radio	Cable/Labor			\$ 108.15
5/3/13	MPE	8013550 Switchq 6330-1 R134A	repaired air conditioning	321009	\$ 472.54
5/8/13	Barnes	P14362-056PR Clamp BT25CO zipties	secured wiring for bumper lights 4		\$ 0.00
5/8/13	MPE	K042-79	Boot Shift		\$ 0.00
5/12/13	MPE	K301270 Switch	replaced switch for winch speed control		\$ 30.39
5/14/13		K301270 Switch	switch		\$ 53.02
5/16/13	Peterbilt	LF691A oil filter	250 hour service	9800	\$ 10.41
		FF105 fuel filter			\$ 3.74
		FF5319 Fuel filter			\$ 8.39
		lucas oil	1 gallon		
	Homax	1052955-1 15W40 oil			\$ 89.20
		11083 brass fitting			
	Snow Dist	02382-120 grease	greased		\$ 7.74
	FleetPride	MJTV-3 Switch	replaced tail roll switch		\$ 43.71
	shop	lucas 10002			\$ 37.79
	MPE	Oil Sample Kit	oil sample to WY Machinery		\$ 24.68
	MPE	99781/99031	sleeves		\$ 42.27
		1685248 gasket	4 each		
5/17/13	MPE	29210050270	replaced oilpan gasket and broken sleeves		\$ 144.00
		37FW1	replaced broken hood cable		\$ 31.13
	Shop	CB12250relay	replaced fender latch		\$ 15.14
	MPE	CC11100 breaker	adjust clutch		\$ 0.00
		R19501 element	ac repair		\$ 239.56
	BARNES	11083-7/99781/99031			\$ 0.00
	WYO Machinery	oil sample monitor	repaired ari leak and replaced mudflap hardward		\$ 3.30
5/24/13	NAPA- Wright Auto	3/4" hose H152	aluminum readings slightly elevated--continue normally scheduled sampling		
5/30/13	Tire rama		hose on binder hanger to protect paint 2		
5/30/13	Barnes	32757 washer	flat repair		\$ 36.75
5/30/13		732-1202	replaced mudflap hardware 2		\$ 0.16
6/4/13	WY Rigging	Clevis hook	hose protector		
6/5/13	Snow Dist	Grease 02382-120	Repair load chains		\$ 20.47
6/6/13	NAPA- Wright Auto	08008 Adhesive	Greased Truck		\$ 7.74
6/12/13			repaired weatherstrip on both doors		\$ 10.80
6/18/13	MPE	6054 Headlamp	repaired trailer cord		
6/20/13	Vernal	load straps	repalced side headlight		\$ 10.80
	MPE	SH716S	put 2 load straps on truck		
		425-65R22.5	replaced passenger side mirror		\$ 23.90
	Vernal		replaced right steer tire		

6/2/13	NAPA- Wright Auto	1133 Grease gun 7151151 coupler	Grease Gun for Truck				\$ 39.71
6/25/13	MPE	7151229 Hose B99 oil filter BF7587 Fuel filter BF957 Fuel filter 1052955-1 15W40 oil 10002 Lucas 02382-120 grease 64-107-12 Alarm 4076282 #8 wedge 1" replaceable knot	250 hour service	330107	10045		\$ 7.86 \$ 10.22 \$ 8.53 \$ 3.77 \$ 89.20 \$ 37.79 \$ 7.74 \$ 23.22
6/26/13	MPE	5-676X U joint BT35-CO Zipties 2 BT25-CO Zipties 2 23830 Ring term 1 25248 air filter 2 23845 connector 1 washer fluid BT4LH-LO zip tie 4 02382-029 Grease H152 3/4 hose 2' 3350x8 1" Bridle for truck 770163 pad lock set	replaced u joint/front diff input secured hoses/wiring under hood repaired wiring for blu alarm replaced air filters filled washer tube grease for truck put hose on binder rack to protect paint fitting				\$ 83.91 \$ 0.30 \$ 0.24 \$ 1.47 \$ 1.04 \$ 1.87 \$ 1.56 \$ 4.46 \$ 26.25
7/15/13	NAPA	Grease Tube Moly sun shade Tail Roll	replaced padlocks on truck LFO flat repair 02382-039 1 tube reflective sun shade 4*6 1/2 tube--repair tail roll 10" Channel R&R Oil pressure sensor head				\$ 10.19 \$ 543.68 \$ 0.00 \$ 135.75
7/11/13	NAPA	oil pressure sensor Weld Supply power steering leak Tail Roll Cap	add PS fluid and stop leak	331850	1013		\$ 42.53 \$ 25.48 \$ 950.00
7/23/13	MPE	8195519 Support	replaced center cap on steer axle				\$ 36.75
7/26/13	NAPA	Kit-Hood	greased truck				\$ 63.69
8/7/13	Snow Dist	37FW1					\$ 31.24
8/10/13	Tire Rama	Flat repair					\$ 7.74
8/15/13	NAPA- Wright Auto	35595 Lug Wrench	lug wrench for truck				\$ 36.75
8/18/13	Barnes	11090 connector union	replaced broken fitting on fan hub				\$ 145.95 \$ 0.76

		7152008	replaced grease zerk			\$ 0.13
8/7/13 NAPA- Wright Auto						
8/19/13 WY rigging	1" Bridle		new bridle for truck			\$ 107.42
8/31/13 Vernal	425/65R22.5		Left Steer Tire	336781	10300	
9/6/13 Hommax	1052955-1 15W40 oil		250 hour service		10342	\$ 91.30
NAPA	10002 Lucas					\$ 37.79
MPE	B99 filter					\$ 10.22
	BF957 filter					\$ 3.77
	BF7587 Filter					\$ 8.52
Snow Dist	380-5840 Breather		replaced crankcase breather			\$ 68.63
Vernal	02382-120 Grease		MOLY GREASE			\$ 7.74
MG Oil	AF25248		changed air filters			
MPE	02382-029 grease		grease for gun on truck			\$ 4.68
9/13/13 NAPA	1960A Light		replaced cab light			\$ 5.31
	1765 Filter		replaced hydraulic filters		10345	\$ 20.48
	1408 filter					\$ 19.55
WYO Rigging	1" Bridle		bridle blank for truck			\$ 107.42
Barnes	BT35-CO Zipties		secured hydraulic lines and tank valves 6			\$ 0.24
	BT45-CO zip tie			6		\$ 2.52
9/24/13 NAPA	09134 brakleen					\$ 2.83
9/26/13 MPE	CT300 clamp		replaced radiator hose and clamp		11243	\$ 7.98
NAPA	7820 hose					\$ 29.49
9/27/13 Sams Club	washer fluid		filled washer resevoir 1 gal			\$ 1.87
MPE	5-676X U joint		replaced u joint/front diff input			\$ 107.73
10/7/13 WY Rigging	1" Bridle		new bridle for truck			\$ 107.42
10/8/13 Barnes	32579 washer		repaired left front fender	6	10502	\$ 1.14
10/14/13 MPE	BF957 FF		200 HR service		10519	\$ 3.77
	BF7587 FF					\$ 8.53
	B99 Oil filter					\$ 10.21
Hommax	1052955-1 15W 40 oil					\$ 91.30
Snow Dist	Grease					
LUCAS						
NAPA	90668 quick connect		repaired airline for filling tires			\$ 37.79
	90674 QC					\$ 5.24
Vernal	TR546D valve stem		replaced leaking valve stem LRO	1		\$ 12.32
NAPA	715-1051/1021 grease zel	2, 3				\$ 2.92
10/18/13 Custom radio	speaker		external speaker for company radio			\$ 57.75
10/22/13 MPE	AC1001 cartridge		replaced air dryer cartridge		10533	\$ 18.43
10/27/13 Vernal	1/2" ratchet binder		new binders for truck 4)			
10/29/13 MPE	Q34767 cap		replaced power steering resevoir cap		10583	\$ 3.23
fleetpride	3800250 hose		fabricate new airlines for trailer 26			\$ 17.68
barnes	2015 sleeve			4		\$ 4.88

10/31/13	Barnes	BT2LH-LO	secure airlines with zipties 4				\$ 0.84
10/25/13	MPE	b71-1001 absorber					\$ 136.35
10/31/13	mpe	rkn28510	valve				\$ 94.26
11/6/13	hobby lobby	Paint supplies					\$ 18.87
11/4/13	Best Deal Spring	St4 Safety Valve	R&R valve on air dryer				\$ 21.89
11/11/13	Snow dist	02382-120 Grease	Greased Truck			10660	\$ 11.61
	WYO Rigging	1" x 175' wire rope	replaced winch line on #1 winch				
11/14/13	MPE	BK313	replaced clutch brake			10689	\$ 25.83
11/18/13	MPE	5-6/76x u joint	replaced u joint on output axu trans			10709	\$ 107.73
	ITP	22254 Nut	replaced output yoke n nut on aux trans				\$ 10.45
		yoke N6.5-4.3561-1x					\$ 155.08
	MPE	D84-1000-0122490	replaced fan belt				\$ 119.95
		K02210ABXW	replaced purge valve on air dryer				\$ 109.18
		B99 oil filter	200 hour service				\$ 10.22
		BF957	Fuel filter				\$ 3.76
		BF7587 FF					\$ 8.53
	Homax	1052955-1	oil				\$ 93.80
	Napa	10002 Lucas					\$ 37.79
	Snow Dist	02382-120 grease					\$ 11.61
	MPE	59-13 wiper	replaced windshield wipers				\$ 18.56
		D84-4000-6122490	replaced serpentine belt				\$ 119.95
	Decker Auto Glass	DW1707 Glass	replaced windshields				\$ 403.12
	NAPA	901001 valve core	replaced valve core RRI				\$ 0.59
	Vernal	AF25248 filter	replaced aire filters (used) 2				
	WY Rigging	1" Bridle	spare bridle for truck				\$ 178.76
11/22/14	Custom Radio	M15100	installed external speaker for concant radio				\$ 57.75
11/25/13	Barnes	external speaker	company radio				
		10747 ferrule	repaired coiled airlines 4				\$ 1.84
12/2/13	Barnes	10856 insert				4	\$ 1.76
12/3/13	UHP Inspections	92-858075KOL	Power steering fluid 1				
	snow distributing	safety inspection	repaired hudraulic leak on valve body			10768	\$ 15.00
	NAPA	02382-120 grease	greased vehicle				\$ 11.61
		091847 brakeleen	cleaned steering gearbox for inspection				\$ 2.30
		90-668 coupler	repaired airline connections				\$ 10.48
	Barnes	2156 seal	new seals in glad hands 4				\$ 3.84
	MPE	800350BXW	VALVE				\$ 19.40
		osl Sign					
12/6/13	MPE	F69-6003-151	replaced A/C compressor			10790	\$ 386.99
	Barnes	BT25-CO Zipties	secired wiring on AC Compressor 3				\$ 0.30
12/10/13	WY Machinery	seal 2H-4145	repaired leak on slave steering gear box				\$ 7.01

Kenworth Vernal NAPA	5545221 seal kit 091847 brakleen 75200 ATF	repaired leaks on primary steering gear box	4 3		\$ 141.17 \$ 4.60 \$ 12.57 \$ 9.38
Homax Vernal	1052955-1 15W40 oil CVM104	2 qts replaced 5th wheel plate OSL sign		10797	
12/12/13 Barnes	99781 5/16th nut CS680 washer	repaired broken dash where MV-4 valve mounts	3		\$ 0.12 \$ 0.40
12/16/13 Kenworth VERNAL MPE	SRK16 kit repair kit slo8 tag bushings 801266 BkW Dryer	released air dryer cartridge failure submitted to kenworth for warranty	3	10811	\$ 967.05 \$ 422.26
Barnes	2156 Seal	replaced glad hand seal			\$ 0.00 \$ 0.96
Fleetpride	T521 Tarp Strap T531Tarp Strap AFT 1608	new tarp straps for truck	2 21" 3 31"		\$ 2.64 \$ 6.03
12/17/13 Barnes	9931N 3/4 hose	replaced coolant hose on transmission cooler			\$ 12.39
Peterbilt	XA1706 shaft	replaced yoke shaft on 5th wheel			\$ 22.55
Barnes	6215 #194Bulb	replaced dash light			\$ 0.35
12/23/13 NAPA	H8226-0511 quick link	repair tire chain			\$ 2.09
12/23/13 Hose and Rubber	Plugs D4F4 (2) D4M4(1)	quick connect fittingsbought by Scott Hobza			\$ 13.56
Barnes	BT2LH-LO zipite		3		\$ 0.60
Barnes	2537 hairpin clip				\$ 1.25
12/30/13 NAPA	B99JAB	10002 Lucas			\$ 25.99 \$ 9.73

2014 Vehicle Maintenance			2007 T-800 Kenworth			
L-537	VIN #228951	Inspected 12/3/13	1NKDXBTXX8J228951			
	EXPIRES DEC		Steer Tires 425/65R/22.5			
License	A010276		Drive Tires 11R/22.5			
	Parts from		Tag 245/70R/17.5			
	Company parts/svcs		Engine Serial # SDP07707			
DATE	purchased from	Part#/Description	WORK PERFORMED	MILEAGE	HOURS	COST
1/2/14	MPE	1/4" airline HE22051	repaired airline for 5th wheel slide	3'	10860	\$ 1.59
	Barnes	10745 Ferrule				\$ 0.32
	MPE	FG8939 Union				
		10853-1 1/4 insert				
	NAPA	75-200	trans fluid			\$ 9.98
1/8/14	NAPA	1002 Lucas	200 Hr Service		10907	\$ 27.29
	Snow Distributing	02382-120 Grease				\$ 11.61
	Homax	1052955-1 15W40				\$ 93.80
	MPE	B99 OF				\$ 10.22
		BF957 FF				\$ 3.76
		BF7587 FF				\$ 8.53
	Tire Rama	Tire repair	repaired flat LRO			\$ 36.75
	Wear Parts	1G179571A Nut	replaced locknut on 5th wheel yoke shaft			\$ 1.90
1/20/14	Kenworth	Oil pan gasket/2 wheel seats	R&R R/F driver hub seal and axle gasket			\$ 237.88
1/21/14	Kenworth	2- SRK16 Busing Kit	R&R Bushings in Tag Axles (Watson Chain)			inc
	Best Deal Spring	3B12-319 Air Spring	R&R Air Spring load side R #2 Tag			\$ 217.28
1/22/14	Best Deal Spring	800530 Braket	R&R R/F Driver torque rod bracket			\$ 392.05
1/22/14	Kenworth	Axle Gasket	R&R Exhaust pipe off turbo			\$ 371.44
		Exhaust pipe	repaired power steering shaft			inc
		Seal kit M100 power steering				\$ 115.44
	Dans Tire	8 11R22.5 Drive tires				\$ 5,632.00
1/23/14	Kenworth	Winterfront		349766	10938	\$ 83.43
1/23/14	V Stock	42 Qt Shell 14-40				
		2 Qt 75-90 gear oil				
		? See handwritten VM Vernal				
	bowden welding	bracket redos				\$ 390.00
	covers n camo	seat upholstery (2)				\$ 420.08
1/28/14	Barnes	99037 5/16 bolt		1		\$ 0.30
		99761 flat Washer		2		\$ 0.10
		34272 Lock Nut		1		\$ 0.05
	WYO Rigging	1" Bridle	New Bridle for Truck			\$ 178.76
1/30/14	Kenworth		installed bug deflector		10975	\$ 253.79
2/3/14	MPE	H6054 Headlight	replaced driver side headlight		11000	\$ 10.80
			installed winterfront			
2/6/14	MPE	8080-06 911	added poser service 911 to fuel			\$ 15.83

		00124 melt down	spare bottles for truck					\$ 36.12
		BF957 fuel filter	changed fuel filter					\$ 3.76
2/11/14	MPE	03-01568	replaced axle gasket-right rear drive axle					\$ 4.78
2/15/14	NAPA	1002 Lucas	200 HR service			11076		\$ 27.29
	HOMAX	1052955-1 15W40						\$ 93.80
	Snow Distributing	02382-120 Grease						\$ 11.61
	MPE	B99 oil filter						\$ 10.22
		BF957 fuel filter						\$ 3.76
		BF7587 fuel filter						\$ 8.53
		3805840 breather	replaced crankcase breather			11076		\$ 69.46
		381240 Bolt	replaced motor mount bolts n nuts					\$ 9.45
		348482 nut						\$ 6.40
2/24/14	Barnes	MW1209BK hub cap	replaced hub cap on steer axle					\$ 8.65
2/258/201	Barnes	2046 7 pin connector	replaced plug in on trailer cord					\$ 16.86
2/28/14	CMI TECO	MP61397	replaced trailer plug in					\$ 12.31
3/7/14	GSS	V-8 4 way valve						\$ 47.78
3/11/14	Goodyear tire	WASH	Wash n Scrub					\$ 171.00
3/3/14	Homax	alignment	sensors calibrated also					\$ 376.43
		1052955-1 15W40 oil	one gallon engine oil					\$ 9.38
3/6/14	sams club	washer fluid	filled windshield washer reservoir					\$ 1.87
	MPE	NA4751001 mount	replaced bushings in charge air cooler mount					\$ 72.38
		CM4844 Clamp	replaced broker clamp on charge air cooler					\$ 7.78
		PE27100 Plug	replaced plue end on trailer cord					\$ 5.96
		19200 Y LAMP	replaced visor lights					\$ 3.84
	Peterbilt	VR 9 5 switch	replaced PTO engage switch					\$ 58.70
	Barnes	23846 connector	repaired right rear marker light					\$ 0.58
		23541 shrink tube						\$ 0.09
		1052955-1 15W40 oil	extra oil					\$ 18.76
	Homax	1208 sea kit for 4 8						\$ 2.47
3/12/14	CMI TECO	30T38111 plug						\$ 17.40
	Peterbilt	K301-197	w9 switch					\$ 50.86
3/14/14	MPE	2H2665 oring	repaired coolant leaks on right side of engine			11235		\$ 7.77
		1250434 gasket						\$ 13.71
		3H1461 oring						\$ 1.76
		3097641 hose						\$ 15.24
		4N0699 Hose						\$ 0.98
		20R1177 turbo	replaced turbo chargers					\$ 1,719.63
		2746851 gasket						\$ 13.34
		2N2766 locknut						\$ 18.19
		1978418 gasket						\$ 5.25
		1978419 gasket						\$ 5.38
		2760200 hose						\$ 3.03

3/15/14	MPE	6.5 70 18Xstrap kit	replaced strap kit on driveline				\$ 10.07
	Fleetpride	575 alarm	replaced back up alarm				\$ 46.50
		EL540016 clamp	replaced clamp on aire contessor tubing				\$ 0.43
3/16/14	Homax	1053887-120 75W90	replaced oil in #1 winch				\$ 77.52
	VERNAL	7000074 75W90	replaced oil in rear differentials				\$ 242.00
		550026909 50W	replaced oil in main and aux transmissions				\$ 304.32
	MPE	LL091810 pigtail	repaired wiring right S T T Light				\$ 1.53
	Barnes	BT4LH co zipite					\$ 0.81
3/21/14	Homaz	1052955-1 15W40 oil	200 hour service			11282	\$ 93.80
	MPE	10002 lucas					\$ 27.99
		B99 oil filtker					\$ 10.22
		BF7587 Fuel filter					\$ 8.53
		BF 1259 fuel filter					\$ 9.71
		02832-120 grease					\$ 11.61
3/24/14	Snow Distributing	MH67A8J	replaced microphone--company radio			11285	\$ 52.50
3/30/14	MPE	LL091810 pigtail	replaced pigtail on eight S T T light			11334	\$ 1.53
	Barnes	23846 connector	repaired rwinging to taillight				\$ 0.58
		23540 shrink tube					\$ 0.22
	Snow Distributing	02382-120 grease	greased truck				\$ 11.61
4/1/14	VERNAL	Ts31 tarp straps	Rotate steer tires		358079		\$ 8.04
	Snow Distributing	greased truck	4 new			11375	\$ 7.74
	MPE	HE2650 coolant hose	replaced lower radiator hose				\$ 15.28
	HOMAX	3200-55 elc	added coolant				\$ 4.22
4/7/14	Wheeler	305-4484 oring seals	reseat windshield				\$ 35.00
4/14/14	Nu View	fix water leak	L/F driver R&R Spring brake L/F.D				
	Stock	30/30 brake chamber	R&R oil pan gasket refill oil				
4/16/14		LF691A oil filter					
		44 qts 15-40 oil					
		3 6lb 139A AC	charge AC R&R Reciver dryer				\$ 58.46
	Kenworth	pinion seal kit F/D	R&R pinion seal front driver				\$ 1,542.68
	Wheeler	CGI coolant and parts	R&R CGI cooler selas tube hoses				\$ 23.38
	Basin Auto	Silicone					\$ 21.90
		tool box lift strut	R&R Lift Strut left tool box lid				\$ 22.17
		Pag 46 oil AC	32 oz				\$ 109.91
	Kenworth	mounting kit	charge air cooler R&R Mounts cahrged air cooler		359673	4400	\$ 38.82
		Dryer AC					\$ 49.20
		NW1191BK	5 hub caps				\$ 19.60
5/8/14	MPE	Hose HE2650	replaced lowe radiator hose			11439	\$ 199.75
	Peterbilt	U bolt T8-7/8x28	replaced u bolts and hardware on steer axle				\$ 3.86
		Washer UBW80					\$ 8.32
		Nut DN5					

	MPE	Spacer	replacedc spacers on steer axle right side				\$ 61.15
		Spacer					\$ 76.44
	VERNAL	425/65R22.5	replaced right steer acle tire				
	MPE	Radiator R1286001	replaced accident damage radiator				\$ 1,955.49
		Air Cooler R1292001					\$ 1,863.32
		Bushing kit n4751001					\$ 75.16
		Bolt hwc04460					\$ 27.60
		Nut hwc12726					\$ 2.90
		Valve v12149					\$ 2.73
5/9/14	Homax	1052955-1 15W 40	200 hour service			11464	\$ 94.40
	MPE	10002 lucas					\$ 27.99
		B99 OF					\$ 10.64
		BF7587 FF					\$ 8.86
		BF957 FF					\$ 3.84
	Snow Distributing	greased truck					\$ 7.74
	NAPA	75200 ATF	filled PS res				\$ 4.19
	Barnes	BT26H LO Zipitie					\$ 0.20
5/14/14	MPE	Boot d50-6040	replaced boots and clamps on charge air cooler				\$ 282.45
		Clamp CM4844					\$ 62.24
	Barnes	Hose clamp 24108	replaced clamps on ps return lines				\$ 1.06
	NAPA Gillette	6004008 plug	parts purchased in gillette to get truck back to casper for repairs				\$ 3.49
		6004002 plug					\$ 3.49
		6004004 plug					\$ 3.49
		12x5nf bolt					\$ 2.30
		12x412nf bolt					\$ 2.72
		12nf nut					\$ 0.35
6/2/14	Peterbilt	XA1706 Shaft	replaced yoke shaft and nut on 5th wheel			11600	\$ 24.95
		25945 Nut					\$ 1.88
6/5/14	Peterbilt	5002741 Kit	rebuilt MV-3 valve				\$ 16.34
6/20/14	Homax	1052955-1 oil 15W40	200 HR service			11694	\$ 89.20
	MPE	10002 Lucas					\$ 27.99
		B99 OF					\$ 10.54
		BF957 FF					\$ 3.84
		BF7587 FF					\$ 8.77
		02382-120 Grease					\$ 7.74
6/21/14	ITP	370150A Seal	replaced wheel seal & Brake shoes on left front tag axle				\$ 27.96
	MPE	A23222T126 Shoes					\$ 99.46
6/24/14	MPE	M11-1917-004	Replaced passenger side upper exhaust bracket			11700	\$ 53.78
7/7/14	MPE	HE2275 hose	replaced compressor output hose				\$ 111.09
		FG3987 fitting					\$ 25.56
			call out for parts				\$ 50.00
7/15/14			tighten nut on input yoke front diff torque, u-joining bolts , grease and adjust brakes				\$ 0.00

7/16/14	fleetpride	15011/15205	license plate lite and lamp kit				\$ 27.74
7/19/14	mpe	6060c light	installed worklight for winch				\$ 51.48
	fleetpride	60704 grommet					\$ 2.73
		60720 bracket					\$ 5.45
	MPe	fg3987 fitting					\$ 1.53
7/25/14	homax	1052955-1 15W40 oil	200 hour service				\$ 89.20
	Snow Distributing	02382-120 grease					\$ 11.61
	MPE	10002 lucas					\$ 27.99
		b99 oil filter					\$ 10.54
		BF957 FF					\$ 3.84
		BF7587 FF					\$ 8.77
7/25/14	wear parts	bolts 4 total	replaced missing parts in air cooler				\$ 3.58
			adjusted brakes				\$ 0.00
7/28/14	fleetpride	NP62-4 1/4 union	removed, repaired and reinstalled PTO switching valve in console				\$ 12.26
8/3/14	overall supply	1" bridle	nut and bolt loosener for truck				\$ 10.45
	WYO Rigging	6V9746 o ring	rebuilt V-44 valve in pto console				\$ 1.79
8/12/14	WYO Rigging	6F4855 o ring					\$ 1.74
		2M4453 o ring					\$ 1.89
	peterbilt	VB-9.5 switch	replaced PTO switch				\$ 62.54
	barnes	998188 30 A fuse	repaired wiring to #1 winch speed switch				\$ 1.30
		998184 10 a fuse	spare fuses for truck				\$ 1.30
		998185 15 a fuse					\$ 1.30
		998186 20 a fuse					\$ 0.65
		998188 30 a fuse					\$ 0.65
8/13/14	MPE	HE22051 1/4 airline	replaced airlines to PTO switch				\$ 1.59
	NAPA	75200 ATF	filled ps res				\$ 4.19
	vernal	Ts31 tarp straps	straps for truck				\$ 8.04
	MPE	P27-1040-03 switch	replaced clearance light switch				\$ 118.65
8/18/14	MPE	H6054 headlight	replaced passenger side headlight				\$ 10.80
8/20/14	Homax	1052955-1 15W40	200 hour service			12070	\$ 89.20
	Snow Distributing	02382-120 grease					\$ 11.61
	mpe	10002 lucas					\$ 27.99
		b99 OF					\$ 10.54
		BF7587 ff					\$ 8.72
		BF957 FF					\$ 3.84
	ITP	370150A seal	replaced wheel seal and brake shoes00 RR tag axle				\$ 26.63
		relined shoes					
		PL1064	replaced aux trans right rear bushings				\$ 19.94
		PL1066					\$ 9.92
	Barnes	38339 cotter pin	rear chain hook				\$ 0.05
		KP81234 male term	repaired ground wire to left headlight				\$ 0.38

		KP81235 seal						\$ 0.17
		23541 shrink tube						\$ 0.10
		BT25-co zip tie						\$ 0.65
	NAPA	08880 brakleen						\$ 2.62
	sutherland	misc						\$ 32.15
8/21/14	MPE	MW 1209BK cap	replaced center cap on left steer tire					\$ 4.33
	napa	90662 coupler						\$ 34.63
9/3/14			repaired ps leak in reservoir					\$ 0.00
9/25/14	MPE	HD94S11 gearbox	replaced slave steering gearbox			12119		\$ 822.11
		L24V08460A11	replaced passenger side draglink					\$ 215.38
		87904M filter	replaced pwer steering filter					\$ 21.47
	NAPA	75200 ATF	replaced ps fluid					\$ 26.20
	Snow Distributing	02382-120 grease	greased truck					\$ 7.74
10/1/14	Kellys alignment		front end alignment					\$ 108.15
10/9/14	MPE	Key Molde						\$ 4.35
1/10/14	MPE	AC1001 cartridge	replaced air dryer cartridge			12143		\$ 21.53
			tightened bolts on winch dogs					\$ 0.00
	NAPA	4421340 quick link	repaire tire chains					\$ 4.18
10/24/14	Snow Distributing	02382-120 grease	greased truck			12235		\$ 11.61
10/28/14	MPE	DW1707-30 glass	replaced driver side windsheid					\$ 20.62
		00212336 light	replaced side marker light					\$ 13.93
		5 676x U joint						\$ 83.95
	class c solutions	71415F connector	repaired wiring to clearance light					\$ 0.96
		23844 conector						\$ 0.88
	sams club	959877 washer fluid	filled reservoir					\$ 1.97
11/4/14	HOMAX	1052955-1 15W40	200Hour Servic			12288		\$ 89.20
	Snow Distributing	02382-120 grease						\$ 11.61
	MPE	10002 Lucas						\$ 27.99
		B99 oil filter						\$ 10.54
		BF937 fuel filter						\$ 3.84
		BF7587 Fuel filter						\$ 8.77
	VERNAL	AF25248 Air filter	replaced air filters/adjusted brakes					
	NAPA	7151051 grease fitting	replaced grease fitting in driveline					\$ 0.73
11/21/14	Vernal	3/8 ratchet binder	new bins for truck					
		1/2 ratchet binder						
	NAPA	4421340 quick link	quick link for hose hanger					\$ 2.09
	MPE	3050 marker light	replaced red marker lights					\$ 10.06
11/28/14	MPE	2790253 tensioner	replaced alternator belt and tensioner					\$ 181.64
	MPE	6061870 belt						\$ 43.80
		070R	spring as					\$ 37.13
	MPE	B2695/(M1974	cap screw/washer					
12/1/14	homax	1052955-1 15W40	200 hour service			12468		\$ 89.20

	Snow Distributing	02382-120 grease						\$ 7.74
	mpe	10002 lucas						\$ 27.99
		b99 of						\$ 10.64
		bf957 ff						\$ 3.82
		bf7587 ff						\$ 8.86
		cross link chain	repaired tire chains					
		3805840 element						\$ 69.46
	vernal	af25248 af	changed air filters (cleaned ones)					
	napa	75200 atf	filled ps reservoir					\$ 4.19
	sams club	959877 wash fluid	filled reservoir					\$ 1.97
	mpe	2790253 tensioner	replaced ac tensioner					\$ 181.64
		6061870 belt	replaced AC belt					\$ 43.80
12/17/14		M&TV3 valve	replaced tail roll air valve			12557		
	wyo rigging	1" bridle	new bridle for truck					\$ 178.76
	homax	3200-55 coolant	added coolant					\$ 7.89
	class c	10747 ferrule	repaired air hose					\$ 0.92
12/24/14	mpe	P271040-10 switch	replaced light switch			12601		\$ 120.75
		P27-1040-13 switch	replaced fan override switch					\$ 120.75
12/26/14	fleetpride	f315 800 battery	replaced one battery cleaned terminals					
	tire rama	TR546d valve stem	repaired tire rro drive					\$ 10.45
	napa	in910 plug						\$ 0.28
		patch						
		in910 plug	repaired tire LRO drive					\$ 1.24
		ra010100 patch						\$ 0.28
			repaired driver door latcg					\$ 1.24
	napa	ec10 connector	repaired wiring power steering sensor					\$ 0.00
	class c	bt35 zip tie						\$ 25.19
12/30/14	vernal	90147 hot line	added deicer to fuel					\$ 0.75
	mpe	bf957 ff	changed fuel filters					\$ 32.64
		bf9587 ff						\$ 3.82
	fleetpride	180-06 ps	added supplement to fuel					\$ 8.86
12/8/14	dan eldredge	inspected 12/3/13						\$ 15.25
								\$ 15.00

2015	Vehicle Maintenance		2007 T-800 Kenworth	Year end	
L-537	VIN #228951	Inspected 12/16/2015	1NKDXBTXX8J228951	404856	13549
	EXPIRES DEC		Steer Tires 425/65R/22.5		
License	A010276		Drive Tires 11R/22.5		
	Parts from		Tag 245/70R/17.5		
	Company parts/svcs		Engine Serial # SDDP07707		
DATE	purchased from	Part#/Description	WORK PERFORMED	MILAGE	HOURS COST
1/6/15	VERNAL?	M85615B Light	replaced left center S/T/T Light		12706
			repaired mirror heat and passenger window. Repaired wiring in driver door, coolant leak on cooler, oil leak on steering pump. Adjusted drive axle brakes		\$ 0.00
					\$ 0.00
					\$ 0.00
	Snow Dist	02382-120 Grease			\$ 0.00
	Homax	1052955-1 15W40 oil	200 Hour SERVICE		\$ 7.74
	MPE	10002 LUCAS			\$ 89.20
		B99 Oil Filter			\$ 27.99
		BF957 Fuel filter			\$ 10.64
		BF7587 Fuel Filter			\$ 3.82
1/8/15	MPE	N9267001 sensor	replaced coolant level sensor		\$ 8.86
		H6054 Headlight	replaced swamp side headlight		\$ 143.07
					\$ 10.80
1/13/15	best deal springs	AS0068 Airbag	replaced left airbag right side 2nd tag axle (FIR W013587705 26C airspring)		12751
	MPE	14966 airbag	replaced suspension airbag left side 2nd tag axle		\$ 178.11
	Class C Solutions	99054 3/8 bolt			\$ 228.61
		99762 flat washer			\$ 0.51
		99722 lock washer			\$ 0.39
1/15/15	MPE	432J62311 Screw	replaced adjusting screws in headlights		\$ 0.39
	Class C Solutions	33829-5 screw	replaced broken screws in right S/T/T light		12770
1/21/15		10745 ferrule	repaired airline to 5th wheel slide		\$ 20.36
		108531 insert			\$ 0.16
		KP81234 male terminal			12805
		KP81235 seal	replaced pigtail to winch lht		\$ 0.32
		LL091810 pigtail			\$ 0.24
1/22/15	Snow Dist	02382-120 grease	greased truck		\$ 0.76
	WYO Rigging	1" bridle	new bridle for truck		\$ 0.50
	NAPA	901001 valve core	replaced valve core in tires (RR/LRO)		\$ 1.53
	Class c Solutions	BT25-CO zip tie	secured wiring in engine compartment		\$ 7.74
1/27/15	HOMAX	3200-55 coolant	added coolant		\$ 179.21
2/5/15	MPE	3-22PDC cable			\$ 1.24
2/6/15	VERNAL	385-65R22.5	replaced 2 steer tires		\$ 0.36
	MPE	15-720 receptacle	repaired wiring and replaced receptacle for trailer lights		\$ 7.39
2/9/15	Tire Rama	TR545D Valve Stem	replaced valve stem on tires 2		\$ 51.82
2/14/15	Homax	1052955-1 15W40 oil	200 Hour SERVICE		\$ 748.00
					\$ 10.12
					\$ 20.90
					\$ 89.20

	Snow Dist	02382-120 grease						\$ 7.74
	MPE	10002 Lucas						\$ 27.99
		B99 Oil filter						\$ 10.14
		BF957 fuel filter						\$ 3.82
		BF7587 Fuel Filter						\$ 8.86
	NAPA	RA010100 patch	repair flat tire RRO					\$ 1.24
		IN910 plug						\$ 0.28
		MMW1209BK hubcap	replaced center cap left steer tire					\$ 4.35
	Class C Solutions	33829-4 screw						\$ 0.10
		2506-4 cotter pin	repair chain					\$ 0.17
2/23/201	Vernal	11R22.5 drive tires	replaced all 8 DT Invoice # 193313					\$ 2,988.40
3/11/15	MPE	4709 Brake Shoe	replaced brake shoe kit-both drive axles			13020		\$ 23.90
		127808 bushing kit	preplaced bushing kit wheel seal and axle gasket					\$ 4.90
		03-01568 gasket	on rear drive axle ad front drive axle right side					\$ 143.67
		47691 Seal						\$ 23.70
	HOMAX	1053887-120 75W90	filled axle hub					\$ 3.34
	MPE	330-3111 Gasket	repaired power steering reservoir					\$ 4.27
	Fleetpride	platf mp qt	replaced broken ignition key and made spare					\$ 14.18
3/20/15	Western Locksmith		replaced tag axle tires right side 245/70r17.5?		388565	13044		\$ 0.62
3/24/15	VERNAL							\$ 39.86
	NAPA	901001 valve core	replaced valve stems on all tag axle tires			13085		\$ 10.45
4/8/15	NAPA	90288 valve stem	replaced valve stem LRO drive tire					\$ 0.25
	Tire Rama	TR546D valve stem	secured wiring under hood					\$ 7.74
	Class C Solutions	BT25-CO zip tie	greased truck					\$ 8.92
	Snow dist	02382-120 grease	1 gal motor oil 15W40					\$ 10.80
5/4/15	Stock	1052955-1	R&R Headlight					\$ 8.54
5/6/15	Stock	H6054 headlight	1 gal motor oil 15W40					\$ 3.82
5/7/15		1052956-1	FULL SERVICE			13121		\$ 8.86
		BF957 fuel filter						\$ 10.64
		BF7587 Fuel filter						\$ 27.99
		B99 Oil Filter						
		10002 LUCAS	clearance light drive side					\$ 23.20
5/11/15	VERNAL STOCK	TRP LL47303						\$ 113.10
5/18/15	Basin Auto	OSL sign	pull clutch hub get new belt- old belt worn out					\$ 112.01
5/11/15	MPE	D84-1000-6122490						
6/1/15	ITP	5-767X	revulid fan clutch and replace					
6/2/15	MPE	clutch Hub Kit	install engin fan and clutch fan			13199		\$ 203.66
	VERNAL STOCK	996813252-001	changed out steer hub cap					\$ 113.10
	MPE/Kenworth	D84-1000 B12290						\$ 1.50
6/3/15	Stock		paper towels					\$ 10.80
6/4/15	Stock	H6054 Headlight	head light					

6/16/15	Stock	BT25-CO zip tie	Wire ties				\$ 0.13
6/29/15	Stock		33846 self tapping screws				\$ 0.41
	Stock		33829 self tapping screws				\$ 2.28
	stock	LM416-50	Wire Loom				
9/1/15	Barnes STOCK	MP28233	cotter pin				\$ 0.10
8/4/15	Stock	10781/10754					\$ 7.67
8/17/15		33829-5					\$ 0.08
	MPE	BF957 Fuel filter	Fuel filter			13333	\$ 3.82
		B99 Oil Filter	Fuel filter				\$ 10.64
		BF7587 Fuel Filter					\$ 8.86
	Stock	1052955-1	11.5 gal oil				\$ 98.56
	Barnes STOCK	BT45-CO	cable tie				\$ 0.42
	Stock	Washer fluid 959877	1 gallon				\$ 1.97
8/26/15	MOE	air bag as77050					\$ 138.44
8/24/15	Fleetpride	valve AV277147					\$ 37.65
	kenworth	hose assy/receiver dryer					\$ 158.74
	A Nu View Auto Glass	repair					\$ 45.00
	stock	134A 3.51 LB	charge AC 3.5 lb 134A reifridgerant		400122	13363	
11/21/15	Fleetpride	849 1025-12 fuel treatmen	2 qts				\$ 13.83
11/30/15	Outpost gas station	halogen bulb					\$ 20.13
12/2/15	MPE	BF957 Fuel filter	secondary fuel filter				\$ 7.69
		BF7587 F	Fuel filter				\$ 17.75
		AC1001	air dryer cartridge				\$ 27.50
12/7/15	stock	715-1021	1/8" pipe grease fitting				\$ 1.53
		715-1060	1/4" taper 90 grease fitting				\$ 1.53
		715-1051	1/4" taper straight				\$ 1.53
12/4/15	MPE	3200-55	anti freeze				\$ 14.78
		1052955-1	motor oil 15-40				\$ 8.54
12/8/15	MPE	B99JAB	Oil filter				\$ 10.64
	NAPA		6054 head light				\$ 9.65
12/23/15	Stock		212 nut and bolt loosener				\$ 10.45
	Barnes stock		2506 3/16 x 3 5/8 hair pins				\$ 1.18
12/5/15	NAPA	mm-014R	1/4 gallon mm oil to airline antifreeze				\$ 4.99

2016	Vehicle Maintenance		2007 T-800 Kenworth				
L-537	VIN #228951	Inspected 12/16/2015	1NKDXBTXX8J228951				
	EXPIRES DEC		Steer Tires 425/65R/22.5	beginning			
License	A010276		Drive Tires 11R/22.5	404856	13549		
	Parts from		Tag 245/70R/17.5	end			
	Company parts/svcs		Engine Serial # SDP07707				
DATE	Company parts/svcs	Part#/Description	WORK PERFORMED	MILEAGE	HOURS	COST	
1/1/16			beginning miles				
1/27/16	Napa	7707	curved radiator hose			\$ 51.37	
1/19/16	Fleet pride	24LCW440FH	40" * 4" winch strap w ratchet			\$ 40.95	
1/6/16	Fleet pride	24LCR430FH	30" * 4" winch strap w ratchet			\$ 55.56	
1/5/16	NAPA	97653	5" * 7" flat mirrors for extendable			\$ 36.21	
1/13/16	Barnes	BT45-CO	15" L Zip ties			\$ 0.42	
	Stock	HE2650	2.5" silicon radiator hose * 6" long			\$ 10.31	
1/14/16	Barnes	C85613	1/4" x 7/8 OD fender washers			\$ 3.31	
		99780	1/4" grade 8 hex nut			\$ 2.95	
		99006	1/4" x 20 x 1 1/2" grade 8 bolt			\$ 0.51	
1/25/16	MPE	3200-55	Ext Life Antifreeze			\$ 29.56	
1/21/16	Barnes	99002	1/4" * 3/4" Bolt			\$ 0.34	
		C85613	1/4" * 20 thread nut			\$ 2.95	
2/24/16	Peterbilt of WY	1613 CHR hubcap			13749	\$ 27.76	
	Barnes	5526-062 hose	replaced hose heater			\$ 7.18	
2/18/16	Peterbilt of WY	2808911 clam-band	replaced clamp on art hed controller			\$ 4.99	
2/18/16	MPE	service filters	BF957JAB, BF7587JAB B99JAB			\$ 22.24	
	Snow dist	02382-120 grease	250 HR service		13700	\$ 7.74	
	homax	15W40				\$ 93.94	
2/1/1/16	MPE	Sensor and seal	2935535 sensor / 2147566 seal o ring			\$ 151.45	
2/19/16	MPE	5004052BXW	Kit delivery check Valve-replace in air dryer			\$ 11.95	
2/4/16	NAPA	Misc parts	Primary wire/terminal/ring term/fuse holder/cir breaker-replace electric brake			\$ 27.53	
			contoller and wiring to 7 pin RV plug. Fabricate lights for corab trailer			\$ 0.00	
	six robes	Misc parts	wire/brake control/light kit/rv receptacle/plug/terminals			\$ 136.09	
	Fleetpride	14/4 wire				\$ 52.50	
2/9/17	MPE	BF957 FF	spare			\$ 3.84	
		BF7587 FF				\$ 8.87	
2/22/16	Fleetpride	battery	45 f31s-800 700CCA Stud Top			\$ 161.76	
3/28/16	Fleetpride	mesh flags	4 mesh flags			\$ 17.56	
3/28/16	Fleetpride	OSL Signs	12*60			\$ 34.52	
3/8/16	Snow dist	02382-120 Grease	greased		13766	\$ 7.74	
4/1/16	Stock	96488					
		99782	3/8" Nut x4			\$ 0.25	
4/4/16	MPE	UJOINT w hardward kit	5-676X			\$ 115.35	

5/23/16		02382-120	Grease 1.5 LBS				\$ 5.81
		1052955-1	15W40 Motor oil				\$ 8.54
5/27/16	MPE	5-676X	U Joint				\$ 119.79
6/10/16	MPE	GD11350 (2)	dryer receiver o ring				\$ 62.46
6/6/16	MPE	LM1350	castrol AC PAG 100 8 OZ				\$ 15.14
	napa	ac134 coolant/AC oil					
7/5/16	Homax	1052955-1 15W40	250 Hour service			13951	\$ 85.40
	Snow dist	02382120 grease					\$ 7.74
	MPE	10002Lucas					\$ 29.40
		B99 filter					\$ 10.64
		BF957 Filter					\$ 3.84
		BF7587 Filter					\$ 8.87
		HE24151 Hose	Relocated 5th wheel slider hose				\$ 38.33
	ITP	FG3950 Fitting					\$ 3.51
		AS1132 adjuster	replaced automatic slack adjusters on rear				\$ 188.83
		5 676x u joint	drive axle				\$ 113.01
		6 5 4 3591-1 yoke	replaced yoke, yoke nut and u joint on bearing end of aux output driveline				\$ 155.21
		20-74-91 nut					\$ 14.80
	Barnes	BT2LH-LO ziptie					
	stock	959877	filled washer reservoir				
7/16/16	Peterbilt	11300M1D Fitting	replaced service brake bulkhead fitting				\$ 12.38
7/25/16	Vernal via dustin	11R22.5 8 tires	replaced drive tires		416853	13997	
		385/65R22.5	replaced left steer tire				
7/30/16	MPE	5-676X ujoint	replaced ujoint/aux trans output				\$ 107.81
		HE22051	airline for 5th wheel				\$ 1.06
	Barnes	205 ferrule	repair airline				\$ 1.66
8/5/16		1" bridle	new bridle for truck				\$ 107.42
	Homax	1052955-1 15W40	Engine Oil for Truck				\$ 8.54
8/8/16	MPE	BF7587 Fuel Filter	replaced fuel filter on truck				\$ 8.87
		HE2197 Hose	Replaced return fuel line to filter				\$ 12.22
	Class C Solutions	99721 Lock Washer	Replaced mudflap and retaining hardware				\$ 0.18
		99029	3/8x1 ubolt				\$ 0.52
		99031	3/8 * 1 1/2 bolt				\$ 0.72
		34274	3/8 nyloc				\$ 0.64
		99571	washer				\$ 1.76
		32580	washer				\$ 0.48
	MPE	243617GK mudflap					\$ 38.70
8/10/16	Tire Rama	245/70R17 2 tires	straighten antisail brackets				\$ 0.00
8/19/16	MPE	3-222 PDC Cable	replaced front tag axle tires				\$ 592.97
8/24/16	Homax	1052955-1 15W40	duraflex 7				\$ 123.17
	Snow dist	02382120 Grease	250 Hour service			14197	\$ 85.40
							\$ 7.74

	MPE	10002 Lucas						\$ 29.40
		BF957 Fuel filter						\$ 3.85
		BF7587 Fuel filter						\$ 8.86
		B99 Oil filter						\$ 10.64
	Homax	3200-55	added one gallon coolant					\$ 7.90
	MPE	3843502 Clamp						\$ 7.75
		2808911 clamp						\$ 17.14
		10R8660	Replaced water pump					\$ 1,237.51
		3097641	replaced hose on EGR cooler				inc	
		core return						-\$ 463.62
		other return						-\$ 20.20
	9/6/16 Class C Solutions	MP32605 clamp	replaced clamp on compressor air line			14220		\$ 0.77
		11083-7 PLUG	replaced pipe plug on airline					\$ 2.52
	Snow dist	02382-029	tube grease for truck					\$ 4.68
	MPE	D13-1001-1	replaced right reat motor mount					\$ 150.38
		K066-421						\$ 82.89
	ITP	6-5-4-3561X	replaced input yoke nut an u joint on input of auxillary transmission					\$ 146.06
		2254						\$ 10.12
		5-676x						\$ 103.62
	9/24/16 MPE	03-01568	replaced axle gasket R/R drive Axle			14301		\$ 4.45
	9/27/16 MPE	2746851 gasket	replaced turbo gasket, lock nuts, oil line gaskets and clamp			14302		\$ 14.33
		2n2766 nut						\$ 20.33
		1978418 gasket						\$ 2.59
		1978419 gasket						\$ 2.75
		2396808 clamp						\$ 26.13
	Class c solutions	32574 washer						\$ 0.17
		c5680 washer						\$ 0.10
		MP38224 cotter pin						\$ 0.05
		MP32606 clamp	replaced broken clamp- compressor intake,					\$ 0.45
		32575 washer	installed fender extension & replaced mudflap on left front fender					\$ 0.32
		99004 bolt						\$ 0.26
		34272 nyloc nut						\$ 0.24
		99760 flat washer						\$ 0.32
		99004 1/4 bolt						\$ 0.36
		32572 washer						\$ 0.32
	10/5/16 MPE	Flywheel						\$ 68.25
	10/6/16 MPE	Sensor/Seal	Q21-6005 / 4301954					\$ 108.18
	10/19/16 MPE	Snow/winter wiper blades	59-13					\$ 18.59
	10/6/16 VERNAL	Clutch	installed new clutch			14338 ?		
	MPE	35P12-2 gasket	replaced PTO Gaskets					\$ 2.14
	NAPA	08880 Brakleen						\$ 2.62

	Homax	1054009-20 50 Wt	topped off transmission oil				\$ 13.78
	MPE	4301954 seal	replaced spec sensor and seal				\$ 2.34
	Class c solutions	BT25-co ziptie					\$ 1.08
	Snow Dist	02382-120 Grease	greased truck				\$ 7.74
	Tire rama	385-65R22.5	installed new steer tires				\$ 1,238.96
	IITP	PL 1064 mount	replaced front right mounting bushings		426079		\$ 11.45
	Class c solutions	PL 1066 mount	on auxiliary transmission				\$ 5.99
	MPE	AC1001 cartridge	repled air dryer cartridge--driver concer re clutch brake. Inspected and found clutch brake lock was not engaged. Cleaned inspected and reinstalled clutch				\$ 1.68
							\$ 25.46
							\$ 0.00
	10/15/16 MPE	LL910810pig tail	brake-test drove				\$ 0.00
	NAPA	7709250 clip	replaced wiring pigtail to winch light				\$ 1.53
	Class c solutions	KP81233 terminal	replaced wiring clips				\$ 0.90
	11/8/16 MPE	CB313465	repaired wirning to left rear marker light				\$ 0.00
	Class c solutions	BT35-CO Zipitie	replaced clutch brake				\$ 27.27
	NAPA	75200 ATF	secured loose airlines				\$ 0.45
		08880 brakeclean	Filled power steering resevoir				\$ 2.20
	11/16/16 MPE	079694 gasket	cleaned inside bell housing and front of transmission				\$ 2.62
	11/21/16 Homax	1052955-1 15W40	removed repaired and reinstalled power steering reseoir				\$ 2.73
	Snow Dist	02382-120 Grease	250 hour service			14434	\$ 76.70
	MPE	B99 Oil Filter					\$ 7.74
		BF957 fuel filter					\$ 10.64
		BF7587 fuel fitter					\$ 3.84
		10002 lucas					\$ 8.87
		BTf@1 Latch	replaced right rear fender latch				\$ 27.99
	11/30/ truck wash	90180 Valve cap	replaced valve cap LFI LRO Tire				\$ 38.02
	11/29/16 ridge equipment co	used 111R22.5 tire					\$ 0.70
	12/8/16 dan	inspection					\$ 100.00
	12/6/17 Peterbilt	xat1706 Shaft	removed 5th wheel, replaced yoke and yoke shaft				\$ 423.16
	12/8/2017 Fleetpride	8025 PS	gelled fuel-replaced fuel filters and added Powerservice				\$ 15.00
	MPE	BF7587 FF					\$ 25.44
		BF1259 FF					\$ 14.68
							\$ 8.87
	12/18/17		rebuilt v-44 valve for PTO				\$ 9.45
	12/21/17 VERNAL	425-65R22.5	installed new tires on steer axle				\$ 0.00
	12/28/17 Fleetpride	OTRA155CS	replaced ABS trailer 7 wire cable				
	12/15/17 Class c solutions	99721 5/16 washer	replaced mudflap hardware				\$ 60.95
		99031 5/16 x 1.5 bolt					\$ 0.24
		99781 5/16 nut					\$ 0.72
	Fleetpride	180 PS	fuel additive/antigel				\$ 0.24
	Peterbilt	M85015R S/T/T	replaced S/T/T light and pigtain in tailboard				\$ 12.08
							\$ 39.44

	MPE	LL91810 pigtail					\$ 1.58
12/28/17	NAPA	Heat Shrink tubing					\$ 13.08
12/23/17	MPE	engine diagnostic				434352	\$ 330.23

2017 Vehicle Maintenance		2007 T-800 Kenworth				
L-537	VIN #228951	Inspected 12/8/2016	1NKDXBTXX8J228951			
	EXPIRES DEC		Steer Tires 425/65R/22.5	beginning		
License	A010276		Drive Tires 11R/22.5	end		
	Parts from		Tag 245/70R/17.5			
	Company parts/svcs		Engine Serial # SDP07707			
DATE	purchased from	Part#/Description	WORK PERFORMED	MILEAGE	HOURS	COST
1/1/16			beginning miles			
1/1/17			beginning miles	434360	14620	\$ 0.00
1/20/17	Peterbilt of WY	Head gasket Check	Advised to replace --did not at this time--Out of Service at this time	434364		\$ 2,894.10
7/5/17	Kenworth	Overhaul kit	overhaul engine			\$ 16,075.28
			cam			
			spacer plate			
			rocker arm injector			
			rocker shafts			
			head bolts			
			thermostats			
			wire clips			
			oil pan sleeves			
	NAPA	105 grease				
	NAPA	Brakeen/Lubriplate				\$ 39.76
	WHEELER	Misc				\$ 151.49
9/7/17	Basin Auto Paint	Paint	paint for fnders, hi build, tape, primer			\$ 274.96
8/21/17	Kenworth	FENDER - FRONT				\$ 1,035.43
11/7/17	Kenworth	DW1707-30 GLASS	Drivers side R&R and wiper blades			\$ 24.18
	Kenworth	5915/LB046402	winter blades and marker lamp			\$ 21.57
11/8/17	Napa	735410 trailer wire				\$ 27.49
	Kenworth	LL044803 Oval LED Lamp	R&R Turn signal--replace wire left front turn signal			\$ 25.28
	fleetpride	G5543 STT Lamp	yellow hi count led lamp replace centr marker light rear			\$ 85.55
11/10/17	Kenworth	AC1001 air dryer cartridge	R&R air dryer cartridge			\$ 28.07
11/15/17	fleetpride	PT1900A	Lamp double bulb model 19 R&R Marker light R&R visor light			\$ 2.39
11/20/17	Vernal	M85615R	hybrid oval R&R P/S spot mirror			\$ 112.06
11/21/17	L & S	Inspections				\$ 15.00

2018	Vehicle Maintenance		2007 T-800 Kenworth Trans FRO18210-C				
L-537	VIN #228951	Inspected 12/20/2018	1NKDXBTXX8J228951				
	EXPIRES DEC		Steer Tires 425/65R/22.5	beginning			
License	A010276		Drive Tires 11R/22.5				
	Parts from		Tag 245/70R/17.5	end			
	Company parts/svcs		Engine Serial # SDP07707				
DATE	Company parts/svcs	Part#/Description	WORK PERFORMED	MILEAGE	HOURS	COST	
1/1/18			beginning miles				
1/30/18		ELD installed		434414			
2/8/18	Superior lube	grease truck		434416		\$ 69.95	
2/8/18	Cal Ranch	ratchets				\$ 103.33	
2/8/18	Kenworth VERNAL	131008K	Kit-Seal Pinio Input seal for FRONT Driver			\$ 67.58	
16-Feb	Tire Rama	245/70R17.5 Tire	?			\$ 547.90	
2/23/18	MPE	AC1001 Cartridge	Replace air dryer sensor	435698	14691	\$ 26.48	
	NAPA	44302R LED S T T Lamp	Replaced broken tail light	435698	14691	\$ 21.55	
23-Feb	Shop/Stock	License plate light	Replaced license plate light	435698	14691		
23-Feb	Worked on	Speedo sensor	Cleaned connection & wrapped wires/w loom	435698	14691		
16-Mar	Shop	Speedometer Sensor	Put electrical grease on plug to fix connection	437094	14739		
16-Mar	Shop	Tire pressure	Checked air pressure on tires	437094	14739		
19-Mar	Shop	Flat Tire	Patched rear right outside driver tire	437094	14739		
22-Mar	Shop	Changed tire	Changed rear right driver tire	437097	14743		
23-Mar	Inland Truck Parts	PS-4413 Air Bag	Changed air bag to front swamp drop axle	437097	14743	\$ 217.14	
23-Mar	Shop	Over Heating	Plugged heat sensor, tightened hose clamps	437097	14743		
23-Mar	Shop	Yoke nut loose	Tightened yoke nut & lock tighted it	437097	14743		
11-Apr	Motor Power	clutch brake	replaced clutch brake, adjusted clutch	437562	14764	\$ 28.29	
24-Apr	Motor Power	temp sensor	replaced tem sensor	439318	14826	\$ 41.36	
29-Apr	Shop	pto light	replaced short in pto light	439318	14826		
27-Apr	Motor Power	tact sensor	replaced tact sensor	439318	14826	\$ 121.56	
30-Apr	Shop		rewired pto light	440146	14852		
30-Apr	Motor Power	wiper blades	replaced wiper blades	440146	14852	\$ 19.15	
30-Apr	Shop	diagnostic scan	hooked up compier to scan for codes	440146	14852		
7-May	Napa	Oil Filter 1792	changed filter	440605	14870	\$ 18.66	
7-May	Napa	Fuel Filter	Changed Filter	440605	14870	\$ 15.81	
7-May	shop/stock	fuel filter BF 957	changed filter	440605	14870		
7-May	shop/stock	10 gallons 15/40	changed oil	440605	14870		
7-May	shop/stock	Greasse	Greased Truck	440605	14870		
7-May	Shop	inspection	Checked all fluid levels	440605	14870		
7-May	shop/stock	tire patch	patched tire				
8-May	shop	Tact not working	removed dash to trace short	440605	14870		
8-May	shop		cleaned truck windows	440605	14870		

17-May	CMI-Teco	Clutch Brake	Replaced Clutch Brake	441839	14924	\$ 37.28
5/31/18	Six States	Transmission	SSD (TA-D69-10R)			\$ 3,400.00
4-Jun	Shop	Transmission	finished removing transmission	443130	14994	
4-Jun		speedo sensor		443130	14994	\$ 40.92
15-Jun	Shop/Six states dis		finished installing transmission	443130	14994	\$ 3,400.00
15-Jun	CMI Teco	Side mirror	Replaced Side Mirrors			\$ 90.00
15-Jun	Napa	Gasket Material	made gasket for PTO			\$ 8.47
15-Jun	DTI	Clutch Kit	Clutch Replaced			\$ 922.49
15-Jun	DTI	Pilot Bearing	Replaced Pilot Bearing			inc
15-Jun	DTI	Clutch Brake	Replace Clutch Brake			inc
26-Jun	DTI	Clutch Brake	Replace Clutch Brake	444592	15038	\$ 33.33
		clutch line up tool				\$ 14.49
26-Jun	Shop	PTO	Shimmed PTO			
23-Jul	motor power kenworth	temp gage	replaced water temp gage	444851	15052	\$ 148.52
23-Jul	motor power kenworth		picked up truck at motor power	444851	15052	
24-Jul	motor power kenworth	batteries/misc	replaced 4 batteries	44851	15052	\$ 1,524.84
			credit			-\$ 124.74
24-Jul	shop	oil leak	tightened bolts on oil pan	44851	15052	
24-Jul	shop/stock	M85615R tail/backup light	replaced light	44851	15052	
1-Aug	Shop/Stock	Fixed air leak	3/8 to 1/2 compression 1/2 to 1/2 air line fitting	445905	15103	
1-Aug	Shop/Stock	Oil Filter B-99	250 Hour Service	445905	15103	
1-Aug	Shop/Stock	Fuel Filter BF-7587	250 Hour Service	445905	15103	
1-Aug	Shop/Stock	Fuel Filter BF-957	250 Hour Service	445905	15103	
1-Aug	Shop/Stock	10 Gallons 15/40 Oil	250 Hour Service	445905	15103	
2-Aug	Shop/Stock	2 Air Filters AF-25248	250 Hour Service	445905	15103	
2-Aug	Shop/Stock	Greased	250 Hour Service	445905	15103	
2-Aug	Shop/Stock	Checked Fluid Levels	250 Hour Service	445905	15103	
2-Aug	Shop/Stock	Tire Air Pressure Good	250 Hour Service	445905	15103	
8/3/18	Peterbilt	Lights				\$ 68.86
16-Aug	Shop	Air tank & Drive Line	Removed Damaged air tank & driveline			
8/16/18	Shop	U-Joints	Removed Damaged u-joints			
8/16/18	Shop	Battery	Removed broken battery	447827	15163	
8/16/18	Shop	Pulled Battery Cables	Removed Damaged battery Cables	447827	15163	
8/21/18	Napa	Liquid tape, seal wrap	fixed battery cables	447827	15163	\$ 20.48
8/21/18	Napa	Battery Cable Lugs	Replaced battery cable lugs	447827	15163	\$ 4.81

8/22/18	ITP	Driveline	Picked up driveline	447827	15163	\$ 628.16
8/22/18	Shop/Stock	Batteries	Installed Batteries	447827	15163	
8/22/18	Shop/Stock	Wiring	Spliced damaged wires	447827	15163	
8/22/18	Shop	Starter	Removed damaged starter	447827	15163	
8/23/18	Dans Auto	Solenoid				\$ 68.25
8/23/18	Shop	Starter	Replaced Damaged silanoid on starter	447827	15163	
8/23/18	Shop	Starter	installed starter	447827	15163	
8/29/18	Fleet Pride	Assorted air Line fittings	installed air tank and plumbed air lines	447827	15163	\$ 82.74
8/30/18	Fleet Pride	Assorted air Line fittings	Plumbed damaged air lines	447827	15163	\$ 34.62
8/31/18	Fleet Pride	6 1/4 union air fittings	spliced air lines	447827	15163	\$ 38.56
8/31/18	Napa	1/4" tee air lines	spliced air lines	447827	15163	\$ 37.26
3-Sep	Shop/Stock	Air Fitting	Fixed air leak	447827	15165	
3-Sep	Shop	Fuel Gauge	Spliced wires to fuel gauge	447827	15165	
3-Sep	Shop	Oil leak	Fixed oil leak on power steering pump	447827	15165	
9/5/2018	napa	air dryer cartridge				
6-Sep	Shop	Bad ground	replaced body ground	448594	15186	
6-Sep	shop/supplies	air tank	sanded, primed and painted air tank	448594	15186	
14-Sep	shop	air tank	swapped out air tank	448594	15186	
18-Sep	fleet pride	u-joint	replace u-joint on back of browsing	450607	15248	\$114.51
18-Sep	fleet pride	yoke	replaced yoke on front of browsing	450607	15248	\$182.04
18-Sep	fleet pride	yoke nut	replaced yoke nut on front of browsing	450607	15248	\$18.04
18-Sep	Motor Power (kenworth)	yoke nut	replace yoke nut on back of transmission	450607	15248	\$28.71
19-Sep	Shop	Oil Leak	tightened bolts on air compressor	451088	15260	
20-Sep	motor power	motor mount	replaced motor mount bushings and bolts	451088	15260	195.97
21-Sep	Shop	Brakes	adjusted brakes	451088	15260	
21-Sep	Shop	odometer	looked for short in speedo cluster	451088	15260	
25-Sep	Shop	Yoke	tightened yoke behind carvier bearing	451088	15260	
9/20/18	NAPA	hood catch/coupler				\$ 29.39
10/14/18	Wheeler	tensioner pulley				\$ 295.68
1-Oct	Motor Power Kenworth	Yoke	Replaced yoke at carrier beaing	453181	15335	\$188.72
1-Oct	Motor Power Kenworth	Yoke Nut	Replaced Yoke Nut	453181	15335	\$9.94
1-Oct	Motor Power Kenworth	u-joint	Replace 2 U-joints	453181	15335	\$205.36
1-Oct	Motor Power Kenworth	Wiperblades	Replace both wiper blades	453181	15335	\$18.24
2-Oct	CMI TECO	Clutch/Brakes	Adjusted clutch brakes	453181	15335	\$37.34
8-Oct	Motor Power	Oil Filter B-99	250 Hour Service	454028	15368	\$10.54
8-Oct	Motor Power	Fuel Filter BF-957	250 Hour Service	454028	15368	\$3.91
8-Oct	Motor Power	Fuel Filter BF-7587	250 Hour Service	454028	15368	\$9.04
8-Oct	Shop/Stock	10 Gallon 15-40 oil	250 Hour Service	454028	15368	
8-Oct	Shop/Stock	1 1/2 Tubes of grease	250 Hour Service	454028	15368	

8-Oct	Napa	1 1/2 Quart of ATF	filled power steering	454028	15368	\$4.50
8-Oct	Shop	Power Steering	fixed leak	454028	15368	
14-Oct	Wyoming Machinery	Tensioner Pulley	replaced alt tensioner & belt	454989	15412	\$295.68
16-Oct	Shop/Stock	Tire 11 R 22.5	replaced blown tire FLI driver side	455454	15434	
17-Oct	Inland Truck Parts	Clutch Brake	replaced clutch brake	455454	14534	\$ 35.84
17-Oct	Shop	PTO Light	traced an dfixd wiring to PTO Light	455454	15434	
22-Oct	Dan's Tire Service	4 Tires 11 R 22.5	Changed tires on rear drive axle	455454	15434	\$1,224.32
31-Oct	Shop	Transmission	removed transmission to replace	456252	15460	0
5-Nov	Six States	Transmission	Installed Transmission	456252	15460	
8-Nov	NAPA	Halogen seal				\$20.98
11-Nov	Motor Power Kenworth	Wheel Seal	Replaced Bad Seal on Left steer Axil	456252	15460	\$47.05
11-Nov	Motor Power Kenworth	Brakes	Replace brakes on steer axil	456252	15460	\$139.32
11-Nov	Motor Power Kenworth	Drums	Replaced brake drums on steer axil	456252	15460	\$348.38
13-Nov	MPE	Filters				\$24.66
12/19/18	MPE	hose assy compdish				\$ 88.36
11/9/18	MPE	Switch reverse				\$ 21.75
10/31/18	NAPA	bearings				\$ 44.12

2019	Vehicle Maintenance		2007 T-800 Kenworth Trans FRO18210-C				
L-537	VIN #228951	Inspected 12/20/2018	1NKDXBTXX8J228951				
	EXPIRES DEC		Steer Tires 425/65R/22.5	beginning			
License	A010276		Drive Tires 11R/22.5				
	Parts from		Tag 245/70R/17.5	end			
	Company parts/svcs		Engine Serial # SDP07707				
DATE	Company parts/svcs	Part#/Description	WORK PERFORMED	MILEAGE	HOURS	COST	
Mileage				456252	15460		
5-Mar	Shop Stock	12 fuses 4-20A 4=15A/4-25A					
5-Mar	Shop Stock	B-99 Oil Filter					
25-Feb	NAPA	40 60 Ros core SL	NOT ON LOG from FEBRUARY			inc	
		soldering pas	?				
25-Feb	Fleet pride	615 EL401038 Stud Standart Battery (2)	?			\$5.34	
26-Feb	MPE Kenworthy	Jumper Cable ASSY BC1044 pos /BC1052 neg	?			\$52.03	
9-Jul	Fleetpride	battery	tested batteries replaced one started making battery cables			\$103.14	
1-Jul	Elite Diesel	ECM				\$4,011.55	
31-Jul	peterbilt of WY	nut R007666				\$29.38	
5-Jul	Allstar service	Battery cable				\$903.38	
8/16/19	MAD Transportation	pick up back end				\$400.00	
8/22/19	Wheeler	Mount	Mount bushings for ECM			\$4.63	
	wheeler	spacer	Spacer for ECM Mount			\$13.37	
	elite deisel	ecm	reinstll ecm				
8/23/2019	Elko	camesa/wedge				\$649.00	
8/30/19	Vernal Stock	LL044803 marker light	R&R Marker lights on bed AMBER				
9/3/19	BART work	mics work by bart	sand and painting			\$1,166.70	
9/3/20	Fleetpride	heat shrink butt connectors				\$70.30	
9/3/19	Kenworth	connector elec	Repair R Diff temp sender plug			\$56.54	
9/6/19	fleetpride	air dryer cartridge	R&R Air dryer cartridge			\$23.99	
		wire loom 3/8	loom wires			\$0.00	
	stock	misc wire connector	repair wiring			\$0.00	
9/9/20	Morcon	silver auto paint				\$229.19	
9/9/19	Kenworth	Clutch brake	Install clutch brake			\$28.61	

9/10/20	stock	5 gal Hyd oil	SERVICE IN VERNAL				\$ 39.99
	fleetpride	5 gal hyd oil	fill hyd tank				\$ 39.99
		10 gal 50-40					\$ 93.20
		2 qt 15W40					\$ 181.48
		B99 Oil filter					\$ 0.00
		BF7587 fuel filter					\$ 0.00
		BF957 fuel filter					\$ 0.00
	STOCK	2 AF25248 air filters	change				
		1 QT 50 W Transoil	top off aux trans				
9/13/19	Napa	Black paint	paint frame				\$ 28.25
		fuel guage	install aux fuel guage				\$ 43.74
	wheeler	socket and pine	R&R Plug comm to grand sensor				\$ 10.23
9/17/19	fleetpride	fuel sending unit	R&R Fuel sensor to grand sensor				\$ 199.15
9/16/19	Best deal springs	marker light	replace marker lights in bed				\$ 219.74
		amber lights					\$ 106.22
9/19/19	fleetpride	1/2 nylon airline	repair air lieak				\$ 12.59
	Dans Tire	235/75R17.5 tire	tag axle				\$ 290.62
9/20/19	wheeler	socked conector	repair elec socket				\$ 6.96
	kenworth	sensor to oring	R&R Crank sensor oring				\$ 118.86
9/30/20	Six states	Tach sensor	install tach sensor for tach				\$ 77.54
10/1/19	Kenworth	Flash CECU	update cab elec control unit				\$ 139.98
10/2/19	stock	grease	grease truck		457966	9524	\$ 20.00
10/2/19	Six States	Tach					\$ 341.94
10/14/19	midwest truck	computer repair					\$ 1,000.00
	LKQ KC Truck Mont	guage cluster					\$ 550.00
19-Oct	shop		checked tire pressure		852180	9544	
25-Oct	Fleet pride	hinge clutch	replaced clutch brake		852501	9560	\$ 29.93
25-Oct	Dans Tire	chain piler					\$ 145.00
26-Oct	Napa	filters					\$ 5.49
		cord					\$ 16.79
1-Oct	Kenworth	Labor on Tach					\$ 115.00
31-Oct	Kenworth	diagnostics ect					\$ 656.59
31-Oct			Checked oil fluid levels and tire pressure		852501	9560	
11-Nov	Fleetpride	air dryer cartrige/farrel	replace nut/farrel on PTD airline and replaced air dryer catridge		852666	9572	\$ 32.81
11-Nov	Shop		bleed all aire tanks on tractor tighten leaking power steering line		852666	9572	
11-Nov	Motor Power	Kit-Purge Valve	Replace purge valve		852666	9572	\$ 121.33
12-Nov	Shop		Hand washed tractor		852666	9572	
13-Nov	Best deal	compressor/core	air compressor				\$ 1,090.95

19-Nov	Motor Power	2 Govenors	replaced only 2 govenors	852666	9572	\$79.22
19-Nov	Vernal Shop	Air Compressor	Replaced air compressor	852666	9572	inc
20-Nov	Motor Power	Air dryer compressor				\$36.45
20-Nov	Napa	Batteries	Replace 4 batteries-returned	852666	9572	\$0.00
26-Nov	Fleetpride	4 Batteries	Purchased batteries (returned the ones from Napa)			\$367.12
2-Dec	Shop		dropped carrier bearings on axel	852877	9588	
3-Dec	ITP	Solid hanger bearing	Purchased for tractor	852877	9588	\$509.77
3-Dec	ITP		u joints	852877	9588	\$121.49
4-Dec	Shop		installed carrier bearing and shaft, checked oil fluids and grease tractor	852877	9588	\$9.00

[illegible]