

| 2013        | Vehicle Maintenance      | Vin# 1NP5LBTX76D896356                                            |                                              |                |              |
|-------------|--------------------------|-------------------------------------------------------------------|----------------------------------------------|----------------|--------------|
| L-564       | 2006 PETERBUILT          | Steer Tires 425/65R22.5<br>Drive Tires 12R24.5<br>Tag 385/65R22.5 |                                              |                |              |
| License     | EXPIRES DEC 140350       |                                                                   |                                              |                |              |
|             | Company parts/svcs       |                                                                   |                                              |                |              |
| <u>DATE</u> | <u>Purchased From:</u>   | <u>Part #/description</u>                                         | <u>WORK PERFORMED</u>                        | <u>MILEAGE</u> | <u>HOURS</u> |
| 1/14/13     | Bessemer Enterprises Inc | Manual Brake Caliper MD1104                                       | for #1 Winch- replaced caliper               |                | \$ 262.50    |
| 1/16/13     | Peterbilt of WY          |                                                                   | Mudflap                                      |                | \$ 8.41      |
| 1/15/13     | 250 Hour SERVICE         |                                                                   | FF105 Fuel Filter                            |                | \$ 3.74      |
|             | Peterbilt of WY          |                                                                   | FF5319 Fuel Filter                           |                | \$ 8.39      |
|             | Peterbilt of WY          |                                                                   | FF691A Oil filter                            |                | \$ 10.41     |
|             | Napa                     |                                                                   | 1 Lucas oil Treatment                        |                | \$ 37.79     |
|             | Homax                    |                                                                   | 15W40 Oil 10 Gal                             |                | \$ 93.35     |
|             |                          | HOMAX                                                             | Grease 3 lbs                                 |                | \$ 11.07     |
| 1/15/13     | Midwest Hose             | Po-04 airhose                                                     | replaced air hose to power divider           |                | \$ 5.73      |
| 1/17/13     | ITP                      | MJTV-4, S768PMT-4-2P                                              | Air Switch-replaced switch for dogs #1 winch |                | \$ 59.81     |
|             | SHOP-Peterbilt           | 1/4" Ferrule/1/4" Insert                                          | Repaired airline to #2 winch air cylinder    |                | \$ 0.41      |
| 1/17/13     | MPE                      | L524X30B                                                          | Replaced mudflaps                            |                | \$ 23.40     |
| 1/17/13     | Peterbilt of WY          | MD1104                                                            | replaced mudflap hangers                     |                | \$ 17.54     |
| 1/17/13     | Cage/Bill/MPE            | 243012GK                                                          | 2 mudflaps.... From ?                        |                | \$ 32.46     |
| 2/8/13      | Fleetpride               | 30-18                                                             | installed new wiper blades                   |                | \$ 17.07     |
| 4/30/13     | ITP                      | PL1064-1066                                                       | Replace AUX transmission mounts              | 6100           |              |
|             | D&H welding              | Trans mounts                                                      |                                              |                | \$ 220.28    |
|             | Snow Dist                | 02382-120                                                         | Greased                                      |                | \$ 7.74      |
|             | Barnes                   | 99784 1/2 Nut                                                     | replaced hardware for Aux Trans 3            |                | \$ 0.54      |
|             |                          | 99763 Washer                                                      | Bracket 6                                    |                | \$ 1.26      |
|             |                          | 99724 Washer                                                      |                                              | 3              | \$ 1.02      |
|             |                          | 99108 1/2 bolt                                                    |                                              | 3              | \$ 1.26      |
|             | NAPA                     | TRTA9225 Paint                                                    | Paint chains and binders                     |                |              |
|             |                          | DAP1692                                                           |                                              |                | \$ 5.98      |
| 5/13/13     | D&H welding              | Weld up cracks                                                    |                                              |                | \$ 178.50    |
| 5/6/13      | ITP                      | PL1066-1064                                                       | Tranny mounts                                |                | \$ 35.32     |
| 5/8/13      | Snow Dist                | 02382-120 Grease                                                  | Greased Truck                                | 6103           | \$ 19.35     |
|             | NAPA                     | 7151030/7151021                                                   | replaced grease zerks 1/6                    |                | \$ 5.11      |
| 5/14/13     | MPE                      | CA338-90 cable                                                    | replaced shift cable aux trans               |                | \$ 254.44    |
|             | Barnes                   | 99797/99722                                                       | nut/washer 1 each                            |                | \$ 0.19      |
| 5/21/13     | NAPA                     | 901001 Core                                                       | replaced valve core LRO                      |                | \$ 0.59      |
| 6/1/13      |                          | chain sling                                                       |                                              |                |              |
| 6/14/13     | Stewart wholesale        | TUL939298                                                         | Lever--plow handles                          |                | \$ 364.48    |

|          |                   |                                         |                                         |  |  |       |      |     |             |
|----------|-------------------|-----------------------------------------|-----------------------------------------|--|--|-------|------|-----|-------------|
| 6/11/13  | MPE               | KIT SEAL TAS650012                      |                                         |  |  |       |      |     | \$ 129.52   |
| 6/11/13  | MPE               | BF957 filter                            | 250 Hr Service                          |  |  |       | 6198 |     | \$ 3.76     |
|          |                   | BF7587 filter                           |                                         |  |  |       |      |     | \$ 8.53     |
|          | HOMAX             | B9955 Filter                            |                                         |  |  |       |      |     | \$ 15.69    |
|          | NAPA              | 1052955-1                               | 15W40 Oil 10 Gal                        |  |  |       |      |     | \$ 89.20    |
|          | NAPA              | 10002 LUCAS                             |                                         |  |  |       |      |     | \$ 37.99    |
|          | Barnes            | MP38237 cotter pins 2                   | repaired chaing                         |  |  |       |      |     | \$ 0.12     |
|          | ?                 | 90-180 valve caps 2                     |                                         |  |  |       |      |     |             |
|          | Snow dist         | 02382-120 greast                        | 3 lb                                    |  |  |       |      |     | \$ 11.61    |
|          | NAPA              | 7151082 grease zerk                     | repaired steering leak                  |  |  |       |      |     | \$ 0.93     |
|          | NAPA              | 7151421 grease zerk                     |                                         |  |  |       |      |     | \$ 0.73     |
| 6/13/13  | Peterbilt of WY   | LL044701 LED Light                      | replaced two marker lights              |  |  | 2     |      |     | \$ 13.12    |
| 6/14/13  | WVY Rigging       | KHSW13 hook                             | hooks and latches for chain slings      |  |  |       | 6199 |     | \$ 217.77   |
| 6/21/13  | Snow distributing | 02382-120 Greased truck                 | G                                       |  |  |       |      |     | \$ 11.61    |
| 6/24/13  | Wvy rigging       | #9 Osha knot 1 1/8" (2)                 | fabricated bridle                       |  |  |       |      |     | \$ 322.14   |
|          |                   | 4060008 wedges (2)                      |                                         |  |  |       |      |     |             |
| 6/26/13  | WVY Rigging       | 1 1/8 bridle                            | Extra bridle                            |  |  |       |      |     | \$ 165.38   |
| 6/26/13  | PDM               | poles for truck                         |                                         |  |  |       |      |     | \$ 5,000.22 |
| 7/22/13  | Kenworth          | SPL250-3X                               | u joints R&R #5 u joints                |  |  |       |      |     | \$ 265.99   |
| 7/23/13  |                   | 250-70-18X                              | Strap kit & Strap                       |  |  |       |      |     | \$ 36.21    |
| 7/12/13  | Simper Supply     | 2A514 Plate                             | for poles                               |  |  | 49712 | 6256 |     | \$ 299.50   |
| 7/26/13  | Basin Auto        | 3 red enamel                            | paint for chains and boomers            |  |  |       |      |     | \$ 40.33    |
| 7/31/13  | Creative décor    | seat cover                              |                                         |  |  |       |      |     | \$ 160.13   |
| 8/1/13   | Bowden welding    | gin pole replacement                    | labor/plates                            |  |  |       |      |     | \$ 3,475.00 |
| 8/2/13   | Basin Auto        | paint/thinner/gloss                     |                                         |  |  |       |      |     | \$ 450.88   |
| 8/13/13  | Tri State         | 8" swatch block                         |                                         |  |  |       |      |     | \$ 1,135.12 |
| 8/16/13  | Tri State         | Alloy latch kit 4320-1096657            |                                         |  |  |       |      |     | \$ 39.94    |
| 10/8/13  |                   | 8 12R24.5 recap drive tires             |                                         |  |  |       |      |     |             |
|          |                   | 8 10 oz balance beads                   |                                         |  |  |       |      |     |             |
|          |                   | 8 4 oz balance beads                    |                                         |  |  |       |      |     |             |
|          | Fleetpride        | air dryer                               | R&R air dryer/cartridge                 |  |  |       |      |     | \$ 39.08    |
|          | stock             | antifreeze                              | gallon and a half                       |  |  |       |      |     |             |
|          | NAPA              | radiator cap                            | R&R radiator cap                        |  |  |       |      |     | \$ 4.99     |
|          |                   | tire guage                              |                                         |  |  | 51234 | 6334 |     | \$ 40.39    |
|          |                   | tire chuck                              |                                         |  |  |       |      | inc |             |
|          | ulhp inspection   | safety inspection                       |                                         |  |  |       |      |     | \$ 15.00    |
| 10/9/13  | napa auto         | 18" flag, antenna, osl sign, latch kits | air freshener                           |  |  |       |      |     | \$ 114.04   |
| 11/4/13  | hsc               | 1 1/8" Bridle                           | slings latch                            |  |  |       |      |     | \$ 53.22    |
| 12/6/13  | Peterbilt         | winterfront                             |                                         |  |  |       |      |     | \$ 64.33    |
| 12/30/12 | Peterbilt         | starter/seal kit                        | R&R starter/R&R input seal front driver |  |  | 51475 | 6351 |     | \$ 434.15   |

|         |                     |                        |                                                      |        |       |           |  |
|---------|---------------------|------------------------|------------------------------------------------------|--------|-------|-----------|--|
| 2014    | Vehicle Maintenance |                        | Vin# 1NP5LBTX76D896356                               |        |       |           |  |
|         |                     |                        | SAFETY INSPECTION 11/20/2014                         |        |       |           |  |
| L-564   | 2006 PETERBUILT     |                        | Steer Tires 425/65R22.5                              |        |       |           |  |
|         |                     |                        | Drive Tires 12R24.5                                  |        |       |           |  |
| License | 140350              |                        | Tag 385/65R22.5                                      |        |       |           |  |
|         | EXPIRES DEC         |                        | Axle Spacing: O 22'3" O 4'9" O 4'9" O 8'9" wide      |        |       |           |  |
|         | Company parts/svcs  |                        |                                                      |        |       |           |  |
| DATE    | Purchased From:     | Part #/description     | WORK PERFORMED                                       | MILAGE | HOURS | COST      |  |
| 1/8/14  | NAPA                | Tire chain parts       |                                                      |        |       | \$ 101.51 |  |
| 2/18/14 | GSS                 | Wash                   | Truck wash                                           |        |       | \$ 96.00  |  |
| 2/15/14 | Barnes              | KP61397X Plug          | Replaced light plug in tailboard                     |        | 6390  | \$ 26.55  |  |
|         |                     | 99029 5/16 bolt        | replaced broken bolts and hardware for trailer pplug |        |       | \$ 0.24   |  |
|         |                     | 99761 5/16 flat washer | plug                                                 |        |       | \$ 0.10   |  |
|         |                     | 99721 5/16 lock washer |                                                      |        |       | \$ 0.12   |  |
| 2/26/14 | MPE                 | PE27100 PLUG           | replaced broker plugs on trailer cord                |        |       | \$ 11.93  |  |
| 3/10/14 | NAPA                | 10002 Lucas            | 200 Hr Service                                       |        | 6407  | \$ 37.79  |  |
|         | snow distrib        | 02382-120 Grease       |                                                      |        |       | \$ 11.61  |  |
|         | Homax               | 1052955-1 15W40        |                                                      |        |       | \$ 93.80  |  |
|         | MPE                 | B99 oil filter         |                                                      |        |       | \$ 10.22  |  |
|         |                     | BF957 FF               |                                                      |        |       | \$ 3.57   |  |
|         |                     | BF7587 FF              |                                                      |        |       | \$ 8.53   |  |
|         | CMI TECO            | LFW4685                | replaced coolant filter                              |        |       |           |  |
|         |                     |                        | tightened input yoke front differential              |        |       | \$ 7.00   |  |
| 3/11/14 | Barnes              | 99062 3/16 bolt        | replaced bolt and nut for gin pole pins              |        |       | \$ 0.72   |  |
|         |                     | 34273 5/16 Nyloc       |                                                      |        |       | \$ 0.08   |  |
|         |                     | 38210 cotter pin       |                                                      |        |       | \$ 0.06   |  |
|         | Vernal              | 550026909              | 50 WT Changed oil inmain and aux trans and winches   |        |       | \$ 314.69 |  |
|         |                     | 7000074 75 W 90        | changed oil in differential                          |        |       | \$ 380.40 |  |
| 3/24/14 | snow distrib        | 02382-120 Grease       | greased truck                                        |        | 6482  | \$ 7.74   |  |
|         | WYO rigging         | Wire rope sling        | new rope sling for truck                             |        |       | \$ 221.03 |  |
|         |                     |                        | coolant lead tightened sensor on coolant tank        |        |       | \$ 0.00   |  |
|         | MPE                 | TAS650012 seal kit     | ps leak replaced sector shaft                        |        |       | \$ 117.52 |  |
|         | NAPA                | 091847 bralkeen        | seal                                                 |        |       | \$ 2.30   |  |
| 3/27/14 | WYO Rigging         | 1" Bridle              |                                                      |        |       | \$ 178.76 |  |
|         | fleetpride          | 8260 Side fastener     | repaired tire chain                                  |        |       | \$ 10.70  |  |
| 3/21/14 | Menards             | ratchet tiedown        |                                                      |        |       | \$ 55.96  |  |
|         | Peterbilt           | BELTS                  | D84-1000-3061340 6 rib, D84-1000-6082520 8 rib       |        |       | \$ 64.28  |  |
| 4/2/14  | Barnes              | 99056 3/8 bolt         |                                                      |        |       | \$ 0.92   |  |
|         |                     | 99782 3/8 nut          |                                                      |        |       | \$ 0.24   |  |
|         |                     | 99762 3/8 washer       |                                                      |        |       | \$ 1.04   |  |
| 4/11/14 | MPE                 | B99 Oil filter         | 200 Hour Service ETD                                 |        | 6593  | \$ 10.64  |  |

|          |              |                        |                                       |  |  |      |           |
|----------|--------------|------------------------|---------------------------------------|--|--|------|-----------|
|          |              | BF957 Fuel filter      |                                       |  |  |      | \$ 3.76   |
|          |              | BF7587 Fuel filter     |                                       |  |  |      | \$ 8.86   |
|          | HOMAX        | 1052955-1 15W/40 oil   |                                       |  |  |      | \$ 84.96  |
|          | Vernal       | 02382-120 Grease       | greased truck                         |  |  |      | \$ 11.61  |
|          | MPE          | 10002 Lucas oil        |                                       |  |  |      | \$ 27.99  |
|          | NAPA         | 7151021 Grease Fitting | replaced grease fitting               |  |  |      | \$ 0.73   |
| 4/14/14  | MPE          | CT300 Clamp            | replaced broken hose clamp            |  |  |      | \$ 7.98   |
| 4/16/14  | Barnes       | 38219 cotter pin       |                                       |  |  |      | \$ 0.46   |
|          | NAPA         | Nut loosener           |                                       |  |  |      | \$ 10.45  |
|          | wy rigging   | 1 crimped bridle       | on back of truck bed                  |  |  |      | \$ 178.76 |
| 4/22/14  | Barnes       | 998185 12A fuse        |                                       |  |  |      | \$ 0.65   |
| 4/30/14  | Snoe dist    | 02382-120 Grease       | greased truck                         |  |  |      | \$ 7.74   |
|          | Barnes       | MP38224                | Cotter pins X 2                       |  |  |      | \$ 0.10   |
| 7/15/14  | NAPA         | 901001 valve core      | replaced valve core LRO tire          |  |  |      | \$ 0.59   |
| 7/30/14  | snow distrib | 02382-120              | greased truck                         |  |  | 6749 | \$ 11.61  |
|          | MPE          | 15-720 receptacle      | replaced trailer plug in              |  |  |      | \$ 10.12  |
|          |              | 3050 light             | replaced rear marker light            |  |  |      | \$ 5.03   |
|          | HOMAX        | 3200-55 coolant        | added gallon coolant                  |  |  |      | \$ 7.12   |
| 8/6/14   | wy rigging   | 1/2" chain sling       | cabin sling for truck                 |  |  |      | \$ 416.30 |
| 8/19/14  | HOMAX        | 1052955-1 15W/40 oil   | 200 Hour Service                      |  |  | 6787 | \$ 89.20  |
|          | snow distrib | 02382-120 grease       |                                       |  |  |      | \$ 11.61  |
|          | mpe          | 10002                  | lucas                                 |  |  |      | \$ 27.99  |
|          |              | b99 oil filter         |                                       |  |  |      | \$ 10.54  |
|          |              | BF957 FF               |                                       |  |  |      | \$ 3.84   |
|          |              | BF7587 FF              |                                       |  |  |      | \$ 8.77   |
|          |              |                        | adjust brakes                         |  |  |      | \$ 0.00   |
| 10/28/14 | VVY rigging  | 1 1/8 osha knot        | osha knot and wedges for truck        |  |  |      | \$ 78.38  |
| 11/6/14  | MPE          | 243012GK mudflap       | replaced right rear mudflap           |  |  | 6887 | \$ 15.42  |
|          | snow distrib | 02382-120 grease       | greased truck                         |  |  |      | \$ 11.61  |
|          | MPE          | R5324 coolant filter   | replaced coolant filter               |  |  |      | \$ 5.96   |
|          |              |                        | straighten bumper guide               |  |  |      | \$ 0.00   |
| 11/21/14 | HOMAX        | 1052955-1 15W/40 oil   | 200 hour service                      |  |  | 7015 | \$ 89.20  |
|          | snow distrib | 02382-10 grease        |                                       |  |  |      | \$ 11.61  |
|          | MPE          | B99 oil filter         |                                       |  |  |      | \$ 10.64  |
|          |              | BF7587 Fuel filter     |                                       |  |  |      | \$ 8.86   |
|          |              | BF957 oil filter       |                                       |  |  |      | \$ 3.82   |
|          |              | 2402GK mudflap         | replace left rear mudflap             |  |  |      | \$ 15.42  |
|          | HOMAX        | 3200-55 coolant        | added coolant                         |  |  |      | \$ 7.12   |
|          | VERNAL       | LAFA816 air filter     | replaced airfilters with cleaned ones |  |  |      | \$ 23.38  |
| 12/15/14 | VVY RIGGING  | 1" osha knot           | osha know and wedges for truck        |  |  | 7130 | \$ 75.38  |
| 12/18/14 | snow distrib | 02382-120 grease       | greased truck                         |  |  |      | \$ 11.61  |

|                |                            |                           |                                              |                   |                 |             |  |
|----------------|----------------------------|---------------------------|----------------------------------------------|-------------------|-----------------|-------------|--|
| <b>2015</b>    | <b>Vehicle Maintenance</b> |                           | <b>Vin# 1NP5LBTX76D896356</b>                |                   | <b>Year end</b> |             |  |
|                |                            |                           | <b>SAFETY INSPECTION</b>                     | <b>12/16/2015</b> | <b>58609</b>    | <b>7387</b> |  |
| <b>L-564</b>   | <b>2006 PETERBUILT</b>     |                           | <b>Steer Tires 425/65R22.5</b>               |                   |                 |             |  |
|                |                            |                           | <b>Drive Tires 12R24.5</b>                   |                   |                 |             |  |
| <b>License</b> | <b>140350</b>              |                           | <b>Tag 385/65R22.5</b>                       |                   |                 |             |  |
|                | <b>EXPIRES DEC</b>         |                           | <b>Axle Spacing: O 22'3" O 4'9" O 4'9" O</b> |                   |                 |             |  |
|                | <b>Company parts/svcs</b>  |                           | <b>8'9" wide</b>                             |                   |                 |             |  |
| <b>DATE</b>    | <b>Purchased From:</b>     | <b>Part #/description</b> | <b>WORK PERFORMED</b>                        | <b>MILEAGE</b>    | <b>HOURS</b>    | <b>COST</b> |  |
| 1/20/15        | Snow Dist                  | 02382-120 Grease          | 200 Hr Service                               |                   | 7269            | \$ 11.61    |  |
|                | Homax                      | 1052955-1 15W40           |                                              |                   |                 | \$ 89.20    |  |
|                | MPE                        | B99 Oil filter            |                                              |                   |                 | \$ 10.14    |  |
|                |                            | BF957 Fuel filter         |                                              |                   |                 | \$ 3.82     |  |
|                |                            | BF7587 fuel filter        |                                              |                   |                 | \$ 8.86     |  |
|                |                            | 10002 Lucas               |                                              |                   |                 | \$ 27.99    |  |
| 1/22/15        |                            | 330-3009 Gasket           | replaced wheel seal-right steer              |                   | 7271            | \$ 1.43     |  |
|                |                            | 43761 seal                |                                              |                   |                 | \$ 46.20    |  |
|                | Homax                      | 1053887-20 75W90          |                                              |                   |                 | \$ 7.90     |  |
|                | Fleetpride                 | 1080-06 PS                | Fuel additive                                |                   |                 | \$ 15.35    |  |
| 11/21/15       | Fleetpride                 | 849 1025-12               | 2 qts fuel treatment                         |                   |                 | \$ 13.83    |  |
| 11/23/15       | HOMAX                      | #1 fuel                   | 110 gal                                      |                   |                 | \$ 320.44   |  |
|                |                            |                           |                                              |                   |                 |             |  |

|          |                     |                     |                                                             |            |       |           |      |  |
|----------|---------------------|---------------------|-------------------------------------------------------------|------------|-------|-----------|------|--|
| 2016     | Vehicle Maintenance |                     | Vin# 1NP5LBTX76D896356                                      |            |       |           |      |  |
|          |                     |                     | SAFETY INSPECTION                                           | 12/16/2015 |       |           |      |  |
| L-564    | 2006 PETERBULT      |                     | Steer Tires 425/65R22.5                                     |            |       |           |      |  |
|          |                     |                     | Drive Tires 12R24.5                                         |            |       | beginning |      |  |
| License  | 140350              |                     | Tag 385/65R22.5                                             |            |       | 58609     | 7387 |  |
|          | EXPIRES DEC         |                     | Axle Spacing: O 22'3" O 4'9" O 4'9" O                       |            |       | end       |      |  |
|          | Company parts/svcs  |                     | 8'9" wide                                                   |            |       |           |      |  |
| DATE     | Purchased From:     | Part #/description  | WORK PERFORMED                                              | MILEAGE    | HOURS | COST      |      |  |
| 1/1/16   |                     |                     | beginning miles                                             |            |       |           |      |  |
| 6/7/16   |                     |                     | Power Steering Fluid                                        |            |       | \$ 3.87   |      |  |
| 7/8/16   |                     |                     | Tested batteries, starting and charging system              |            |       |           |      |  |
|          | stewart             | BRA11658            | grease seal kit                                             |            |       | \$ 29.93  |      |  |
| 7/11/16  | Fleetpride          | F315-1000 battery   | replaced four batteries, cleaned cable ends and battery box |            | 7411  | \$ 407.29 |      |  |
|          |                     | core credit         |                                                             |            |       | -\$ 23.63 |      |  |
| 7/26/16  | VERNAL              | Seal                | Replaced worm gear seal #1 winch                            |            |       |           |      |  |
| 7/27/16  | HOMAX               | 15W90 oil           |                                                             |            |       | \$ 135.98 |      |  |
| 11/14/16 | IME                 | Ac1001 Cartridge    | replaced air dryer cartridge                                |            |       | \$ 29.60  |      |  |
|          |                     | B5134               | Replaced coolant filter-cleaned air cab air filter          |            |       | \$ 5.96   |      |  |
|          | NAPA                | 75200 ATF           | fixed power steering reservoir                              |            |       | \$ 2.20   |      |  |
|          | IME                 | LL091810 pigtail    | replaced right turn light and pigtrain in headache rack     |            |       | \$ 1.50   |      |  |
|          |                     | 60605 reverse light |                                                             |            |       | \$ 51.43  |      |  |
|          |                     | LL09181810pig tail  |                                                             |            |       | \$ 1.58   |      |  |
|          |                     | 6050 oval STT Light | inspected suspension, drivelines and checked all fluids     |            |       | \$ 21.99  |      |  |
| 12/5/16  | dan                 |                     | vehicle inspection                                          |            |       | \$ 15.00  |      |  |
|          |                     |                     |                                                             |            |       |           |      |  |
|          |                     |                     |                                                             |            |       |           |      |  |

|         |                     |                         |                                                                            |            |           |           |  |
|---------|---------------------|-------------------------|----------------------------------------------------------------------------|------------|-----------|-----------|--|
| 2017    | Vehicle Maintenance |                         | Vin# 1NP5LBTX76D896356                                                     |            |           |           |  |
|         |                     |                         | SAFETY INSPECTION                                                          | 12/05/2017 |           |           |  |
| L-564   | 2006 PETERBUILT     |                         | Steer Tires 425/65R22.5                                                    |            |           |           |  |
|         |                     |                         | Drive Tires 12R24.5                                                        |            | beginning |           |  |
| License | 140350              |                         | Tag 385/65R22.5                                                            |            |           |           |  |
|         | EXPIRES DEC         |                         | Axle Spacing: O 22'3" O 4'9" O 4'9" O                                      |            | end       |           |  |
|         | Company parts/svcs  |                         | 8'9" wide                                                                  |            |           |           |  |
| DATE    | Purchased From:     | Part #/description      | WORK PERFORMED                                                             | MILEAGE    | HOURS     | COST      |  |
| 1/1/17  |                     |                         | beginning miles                                                            | 58853      | 7429      | \$ 0.00   |  |
| 1/9/17  |                     |                         | reinstalled winch chain and sprocket on pillar block.                      |            | 7443      |           |  |
| 1/17/17 | Peterbilt           | 304446 seal             | locitte allen screws. replaced wheel seals and brake shoe on               |            |           |           |  |
|         | NAPA                | 470BTCR Brake Shoe      | front differential. Cleaned and inspected bearings. hubs and brake         |            | 7457      | \$ 111.38 |  |
|         | HOMAX               | 09134 Brakleen          | drums. Filled hubs & Differential with 75W90 synthetic oil.                |            |           | \$ 195.59 |  |
|         |                     | 1053887-20 75W90        |                                                                            |            |           | \$ 5.66   |  |
|         |                     |                         | adjusted brakes adjusted clutch                                            |            |           | \$ 27.56  |  |
| 1/20/17 | MPE                 | TE12938 rod end         | replaced left tie rod end- adjusted toe in                                 |            |           | \$ 50.04  |  |
|         | Snow Dist           | 02382-120 Grease        | rotated steer tires greased front end                                      |            |           | \$ 3.87   |  |
| 1/31/17 | Homax               | 1052955-1 15W40         | 250 HR Service                                                             |            | 7514      | \$ 76.70  |  |
|         | Snow Dist           | 02382-120 Grease        |                                                                            |            |           | \$ 7.74   |  |
|         | MPE                 | B99 Oil filter          |                                                                            |            |           | \$ 10.95  |  |
|         |                     | BF7587 Fuel filter      |                                                                            |            |           | \$ 9.32   |  |
|         |                     | BF957 filter            |                                                                            |            |           | \$ 4.11   |  |
|         |                     | 1002 Lucas              |                                                                            |            |           | \$ 29.40  |  |
| 2/23/17 | Auto Glass Pro      | 22*20 X 2               | windows-rear window replacement                                            |            |           | \$ 94.52  |  |
| 2/21/17 | Pacific Steel       | 1 1/2" 4140 round steel | fabricated new pin for rear sheep foot                                     |            |           | \$ 11.45  |  |
|         | Class c Solutions   | 99724 1/2" washer       |                                                                            |            |           | \$ 0.17   |  |
| 3/1/17  |                     | 1 1/8 x 165" wire rope  | replaced wire rope on #1 winch. Inspected front axle & Springs             |            | 7575      |           |  |
| 3/2/17  |                     |                         | tightened front wheel bearings. Rear pins and bushings on steer axle       |            |           | \$ 0.00   |  |
|         |                     |                         | are worn.                                                                  |            |           | \$ 0.00   |  |
| 3/6/17  | Snow                | 02382-120 Grease        | greased truck                                                              |            | 7602      | \$ 11.61  |  |
| 3/7/17  | Peterbilt           | MPB452 Shackle kit      | replaced pins, busings and shackles on steer axle rear springs and hangers |            |           | \$ 294.04 |  |
|         |                     | 1" Bridle               | new bridle for truck                                                       |            |           | \$ 178.76 |  |
|         |                     |                         |                                                                            |            |           |           |  |
| 5/12/17 | Homax               | 1078334-1 15W40 oil     | 250 Hour Service                                                           |            | 7829      | \$ 84.37  |  |
|         | Snow                | 02382-120 Grease        |                                                                            |            |           | \$ 7.74   |  |
|         | MPE                 | B99 OF                  |                                                                            |            |           | \$ 10.96  |  |
|         |                     | BF7587 Ff               |                                                                            |            |           | \$ 9.33   |  |
|         |                     | BF957 FF                |                                                                            |            |           | \$ 3.84   |  |
|         | Peterbilt           | 572-1014 fuel cap       | Replaced missing cap                                                       |            |           | \$ 110.70 |  |
| 6/15/17 |                     | 02382-120 Grease        | inspected/greased/adjusted brakes/cleaned inner & Outer air filters        |            | 7891      | \$ 11.61  |  |

|           |                   |                     |                                                                 |  |  |      |           |
|-----------|-------------------|---------------------|-----------------------------------------------------------------|--|--|------|-----------|
| 6/22/17   |                   |                     | A/C Evaprator, blower fan and ducting                           |  |  | 7893 | \$ 0.00   |
|           | Peterbilt         | 531-6016 cylinder   | replaced mode actuator cylinder/air flow cylinder               |  |  |      | \$ 144.30 |
| 6/29/17   | Snow Dist         | 02382-120 Grease    | greased/adjusted brakes                                         |  |  | 7904 | \$ 7.74   |
| 8/18/17   |                   |                     | repaired broken section of dashboard, repaired glove box        |  |  | 7980 | \$ 0.00   |
| 8/29/17   | Snow Dist         | 02382-120 Grease    | greased/adjusted brakes, adjusted and lubricated #2 winch chain |  |  | 7985 | \$ 7.74   |
| 10/26/17  | Casper Fire       | 442238 extinguisher | replaced fire extinguisher and bracket                          |  |  | 8003 | \$ 57.75  |
|           | Fleetpride        | 5008414 cartridge   | replaced airdryer cartridge                                     |  |  |      | \$ 19.94  |
|           | Class C solutions | 99006 1/4 bolt      |                                                                 |  |  |      | \$ 0.26   |
|           |                   | 99740 1/4 washer    |                                                                 |  |  |      | \$ 0.14   |
|           |                   | 32577 fender washer |                                                                 |  |  |      | \$ 0.24   |
|           |                   | 34272 1/4 nyloc     |                                                                 |  |  |      | \$ 0.08   |
| 11/7/2017 | Snow Dist         | 02382-120 Grease    | greased/adjusted brakes-replaced hardware in bug deflector      |  |  |      | \$ 0.00   |
|           |                   |                     |                                                                 |  |  |      |           |
|           |                   |                     |                                                                 |  |  |      |           |

|           |                             |                    |                                     |         |       |          |  |  |
|-----------|-----------------------------|--------------------|-------------------------------------|---------|-------|----------|--|--|
| 2018      | Vehicle Maintenance         |                    | Vin# 1NP5LBTX76D896356              |         |       |          |  |  |
| L-564     | 2006 PETERBUILT             |                    | SAFETY INSPECTION 12/05/2018        |         |       |          |  |  |
| License   |                             |                    | Steer Tires 425/65R22.5             |         |       |          |  |  |
|           |                             |                    | Drive Tires 12R24.5                 |         |       |          |  |  |
|           |                             | 140350             | Tag 385/65R22.5                     |         |       |          |  |  |
|           | EXPIRES DEC                 |                    | Axle Spacing: O 22'3" O 4'9" O      |         |       |          |  |  |
|           | Company parts/svcs          |                    | 8'9" wide                           |         |       |          |  |  |
| DATE      | Company parts/svcs          |                    |                                     |         |       |          |  |  |
| 1/1/18    | Purchased From:             | Part #/description | WORK PERFORMED                      | MILEAGE | HOURS | COST     |  |  |
|           |                             |                    | beginning miles                     |         |       |          |  |  |
|           |                             |                    |                                     |         |       |          |  |  |
|           |                             |                    |                                     |         |       |          |  |  |
|           |                             |                    |                                     |         |       |          |  |  |
|           |                             |                    |                                     |         |       |          |  |  |
| 4/13/2018 | shop                        |                    | adjusted clutch                     | 65211   | 8137  |          |  |  |
| 4/13/2018 | shop                        | air fitting        | fixed air leak                      | 65211   | 8137  |          |  |  |
| 4/13/2018 | shop                        |                    | checked fluid levels                | 65211   | 8137  |          |  |  |
| 25-Apr    | shop                        |                    | adjusted clutch                     | 65211   | 8137  |          |  |  |
| 2-May     | Napa                        | Turn Signal Lights | Replace turn signal lights          |         |       | \$33.98  |  |  |
| 3-Jul     | shop                        | pillar block       | realine the pillar block and #winch | 65612   | 8187  |          |  |  |
| 5-Jul     | shop                        |                    | slip oshaknot on #1 line            | 65612   | 8187  |          |  |  |
| 5-Jul     | shop                        |                    | finished pillar block               | 65612   | 8187  |          |  |  |
| 5-Jul     | shop                        |                    | adjusted clutch                     | 65612   | 8187  |          |  |  |
| 5-Jul     | shop                        |                    | freed up top block                  | 65612   | 8187  |          |  |  |
| 20-Jul    | shop                        | pillar block       | tightened set screws                | 65829   | 8227  |          |  |  |
| 24-Jul    | western sling and supply co | sling hook         | replaced 2 sling hooks              | 65829   | 8227  | \$211.01 |  |  |
| 4-Dec     | Shop                        | Annual Inspection  | Preformed Annual Inspection         | 65958   | 8262  |          |  |  |
| 4-Dec     | Shop                        | Brakes             | Adjusted Brakes                     | 65958   | 8262  |          |  |  |
|           |                             |                    |                                     |         |       |          |  |  |
|           |                             |                    |                                     |         |       |          |  |  |

|         |                     |                                               |                                                                              |                 |        |          |  |
|---------|---------------------|-----------------------------------------------|------------------------------------------------------------------------------|-----------------|--------|----------|--|
| 2019    | Vehicle Maintenance |                                               | Vin# 1NP5LBTX76D896356                                                       |                 |        |          |  |
| L-564   | 2006 PETERBUILT     |                                               | SAFETY INSPECTION 12/05/2018                                                 |                 |        |          |  |
| License |                     |                                               | Drive Tires 425/65R22.5                                                      |                 |        |          |  |
|         | EXPIRES DEC 140350  |                                               | Tag 385/65R22.5                                                              | beginning 66279 |        |          |  |
|         | COMPANY parts/svcs  |                                               | Axle Spacing: O 22'3" O 4'9" O 4'9" O 8'9" wide                              | end 68194       |        |          |  |
| DATE    | Purchased From:     | Part #/description                            | WORK PERFORMED                                                               | MILEAGE         | HOURS  | COST     |  |
| Mileage |                     |                                               |                                                                              | 66279           | 8309.4 |          |  |
| 2/25/19 | WESTERN CLING       | Wedge Ferrule 1                               | NOT ON LOG                                                                   |                 |        | \$ 74.40 |  |
| 4-Mar   | ???                 | Steel Tires                                   | 2 425-65R22.5 Tires installed                                                | 66766           | 8346   |          |  |
| 3-Mar   | Shop Stock          | BF 7587 Fuel Filter and<br>BF 957 Fuel Filter | full service, grease checked gear boxes                                      | 66766           | 8346   |          |  |
| 6-Mar   |                     |                                               | Grease small drive lines steering had to buy new grease needles<br>paid cash | 66766           | 8346   | \$0.00   |  |
| 8-Mar   | ??                  | 2-H4651 Head Lights                           | Change out                                                                   | 66766           | 8346   |          |  |
| 5/17/19 | napa                | 50-6050-3 LED SS S T T                        | ?                                                                            |                 |        | \$ 23.65 |  |
|         |                     | 3 wire plug                                   | ?                                                                            |                 |        | \$ 3.61  |  |
|         |                     | 770-1757 tape                                 | ?                                                                            |                 |        | \$ 4.92  |  |
| 15-Jul  | Napa                | PAG Oil A/C oil 8 oz<br>2.87lbs               | charged the AC                                                               |                 |        | \$24.35  |  |
|         |                     | 209578 sch core                               |                                                                              |                 |        | \$17.75  |  |
| 16-Jul  | Fleetpride          | SPL250 U-Joint                                | Replaced u-joint behind the browny                                           | 67299           | 84693  | \$84.54  |  |
| 13-Aug  | Fleetpride          | SPL250-3X u joint                             |                                                                              |                 |        | \$151.14 |  |
| 14-Aug  | Fleetpride          | 864 250-70-18X                                |                                                                              |                 |        | \$158.35 |  |
| 15-Aug  | napa                | silver/red line lumen                         |                                                                              |                 |        | \$21.85  |  |
| 16-Aug  | napa                | silver and masking tape                       |                                                                              |                 |        | \$161.41 |  |
|         | Napa                | fill in and paint                             |                                                                              |                 |        | \$178.22 |  |
| 19-Aug  | Napa                | Siler (Paint?)                                |                                                                              |                 |        | \$122.57 |  |
| ?       | Napa                | silver paint                                  |                                                                              |                 |        | \$84.29  |  |
|         | fleetpride          | u joints                                      | sp1250-3X/864 250 70 18X                                                     |                 |        | \$7.02   |  |
| 20-Aug  | DRB Metal Works     | Welding                                       | repaired right hand tool boc and access ladder                               |                 |        | \$172.99 |  |
| 24-Aug  | billy curtis        | check codes                                   |                                                                              |                 |        | \$420.00 |  |
| 20-Sep  | Fuel Filters        | Fuel Filters                                  | replaced 2 fuel filters                                                      |                 |        | \$90.00  |  |
|         | comm tech           | mic                                           |                                                                              |                 |        | \$17.21  |  |
| 22-Sep  | ghostown            | mic holder/misc                               |                                                                              |                 |        | \$20.60  |  |
| 1-Oct   | Shop                |                                               | clean batteries/sprayed protectant on them                                   | 67527           | 8526   | \$18.86  |  |
| 2-Oct   | MPE                 | check codes                                   |                                                                              |                 |        |          |  |
| 8-Oct   | DFS Supplement      | fleetpride                                    | added to fuel tanks                                                          | 67527           | 8526   | \$132.68 |  |
| 12-Oct  | Key Stock           |                                               | replaced key stock and whinch                                                | 67527           | 8526   | \$16.49  |  |
|         |                     |                                               |                                                                              | 67527           | 8526   | \$8.27   |  |

|        |                 |                                                      |                                                                                  |                                           |       |      |          |
|--------|-----------------|------------------------------------------------------|----------------------------------------------------------------------------------|-------------------------------------------|-------|------|----------|
| 26-Oct | Napa            | filters                                              |                                                                                  | Clean tractor check fluids grease tractor | 67758 | 8595 | \$16.39  |
| 27-Oct |                 |                                                      |                                                                                  |                                           |       |      |          |
| 4-Nov  | Best deal       | Brake reline                                         |                                                                                  |                                           |       |      | \$109.33 |
| 12-Nov | Napa            | Oil and fuel filters                                 | replaced fuel/oil filters greased tractor clean interior put poles back together | 68072                                     | 8613  |      | \$30.99  |
| 12-Nov | shop            |                                                      | handwashed tractor                                                               | 68072                                     | 8613  |      |          |
| 13-Nov | walmart         | spray paint                                          | painted the front bumper                                                         | 68072                                     | 8613  |      | \$43.66  |
| 4-Dec  | Peterbilt of Wy | Power steering pump, seal, gasket, o ring and filter | replaced power steering pump, seal and filter greased tractor                    | 68115                                     | 8634  |      | \$540.00 |
| 16-Dec | fleetpride      | new air dryer                                        | removed and replaced air dryer replaced broken chain                             | 68194                                     | 8695  |      | \$121.01 |
| 17-Dec | shop            |                                                      | removed and replaced mud flaps, and greased truck                                | 68194                                     | 8695  |      |          |
|        |                 |                                                      |                                                                                  |                                           |       |      |          |
|        |                 |                                                      |                                                                                  |                                           |       |      |          |
|        |                 |                                                      |                                                                                  |                                           |       |      |          |

| 2020    | Vehicle Maintenance | Vin# 1NP5LBTX76D896356                |                                |         |           |
|---------|---------------------|---------------------------------------|--------------------------------|---------|-----------|
|         |                     | <b>SAFETY INSPECTION</b>              |                                |         |           |
| L-564   | 2006 PETERBUILT     | Steer Tires 425/65R22.5               |                                |         |           |
|         |                     | Drive Tires 12R24.5                   | beginning                      |         |           |
| License | 140350              | Tag 385/65R22.5                       | 68194                          |         |           |
|         | EXPIRES DEC         | Axle Spacing: O 22'3" O 4'9" O 4'9" O | end                            |         |           |
|         | Company parts/svcs  | 8'9" wide                             |                                |         |           |
| DATE    | Purchased From:     | Part #/description                    | WORK PERFORMED                 | MILEAGE | HOURS     |
| 1/8/20  | Eiko                | 1/2 grade chain                       |                                |         | \$ 268.76 |
| 2/18/20 | Peterbilt of WY     | Pump                                  | windshield washer              |         | \$ 49.94  |
| 26-Aug  | Napa                |                                       | Replaced Batteries 4 batteries |         | \$367.46  |
| 12/9/21 | Shop                |                                       | Cleaned air filter             | 68540   | 8738      |
|         |                     |                                       |                                |         |           |
|         |                     |                                       |                                |         |           |
|         |                     |                                       |                                |         |           |
|         |                     |                                       |                                |         |           |