

2013	Vehicle Maintenance	Vin# 1NKCLBTX07R194462		
L-566 License	2007 KENWORTH EXPIRES DEC 154370	Steer Tires 425/65R22.5 Drive Tires 1200/24	1200/24	
DATE	Company parts/svcs Purchased From:	Part #/Description	WORK PERFORMED	MILEAGE HOURS COST
1/6/13	Peterbilt of WY	40979397/96 MID	Slack Adjusters-replaced on rear drive axle	5608 \$ 571.70
1/3/13	NAPA	QG20061	4 side chain fasteners (cam locks) not on VM log	\$ 18.86
1/4/13	Peterbilt of WY	CF2M1D	Kit-Yoke	\$ 10.86
1/7/13	SHOP	250 Hour SERVICE	LF691A Oil Filter	5608 \$ 10.40
			LF5319 Fuel Filter	\$ 8.39
			FS1000 Water Separator	\$ 10.52
			Lucas Oil Treatment 1	\$ 37.49
			15W40 Oil 10 Gal	\$ 92.30
			brake clean (2)	\$ 6.21
			Grease 3	\$ 11.62
1/8/13	NAPA	02382-120-HOMAX BP1255H3	halogen bulb -replaced work light	5608 \$ 9.85
	SHOP		Adjusted clutch	\$ 0.00
1/29/13	SHOP	PERMATURE 250 hr service	LF691A Oil Filter	5660 \$ 10.21
			FF5319 Fuel Filter	\$ 10.40
			FS1000 Water Separator	\$ 8.39
1/29/13		NAPA 10002	Lucas Oil Treatment 1	\$ 37.49
1/29/13	MPE	Homax	15W40 oil 10 Gal	\$ 92.30
2/1/13	WRIS	F63976	GREASE	\$ 7.38
2/4/13	Cage JR	Line	Union Repair air leak	\$ 10.21
2/7/13	Peterbilt of WY	WRIS	1 1/4"X175' Winch Linewire rope straight cut,	5660 \$ 1,169.74
	NAPA	BA22250 switch	1" Bridle	\$ 107.68
	NAPA		installed battery disconnect switch	\$ 132.74
	NAPA		728118 LUG	\$ 36.91
	Hensley		727653 Shrink Tubing	\$ 10.65
2/10/13	SHOP	052955-1	4725 Battery Cable(4)	\$ 35.87
2/25/13	shop-bill	WRIS	Added 3 Gal of engine oil	\$ 28.00
2/27/13	shop-JR	WRIS	1 1/8" bridle	\$ 165.78
3/1/13	Vernal	Brake shoes?	1 1/8" bridle	\$ 165.78
			replaced right rear drive axle brake shoe kit	
			replaced right rear drive axle brake shoe kit	
			brakeclean	
3/11/13	WY Rigging	LIUGNUT WN6000	replaced lugnut on right rear drive axle	
3/27/13		1 1/8" bridle	Bridle for truck--new	\$ 165.38
4/2/13	Vernal Shop	glass cleaner	replaced brake shoes left rear drive axle	
		brake shoes (2)		50679 5899

	NAPA	091314 Brakleen	Greased				\$ 11.61
	Snow Distributing	02380020 Grease					
4/12/13	ITP	Brakes	relined brakes				\$ 100.00
4/18/13	ITP		Built driveline/front section from Aux Trans				\$ 1,290.75
	Peterbilt of WY	LF691A	Oil Filter 250 HR Service				\$ 10.41
	Peterbilt of WY	FF5319	Fuel filter				\$ 8.39
		FF1000	Fuel filter				\$ 10.52
	NAPA	10002 Lucas	Oil treatment				\$ 37.79
	Homax	15W40	Oil				
	Snow Distributing	02382-120 Grease					
	NAPA	RTA9200 Paint	Painted drive axle wheels				\$ 7.32
4/23/13	NAPA	H8226-0511 Quick Link	Repair tire chains				\$ 8.76
5/1/13	Peterbilt of WY	LF691A oil filter	250 hour service			5973	\$ 10.41
	Peterbilt of WY	FF5319 Fuel filter					\$ 8.39
		FS1000 separator					\$ 10.52
		atf 353 1 qt					
		02382-120 grease	2.5 lb				
	Homax	1052955-1 15W40 oil	10 gal				\$ 89.20
	NAPA	10002 Lucas					\$ 37.79
	ITP	Warranty work	driveline				\$ 0.00
5/6/13	NAPA	RTA9200 Spray Paint	paint chains and binders				\$ 3.66
5/9/13	Snow Distributing	02382-120 Grease	greased truck			5980	\$ 7.74
	Barnes	10745/10740	ferrule and nut--repaired grease lines 3/1				\$ 1.91
	NAPA	7151021/26 grease Zerks	replaced 13/1				\$ 8.76
5/22/13	WY Rriging	1 1/8" bridle					\$ 165.38
6/5/13	Snow Distributing	Grease	Greased vehicle				\$ 15.48
6/14/13	WY rigging	1 1/8" bridle	extra bridle for truck				\$ 165.38
6/18/13	MPE	BOOT	replaced shifter boot-aux trans			6060	\$ 4.30
	Barnes	6202 H3 Bulb	replaced bulb in work light				\$ 66.49
6/27/13	NAPA		7142 hyd filter				
		1 ATF					
7/16/13	Snow Distributing	BP1255/H3, 6202 12V bulb	greased			6130	\$ 11.61
	Vernal	1200R24	replaced drive tire and tube RFO				
	TDS	549665 tube					\$ 83.96
	Barnes	10745 ferrule	replaced broker grease lines				\$ 1.28
	MPE	HE22051 nylon hose					\$ 1.06
	WYO Rigging	1 1/8 X 30 Bridle	new bridel and knots				\$ 165.38
		4060008 knot				2	\$ 156.76

8/16/13	NAPA	vw3y6	filled PS reservoir						\$ 3.87
	MPE	B99 Oil filter	250 HR service					6198	\$ 10.22
	MPE	BF7587 FF							\$ 8.52
		BF1259 FF							\$ 9.70
	Snow Distributing	02382-120 Grease							\$ 15.48
	Homax	1052955-1 15W40 oil							\$ 89.20
	Napa	10002 Lucas							\$ 37.79
	FleetPride	Cas21x24 bracket	replaced missing antisail brackets						\$ 22.70
	Barnes		99058 3/8 bolt for rear mudflaps	4					\$ 1.08
			99722 lock washer	4					\$ 0.52
			99782 nut	4					\$ 0.24
			32715 fender washer	4					\$ 1.36
			10745 ferrule--repaired grease line						\$ 0.32
			99760 wahser-replaced muffling hardware on the step						\$ 0.09
		ATFV346				1			
8/28/13		LAF4816 air filters							
9/5/13	Snow Distributing	02382-120 grease	greased truck			2			\$ 11.61
	WYO rigging	1 1/8" Bridle	tightened loose bolts on front differential						\$ 0.00
	Sams club	glass cleaner/paper towels	new bridle for truck						\$ 165.38
		99726 5/8 LOCK WASHER				5			\$ 2.20
9/23/13	ITP	trans flu 75-200	rebuild driveline						\$ 1,336.77
	NAPA	AM01000-4							\$ 5.03
9/25/13	Vernal	7151030 grease zerk	replaced aux transmission and power tower						
	NAPA	091314 brakleen	replaced bad grease zerks	3					\$ 2.19
	BARNES	10745 ferrule	clean parts						\$ 2.83
		10853-1 insert	repaired air line	2					\$ 0.64
		99760 flat washer				2			\$ 0.23
		99029 5/16 bolt				2			\$ 0.16
		99781 5/16 nut				4			\$ 0.52
9/26/13	NAPA	3046 gasket material	fabricate gaskets for aux trans			2			\$ 0.06
	ITP	T51/2x20 rod	fabricate transmission mount				52500		\$ 6.29
		472015 seal	replace seals in power tower						\$ 9.90
		471570 seal							\$ 14.75
9/30/13	SST Shipping		brownie transmission shipping						\$ 14.68
10/2/13			adjusted aux trans linkage						\$ 83.46
10/10/13	six sises	driveline repair							\$ 0.00
									\$ 5,245.39
10/22/13	MPE	AC1001 Cartridge	correction on dl billing						6331
10/27/13	WYO Rigging	Bridle 1 1/8"	replaced air dryer cartridge						-\$ 120.31
			new bridle for truck						\$ 18.43

10/29/13	barnes	6215 194 bulb	replaced light bulb					\$ 0.35
10/31/13	Snow Distributing	02382-120 grease	200 hour service 1/2 gal?					\$ 11.61
	Homax	10002 Lucas	10529554 15W40 oil				6385	\$ 93.80
	NAPA	B99 Oil filter						\$ 37.79
	MPE	BF1259 FF						\$ 10.22
		BF7587 FF						\$ 9.70
	Homax	1053928-5 Hydraulic Oil						\$ 8.52
	Barnes	10745 sleeve	repaired broken grease lines					\$ 22.72
11/1/13	NAPA	10002 Lucas	200 Hr service					\$ 0.66
	Homax	1052955-1 15W40 oil	10 gal				6385	\$ 37.79
	Snow Distributing	02382-120 Grease						\$ 93.80
	MPE	B99 Oil filter						\$ 11.61
		BF7587 FF						\$ 10.22
		BF1259 FF						\$ 8.52
	NAPA	75200 ATF	filled power steering reservoir 1					\$ 9.70
11/20/13	Six States	1 1/8 bridle	spare driveline with driveline saver					\$ 5.03
	WV Rigging	212 nut/bolt loosener	spare bridle					\$ 3,230.98
	Overall	BT35-CO zip tie	Barb Tie 2					\$ 209.66
12/2/13	Six States	driveline repair						\$ 10.45
12/3/13	UHP Inspection	safety inspection						
12/4/13	MPE	800350 Valve	replaced safety valve-air dryer			53964		\$ 2,662.60
		5-103X u-joint	replaced u joint in steering sector shift					\$ 15.00
	Barnes	BT45-co	zip tie 2					\$ 20.37
	NAPA	4800 Brakeleen						\$ 17.01
		091847 brakeleen	cleaned steering shaftand gearbox					\$ 2.09
	Barnes	KP81234 Terminal Female	repaired wiring to back up alarm			2		\$ 2.30
		BT35-CO zip tie						\$ 0.76
12/9/13	MPE	8025-12 Diesel 9-1-1	added to gelled fuel in tank					\$ 0.24
12/13/13	MPE	HE22051 1/4 Airline	repaired broker grease line 3'					\$ 9.40
	Barnes	10745 Ferrule	compress ion sleeve 3				6524	\$ 1.59
	WV Rigging	1 1/8th bridle						\$ 0.96
	Homax	1052955-1 15W40 oil	extra engine oil for truck 1/2 gal					\$ 209.06
		103051 Howes	fuel treatment for truck 1/2 gal					\$ 9.38
	Vernal Stock	cvm104	oversize load sign					\$ 5.49
	Barnes	BT45-CO zip tie	secured u joint caps on new driveline			4		\$ 1.68
			removed to be repaired					\$ 0.00
12/17/13	Barnes	OSL Sign						
		99724 1/2" lockwasher				2		\$ 0.34
		1 1/4 osha knot/wedges	extra knot and wedges for #1 line					\$ 85.94

12/17/13	Bloedorn Lumber	padlock				\$ 43.56
	NAPA	mothers polish				\$ 13.63
12/19/13	ITP		drive line repair and balance (bill to six States \$179.76)			\$ 0.00
12/24/13			Reinstalled drive line with line saver			
	NAPA	EAR322 Stripper	welded deck step and painted			\$ 12.17
		RTA9706 Gray				\$ 5.97
		08880 brakleen				\$ 2.99

2014	Vehicle Maintenance		Vin# 1NKCLBTX07R194462				
L-566	2007 KENWORTH		SAFETY INSPECTION 11/18/2014				
License	154370		Steer Tires 425/65R22.5				
	EXPIRES DEC		Drive Tires 1200/24	1200/24			
	Company parts/svcs						
DATE	Purchased From:	Part #/Description	WORK PERFORMED	MILEAGE	HOURS	COST	
1/8/14	Vernal	30' tape measure	tape measure for truck			\$ 10.00	
			repaired cab marker lights-cleaned flash to pass switch			\$ 0.00	
		1/2 Gal HOWES					
1/10/14	Vernal	T521 tarp strap	21" tarp strap for truck 4			\$ 5.28	
1/15/14	Six States	Hyd Pump Assy				\$ 953.12	
1/20/14	Custom radio	MH	new mic for company radio			\$ 52.50	
1/23/14	Homax	1052955-1 15W40 oil	200 hour service 40 QT		6670	\$ 93.80	
	NAPA	10002 Lucas				\$ 27.29	
	Snow Dist	02382-120 Grease				\$ 11.61	
	MPE	B99 OF				\$ 10.22	
		BF7587 FF				\$ 8.53	
		BF1259 FF				\$ 9.71	
		060523 Belt	replaced AC Belt P00946 A SPO			\$ 32.80	
	Pacific Steel	3/16 x 2 flat steel	fabricated new step			\$ 3.26	
	common sense	AF25247	replaced air filter with a cleaned filter				
	NAPA	75200 ATF	filled power steering reservoir			\$ 5.24	
	Sams club	Washer fluid	filled windshield washer reservoir 1 gal			\$ 1.87	
	Homax	1053887-20	added 25W90 to rear diff			\$ 6.46	
	Tire Rama	labor	mount tire on split rim			\$ 47.25	
		75/95 gearl oil	1 qt				
1/30/14	HSC	7176780 SAFETY HOOK	fabricate new tag line			\$ 31.78	
2/3/14	VVY Machinery	rings/o ring seals				\$ 7.20	
2/5/14	CMI Teco	Oil Level Gauge				\$ 25.52	
2/18/14	GSS	Truck wash	Wash			\$ 133.50	
2/3/14	VVY Machinery	5B4399 O ring	replaced Hydraulic Pump		6726	\$ 2.82	
		4J0527 Oring				\$ 2.53	
		4J0522 Oring				\$ 1.85	
	Six States	NSM7B4C20KK16D1	Pump			\$ 953.12	
	Barnes	BT25-CO	Secure wiring			\$ 2.16	
2/5/15	Contractor Supply	8806793 Handle	new handle for broom			\$ 5.49	
	MPE	8080-06	added power service 911 to gelled fuel			\$ 31.66	
	NAPA	091847 Brakleen	cleaned winch brake parts			\$ 2.30	
	BARNES	99004 1/4 bolt				\$ 0.45	
		99760 1/4 washer				\$ 0.24	

		34272 1/4 nylloc						\$ 0.20
	HOMAX	1055927-55 Aw32	refilled hydraulic system					\$ 528.31
	NAPA	DA1600 Black Paint	cleaned & repainted covers & steps. Welded crack w hyd tank and broker step					\$ 35.85
		7142 hydraulic filter						\$ 56.99
		732-1205 protector						\$ 4.69
	3/4/14 GSS	Truck Wash						\$ 133.50
	3/3/14 VERNAL	425-65R 22.5	replaced 2 damaged steer tires		55482			
	Snow dist	02382-120 Grease	greased truck- tightened input yoke front drive axle					\$ 15.48
	3/14/14 VERNAL	550026909 50 WT	changed oil in Main and AUX					\$ 304.32
		7000074 75-90 W	changed oil winched/differentials/planitars					
	3/26/14 WV Rigging	1 1/8" BRIDLE						\$ 209.06
	3/31/14 MPE	K264-14 GROMMETS	replaced shift boot aux trans					\$ 46.81
	4/1/14 HOMAX	1052955-1 15W40 oil	200 HOUR SERVICE			6900		\$ 94.40
	MPE	B99 O F						\$ 10.22
		BF7587 FF						\$ 8.86
		BF1259 FF						\$ 9.71
		10002 Lucas						\$ 27.99
	Snow Dist	02382-120 Grease						\$ 11.61
	Homax	1053881-120 75W90	rebuilt #1 winch brake					\$ 25.84
	Stewart Wholesale	TUL42230 Spring	PARTS for #1 Winch					\$ 307.85
		TUL42148 Plate						\$ 0.00
		TUL32765 Disc						\$ 0.00
		TUL4513 Seal Kit						\$ 0.00
		Freight						\$ 0.00
	MPE	RS3539JAB	element					\$ 94.82
	NAPA	75200 ATF	Filled Power Steering Reservoir					\$ 4.19
	4/17/14 WYO Rigging	1 1/4 x 150' wire rope	replaced #1 winch line			6942		\$ 693.00
	MPE	FG9005 air fitting	repaired broken air lines					\$ 24.63
	Homax	3200-55 Coolant	added coolant					\$ 7.64
	4/18/14 WV Rigging	1 1/8 bridle	new bridle for truck					
		#10 OSH Knot	osha knot for winch line					\$ 190.00
	4/29/14 Barnes	99106 1/2" bolt						\$ 0.82
		MP38237 cotter pin	cotter pins for chain repair					\$ 0.60
	Snow Dist		lube for winch lines					
	NAPA	75200 ATF						\$ 4.19
	WV Rigging	1" * 100'	replace #2 winch line					\$ 298.20
	5/22/14 HOMAX	1052955-1 15W40	200 hour service			7088		\$ 94.40
	Snow Dist	Grease	greased truck- tightened input yoke front drive axle					\$ 11.61
	MPE	10002 Lucas						\$ 27.99
		B99 O F						\$ 10.64
		BF1259 FF						\$ 10.24
		BF7587 FF						\$ 8.86

	NAPA	901001 valve core	replaced valve core left rear steer tire				\$ 0.59
		75200 ATF	fills power steering res				\$ 4.19
		091314 brakeleen	cleaned parts				\$ 2.82
5/28/14	GHOSTOWN	CB RADIO					\$ 136.49
6/3/14			changed flat tire RRO				\$ 0.00
6/7/14	MPE	HE22051 Airline	repaired airlines to winch control				\$ 3.18
		FG9005 connector					\$ 65.69
6/10/14	TIRE RAMA	tire fix					\$ 141.90
6/11/14	CMI TECO	3398W1270 Stud	replaced wheel stud right rear drive axle			7288	\$ 6.60
		21807998 NUT					\$ 4.70
6/12/14	MPE		computer time MAX SPEED set @ 55 MPH				\$ 0.00
	HOMAX	1053887-20 75W90	changed oil				\$ 316.00
6/19/14	WYDOT	WY PERMIT					\$ 364.00
6/23/14	WY RIGGING	1 1/8" Bridle	new bridle for truck				\$ 209.06
	VERNAL	TS31 Tarp Strap	tarp straps fpr OSL sign				\$ 12.06
	BARNES	23846 connector	wiring for heat exchanger				\$ 2.70
6/16/14	TIRE RAMA		repaired RRO				\$ 149.00
6/25/14	Six States	NMS7B4C20K16DA	replaced hydraulic pump				\$ 938.88
	VERNAL		installed heat exchanger hydraulics				
	WY Machinery	4-J0527 oring					\$ 5.06
		5B 4399 o ring					\$ 5.65
	HOMAX	1055927-55	filled hydraulic system				\$ 429.08
	Barnes	23846 connector	wired in heat exchanger				\$ 0.90
		23847 connector					\$ 0.90
		23829 terminal					\$ 2.40
		23826 terminal					\$ 0.88
		23465 green wire					\$ 0.88
		422398 red wire					\$ 5.60
		422394 black wire					\$ 5.60
	Fleet pride	CM4061-.00wire loom					\$ 5.60
	VERNAL	fuse holder					\$ 6.00
		switch					
	BARNES	998187 25A fuse					\$ 0.65
	Midwest Hose	6502-20-20-FG	hydraulic fittings and hose to install heat exchanger				\$ 21.02
		2503-20-24-FG					\$ 31.55
		6500-20-20-FG					\$ 20.24
		2501-20-24 FG					\$ 48.04
		6500-20-20-1g					\$ 15.44
		25N20-2WB-20FJX-20FJX					\$ 79.18
		25N20-2WB-20FJX-20FJX					\$ 82.38
	Pacific Steel	2 x 2 x 3/16 20' angle					\$ 23.42
6/24/14	NAPA		7760250				\$ 10.49

6/26/14		7142 HYDRAULIC FILTER							\$ 60.80
6/30/14	mpe	PULLEY AS	1979641/1979642						\$ 177.72
7/2/14	ADVANCED HYDRAULIC	SEAL KIT/ORINGS	568-030700, dv35k12, 56802470d, or4218						\$ 74.42
	NAPA	09134 brakleen							\$ 2.82
	mpe	MF185 Magnet	flag mag						\$ 52.92
7/1/14	MPE	1979641 pulley	replaced pulleys for serpentine fan belt				2228		\$ 61.04
		1979642 pulley							\$ 116.68
	Midwest Hose	hydraulic hose							\$ 108.74
		hydraulic hose							\$ 76.90
7/10/14	Homax	1052955-1 15W40					7298		\$ 89.20
	MPE	10002 Lucas	200 hour service						\$ 27.99
		B99 Oil filter							\$ 10.54
		BF1259 FF							\$ 9.91
		BF7587 FF							\$ 8.77
	Snow dist	02382-120 grease							\$ 15.48
	NAPA	091314 brakleen	reselaed fittings on heat exchanger						\$ 5.64
	MPE	MF185 Magnet	magnets for OS signs						\$ 52.92
	NAPA	7142 filter	extra hydraulic filter						\$ 60.80
	Barnes	23847 connector	extended wiring for heat exchanger						\$ 3.60
		BT35-CO zipitie							\$ 0.75
		BT45-CO							\$ 2.10
		38217 cotter pin							\$ 0.08
	VVO rigging	1 1/8 crimp bridle	extra bridle for truck						\$ 209.06
	Barnes	BT25CO zipitie							\$ 0.24
		BT45-co zipitie							\$ 0.45
		25354 heat chrink	resealed motor bolts #1 winch				7312		\$ 0.21
7/10-24/2014	SIX STATES	DRIVELINE FUSES							\$ 434.26
8/3/14	Overall Supply	212 nut loosener	nut and bolt loosener for truck						\$ 10.45
8/13/14	mwic	99a9405 fan hub	replaced fan hub						\$ 1,593.13
	MPE	HE8716 hump hose	replaced charge air cooler andn turbo hump hoses				7445		\$ 71.93
	Fleetpride	14-256 fan kit	rebuild kit for fan hub						\$ 468.62
	sams club	m5702 glass cleaner							\$ 2.10
			OSHA knot for TRUCK						\$ 75.60
	BARNES	99744 flat washer	replaced missing hardware						\$ 0.40
		99734 lock washer							\$ 0.34
		1/4 air fitting	installed train horn						\$ 6.03
		23434 16 GA wire							\$ 2.60
		23540 shrink tube							\$ 0.10
		21415F connector							\$ 0.48
	Fleetpride	LM406-100 wire loom							\$ 3.00
	VVY rigging	1 1/8 bridle	new bridle for truck						\$ 209.06
8/14/14	Snow dist	02382-120 grease	200 hour service						\$ 15.48

	homax	1052955-1 15W40 oil							\$ 89.20
	MPE	10002 Lucas							\$ 27.99
		B99 oil filter							\$ 10.54
		BF1259 fuel filter							\$ 9.91
		BF7587 Fuel filter							\$ 8.77
	NAPA	75200 ATF	Filled Power Steering Reservoir						\$ 4.19
9/2/14	napa	trfa9200/da1620	paint						\$ 29.87
9/4/14	MPE	800350 St4 valve	replaced safety valve on air dryer			59903			
	Pacific steel	1/8 x 2 flat steel	stell to fabricate mudflap hangers						\$ 13.70
	MPE	243612GK mudflap	installed mudflaps on steer axle						\$ 17.95
		99721 lock washer							\$ 0.60
		C703063 5/16 bolt							\$ 1.80
		C713003 5/16 nut							\$ 0.50
9/7/14	midwest hose		replaced hydraulic line					7541	\$ 101.51
	Homax		refilled hydraulic tank						\$ 93.20
9/8/14	Fleetpride	F315-1000	replace batteries						\$ 381.91
9/26/14	MPE	B99 oil filter	200 hour service					7615	\$ 10.54
		BF1259 FF							\$ 9.91
		BF7587 FF							\$ 8.77
		10002 Lucas							\$ 27.99
	Snow dist	02382-120 grease							\$ 11.61
	Homax	1052955-1 15W40							\$ 89.20
	WYO rigging	1 1/8 bridle	new bridle for truck						\$ 206.06
	NAPA	75200 ATF	added att to PS						\$ 10.48
10/7/14	MPE	5545621 seal kit	replaced seals in slave steering box					7616	\$ 80.20
10/10/14	Class C solutions	6215 194 bulb	replaced bulb in dash					7626	\$ 0.46
	Fleet pride	211-2 bulb	replaced bulb in driver door						\$ 1.20
	WYO rigging	1 1/8" bridle	replaced bridle						\$ 209.06
			replaced #1 winch line						\$ 727.65
	MPE	CB12750 Relay	replaced ignition bus relay						\$ 11.40
		P27104003 switch	replaced clearance light switch						\$ 118.65
	mpe		spare key made						\$ 8.10
10/16/14	Tire Rama	Tire Flat	fix tire rear drive axle						\$ 299.09
	NAPA	32115 sand paper	clean brake drums both drive axles						\$ 7.34
		Paint	paint wheels						\$ 17.93
	Kenworth VERNAL		treplaced slack adjusters front drive axle						
	Class C solutions	MP38231 cotter pin							\$ 0.16
	NAPA	09134 Brakeleen	clean brake parts						\$ 11.28
	WYO Rigging	1 1/4 osha knot	osha knot & wedges for #1 winch						\$ 85.94
10/29/14	WYO rigging	1 1/8 bridle	spare bridle for truck						\$ 209.06
11/3/14	MPE	P27104003 switch	replaced clearance light switch					7704	\$ 118.65
	VERNAL	425/65R22.5	replaced right rear steer tire						

11/5/14	MPE	Sensor 2566453	replaced coolant temperature sensor					\$ 38.02
		ORING	6V6609					\$ 0.86
	HOMAX	Coolant	3200-55					\$ 7.12
	Snow dist	Grease 02382-120	greased truck - tightened input yoke front drive axle					\$ 11.61
11/18/14	annual							\$ 15.00
11/19/14	Pacific Steel	1 1/2" CF square	fabricate skids for two block					\$ 68.86
	Homax	1052955-1 15W40 oil	200 hour service			7837		\$ 89.20
	Snow dist	02382-120 grease						\$ 11.61
	MPE	10002 ucas						\$ 27.99
		B99 Oil filter						\$ 10.64
		BF7587 Fuel filter						\$ 8.86
		BF1259						\$ 9.59
	NAPA	75200 ATF	filled ps res					\$ 4.19
		dap1699 primer	painted 2 blocks					\$ 5.98
		R00439	yellow					\$ 8.39
	vernal	cross link chain	repair tire chains					
12/3/14	wy rigging	1 1/8 bridle	new bridle for truck					\$ 209.06
	Tire rama		replaced tube RFI drive tire					\$ 117.50
12/13/14	Snow dist	02382-120 grease	greased truck			7968		\$ 11.61
	Class C solutions	23845 connector	repaired poser cord for engine heater					\$ 1.59
	NAPA	7151051 replaced grease zerk						\$ 0.73
	Class C solutions	MP38229 cotter pin						\$ 0.25
	homax	1055928-5 4W32?	topped off hydraulic tank					\$ 21.00
12/22/14	Fleetpride	h3-55 h3 bulb	replaced worklight bulb					\$ 4.73
	MPE	k068-5616-23-9	replaced block heater cord					\$ 104.08
12/31/14	Fleetpride	1080-06 power service	added supplement to fuel					\$ 15.35

2015	Vehicle Maintenance		Vin# 1NKCLBTX07R194462				
L-566	2007 KENWORTH		SAFETY INSPECTION 11/17/2015		Year end		
License	154370		Steer Tires 425/65R22.5		63130	1.7	BAD ECM...
	EXPIRES DEC		Drive Tires 1200/24				
	Company parts/svcs		1200r24				
DATE	Company parts/svcs	Part #/Description	WORK PERFORMED	MILEAGE	HOURS	COST	
1/6/15	Tire rram	tire repair	replaced tier LRI drive tire		8100	\$ 68.25	
1/7/15	Snow Dist	02382-120 grease	200 hour service		8104	\$ 11.61	
	Homax	1052955-1 15W40				\$ 89.20	
	MPE	10002 Lucas				\$ 27.99	
		B99 oil filter				\$ 10.64	
		BF1259 Fuel filter				\$ 9.59	
		BF7587 Fuel filter				\$ 8.86	
	Class C solutions	10745 ferrule	repaired grease lines			\$ 0.66	
	NAPA	75200 ATF	filled owier steering reservoir			\$ 4.19	
1/8/15			installed external speaker-company radio				
	Class C solutions	c99561 fender washer				\$ 0.06	
1/13/15	Wyo rigging	1 1/8" bridle	bridle blank for truck		8131	\$ 209.52	
1/21/15	MPE	K042-79 boot	replaced upper and lower shift boot on main transmission		8193	\$ 30.52	
		K042-80 boot				\$ 47.47	
		K264-14 boot	replaced shifter boot on aux trans			\$ 50.37	
	ghost town	gear keepers (2)				\$ 52.48	
1/28/15	Tire Rama	replaced tire LRI				\$ 98.65	
2/16/15	Six States	1020 Torque fuse	Bolts for Driveline Saver		8271	\$ 217.13	
2/26/15	MPE	43761 seal	replaced wheel left rear steer axle		8318	\$ 46.20	
	Homax	1053887-20 75W90				\$ 7.90	
		1052955-1 15W40	200 hour service			\$ 85.40	
	MPE	10002 Lucas				\$ 27.99	
	Snow Dist	02382-120 grease				\$ 11.61	
	MPE	B99 oil seal				\$ 10.14	
		B1259 Fuel filter				\$ 9.45	
		BF7587 Fuel filter				\$ 8.86	
	Tire Rama	TR5450 Valve Stem	replaced valve stem RFS tire, tightened input yoke aux tran			\$ 10.45	
3/2/15	Six States	N51020 D/L fuse	fuse for driveline saver		8318	\$ 220.11	
3/9/15	Tire Rama		flat repair RRO			\$ 47.25	
4/10/15	Tire Rama	replaced tube	WARRANTY			\$ 0.00	
5/26/15	Kenworth	BELT D84-1000-6122490				\$ 113.10	
6/5/15	MPE	ECM Program	L-566 engine light on and deraided			\$ 32.32	
11/12/15	Stock	Antifreeze	2 gal				
		safety inspection				\$ 15.00	

[illegible]

[illegible]

2019	Vehicle Maintenance	Vin# 1NKCLBTX07R194462						
L-566	2007 KENWORTH		SAFETY INSPECTION			beginning		
License	154370		Steer Tires 425/65R22.5			63378		
	EXPIRES DEC		Drive Tires 1200/24			end		
	Company parts/svcs		1200r24			63507		
DATE	Purchased From:	Part #/Description	WORK PERFORMED			MILAGE	HOURS	COST
3/11/19	Fleet Pride	Power Steering Fluid	start miles			63378		
3/11/19	Fleet Pride	Air Dryer Cartridge OTR500	5 Qts ATF					\$ 60.73
			R&R Air Dryer/Cartridge					\$ 38.20
3/12/19	Fleet Pride/Stock	H4651/4626 Headlights	R&R Right side headlights					
3/14/19	DAN-Vernal Shop	Inspection						\$ 15.00
8/24/19	Billy Curtis	reset fault codes from old ECM						\$ 90.00
14-Sep	Napa	"6 sticket spray paint	Painted truck					133.32
10-Sep	Napa	Paint	Paint for rig ups on trucks					104.39
1-Oct	Shop		Cleaned batteries spray protectant			63379	42.6	
8-Oct	Shop		Anti freeze -50 degrees			63379	42.6	
7-Oct	DFS Supplement		Added to fuel tanks			63379	42.6	34.64
24-Oct	six robes	fleetpride						120.54
26-Oct	Napa	flags/magnets						12.49
		filters						10.9
30-Dec	Shop		Checked lights, grease job, check tire pressure and fluids			63507	995	

2020	Vehicle Maintenance	Vin# 1NKCLBTX07R194462			
		SAFETY INSPECTION	beginning		
L-566	2007 KENWORTH	Steer Tires 425/65R22.5	63507		
License	154370	Drive Tires 1200/24	end		
	EXPIRES DEC	1200r24			
	Company parts/svcs	Axle Spacing			
DATE	Purchased From:	Part #/Description	WORK PERFORMED	MILEAGE	HOURS
3-Jan	shop		tighten tail roll bolts	63507	100.5
1/8/20	Elko	14' legs			\$ 690.85