

2013 Vehicle Maintenance			Vin#1NKCX4TX27R205462		
L-567	2007 KENWORTH		Steer Tires 425/65R22.5		
License	Z000555		Drive Tires 1200-24		
EXPIRES DEC					
Company Parts/svcs					
<u>DATE</u>	<u>Purchased From:</u>	<u>Part#Description</u>	<u>WORK PERFORMED</u>	<u>MILAGE</u>	<u>HOURS</u>
1/5/13	NAPA- Wright Auto		760 AW hyd 1503	Not on VM	74.94
1/8/13	D & H Welding	WELDING	weld hydraulic tank up and fix leak(VM says Charing)		4093
1/18/13	D & H Welding	WELDING	weld angle iron bottom side hydraulic tank		78.75
1/8/13	HOMAX	Oil	Megaflow AW Hyd 32 PAIL--replaced HYD oil		157.5
1/9/13	VVY Machinery Co	2H-4145 SEAL	Seal--replaced seal on filter assembly		489.04
1/9/13	Honnen Equipment	AT181127	Filter element--replaced hydraulic filter		\$ 3.51
1/15/13	Kenworth VERNAL	S4100SA,SIS-1SK,S1116	Brake lining kit for Axle	Not on VM	\$ 82.69
1/17/13	Pacific Steel	steel	Angle iron to repair hydraulic tank		\$ 2,853.16
1/21/13	Kenworth VERNAL	S4100SA,SIS-1SK,S1116	Brakes Shoe Complete	Not on VM	\$ 26.21
2/1/13	WRIS	Winch Line	1 1/4" x 150' winch line/wire rope straight cut Dbl Yellow	Not on VM	\$ 1,589.93
2/4/13	Shop		Change batteries-door open and Key left in Acc		\$ 997.20
2/8/13	Peterbilt	BA22250 Switch	Installed Battery disconnect switch		
	NAPA	728118 Lug	LUG(5)		\$ 132.74
	NAPA		727653 Shrink tubing (2)		\$ 36.91
	NAPA	732-1202	Protector (2)		\$ 10.65
	Hensley		4725 Battery Cable(4)		\$ 8.38
2/10/13	cage Joe	WRIS	1 1/8" bridle		\$ 35.87
2/12/13	Cage Joe	WRIS	synic brdal		\$ 165.78
2/12/13	cage Joe	WRIS	1 1/8" bridle		\$ 165.79
2/12/13	cage Joe		2 gal windshield wash		\$ 165.78
2/18/13	Shop-kelly O		Filled windshield washer 1 gallon		\$ 7.58
			3200.55 added 2 gallons of coolant red antifreeze		\$ 1.87
2/27/13	SHOP	250 hour service?			\$ 15.10
		LF9080	Oil Filter	4310	\$ 0.00
		FF2200	Fuel Filter		\$ 28.08
		FF2203	Fuel Filter		\$ 13.97
		Lucas 1002	1 gallon additive		\$ 13.65
	schaeffers	02382-120	Grease		\$ 37.79
		1056009-1	15W40 Oil 9.5 gallons		\$ 8.04
	cage jake		5/16" lock washer		\$ 107.63
2/28/13	cage kelly o	M63322R	6" oval tail light MPE		\$ 11.55
3/6/13	Fleetpride	Chain fastener 8260	repair tire chains 6		\$ 64.20
3/13/13	MPE	K264-14	grommet-s		\$ 22.41
3/18/13	two way radio	MHB5500	replaced antenna/troubleshoot company radio		\$ 131.25

3/26/13	NAPA	grease zerk 7151060	replaced broken grease zerk		\$ 0.73
		7151051			\$ 0.73
	Peterbilt	90-100-1	valve core (1)		
	Mpe	cartridge AC1001	replaced air cartridge		\$ 20.99
	Kenworth VERNAL	K022105BXW	replaced purge valve		\$ 109.18
3/27/13	MPE	KW13J	repaired coolant leak (engine)		\$ 1,853.68
		Gaskets 3104229cum/2104230cum			\$ 64.20
		4318197CUM	thermostat gum		\$ 31.97
		186780CUM	seal		\$ 12.76
		3684336CUM/3682673CUM	gaskets		\$ 33.54
		ct300	hose clamp		
3/28/13		wf2127	Grease zerk replaced in steering shaft		\$ 0.73
		5/16-18x3/4 99027	coolant filter		
		1/4 flat washer 99725			
		bt3s-co zip ties		2	
3/29/13		RTA9213	spray paint SILVER		
3/2/13	CMI Teco	LDR02	Oil level guage		\$ 22.03
4/6/13	NAPA	RTA2913 Spray paint	Painted planetaries-silver		\$ 5.97
4/1/13			would not start-charged and tested batteries		
4/25/13	HOMAX	3200-55 coolant	2 gallons put on truck -refilled radiator	4434	
4/29/13			Tightened clamps on lower coolant hose		
	NAPA	RTA9200	Painted drive axle wheels		\$ 7.32
4/30/13	NAPA	V353 ATF	Topped off Power Steering Fluid		\$ 3.87
	NAPA	735310 Wire	Replaced wiring to company radio 10'		
	MPE	P54-1041R	Loght Assembly		\$ 172.61
	MPE	350-0038/3684337CUM	Heater/Gasket		\$ 70.08
5/1/13	MPE	3500038/36884337	replaced engine heater and gasket	4436	\$ 70.08
		P541041B light	replaced broken dome light		\$ 172.61
5/2/13	Snow Dsitributing	02382-120 Grease	greased truck 3.5 lb		\$ 13.55
	Fleetpride	NP68-8-4 fitting	replaced broken fittings on air dryer		\$ 18.78
5/6/13	NAPA	Paint royal bl/white			\$ 28.92
5/6/13	NAPA	901001 valve core	replaced valve core RFI		\$ 0.59
5/8/13	ITP	fabricate driveline	greased truck	4444	\$ 1,440.56
5/9/13	Snow Dsitributing	02382-120 grease	replaced grease zerk 1 each		\$ 7.74
	NAPA	7151030/7151021 zerk			\$ 1.46
5/16/13		glass cleaner			
5/22/13	NAPA	R10339 paint	paint chains and binders		\$ 9.32
	VVY rigging	11/8" Bridle	greased truck		\$ 165.38
5/31/13	Snow Dsitributing	02382-120 grease	repaired leak in hydraulic filter	4470	\$ 11.61
	Honen equipment	at18155 seal kit			

6/3/13	ITP	Driveline	fabricate/install driveline			
	NAPA	7151053 grease zerkl	replaced broken grease zerkl			\$ 0.73
6/11/13	NAPA	H82260511 quick link	repaired tire chains	3		\$ 6.57
6/12/13	HSC		mor-blade & Pin repl model 2			\$ 30.31
6/14/13	WVY Rigging	1 1/8' Bridle	extra bridle for truck			\$ 165.68
6/24/13	Advanced Hydraulics	Hyd Pump	R&R Hyd Pump and pressure hose			\$ 1,767.05
6/25/13	Basin	Hyd filter	add hyd cooler with override switch and hoses			\$ 63.97
6/25/13	Wheeler	O rings				\$ 19.03
	Morcon	hose-bushing				\$ 421.84
		#8 Jlc 90	adaptor			\$ 2.92
6/25/13	stock	mfr-30-2-4A-60				
	stock	temp control kit				
6/25/13	Cardwell	drum hyd oil				\$ 585.20
	Kenworth VERNAL	K374-26	steer axle shocks--- R&R			\$ 247.82
6/26/13	Basin auto	conductor cable, 1 30 amp switch, 2 inline fuse holders				\$ 115.75
		HYD tank cap				\$ 24.31
	Morcon	hose #20 JIC, 45 degree #20 JIC, 90degree #20 JIC				\$ 141.61
	STOCK	1/2 wire loom 20'				
		1/4" wire loom 20'				
		16 3/8x1.5 bolts 63132				
		16 3/8 nuts 64046				
		16 3/8 lock washers 54508				
		16 3/8 flat washers 54573				
		32 nylon ties 44927	rotate steer tires and adjust clutch			
7/1/13	Snow Distributing	02382-120 grease	greased truck		42152	4543
7/5/13	HSC	7108996 ferrul choker knot	replaced #2 winch line and retaining ferrule			\$ 7.74
	WYO Rigging	1" x 150' wire rope				\$ 2.00
7/16/13	WYO Rigging	1 1/8 bridle	new bridle			\$ 726.32
7/17/13	MFCP	?				\$ 165.38
7/19/13	MPE	3678786 oring	rebuild air compressor head			\$ 21.07
		313015 seal			4578	\$ 5.40
		AC1001 cartridge	replaced governor and cartridge			\$ 4.74
		5004049 governor				\$ 29.60
		Shipping				\$ 74.22
7/22/13	UPS					\$ 9.70
7/25/13	RUSH TRUCK		4089238 replaced air control for turbo		4578	\$ 169.10
7/29/13	MPE	belts (2)	ac and fan belts			\$ 26.45
8/5/13	MPE	belt spo				\$ 60.45
8/7/13	Snow Distributing	02382-120 Grease	250 HR Service	3	4580	\$ 11.61
	Homax	1052955-1 15W40				\$ 89.20
	NAPA	1002 Lucas				\$ 37.79
	MPE	BD7154 oil filter				\$ 26.40

		BF 7760	fuel filter						\$ 10.58
		BF 7766 fuel filter							\$ 13.33
8/18/13	Homax	1055928-5 hyd oil	filled hyd tank						\$ 21.76
9/5/13	WV rigging	1" Bridle 1/8"	new bridle						\$ 107.42
9/18/13	Snow Distributing	Grease	greased truck					4740	\$ 11.61
9/18/13		brakleen					1		\$ 165.38
9/20/13	WV rigging	1 1/8" bridle	added oil	2 gal?					\$ 18.26
9/23/13	Homax	1052955-1 15W40 oil	repaired fuel tank						\$ 106.32
10/8/13	Kersten Trialer sales	labor	replaced broker driveline					4699	\$ 1,127.20
10/4/13	ITP	Driveline	replaced broker step	4					\$ 0.12
10/7/13	Barnes	99781 5/16 nut							\$ 0.36
		99760 washer					8		\$ 0.52
		99029 3/16 bolt					4		\$ 0.36
		99784 1/2 nut	replaced carrier bearing mounting hardware	2					\$ 0.42
		99763 washer					2		\$ 0.82
		99106 1/2 bolt					2		\$ 0.00
10/8/13			repaired leak on oil cooler						\$ 0.00
10/9/13			repaired leak on hydraulic filter						\$ 11.87
10/9/13	Fleetpride	7400 bulb	replaced bulb in wiring beacon						\$ 0.00
			repaired leak on air dryer						\$ 57.75
10/18/13	Custom Radio	MK5100 speaker	external speakerfor radio						\$ 52.50
		MH Mic	mic for company radio						\$ 165.38
10/24/13	WYO Rigging	1 1/8 bridle	new bridle for truck						\$ 37.79
1/1/13	NAPA	10002 lucas	200 hour service					4774	\$ 103.18
	Homax	1052955-1 15W40	11 gal						\$ 11.61
	Snow Dist	02382-120 grease							\$ 28.08
	MPE	LF9080 oil filter							\$ 13.97
		FF2200 Fuel Filter	3 lbs						\$ 10.58
		BF7760 fuel filter							\$ 20.44
	inventory stock	WF2127 Water filter	replaced water filter						\$ 6.96
	Homax	1053887-20 75W90	added oil to #1winch						\$ 14.02
	NAPA	1622 Hydraulic Filter	changed transmission filter						\$ 165.38
11/6/13		CVM104 oversize load	oversize load sign for truck						\$ 2.10
	WYO Rigging	1 1/8 bridle	removed from 565 put on 567						\$ 329.99
		1 1/8 bridle	new bridle for truck						\$ 2,662.60
11/11/13	samsclub	glass cleaner							\$ 15.00
11/18/13	ITP		driveline repair						
11/23/13	six states		installed driveline with driveline saver					4807	\$ 3,230.98
11/27/13	Barnes	BT45-co ziptie	barb tie	2					\$ 0.84
12/3/13	Six States	drive line with saver on it							\$ 2,662.60
12/3/12	UHP inspection	safety inspection							\$ 15.00

ITP	BILL TO SIX STATES	driveline repair and balance	\$ 303.35
MPE	H4656 Low Beam	replaced headlight passenger side	\$ 7.71
Barnes	BT45-CO Zipitie		\$ 1.68
NAPA	901001 valve core	4	\$ 0.59
Sams Club	M5702 glass cleaner		\$ 2.10
12/16/13	Flat Repair	right front steer tire	4851 \$ 47.25
12/26/13	Homaz coolant 3200-55	added one gallon coolant	4855 \$ 7.64

2014	Vehicle Maintenance		Vin#1NKCX4TX27R205462				
L-567	2007 KENWORTH		SAFETY INSPECTION	11/18/2014			
License	Z000555		Steer Tires 425/65R22.5				
	EXPIRES DEC		Drive Tires 1200-24				
	Company Parts/svcs						
<u>DATE</u>	<u>Purchased From:</u>	<u>Part#/Description</u>	<u>WORK PERFORMED</u>	<u>MILAGE</u>	<u>HOURS</u>	<u>COST</u>	
1/3/14	Snow Distributing	02382-120 Grease	greased truck			\$ 11.61	
			tested batteries			\$ 0.00	
1/7/14			trouble shoot #1 winch brake			\$ 0.00	
	Barnes	33831 screw	replaced missing screws in winch console	4		\$ 0.28	
1/10/14	MPE	MW1285BK	Wheel covers			\$ 9.47	
1/15/14	Six States	Pump Assy	hyd pump			\$ 953.12	
1/20/14			Rotate steer tires		44263	\$ 0.00	
	Homax	1052955-1 15W40 oil	200 hour service		4964	\$ 103.14	
	Snow Distributing	02382-120 Grease				\$ 11.61	
	NAPA	10002 Lucas				\$ 27.29	
	MPE	BD7154 OF				\$ 26.41	
		BF7760 FF				\$ 10.58	
		BF7766 FF				\$ 13.32	
	Sams Club	Washer Fluid	filled washer fluid			\$ 1.87	
1/21/14	Pacific Steel	1/4x8x14 flat	fabricate access panel in skid plate			\$ 14.92	
	Barnes	99724 1/2 nut		2		\$ 0.36	
		99108 1/2 bolt		2		\$ 0.80	
		99784 lock washer		2		\$ 0.34	
1/22/14	WV Rigging	1" Bridle				\$ 178.76	
		1 1/8" Bridle				\$ 209.06	
1/30/214	Auto Glass Pro		replaced gladd in rear window		4969	\$ 36.75	
	HSC	7176780 safety hook	fabricate new tag line			\$ 31.78	
	Barnes	MP38237 cotter pin	replaced cotter pin in chain hook	1		\$ 0.07	
		stewart wholesale	plate disc kitseal freight			\$ 323.97	
2/18/14	GSS	Truck Wash	Wash			\$ 133.50	
2/5/14	Stewart Wholesale	TUL42148 Plate	repaired internal brake #1 winch			\$ 39.20	
		TUL32765 Disc				\$ 139.20	
		TUL4513 seal kit				\$ 66.40	
		Freight				\$ 79.17	
	MPE	K068-5616-22-9 Power Cord	installed New power cord for block heaters			\$ 73.98	
		K333-449 connector				\$ 4.87	
		K333-325-22 connector				\$ 26.02	
	Barnes	BT35-CO zipitie	secured wiring for block heaters			\$ 1.20	
		BT25-CO zipitie				\$ 0.96	
2/27/14	MPE	K264-14 shift boot				\$ 46.81	

3/5/14	GSS	Truck wash n scrub					\$ 158.25
3/3/14	Vernal shop	425-65R22.5	changed all steer tires		45000		
3/4/14	Snow Distributing	02382-120 Grease	greased truck				\$ 11.61
	ITP	PL1064	replaced rear mounts on auxiliary trans				\$ 23.79
		PL1066					\$ 12.35
3/14/14	MPE	K264-14 shift boot	replaced aux transmission shifter boot				\$ 46.83
	Vernal shop	550026909 50WT	changed oil in main and Aux				\$ 304.32
		7000074 75-90 WT	changed oil in winches/differentials/planit...				\$ 363.00
3/19/14	MPE	H4656 Low Beam	replaced swamp side low beam				\$ 7.71
3/26/14	Snow Distributing	1052955-120 Grease	200 HOUR SERVICE				\$ 11.61
	Homax	1052955-1 15W40 oil				5147	\$ 103.18
	MPE	10002 Lucas					\$ 27.99
		BD7154 OF					\$ 28.20
		BF7760 FF					\$ 11.00
		BF7766 FF					\$ 14.20
3/27/14	WY rigging	#9 Osha Knot & Wedge					\$ 78.38
		1 1/8" Bridle					\$ 209.06
	ITP		DRIVELINE REPAIR				\$ 1,010.84
4/30/14	radio shack	led light bulbs					\$ 9.43
4/8/14	tire rama	balanced tires					\$ 0.00
4/16/14	iowa 80 . Com	lights					\$ 32.94
4/11/14	Snow Distributing	02382-20	greased truck				\$ 11.61
	WYO Rigging	1 1/8" Bridle	new bridle for truck				\$ 209.06
	NAPA	7151051 Grease fitting	replaced grease fittings				\$ 1.46
		7151053 Grease Fitting					\$ 0.73
4/16/14	wyo rigging	1 1.4 x 150' iwrw winch line	R&R Winch cable				\$ 727.65
	NAPA	ATF 75200	Power Steering fluid				\$ 4.19
	Barnes	11096 1/4 nipple					\$ 1.86
4/21/14			Rotate and clean drive tires				\$ 0.00
	WYO Rigging	1 1/4" Osha Knot	osha knot & Wedges for #1 winch				\$ 190.00
	Stewart Wholesale	TUL44341 air cylider	replaed air culinder #1 bank brake				\$ 470.82
	Barnes	BT25-CO Ziptie	secured air lines				\$ 0.24
5/2/14	HOMAX	1057955-1 15W40	200 hour service			5301	\$ 103.84
	Snow Distributing	02382-120 Grease					\$ 11.61
	MPE	10002 Lucas					\$ 27.99
		BF7760 FF					\$ 10.58
		BF7766 FF					\$ 13.31
		BD103 OF					\$ 21.20
		R83539 AF					\$ 94.82
	Barnes	2156 Seal					\$ 1.00
5/13/14	WYO Rigging	1 1/8 crimp bridle	new bridle for truck				\$ 209.06
		1 1/8 bridle blank					\$ 165.38

5/22/14	Snow Distributing	02382-120 grease						\$ 11.61
	Iowa 80 . Com	35583 LED lights						\$ 53.93
	empire chrome	1360 led lights						\$ 53.98
?	Sutherland's	padlocks/key and broom						\$ 20.81
6/10/14	NAPA	08880 Brakeen					5512	\$ 5.24
	Homax	1052955-1 15W40	cleaned front diff housing after removing diff & Planetaries					\$ 98.12
	Snow Distributing	02382-120 GREASE	200 HOUR SERVICE					\$ 11.61
	MPE	10002 LUCAS						\$ 27.99
		BD7154 OF						\$ 28.20
		BF7760 FF						\$ 14.20
		BF7766 FF						\$ 11.00
	Barnes	6202 H-3 Bulb	replaced bulb in worklight					\$ 4.70
6/12/14	MPE		installed new 3rd member in frond differential filled W Synthetic					
	Homax	1053887-20	75W90 oil					\$ 189.60
	MPE	CTD6511 cable tie						\$ 23.77
	Barnes	BT25-co zip tie						\$ 0.96
		C313007 NUT						\$ 1.44
		99723 lock washer	replaced hardware on input flange on front diff					\$ 1.20
	MPE	RS3539air filter	replaced air filters					\$ 93.27
	WVY Rigging	1 1/8" Bridle	new bridle for truck					\$ 209.06
	NAPA	55415 16 M Tap	repaire threads in dife housing					\$ 8.70
		7653015 grey silicone						\$ 24.99
	MPE		computer time--max speed @55 MPH					\$ 0.00
6/30/14	MPE	DRIVE LINE						\$ 22.977.27
7/10. 17/2014	Six States Dist	NS1021 FUSES (2)	extra fuses for driveline savers					\$ 434.26
6/19/14	WVY ANNUAL PERMIT	PERMIT						\$ 364.00
7/11/14	Snow Distributing	02382-120 Grease	greased truck				5663	\$ 15.48
	Fleetpride	7400 Bulb	replaced bulbs in beacon lights					\$ 32.00
	WVY Rigging	1 1/8 bridle blank						\$ 165.38
		1 1/8 crimp bridle						\$ 209.06
7/22/14	MPE	10002 lucas	200 hour service				5702	\$ 27.99
		BD7154 oil filter						\$ 28.17
		BF7760 Fuel filter						\$ 10.58
		BF7766 FF						\$ 13.32
	HOMAX	1052955-1 15W40 oil						\$ 98.12
	Snow Distributing	02382-120 Grease						\$ 11.61
	NAPA	7151051 grease fitting	replaced grease fittings in tailroll					\$ 1.46
7/25/14	NAPA	7151051 grease fitting	replaced grease fittings in tailroll					\$ 1.46
8/3/14	WVYO Rigging	1 1/8 bridle blank	new bridle for truck					\$ 209.06
8/13/14	MPE	q21-6005/4301954/p92-1396-06	sensoe/seal/wire xt					\$ 105.96
8/18/14	MPE	8960 A Lens	replaced left marker turn signal lens					\$ 8.03
	Snow Distributing	02382-120 grease	200 hour service					\$ 15.48

	HOMAX	1052955-1 15W40							\$ 98.12
	MPE	10002 Lucas							\$ 27.99
		BD7154 oil filter							\$ 28.20
		BF7760 FF							\$ 10.59
		BF7766 FF							\$ 13.31
	BARNES	99106 1/2 bolt	replaced bolts in left tail light cover						\$ 0.82
		1156 bulb	replaced left marker turn signal bulb						
	Sams Club	959872 wash fluid	filled reservoir						\$ 1.97
	MPE	8960A Lens	replaced lens on left marker turn signal						\$ 8.03
	8/22/14 D&H welding		fabricate pin						
	Barnes	99106 1/2 bolt	install new pin						\$ 0.41
		99763 flat washer							\$ 0.21
	9/9/14 WYO Rigging	1 1/8 bridle blank	new bridle for truck						\$ 209.06
	9/2/14 D&H welding		fabricate pivot pin						\$ 121.11
	9/20/14 bailey tire	service call/425/65r22.5							\$ 947.62
	10/1/14		tested starting and charging system						\$ 0.00
	10/17/14 MPE	H4656 low beam	replaced low beam headlight- driver side				6067		\$ 10.57
		110-5555ph0/84-1000-3061620	alternator and belt						\$ 223.26
	10/22/14 MPE	Q2160075 sensor	replaced low coolant sensor				6103		\$ 130.69
		WF2127 filter	replaced coolant filter						\$ 22.44
		AC1001 cartridge	replaced air dryer cartridge						\$ 22.16
		BF7760 ff	200 HOUR SERVICE						\$ 10.59
		BF7766 FF							\$ 13.31
		10002 Lucas							\$ 27.99
	Snow Distributing	02382-120 grease							\$ 11.61
	MPE	BD7154 oil filter							\$ 28.20
		B252 OF	changed transmission filter						\$ 7.33
		Q431144301K guage	replaced volt meter						\$ 79.89
		Q20-1002 lock ring							\$ 4.92
	Class C solutions	6220 #921 bulb	replaced driver door light						\$ 0.62
		6202 H3 bulb	replaced bulb in worklight						\$ 4.69
	Vernal shop	AF25247 air filter	changed air filters						
	NAPA	75200 ATF	filled power steering fluid						\$ 4.19
	11/7/14 WY rigging	1 1/8" Bridle	Bridles for truck (20						\$ 418.12
	11/11/14 Fleetpride	1080-06 PS	antigel supplementfor truck				6164		\$ 23.02
	11/17/14	1021V line saver bolt	extra line saverbolts for truck						
		#9 Osha Knot & Wedge							\$ 85.94
	WY Rigging	1 1/4" x 150' wire rop	replaced #1 winch line						\$ 460.00
	11/19/14 Pacific Steel	1 1/2 CF Square	fabricate skid for two blocks						\$ 68.86
			rotate steer tires			52079			
	HOMAX	1052955-1 15W40	200 hour service				6329		\$ 98.12
	Snow Distributing	02382120 grease							\$ 11.61

	MPE	10002 Lucas					\$ 27.99
		BD7154 oil filter					\$ 28.20
		B7360 FF					\$ 10.59
		B7766 FF					\$ 13.31
	Sams Club	959877 washer fluid	filled resevoir				\$ 1.97
	class c solutions	6202 h3 bulb	replaced bulb in worklight				\$ 4.69
	NAPA	R00439 yellow	paint two blocks				\$ 8.39
		dap1699 primer					\$ 5.93
	homax	1052955-1 15w40 oil	xtra oil for truck				\$ 8.92
	NAPA	75200 ATF	topped off PS				\$ 4.19
12/31/14	peterbilt	P27-6100-111 battery	replaced 2 batteries				\$ 340.78
	Fleetpride	1080-06 PS	added supplement to fuel				\$ 15.35

2015	Vehicle Maintenance		Vin#1NKCX4TX27R205462	year end			
L-567	2007 KENWORTH		SAFETY INSPECTION 12/16/2015	54290	6921		
License	Z000555		Steer Tires 425/65R22.5				
	EXPIRES DEC		Drive Tires 1200-24				
	Company Parts/svcs						
DATE	Purchased From:	Part#/Description	WORK PERFORMED	MILAGE	HOURS	COST	
1/12/15	Homax	1052955-1 15W40	2000 hour service		6655	\$ 98.12	
	Snow Dist	02382-120 Grease				\$ 15.48	
	MPE	BD7154 Oil filter				\$ 28.20	
		BF7760 FF				\$ 10.59	
		bf7766 ff				\$ 13.31	
	WVY rigging	10002 Lucas	new bridle for truck			\$ 27.99	
	Homax	1 1/8" Bridle				\$ 209.52	
		3200-55 coolant				\$ 14.58	
1/14/15	annual permit					\$ 312.00	
2/23/15	Homax	1052955-1 15W40 oil	200 Hour Service		6910	\$ 93.94	
	Snow Dist	02382-120 Grease				\$ 11.61	
	MPE	10002 Lucas				\$ 27.99	
		BD7154 Oil filter				\$ 28.20	
		BF7760 Fuel Filter				\$ 10.59	
		6050-3SIG Light	replaced Left S/TT Lights/Repaired light bracket				
	VERNAL	RS3539	replaced 2 air filters- REFURBISHED			\$ 46.76	
2/26/15	MPE	4955592 gasker	repaired leak on oil cooler			\$ 28.10	
		3104230 oring				\$ 5.12	
		109080 o ring				\$ 5.10	
		212161 oring				\$ 2.37	
		3049221oring				\$ 11.47	
		3102314 gasket			0	\$ 22.28	
		4298220 stud				\$ 25.87	
		4985492 Nut				\$ 23.87	
		EC40PLA Clamp				\$ 9.14	
		3682826 seal				\$ 9.45	
		3678606 o ring				\$ 24.22	
		3104229 o ring				\$ 38.68	
		10028-6 clamp				\$ 26.82	
		3037537 oring				\$ 2.53	
		3883150 seal				\$ 5.94	
		3957131 oring				\$ 1.58	
		4919970 hose				\$ 25.94	
2/23/15	SIX STATED	Drive line saver fuses	NS1021		6910	\$ 220.10	
11/21/15	Fleetpride	849-1025-12	2 qts fuel treatment			\$ 13.83	

2016	Vehicle Maintenance		Vin#1NKCX4TX27R205462				
L-567	2007 KENWORTH		SAFETY INSPECTION	12/16/2015			
License	Z000555		Steer Tires 425/65R22.5		beginning		
	EXPIRES DEC		Drive Tires 1200-24		54290	6921	
	Company Parts/svcs				end		
DATE	Purchased From:	Part#/Description	WORK PERFORMED	MILEAGE	HOURS	COST	
1/1/16			beginning mileage				
5/6/16		V535	ATF			\$ 3.87	
7/16/16	Midwest Hose	Pressure Hose	Pressure washed engine and steering components. Was told			\$ 0.00	
			??? Coolant and power steering leaks. Inspected for Causes			\$ 0.00	
			replaced o ring on pump and pressure hose			\$ 22.00	
	Barnes	BT2LH-LO zip tie				\$ 0.80	
9/21/16	MPE	110-555PHO & K264-14	alternator and grommet shift lever--not on VM sheet			\$ 259.75	
		return 110-555PHO 9/29				-\$ 206.30	
9/22/16	wal mart	spray paint	painted front bumper			\$ 35.78	
	peterbilt	P27-6100-111	replaced battery-tested alternator, starter and all batteries		7072	\$ 144.06	
	MPE	K264-14 boot	replaced aux trans shift boot			\$ 53.45	
		AC1001 Cartridge	replace air dryer cartridge			\$ 25.46	
	Snow Dist	02382-120 grease	greased truck, adjusted brakes			\$ 11.61	
	Tire Rama		replaced tube in tire RFI			\$ 112.30	
	Iowa 80	1355B3 LED Light	Lights for bumper guides to be installed when received			\$ 29.53	
9/14/16	MPE	Filters on BILL but not on VM?	BD7154, BF7766, BF7760, Lucas 10002			\$ 76.15	
10/5/16	Iowa 80	LED Lights	replaced clue led lights in bumper guides			\$ 29.53	
	Class C solutions	BT4LH-LO Zip tie				\$ 1.08	
10/20/16	HOMAX	fuel?	accounted for in IFTA/fuel charges			\$ 0.00	
12/9/16	Dan	Inspection				\$ 15.00	

2017	Vehicle Maintenance		Vin#1NKCX4TX27R205462				
L-567	2007 KENWORTH		SAFETY INSPECTION 12/09/2016				
License	Z000555		Steer Tires 425/65R22.5	beginning			
	EXPIRES DEC		Drive Tires 1200-24				
	Company Parts/svcs			end			
<u>DATE</u>	<u>Company Parts/svcs</u>	<u>Part#/Description</u>	<u>WORK PERFORMED</u>	<u>MILEAGE</u>	<u>HOURS</u>	<u>COST</u>	
1/1/17	<u>Purchased From:</u>		<u>beginning mileage</u>	56027	7167		
1/6/17	Homax	1052955-1 15W40 Oil	250 Hour Service	56158	7190	\$ 84.37	
	MPE	10002 Lucas				\$ 29.04	
		BD7154 oil filter				\$ 28.76	
		BF7760 Fuel filter				\$ 11.44	
		BF7766 Fuel filter				\$ 14.30	
	Snow dist	02382-120 Grease				\$ 11.61	
	MPE	B252 Oil filter	Charged Transmission Filter			\$ 7.54	
		B5087 Coolant Filter	charged coolant filter			\$ 22.00	
1/10/17	Fleetpride	B260 Side Hook	repair parts for tire chains			\$ 42.80	
1/20/17	Snow Dist	02382-120 Grease	Greased drivelines		7240	\$ 3.87	
			Adjusted brakes			\$ 0.00	
2/14/17	MPE		took truck to dealer for check engine light. All codes now		7349	\$ 0.00	
			inactive. Inspected connections and wiring to ECM and coolant sensor			\$ 0.00	
2/16/17	Class C solutions	KP81235 Seal	repaired wiring to low coolant sensor			\$ 0.72	
	MPE	CN26250 terminal				\$ 2.29	
	Class C solutions	BT25-CO Zip tie				\$ 0.36	
2/17/17	Snow dist	02382-120 Grease	Greased truck			\$ 11.61	
	MPE	4962608 Cap	fabricated oil foller cap and seal			\$ 0.00	
		3936876 Seal	replaced oil filler cap an dseal			\$ 11.28	
						\$ 3.72	
2/20/17	MPE	7400 bulb	Replaced bulb in beacon light			\$ 15.21	
3/1/17	Six States	1020 fuse bolt kit	replaced bolts in driveline saver		7397	\$ 214.58	
3/14/17	MPE	59-13 wiper blades	replaced wipers			\$ 18.59	
3/19/17	GCR Tire	Call out tire replacement	replaced tubes in front drive axle tires RFI/FRO		7450	\$ 381.15	
3/20/14			Repaired air flow problem to front driv axle brake cans/adjusted brakes			\$ 0.00	
4/18/17	MPE	1464*4 air fitting	installed t fitting and blower hose			\$ 19.99	
5/1/17	Homax	15W40 oil	250 Hr Service		7616	\$ 92.04	
	Snow dist	02382-120 Grease				\$ 7.74	
	MPE	BD7154 OF				\$ 28.76	
		BF7760 FF				\$ 11.44	
		BF7766 FF				\$ 14.43	
	fleetpride	8260 side fastener	repair tire chains			\$ 53.50	
		829564 quick link				\$ 13.56	
		71788174 cross hook					

[illegible]

2018	Vehicle Maintenance		Vin#1NKCX4TX27R205462				
L-567	2007 KENWORTH		SAFETY INSPECTION 12/05/2018				
License	Z000555		Steer Tires 425/65R22.5	beginning			
	EXPIRES DEC		Drive Tires 1200-24	end			
	Company Parts/svcs						
DATE	Company Parts/svcs	Part#/Description	WORK PERFORMED	MILEAGE	HOURS	COST	
1/1/18			beginning mileage				
12/2/17	Napa	Gp31s batteries (4)	Replaced batteries and checked charging system and all battery and starter connections.			\$ 134.95	
12/22/17	Central Truck&Diesel	SP0116500/Block Heater	Replace Engine Block Heater			\$ 72.41	
1/8/18	Airgas	RAD64006314/RAD64057178	lights/?			\$ 92.94	
3/9/2018	shop	Battery stabilizer	installed battery stabilizer				
	NAPA	Rubber Wiring Grom				\$5.24	
3/12/2018	Peterbuilt	master switch	replaced master switch			\$161.45	
11/8/2018	CMI Teco	Air Line & Fittings	Replaced broken air line			\$45.39	
11/8/2018	Fleet Pride	U-joints	Replace u joint behind carrier bearing			\$90.26	
11/8/2018	Inland truck parts	end yoke	replaced end yoke behind carrier bearing			\$204.26	
11/18/2018	CMI Teco	tubing/union				\$45.39	
12/4/2018	Shop	Annual Inspection	Annual Inspection	62740	7949		
12/4/2018	Shop/Stock	Left Turn signal	Replaced Bulb	62740	7949		
12/10/2018	Inland truck part	end yoke	replaced end yoke behind carrier bearing	62740	7949	\$204.57	
12/10/2018	Inland truck part	u-joint	replaced u-joint			\$99.31	
12/11/18	MPE	Grommet/shift lever				\$ 67.03	
12/4/18	MPE	Thermostat/seal/housing cover				\$ 92.51	

2019	Vehicle Maintenance		Vin#1NKCX4TX27R205462				
L-567	2007 KENWORTH		SAFETY INSPECTION 12/05/2018				
License	Z000555		Steer Tires 425/65R22.5	beginning			
	EXPIRES DEC		Drive Tires 1200-24	63419			
	Company Parts/svcs			end			
				64826			
DATE	Company Parts/svcs Purchased From:	Part#/Description	WORK PERFORMED	MILEAGE	HOURS	COST	
Mileage				63419	8031.5		
1/4/2019		Drive Tire	Took tire to have fixed			\$100.98	
1/21/19	MPE	Filters	BF7766JAB/BF7760JAB			\$ 27.83	
2/2/19	Western Sling	Wedge Ferrule-2	NOT ON LOG			\$ 148.81	
3/7/2019	11 quarts of oil	15-40	full service, checked gear boxes and greased	63733	8063		
	BD-7154 B-252	Engine oil filter transmission filter					
	BF-7760 BF-7766	2-Fuel Filter					
3/21/19	GCR	Tire repairs?	NOT ON LOG			\$ 135.46	
6/24/19	six states	fuse set	drive line saver			\$ 291.14	
7/9/2019	Fleetpride/Napa	409975/tt40024mdgs	charged the A/C also fixed the exhaust leak new flex pipe	64367	8171.7	\$50.46	
	napa	paint for bed				\$35.12	
8/8/2019	Peterbilt of WY	oil seal				\$48.05	
8/23/2020	NAPA	paint for bed				\$188.69	
8/30/2020	Napa	sand paper				\$25.99	
9/23/2020	Best Deal Spring	Intraxx Spring	Brake pad			\$93.10	
9/26/2019	N/A		Greased, checked oil and fluid levels, checked tire	64715	8210.7		
			Pressures, cleaned batteries antifreeze -60degrees				
10/1/2019			clean batteries/spray protectant	64714	8212.1		
10/2/2019	MPE	checked codes				\$132.68	
10/8/2019			antifreeze test -60 degrees	64714	8212.1		
10/7/2019	DFS Supplement	fleetpride	added to fuel tanks	64714	8212.1	\$34.64	
10/26/2019	NAPA	Filters				\$29.29	
11/6/2019	Vernal shop		replace slip yoke/drive shaft grease u-joints			\$1,186.17	
11/11/2020	Greg Goodrich	welding	drive line			\$95.54	
12/10/2020	GCR Tire	tire fix					
12/11/2019	Napa	head light	greased tractor, checked fluids, tire pressure, oil level and replaced head light	64735	8230	\$13.11	
12/30/2019	Shop		greased job, check fluids, tire pressure, oil levels and lights repaired driver side step	64825	8244		

2019	Vehicle Maintenance	Vin#1NKCX4TX27R205462			
		SAFETY INSPECTION			
L-567	2007 KENWORTH	Steer Tires 425/65R22.5	beginning		
License	Z000555	Drive Tires 1200-24	64826		
	EXPIRES DEC	Axle Spacing	end		
	Company Parts/svcs				
<u>DATE</u>	<u>Purchased From:</u>	<u>Part#/Description</u>	<u>WORK PERFORMED</u>	<u>MILAGE</u>	<u>HOURS</u> <u>COST</u>
1/3/2020	Shop		tighten tail roll bolts	64827	8245 \$0.00
1/3/2020	David Metal Works		removed broken bolt 4 hours of man labor		\$262.50
1/3/2020	Napa		1-7PC MM HX Set/1-7PC STD HX Set		\$74.53
1/8/20	Elko	14' legs			\$ 690.85
9/16/20	Horizon Cable	Wedge Type Ferrule 7/8" black and #7 bronze			\$ 52.38
12/8/2021	Shop		cleaned air filters	65332	8327
12/30/2020	NAPA	batteries	2		\$324.83