

ABS Module Fault	9/25/2020	Replaced ABS Module
Replaced Headlights	9/25/2020	Installed 2 New LED Headlights
PM Service	10/28/2020	PM Service / Oil Change
Grease Service	10/28/2020	Greased All Grease Points
Air Filter Service	10/28/2020	Replaced Cabin & Intake Air Filter
Carrier Bearing	10/28/2020	Replaced Carrier Bearing
U - Joint	10/28/2020	Replaced U-Joint
Coolant Treatment	10/28/2020	Drained & Replaced Coolant and Coolant Filter
Bad Air Compressor	3/2/2021	Rebuilt Air Compressor
No Interior Lights	3/2/2021	Replaced Cabin Light Module
PM Service	3/3/2021	PM Service / Oil Change
Grease Service	3/3/2021	Greased All Grease Points
Air Filter Service	3/3/2021	Replaced Cabin & Intake Air Filter
Drive Tires Replaced	4/19/2021	Replaced Drive tires
Alternator	5/1/2020	Replaced Alternator
Worn Brakes	7/20/2021	Replaced Drums & Pads - Steer Axle
Brake Chambers	7/20/2021	Replaced Brake Chambers - Steer Axle
Steer Axle Hubs	7/20/2021	Replaced Both Steer Axle Hubs w/Sight Glass Hubs
Wheel Seal	7/20/2021	Replaced Wheel Seals - Steer Axle
Brake Airlines	7/20/2021	Replaced Brake Air Lines - Steer Axle
Steering Rod	7/20/2021	Replaced Steering Rod
King Pins	7/20/2021	Replaced Steer Axle King Pins
Steering Linkage	7/20/2021	Replaced All Steering Linkage
Shocks	7/20/2021	Replaced all 6 Shocks
Tie Rod	7/20/2021	Replaced Tie Rod & Tie Rod ends
Radiator Service	7/20/2021	Flush Radiator and Changed filter
PM Service	7/20/2021	PM Service / Oil Change
Grease Service	7/20/2021	Greased All Grease Points
Air Filter Service	7/20/2021	Replaced Cabin & Intake Air Filter
Steer Tires Replaced	9/2/2021	Replaced Both Steer Tires
Alignment	9/2/2021	Computer Alignment - All 3 Axles
Replace Air Dryer	9/3/2021	Replaced Air Dryer
Water Pump Hoses	9/24/2021	Replaced Water Pump Hoses & Clamps
Spot Mirror	9/26/2021	Replaced Spot Mirror on Hood
Replaced Windshield Glass	9/27/2021	Replaced Entire Front Windshield
Differential Service	9/27/2021	Drained & Filled Rear Axles with New Oil
Fifth Wheel Draw Bar	9/28/2021	Replaced Fifth Wheel Draw Bar
Fifth Wheel Rebuild - Major	9/28/2021	Major Rebuild Kit - Fontaine No-Slack II
Bumper	10/9/2021	Replaced Passenger Side Bumper
Trailer Lights	10/9/2021	Fixed Electrical Plug for Trailer Lights
Turn Signals	10/9/2021	Found Wire Short and Replaced Patched Wires with New Runs