



SANTA MONICA PROPELLER

Propeller Logbook

3135 DONALD DOUGLAS LOOP S, SANTA MONICA, CALIF. 90405-6186
PHONE #: 1-800-421-9995
FAA ARS ZY2R362L

PROPELLER MAINTENANCE RECORD

LEFT ENGINE		RIGHT ENGINE	
Hub Model	<u>72CK-0-52</u>	Hub Model	_____
Blade Design	_____	Blade Design	_____
Diameter	_____	Diameter	_____
Hub Ser. No.	<u>K7309</u>	Hub Ser. No.	_____
Blade Ser. Nos.	_____	Blade Ser. Nos.	_____
No. 1	_____	No. 1	_____
No. 2	_____	No. 2	_____
No. 3	_____	No. 3	_____
No. 4	_____	No. 4	_____
No. 5	_____	No. 5	_____
PITCH RANGE		PITCH RANGE	
High	_____	High	_____
Low	_____	Low	_____
Feather	_____	Feather	_____
Reverse	_____	Reverse	_____
Governor Model	_____	Governor Model	_____

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
10/30/92		Propeller furnished new by Santa Monica Propellers W.O. # 6216	

THE AIRCRAFT AND/OR COMPONENT IDENTIFIED ABOVE WAS
~~REPAIRED~~ INSPECTED IN ACCORDANCE WITH CURRENT
FEDERAL AIR REGULATIONS AND WAS FOUND AIRWORTHY FOR
RETURN TO SERVICE. PERTINENT DETAILS OF THE REPAIR ARE
ON FILE AT THIS AGENCY UNDER THIS INVOICE NUMBER AND
DATE.

SIGNED 
AUTHORIZED SIGNATURE F.A.A. A.R.S. NO. ZY2R362


11/3/91 TACH. 1841
THIS PROPELLOR INSTALLED ON GRUMMAN
AA-1C S/N AAIC-0131.

SANTA MONICA AVIATION
3141 DONALD DOUGLAS LOOP SOUTH
SANTA MONICA, CA 90405-3212
PH. 310-398-9392
FAX 310-398-2914

DOUGLAS R. LAWSON
A & P 562085855 I.A.

W.O. # 5200

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

DATE	TACH TIME	DESCRIPTION OF WORK	SIGNATURE
2-27-99	Tach: 2069.12 Hobbs: 2914.1 SMOH: 1654.12 A/C T.T.: 3399.5	Total Time on prop: 228.12 INSPECTED + profiled prop. STLE & A & P 57069360.	
11-18-99	Tach: 2360.16	INSPECTED + profiled prop. STLE & A & P 57069360.	
12-22-99	Tach: 2427.19 SMOH: 2012.19 A/C T.T.: 3757.57 E.P.S. T.T.: 3757.57	PROP SINCE NEW: 586.16 INSPECTED PROP. STLE & A & P 57069360.	
BILL'S AIR CENTER INC. W.O. # 92358			 WILLIAM M. HEARD A & P 76161151A

new
6

DESCRIPTION OF ALL OPERATIONS
PERTAINING TO AIRWORTHINESS DIRECTIVES,
SERVICE BULLETINS, SERVICE LETTERS,
& MINOR ADJUSTMENTS

12-19-02 Tach Time: 0444.57 Eng. SMOH: 1540.70 Eng. T.T.: 4713.06 Aircraft T.T.: 4713.06
Prop since new: 954.24 Inspected, profiled and painted back side of prop flat black.
G. Stuart Cook *G. Stuart Cook* A & P 570688360. Date: 12-19-02

N9805U PROPELLER 100 HOUR INSPECTION

TACH READS _____ TIME SN AIRFRAME _____
TIME SMOH ENGINE _____ TIME SN ENGINE _____
TIME ON PROPELLER SINCE NEW _____

Inspected prop bulkhead and spinner for cracks. Found acceptable.

Jimmy Hankins A&P 1982460 *Jimmy Hankins* October 1, 2010

11/28/2023

N9805U

TACH: 286.3

Propeller

TT: Prop: 2072

Removed spinner and propeller for engine Overhaul. Reinstalled propeller and spinner. AD's for this propeller reviewed.

I certify that this Propeller has been inspected IAW an ANNUALL inspection and been found to be in an airworthy condition at this time.

Jeff Pollnow A&P/IA 430436342

Jeff Pollnow