

RDO Equipment Co. 5401 NW Rieth Road PO Box 1368

Pendleton, OR 97801

Phone: 541-276-6341 • Fax: 541-276-0085

Service Manager: PE.Service@rdoequipment.com General Manager: PE.GenMgr@rdoequipment.com

www.rdoequipment.com

	EQUIPMENT CO.	Filone, 541-270-0041	Branch				
Ship to:	N/A		Date 11/07/2016		30:13 (0		Page
ts			Account No. 2270030 Ship Via	Phone N 541	o. <u>5662270</u> Purchase Or	00	mate No. 2800
ice t	DIAMOND X RANCH LLC MARK PERKINS 79017 GERKING FLAT R						
	ATHENA OR 97813-6009				ВJ4	llesperson BJ4	
			ESTIMATE EX	PIRY DA	TE: 11/0	3/201	6

SERVICE ESTIMATE

\*\*\*\*\*\* Segment 01 \*\*\*\*\*\*

Stock #: X503299 S680 STS CORN COMBINE

Make: JD Model: COMBINES

Is to have the following work done

RDO COMBINE MAINTENANCE PACKAGE, PLATINUM

ADDITIONAL DESCRIPTION:

Change engine oil and filter.

Change fuel filters.

Change hydraulic/hydrostatic filters.

Change engine air filters (high capacity).

Change cab filters.

Change oil in feeder house reverser and cooler.

Change oil in dual range cylinder/rotor gear case.

Check oil level in final drives.

Check oil level in engine gear case.

Check oil level in loading auger gear case.

Grease machine.

Authorization:

Parts: Labor:

1050.99

Subtotal:

MS #: 1H0S680SAC0746348

510.00 1560.99

\*\*\*\*\*\* Segment 02 \*\*\*\*\*\*

REPLACE THE FEEDER HOUSE MAIN FLOOR.

ADDITIONAL DESCRIPTION:

Replace the main floor of the feeder house as the front

edge is starting wear.

Parts:

882.96

Labor:

220.00

Subtotal:

Authorization: \_\_\_

1102.96

Stocked parts can be returned within 30 days with copy of invoice. Special SIGNATURE order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales TERMS AND CONDITIONS: All invoices are due Net-20 days from the are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.



Service Manager: PE.Service@rdoequipment.com General Manager: PE.GenMgr@rdoequipment.com www.rdoequipment.com

		Phone: 541-276-6341	• Fax: 541-276-00	85			
	EQUIPMENT CO.		Branch				
	N/A		PE - PENDLE	מס זאסיז			
to:			Date	Time	Page		
Ship to:			11/07/2016	13:30:13			
S			Account No.	Phone No.	Estimate No		
			2270030	541566227			
			Ship Via	Purchase			
:0	DIAMOND X RANCH LLC						
invoice to:	MARK PERKINS		-				
live	79017 GERKING FLAT R						
	ATHENA OR 97813-6009				Salesperson		
					BJ4		
			ESTIMATE EXE	PIRY DATE: 11,	/03/2016		
		SERVICE ESTIMA	TE				
******	******* C	egment 03 ******	Le				
	5	adment of the second	`				
CONVEYOR	SHAFT SPROCKETS, REAR, R&R						
	JAL DESCRIPTION:						
	the upper sprockets and bear	rings.					
	the feed plate while it is						
	~						
Authoriz	ation:		Parts: Labor: Subtotal:	892.15 660.00 1552.15			
	***** Se	egment 04 ******		The state of the s	e programa in the dist		
SEPERATO	R REPAIRS						
	AL DESCRIPTION:						
	the front and middle seperat	or covers					
	the intake flight on the rot						
	the left hand seperator rail						
	a wear plate onto the new se						
		polator rair.					
		50.550	Parts:	4372.01			
	Labor: 3850.00						
Authoriza	ation:		Subtotal:	8222.01			
	****** Se	gment 05 ******		14. (As.			
			WENT ((	<u>)</u>			

LOWER CLEAN GRAIN AUGER, R&R ADDITIONAL DESCRIPTION:

Replace the lower auger and bearings.

Replace the belly door of the clean grain auger.

Parts:

1119.49

Labor:

264.00

Stocked parts can be returned within 30 days with copy of invoice. Special SIGNATURE order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales TERMS AND CONDITIONS: All invoices are due Net-20 days from the uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

are final on special order non-returnable parts. All parts must be new, invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.



Service Manager: PE.Service@rdoequipment.com General Manager: PE.GenMgr@rdoequipment.com www.rdoequipment.com

Phone: 541-276-6341 • Fax: 541-276-0085

DEC   PRINTLETON   OR   Page		EQUIPMENT CO.	Branch			
### Segment 06 ********  ### Parts: 691.73  Authorization:  RAR VARIABLE SPEED ADJUST PISTON  Authorization:  *************** Segment 07 *********  *************************		N/A	PE - PENDLE			
### Segment 07 ********  ### Parts: 591.78  Authorization:  RAW Parts: 591.78  Authorization:  RAW Parts: 591.78  Authorization:  ***********************************	o to;		Date	Time		Page
DIAMOND X RANCH LLC MARK PERKINS TOTAL TOT	Shi			Phone N	30:13 (0)	3 Estimate No
DIAMOND X RANCH LLC  MARK PERKINS  79017 GERKING FLAT R ATHENA OR 97813-6009  SERVICE ESTIMATE  Authorization:  SUBOUTALL  SUBOUTALL				}	-	1
MARK PERKINS 79017 GERKING FLAT R ATHENA OR 97813-6009  Selesperson  BJ4 ESTIMATE EXPIRY DATE: 11/03/2016  SERVICE ESTIMATE  Authorization:  Subtotal: 1383.49  ************** Segment 06 **********  UPPER CLEAN GRAIN SHAPT, BEARING, AND SPROCKET, RGR ADDITIONAL DESCRIPTION: Replace the upper clean grain sprocket and bearings. Replace the clean grain chain.  Parts: 691.73 Labor: 495.00 Subtotal: 1186.73  ********** Segment 07 ********  RER VARIABLE SPEED ADJUST PISTON ADDITIONAL DESCRIPTION: The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtohal: 855.78  ********* Segment 08.**********  UPPER COUNTERSHAFT BEARINGS, RGR ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Subtotal: 392.50				1 541		<u> 1 002800</u> er
ATHENIA OR 97813-6009  BJ4  ESTIMATE EXPIRY DATE: 11/03/2016  SERVICE ESTIMATE  Authorization:  Subtotal: 1383.49  ********** Segment 06 **********  UPPER CLEAN GRAIN SHAFT, BEARING, AND SPROCKET, R&R ADDITIONAL DESCRIPTION: Replace the upper clean grain sprocket and bearings. Replace the clean grain chain.  Parts: 6911.73 Labor: 495.00 Subtotal: 1186.73  ***********************************	ć:	DIAMOND X RANCH LLC				
ATHENNA OR 97813-6009  BJ4  FSTIMATE EXPIRY DATE: 11/03/2016  SERVICE ESTIMATE  Authorization:  Subtotal: 1383.49  ********** Segment 06 **********  UPPER CLEAN GRAIN SHAFT, BEARING, AND SPROCKET, RER ADDITIONAL DESCRIPTION: Replace the upper clean grain sprocket and bearings. Replace the clean grain chain.  Parts: 691.73  Labor: 495.00 Subtotal: 1186.73  ***********************************	Se					
SERVICE ESTIMATE EXPIRY DATE: 11/03/2016  SERVICE ESTIMATE  Authorization:  Subtotal: 1383.49  *********** Segment 06 *********  UPPER CLEAN GRAIN SHAPT, BEARING, AND SPROCKET, RER ADDITIONAL DESCRIPTION: Replace the upper clean grain sprocket and bearings. Replace the clean grain chain.  Parts: 691.73. Labor: 495.00 Subtotal: 1186.73  *********** Segment 07 *********  RER VARIABLE SPEED ADJUST FISTON ADDITIONAL DESCRIPTION: The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ***********************************	<u>18</u> 0					
SERVICE ESTIMATE  Authorization:  Subtotal: 1383.49  ****************  Segment 06 **********  *************  Segment 06 **********  *************  **********		ATHENA OR 97813-6009			Sal	esperson
Authorization: Subtotal: 1383.49  ***********************************						
Authorization:  Subtotal: 1383.49  ***********************************		SERVI		PIRY DA	TE: 11/03/	/2016
####### Segment 06 ******  UPPER CLEAN GRAIN SHAFT, BEARING, AND SPROCKET, R&R  ADDITIONAL DESCRIPTION: Replace the upper clean grain sprocket and bearings. Replace the clean grain chain.  Parts: 691.73 Labor: 495.00 Subtotal: 1186.73  ***********************************	Authoriz			1383	49	
UPPER CLEAN GRAIN SHAFT, BEARING, AND SPROCKET, R&R ADDITIONAL DESCRIPTION: Replace the upper clean grain sprocket and bearings. Replace the clean grain chain.  Parts: 591.73 Labor: 495.00 Subtotal: 1186.73  ************ Segment 07 *********  R&R VARIABLE SPEED ADJUST PISTON ADDITIONAL DESCRIPTION: The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ***********************************			Subcocar.	T303	. 47	
ADDITIONAL DESCRIPTION: Replace the upper clean grain sprocket and bearings. Replace the clean grain chain.  Parts: 691.73 Labor: 495.00 Subtotal: 1186.73  ***********************************		***** Segment 06	*****			
ADDITIONAL DESCRIPTION: Replace the upper clean grain sprocket and bearings. Replace the clean grain chain.  Parts: 691.73 Labor: 495.00 Subtotal: 1186.73  *********************************  RAR VARIABLE SPEED ADJUST PISTON ADDITIONAL DESCRIPTION: The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ***********************************						
Replace the upper clean grain sprocket and bearings.  Replace the clean grain chain.  Parts: 691.73 Labor: 495.00 Subtotal: 1186.73  ***********************************			Γ, R&R			
Replace the clean grain chain.  Parts: 691.73 Labor: 495.00 Subtotal: 1186.73  ************* Segment 07 **********  RAR VARIABLE SPEED ADJUST PISTON ADDITIONAL DESCRIPTION: The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ************* Segment 08 ***********  UPPER COUNTERSHAFT BEARINGS, RAR ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Subtotal: 392.50						
Authorization:  REAR VARIABLE SPEED ADJUST PISTON ADDITIONAL DESCRIPTION: The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ***********************************			arings. 	Dag (EDA)	vitatikas avainus	JEL WOR
Authorization:    Labor: 495.00	кертасе	Cile Creali grain chain.				
Authorization:    Labor: 495.00						
Authorization:    Labor: 495.00			Parts:	691	73	and the second
Authorization:  Subtotal: 1186.73  ***********************************				G 4 K 102.251	<ul> <li>A STATE OF THE STA</li></ul>	
R&R VARIABLE SPEED ADJUST PISTON  ADDITIONAL DESCRIPTION: The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ***********************************	Authoriz	ation:				
R&R VARIABLE SPEED ADJUST PISTON  ADDITIONAL DESCRIPTION: The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ***********************************						
ADDITIONAL DESCRIPTION:  The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ***********************************		****** Segment 07	****			
The vari speed piston needs to be replaced.  Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ***************************  UPPER COUNTERSHAFT BEARINGS, R&R ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Subtotal: 392.50	R&R VARI	ABLE SPEED ADJUST PISTON				
Parts: 591.78 Labor: 264.00 Subtotal: 855.78  ********** Segment 08 ********  UPPER COUNTERSHAFT BEARINGS, R&R ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Authorization: Subtotal: 392.50						
Authorization:  Authorization:  ********** Segment 08 *********  UPPER COUNTERSHAFT BEARINGS, R&R  ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50  Labor: 264.00  Authorization:  Subtotal: 392.50	The vari	speed piston needs to be replaced.				
Authorization:  Authorization:  ********** Segment 08 *********  UPPER COUNTERSHAFT BEARINGS, R&R  ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50  Labor: 264.00  Authorization:  Subtotal: 392.50						
Authorization:  Authorization:  ********** Segment 08 *********  UPPER COUNTERSHAFT BEARINGS, R&R  ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50  Labor: 264.00  Authorization:  Subtotal: 392.50						
Authorization:  ********* Segment 08 ********  UPPER COUNTERSHAFT BEARINGS, R&R ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Authorization: Subtotal: 392.50			<del></del>			
#******** Segment 08 *******  UPPER COUNTERSHAFT BEARINGS, R&R ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Subtotal: 392.50	Authoria					
UPPER COUNTERSHAFT BEARINGS, R&R  ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Authorization: Subtotal: 392.50	MUCHOLLE	4011.	. SMDLOLAI:	855.	. 78	
ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Authorization: Subtotal: 392.50		***** Segment 08 *	*****	30		
ADDITIONAL DESCRIPTION: Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Authorization: Subtotal: 392.50			TANGON TO THE TOTAL THE TANGON TO THE TANGON			
Replace the bearings in the upper counter shaft of the feeder house.  Parts: 128.50 Labor: 264.00 Authorization: Subtotal: 392.50		JNTERSHAFT BEARINGS, R&R	XUITMEN L	Are <sup>3</sup> o		
Parts: 128.50 Labor: 264.00 Authorization: Subtotal: 392.50						
Parts: 128.50  Labor: 264.00  Authorization: Subtotal: 392.50			t or the			
Authorization: Labor: 264.00 Subtotal: 392.50	recast H	June.				
Authorization: Labor: 264.00 Subtotal: 392.50						
Authorization: Subtotal: 392.50			Parts:	128.	50	
				264.	00	
Steeled parts can be returned within 20 days with a second	Authoriza	Ation:	Subtotal:	392.	50	
	Observation	make and he makes at 1985 OF 10 at 1995		***************************************		

order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales are final on special order non-returnable parts. All parts must be new, invoice days of your account agreement. uninstalled and in original packaging. No returns on electrical components. Please refer to your finance agreement for details. No refunds on freight charges.



Service Manager: PE.Service@rdoequipment.com General Manager: PE.GenMgr@rdoequipment.com www.rdoequipment.com

Phone: 541-276-6341 • Fax: 541-276-0085

~4	EQUIPMENT CO.	. 01. 2.70 00-77	Branch		······································	т	
	N/A			7017 OT			
::	IV/A		PE - PENDLET  Date	Time			Page
Ship to:							_
Sh			11/07/2016 Account No.	Phone N	30:13 (O)		<u>I 4</u> imate No.
						1	0.5
		i	2270030 Ship Via	541	5662270 Purchase Ord	0.0	2800
<u></u> .	DIAMOND X RANCH LLC	]			T dronded Ord	Ç,	
e C	MARK PERKINS	e de la constitución de la const					
Invoice to;	79017 GERKING FLAT R						
Ē	ATHENA OR 97813-6009				l Sa	lespera	son.
	AIRBNA OR 97813-0009	***************************************			"		
			ESTIMATE EXE	PTRY DA	<u> </u> TE: 11/03	BJ4 /201	
	9	ERVICE ESTIMA				/20=	· <del>V</del>
******		**************************************		····			
	***** Segment	09 ******					
REEL PUN	MP, R&R						
ADDITION	NAL DESCRIPTION:						
Replace	the bearings in the reel pump carr	cier.					
		F2 - 32 F3.	Parts:	194	.63	4 (4 ( ) ) (3 ( ) ( ) ( )	
	- '' 보고 있는 사람이 발생하는 것이 되었다 '' 보고 있는 것이 되었다 '' 보고 있다.		Labor:	11 Table 1 1 Table 1 1 Table 1 1 Table	.00	3 17 77 3	
Authoriz	ation:		Subtotal:	524	\$45-03d	848	
						4545	
	****** Segment	10 *******					
	FAN BEARING, R&R						
***************************************	MAL DESCRIPTION:						
Replace	both cleaning fan bearings.						
	unitation and the second						
			Parts:	95	.24		
			Labor:	264	.00		
Authoriz	ation:		Subtotal:	359			
	****** Segment	11 *******					
REPLACE	THE STRAW CHOPPER CHUTE.						
				<u> </u>			
	***		. I have a since here in	e philips			
			Parts:	1029	.79		
		which wish a mark	Labor:	110	.00		
Authoriz	ation:		Subtotal:	1139			
	****** Segment	12 *******					
	AL DIAGNOSTICS						
ADDITION.	AL DESCRIPTION:						

Stocked parts can be returned within 30 days with copy of invoice. Special SIGNATURE order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales TERMS AND CONDITIONS: All invoices are due Net-20 days from the are final on special order non-returnable parts. All parts must be new, uninstalled and in original packaging. No returns on electrical components.

Diagnose the brake switch issue.

No refunds on freight charges.

invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.



Service Manager: PE.Service@rdoequipment.com General Manager: PE.GenMgr@rdoequipment.com www.rdoequipment.com

Phone: 541-276-6341 • Fax: 541-276-0085

	EQUIPMENT CO.		Branch			
Ship to:	N/A		PE - PENDLET Date 11/07/2016	Time 13:30	:13 (0)	Page 5
o,			Account No.  2270030 Ship Via	Phone No.   541566	62270 rchase Orde	Estimate No.
Invoice to:	DIAMOND X RANCH LLC MARK PERKINS 79017 GERKING FLAT R		AF-1107/07/10-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-1-	***************************************	· · · · · · · · · · · · · · · · · · ·	V-04/10/10/10/10/10/10/10/10/10/10/10/10/10/
=	ATHENA OR 97813-6009		TOTAL OF 122			sperson BJ4
	SE	RVICE ESTIMA	ESTIMATE EXE TE	PIRY DATE	: 11/03/	2016
 Authoriz	zation:		Labor: Subtotal:	110.00 110.00		
			Parts: Labor: TOTAL:	11049.27 7341.00 18390.27	)	
	- 3894 - 1998 - LANDONIA, ROBITANTONO - ATORE, 1898 - MA	Os. 1399 2389	ence encore decore social	N. 555 AS	Storie, apreviolen	#1.50





Stocked parts can be returned within 30 days with copy of invoice. Special SIGNATURE order parts \$20.00 and up may be returned within 30 days with copy of invoice. 20% restock charge will apply to all special order parts. All sales TERMS AND CONDITIONS: All invoices are due Net-20 days from the uninstalled and in original packaging. No returns on electrical components. No refunds on freight charges.

are final on special order non-returnable parts. All parts must be new, invoice date or in accordance with the terms of your account agreement. Please refer to your finance agreement for details.