















This CARFAX Vehicle History Report is based only on information supplied to CARFAX and available as of 10/6/20 at 7:23:44 AM (CDT). Other information about this vehicle, including problems, may not have been reported to CARFAX. Use this report as one important tool, along with a vehicle inspection and test drive, to make a better decision about your next used car.

CARFAX Ownership History The number of owners is estimated	🚨 Owner 1
Year purchased	2012
Type of owner	Personal
Estimated length of ownership	8 yrs. 4 mo.
Owned in the following states/provinces	Pennsylvania
Estimated miles driven per year	9,925/yr
Last reported odometer reading	50,715

🚨 Owner 1	
Guaranteed No Problem	
Guaranteed No Problem	



GUARANTEED - None of these major title problems were reported by a state Department of Motor Vehicles (DMV). If you find that any of these title problems were reported by a DMV and not included in this report, CARFAX will buy this vehicle back.

Register | View Terms | View Certificate

CARFAX Additional History Not all accidents / issues are reported to CARFAX	a Owner 1
Total Loss No total loss reported to CARFAX.	✓ No Issues Reported
Structural Damage No structural damage reported to CARFAX.	✓ No Issues Reported
Airbag Deployment	

No airbag deployn	V	No Issues Reported		
Odometer Check No indication of a	n odometer rollback.	✓	No Issues Indicated	
Accident / Damag No accidents or da	e amage reported to CARFAX.	✓	No Issues Reported	
Manufacturer Rec At least 1 manufac	all sturer recall requires repair. Most recalls can be repaired free of char	ge.	Recall Reported	
Basic Warranty Original warranty	stimated to have expired. Interested in an extended warranty?		Warranty Expired	

CARFAX Detailed History

Owner 1 Purchased: 2012



Low mileage! This owner drove less than the industry average of 15,000 miles per year.

Personal Vehicle 9,925 mi/yr

1	Mileage	Source		Comments
04/23/2012	2	Becker Subaru Allentown, PA 610-395-3745 beckersubaru.com	×	Vehicle serviced - Pre-delivery inspection completed - Brakes checked - Interior trim checked - Exterior trim checked - Emissions or safety inspection performed
04/27/2012	6	Service Facility	×	Vehicle serviced - Exterior trim checked - Interior trim checked - Emissions inspection performed - Emissions or safety inspection performed
04/27/2012		Inspection Station		Exempt from emissions inspection
05/07/2012	7	Becker Subaru Allentown, PA 610-395-3745 beckersubaru.com		Vehicle sold
05/07/2012		Pennsylvania Motor Vehicle Dept.		Vehicle purchase reported
05/11/2012		Pennsylvania Motor Vehicle Dept. Zionsville, PA Title #70760332KR01		Title issued or updated - First owner reported - Titled or registered as personal vehicle - Loan or lien reported
08/27/2012	3,928	Becker Subaru Allentown, PA 610-395-3745 beckersubaru.com	×	Vehicle serviced - Oil and filter changed
01/07/2013	8,026	Service Facility	×	Vehicle serviced - Recommended maintenance performed - Engine electrical system checked - Drive belts checked - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Tires rotated
03/18/2013	9,873	Service Facility	×	Vehicle serviced - Recommended maintenance performed - Engine/powertrain computer/module reprogrammed - Computer reprogrammed - Drive belts checked - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Emissions inspection performed

3/18/2013		Inspection Station	- Emissions or safety inspection performed
3/10/2013		Inspection Station	Passed emissions inspection
04/05/2013		Pennsylvania Motor Vehicle Dept. Zionsville, PA Title #70760332KR01	Registration issued or renewed
07/23/2013	13,522	Service Facility	Vehicle serviced - Recommended maintenance performed - Drive belts checked - Fluids checked - Oil and filter changed - Tire condition and pressure checked - Tires rotated
10/22/2013	16,610	Service Facility	Vehicle serviced - Oil and filter changed - Tire condition and pressure checked
01/24/2014	20,323	Service Facility	Vehicle serviced - Oil and filter changed - Cabin air filter replaced/cleaned - Air filter replaced
04/09/2014		Pennsylvania Motor Vehicle Dept. Zionsville, PA Title #7076033201 KR	Registration issued or renewed
04/23/2014		Greg's Auto & Tire Service Emmaus, PA 610-966-5995 gregsautoandtireservice.com/ 4.9 / 5.0 12 Verified Reviews 13 Customer Favorites	Vehicle serviced - Drive belts checked - Oil and filter changed - Tire condition and pressure checked
4/23/2014	22,920	Inspection Station	Passed emissions inspection
7/10/2014	25,092	Service Facility	Vehicle serviced - Maintenance inspection completed
8/26/2014	26,521	Service Facility	Vehicle serviced - Maintenance inspection completed - Oil and filter changed
1/09/2015	30,920	Ciocca Subaru Allentown, PA 610-395-3745 cioccasubaru.com/index.htm 4.6 / 5.0 1045 Verified Reviews 4,497 Customer Favorites	Vehicle serviced - Maintenance inspection completed - Tire(s) replaced - Four tires balanced - Four tires mounted - Oil and filter changed
2/13/2015	31,901	Ciocca Subaru Allentown, PA 610-395-3745 cioccasubaru.com/index.htm 4.6 / 5.0 1045 Verified Reviews 4,497 Customer Favorites	Vehicle serviced - Maintenance inspection completed
5/22/2015		Greg's Auto & Tire Service Emmaus, PA 610-966-5995 gregsautoandtireservice.com/ 4.9 / 5.0 12 Verified Reviews 13 Customer Favorites	Vehicle serviced
	33,936	Inspection Station	Passed emissions inspection

05/17/2016	39,924	Inspection Station	Passed emissions inspection
09/23/2016	09/23/2016 Subaru of America		Manufacturer Safety recall issued - NHTSA #16V694000 - Recall #WTK71 2010-2014 LEGACY/OUTBACK WINDSHIELD - WIPER MOTOR - Status: Remedy Available Click Here or email us at customers@subaru.com to
	locate an authorized Subaru dealership near you to obtain more information about this recall. Learn more about this recall		

Description: Subaru of America, Inc. (Subaru) is recalling certain model year 2010-2014 Legacy vehicles manufactured November 26, 2008, to June 7, 2013, and 2010-2014 Outback vehicles manufactured January 9, 2009 to June 7, 2013. Due to contamination, components within the windshield wiper motor bottom cover may interfere with each other. If an obstruction, such as a buildup of snow or ice prevents the wiper arms from being able to stop in the parked position, the wiper motor may overheat and the bottom cover may melt.

If the windshield wiper motor overheats, the wipers may fail, reducing driver visibility and increasing the risk of a crash. Additionally, the wiper motor cover may melt, increasing the risk of a fire.

Remedy: Subaru will notify owners, and dealers will replace the windshield wiper motor bottom cover assembly, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Subaru customer service at 1-800-782-2783. Subaru's number for this recall is WTK-71. Note: This recall supersedes recall 11V-469. All vehicles that were remedied under that campaign are affected by this campaign, and need to have their wiper motor bottom cover replaced again. NOTES: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

01/06/2017

46,553

Greg's Auto & Tire Service Emmaus, PA

610-966-5995

gregsautoandtireservice.com/



12 Verified Reviews



13 Customer Favorites



Vehicle serviced

- Oil and filter changed - Brakes checked
- Drive belts checked
- Tire condition and pressure checked

06/15/2017 50.715 Inspection Station Passed emissions inspection 01/09/2019 Subaru of America Manufacturer Safety recall issued - NHTSA #19V008000 - Recall #TKB19 10-14 LEG&OUT TAKATA AB **INFLATOR** - RECALL - Status: Remedy Available Click Here or email us at customers@subaru.com to locate an authorized Subaru dealership near you to obtain more information about this recall. Learn more about this recall

Description: Subaru of America, Inc. (Subaru) is recalling certain 2010-2014 Legacy, Tribeca, WRX and Outback vehicles. 2010-2013 Forester vehicles and 2010-2011 Impreza vehicles sold, or ever registered, in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia. These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

An explosion of an inflator within the passenger frontal air bag module may result in sharp metal fragments striking the front seat passenger, driver or other occupants resulting in serious injury or death.

Remedy: Subaru will notify owners, and dealers will replace the front passenger air bag inflator, free of charge. Owners may contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is TKB-19. Notes: Owners may also contact the National Highway Traffic Safety Administration Vehicle Safety Hotline at 1-888-327-4236 (TTY 1-800-424-9153), or go to www.safercar.gov.

Have Questions? Please visit our Help Center at www.carfax.com.



First Owner

When the first owner(s) obtains a title from a Department of Motor Vehicles as proof of ownership.

Manufacturer Recall

Automobile manufacturers issue recall notices to inform owners of car defects that have come to the manufacturer's attention. Recalls also suggest improvements that can be made to improve the safety of a particular vehicle. Most manufacturer recalls can be repaired at no cost to you.

Ownership History

CARFAX defines an owner as an individual or business that possesses and uses a vehicle. Not all title transactions represent changes in ownership. To provide estimated number of owners, CARFAX proprietary technology analyzes all the events in a vehicle history. Estimated ownership is available for vehicles manufactured after 1991 and titled solely in the US including Puerto Rico. Dealers sometimes opt to take ownership of a vehicle and are required to in the following states: Maine, Massachusetts, New Jersey, Ohio, Oklahoma, Pennsylvania and South Dakota. Please consider this as you review a vehicle's estimated ownership history.

Title Issued

A state issues a title to provide a vehicle owner with proof of ownership. Each title has a unique number. Each title or registration record on a CARFAX report does not necessarily indicate a change in ownership. In Canada, a registration and bill of sale are used as proof of ownership.

Follow Us:



facebook.com/CARFAX



@CARFAXinc



About CARFAX

CARFAX DEPENDS ON ITS SOURCES FOR THE ACCURACY AND RELIABILITY OF ITS INFORMATION. THEREFORE, NO RESPONSIBILITY IS ASSUMED BY CARFAX OR ITS AGENTS FOR ERRORS OR OMISSIONS IN THIS REPORT. CARFAX FURTHER EXPRESSLY DISCLAIMS ALL WARRANTIES, EXPRESS OR IMPLIED, INCLUDING ANY IMPLIED WARRANTIES OF MERCHANTABILITY OR FITNESS FOR A PARTICULAR PURPOSE.

© 2020 CARFAX, Inc., a unit of IHS Markit Ltd. All rights reserved. 10/6/20 7:23:44 AM (CDT)