



Hilti Inc.
5400 South 122nd East Ave.
TULSA, OK 74146

Bill-To Address

A & H ELECTRIC
19705 190TH ST
RICHMOND MN 56368-8217

Delivery Address

A & H ELECTRIC
19705 190TH ST
RICHMOND MN 56368-8217

AMS Repair Order 7208099310

Page 1(1)

Order Type:	AMS Repair Order	Customer Number:	10764409
	02/10/2017	Purchase Order No.:	RON
Order Date:	02/10/2017	Your Reference:	
Our Contact:	Carl Deibel	Your Main Contact:	RON HENNON
		Your Main Contact Tel.:	320-597-2222

Item No.	Description	Ordered Quantity	Net Price/Unit	Net Value
372224	DD 130 Diamond Core Drill (Motor Only)	1 EA	0.00 EA	0.00
372224	DD 130 Diamond Core Drill (Motor Only)	1 EA	0.00 EA	0.00
372017	Functional Performance Check	1 EA	0.00 EA	0.00
278464	DRIVE RING (REPAIR PART)	1 EA	6.25 EA	6.25
279001	ROTOR 110/120 VOLT (REPAIR PART)	1 EA	145.00 EA	145.00
278976	CARBON BRUSH (REPAIR PART)	2 EA	25.95 EA	51.90
278137	BEARING PLATE ASSEMBLY	1 EA	73.50 EA	73.50
213307	SEAL 12X20X6 (REPAIR PART)	1 EA	10.25 EA	10.25
333716	LABOR DIAMOND CORING TOOLS	3 EA	55.25 EA	165.75
439174	Electrical safety check	1 EA	0.00 EA	0.00
Line Total				452.65
FREIGHT				15.00
Upper price limit v.				563.68
Sales Tax				488.03
Final Total USD				488.03