Westfall GMC Truck, Inc.

Westfall Volvo & GMC Truck Center Westfall-O'Dell Truck Sales Westfall Freightliner Truck Center Westfall Isuzu

757226

CUSTOMER #: 8166820417

(SIGNED)

INVOICE

4001 N.E. RANDOLPH RD. K.C., MO. 64161 (816) 455-7262

Heavy Duty Service & Sales Kansas Parts & Service

600 Kew Drive KANSAS CITY, MD 64141

(913) 647-9100 Www.westlebgrat.com CONCRETE WORKS ELENT DE ISUSU 305 NW 83RD ST Mack GMC KANSAS CITY, MO 64118 HOME:816-682-0417 CONT:816-682-0417 PAGE 2 MCKOWN 1344 TAG SERVICE ADVISOR: MILEAGE IN/ OUT BUS: LICENSE CELL: VIN COLOR YEAR MAKE/MODEL 258977/258977 T302MM 1M2AX04Y38M003278 INV. DATE WHITE MACK GU713 PAYMENT 8 0 RATE PO NO. PROMISED DEL DATE PROD. DATE WARR. EXP. 310CT17 CASH 09:40 31OCT17 17SEP07 DD DLR:30200 OPTIONS: R.O. OPENED READY TOTAL 11:28 310CT17 NET 09:43 11JUL17 LIST LINE OPCODE TECH TYPE HOURS 84.80 TOTAL LINE 0.00 OTHER: LABOR: 75.00 PARTS: 9.80 -- TOWED UNIT INTO THE SHOP AND INSTALLED DRIVELINE 258977 4169 ********* D CHECK AND ADVISE FOR COOLANT IN THE OIL ER CHECK AND ADVISE FOR COOLANT IN THE OIL 7350.00 7350.00 4169CPHDM 24230.76 24230.76 41420.10 1 3514*20475005* ENGINE MP7 7/8 177.34 177.34 217.60 21225304 COOLING COIL 11.16 3.72 4.90 953071 STUD 6.93 2.31 3.41 3 11543499 FLANGE NUT 11.59 14.79 11.59 1 977030 O-RING 53.58 53.58 65.74 20512915 BEARING 1 2.97 35.64 3.64 12 60112884 FLANGE SCREW 1.45 17.40 1.78 12 25102025 WASHERS 37.96 22.10 22.10 1 SP-12776050 CLUTCH BRAKE ASSY KIT 13.24 8.73 6.62 1547252 SEALING RING 5.61 5.61 7.40 975675 O-RING 212.85 425.70 261.16 20499469 RUBBER CUSHION 6.19 6.19 7.60 20570437 CLAMP 19.82 15.53 15.53 20566175 FITTING 98-47 98.47 120.82 21276538 FUEL PIPE 7 5.01 0 13.80 P 7.60 1675066 SEALING RING 2 29.19 29.19 35.82 20592783 V-CLAMP 34.62 28.22 28.22 20592787 CLAMP 1 1.40 2.49 1.40 21096684 O-RING 4.c.36 3.22 2.18 984819 FLANGE SCREW 2 WEST201.720 25.42 20976693 RUBBER CUSHION 2 9.92 91200 UNION1/4PUSHIN 4.96 6.54 2 8082135 ELBOW NIPPLE 18.79 18.79 23.06 1 NEV 45 3 2014.90 534-12 CLAMP 3.23 2 5.18 6.84 10.36 982508 GASKET PO 2.45 8050 P.O. 2.45 8050 2.45 KANIA TOTAL MO 1.73 3.23 534-12 CLAMP 1 2.54 1|960629 PLUG 1.51 0.85 0.85 11994 GASKET STATEMENT OF DISCLAIMER DESCRIPTION TOTALS The Terms and Conditions of this transaction are set forth in the Terms and Conditions which may be viewed on the Web at www.westfallgmc.com ("Web Terms and Conditions"). The Web Terms and Conditions are incorporated by reference herein and are hereby made STATEMENT OF DISCLAIMER
The factory warranty constitutes all
of the warranties with respect to
the sale of this item\texture. The
Selfor hereby expressly disclaims all
warranties oither express or
implied, including any implied
warranty of merchantability or
fitness for a particular purpose.
Selfor neither assumes nor
outhorizes any other person to
assume for it any liability in
connection with the sale of this
item\texture. LABOR AMOUNT PARTS AMOUNT and Conditions are incorporated by reference neron and are hereby made a part of the contractual relationship between Customer (you) and Dealer (us). If you do not have access to the Web, please ask our representative to print out a copy of the Web Terms and Conditions for your review <u>before</u> entering into this contractual relationship. GAS, OIL, LUBE SUBLET AMOUNT MISC. CHARGES TOTAL CHARGES By signing this page, Customer hereby authorizes the repair work listed to be done (above) with the necessary materials. LESS INSURANCE Item/Items. SALES TAX CUSTOMER SIGNATURE DEALER, GENERAL MANAGER OR AUTHORIZED PERSON PLEASE PAY

CUSTOMER COPY

THIS AMOUNT

Westfall GMC Truck, Inc.

Westfall Volvo & GMC Truck Center Westfall-O'Dell Truck Sales

757226

Westfall Freightliner Truck Center Westfull Isuzu

INVOICE

4001 N.E. RANDOLPH RD. K.C., MO. 64161 (816) 455-7262

Heavy Duty Service & Sales Kansas Parts & Service P D BOX 418050 KANSAS CITY, MO 84141 www.west/allgmc.com 6008 Kaw Drive KANSAS CITY, KS 60111 (913) 647-9100 WWW.WOUTUCK.com

CONCRETE WORKS 305 NW 83RD ST

CUSTOMER #: 8166820417

KANSAS CITY, MO 64118

PAGE 3

GMC

Suzu

HOME:816-6 BUS:	82-0417 CONT:816-682-0 CELL:	SERVICE ADVISOR:	1344 MIC	KY MCKOWN MILEAGE IN/ OU	JT TAG
COLOR	YEAR MAKE/MODEL	VIN		258977/2589	77 T302MM
WHITE	OB MACK GU713	1M2AX04Y38M003278	RATE	258977/2589 PAYMENT IN	V. DATE
DEL DATE	PROD. DATE WARR. EXP.	ROMISED		CASH 310	CT17
17SEP07 DE	09:4	10 310CT17		CASII	

DLR:30200 **OPTIONS:** READY R.O. OPENED

THE CHENE			
09:43 11JUL17 11:28 31OCT17	LIST	NET	TOTAL
09:43 11JUL17 11:28 310CT17			18.10
LINE OPCODE TECH TYPE HOURS	11.54	9.05	
2 20840154 HOSE CLAMP	6.94	5.26	5.26
1 20579690 SEALING RING		7.82	7.82
1 208/9690 SERETHO	9.60		25.74
1 88865601 FLUID	31.58	25.74	
1 21060426 V-CLAMP	12.23	9.58	9.58
1 21095721 GASKET		25.28	25.28
	31.02		9.58
1 21021852 V-CLAMP	12.23	9.58	
1 21095721 GASKET	6.54	4.96	9.92
2 91200 UNION1/4PUSHIN		11.52	11.52
1 21062932 HEXAGON SCREW	14.71		9.04
1 21062932 HEARON SCREW	5.96	4.52	
2 1674454 SPACER PLATE	1 3 5 7	2.71	2.71
1 OSRB157NA LAMP		8.46	8.46
1 984873 FLANGE SCREW	10.80		179.10
10 MBL122492 MOBIL DELVAC 1300 SUPER 1	24.44	17.91	
10 MBL122492 MOBIL DELVACE TO CORRENTY 50	/50 19.86	10.60	127.20
10 MBL122492 MOBIL BELLA ELC PREMIX 50 12 6019*9404206021* ROTELLA ELC PREMIX 50		D: 3	33091.76
7350 UU 0106K;	0.00 TOTAL LINE		
PARTS: 25741.76 LABOR: 7330.00 0111111			

4169--TOWED UNIT INTO SHOP TO DIAG FOR COOLANT IN THE OIL. WAS ADVISED NOT TO START ENGINE DUE TO OIL BEING IN THE INLET CAC PIPE. CHECKED OVER AND FOUND OIL IN PIPE IS FROM A HOLE IN THE VALVE COVER AND AIR INTAKE PIPE. THEY HAVE WORE HOLES IN EACH OTHER. HOOKED UP TO TECH TOOL AND CHECKED CODES. HAS ACTIVE CODES FOR INJECTOR 4 FMI 7 AND VGT FMI 7. DRAINED OIL AND A LARGE AMOUNT OF COOLANT IS IN THE OIL: REMOVED THE VALVE COVER AND FOUND TRUCK HAS DROPPED AN EXHAUST VALVE ON THE #4 CYLINDER. REMOVED THE HEAD AND FOUND PISTON DAMAGED AND A CRACKED LINER. ALSO FOUND INJECTOR ON #4 CYLINDER IS BAD AND THE CAM IS BAD FLAKING BADLY ON THE #6 INTAKE LOBE. NEED TO ADVISE CUSTOMER AND SEE WHICH WAY THEY WANT TO REPAIR. VESTEALL G.M.O. TRUCK INC

SEE WHICH WAI INDER HEAD BACK ON THE ENGINE AND REMOVED ENGINE 4169--INSTALLED CYLINDER HEAD BACK ON THE ENGINE AND REMOVED ENGINE FROM THE TRUCK. FOUND REAR MOTOR MOUNTS ARE BAD AND NEED REPLACED. QUOTED. GOT ENGINE OUT OF THE TRUCK AND ASSEMBLED FOR A CORE. SWAPPED PARTS OVER TO NEW ENGINE. REMOVED VALVE COVER OFF NEW ENGINE AND WROTE 11107 PARTS OVER TO NEW ENGINE. REINGUISTALLED VALVE COVER AND THE LIFTING BRACKET, R&R
DOWN THE TRIM CODES. INSTALLED NEW ENGINE IN THE TRUCK AND MOUNTED THE
REAR MOTOR MOUNTS. INSTALLED NEW ENGINE IN THE TRUCK AND MOUNTED THE
TRANS WITH NEW BOLTS. PREVIOUS BOLTS WERE OF VARIOUS SIZES AND LENGTHS.

The factory warranty constitutes all of the warranties with respect to The Terms and Conditions of this transaction are set forth in the Terms The Terms and Conditions of this transaction are set forth in the Terms and Conditions which may be viewed on the Web at www.westfallgme.com ("Web Terms and Conditions"). The Web Terms and Conditions are incorporated by reference herein and are hereby made a part of the contractual relationship between Customer (you) and Dealer (us). If you do not have access to the Web, please ask our representative to print out a copy of the Web Terms and Conditions for your review belove entering into this contractual relationship.

By signing this page. Customer hereby authorizes the repair work listed to be done (above) with the necessary materials.

DEALER, GENERAL MANAGER OR AUTHORIZED PERSON

(SIGNED)

of the warranties with respect to the sale of this Itembioms. The Sellor hereby expressly disclaims all warranties either express or implied, including any implied warranty of merchantability or intees for a particular purpose. Soller neither assumes nor authorized any other person to assume for it any liability in connection with the sale of this Itematicans. CUSTOMER SIGNATURE

DESCRIPTION LABOR AMOUNT PARTS AMOUNT GAS, OIL, LUBE SUBLET AMOUNT MISC. CHARGES TOTAL CHARGES LESS INSURANCE SALES TAX PLEASE PAY THIS AMOUNT

CUSTOMER COPY

Westfall GMC Truck, Inc.

Westfall Volvo & GMC Truck Center Westfall-O'Dell Truck Sales

Westfall Freightliner Truck Center Westfall Isuzu

757226

4001 N.E. RANDOLPH RD. K.C., MO. 64161 (B16) 455-7262 INVOICE

Heavy Duty Service & Sales Kansas Parts & Service (913) 647-9100

CONCRETE WORKS 305 NW 83RD ST

KANSAS CITY, MO 64118

CUSTOMER #: 8166820417

PAGE 4





TOTAL

12.00

12.00

KANSAS CITY, MO 64118		Olates)			
HOME:816-682-0417 CONT:816-682-0417 BUS: CELL:	SERVICE ADVISOR:		KY MCKOWI MILEAGE	N IN/ OUT	TAG
COLOR YEAR MAKE/MODEL			258977/	050077	T302MM
WHITE UN MACK GU713	1M2AX04Y38M003278		258977/ PAYMENT	INV. DA	TE
DEL DATE PRODI DATE WARR. EXP.	r e		CASH	310CT1	.7
17SEP07 DD 09:40 31 R.O. OPENED READY OPTIONS:					

11:28 310CT17 NET LIST 09:43 11JUL17 LINE OPCODE TECH TYPE HOURS HOOKED UP ALL CONNECTIONS, FUEL LINES, COOLANT PIPING, COMPRESSOR LINE AND INSTALLED THE COOLANT PACK. AS STATED IN THE CHECK 22, THE EXPANSION TANK IS SWOLLEN AND COULD USE REPLACED. FINISHED ASSEMBLY AND TOPPED OFF FLUIDS AND CHARGED AC SYSTEM. HOOKED TRUCK UP TO PTT AND PROGRAMMED THE NEW ENGINE ECU AND SET TRIM CODES. PRIMED FUEL SYSTEM AND RAN THE TRUCK. NO LEAKS AT THIS TIME. INSTALLED THE HOOD. HEADLIGHT HARNESS HAS PREVIOUSLY BEEN SPLICED DIRECTLY INTO THE CHASSIS HARNESS WITH NO CONNECTOR. INSTALLED THE HOOD AND ROUTED THE HARNESS. INSTALLED THE HEAD LIGHTS AND SECURED IN PLACE. RAN THE ENGINE TO CHECK FOR LEAKS. NONE AT THIS TIME. TRUCK HAS ACTIVE CODES FOR ABS, AND FUEL LEVEL. FUEL LEVEL ISNT HOOKED UP DUE TO HAVING WRONG SENSOR INSTALLED. TOOK ON SMALL TEST DRIVE AND NO LEAKS AT THIS TIME. CUSTOMER DECLINED ANY FURTHER DIAG ON FUEL TANK ISSUE AND ABS LIGHT *************

E** IDOD VERIFICATION

IDOD IDOD VERIFICATION

4032CPHDM PARTS: 0.00 LABOR: 12.00 OTHER: 0.00 TOTAL LINE E 258977 4032-checked fuel sender. I have the pig tail for the truck TOTAL LINE E:

PARTS: side but there is no pig tail for the actual fuel level sender to splice up a harness. need to get the pig tail for the fuel sender, also i printed off the dtc report for bedix for the customer. Customer declined any further diag on issue

F** MALF LIGHT ON. CK AND ADVISE.

ER ENGINE REPAIR

0.00 0.00 4169CPHDM 11 ...

PARTS: 0.00 LABOR: 0.00 OTHER: 0.00 TOTAL LINE F: 258977 TRUCK HAS ACTIVE CODES FOR ABS, AND FUEL LEVEL. FUEL LEVEL ISNT HOOKED UP DUE TO HAVING WRONG SENSOR INSTALLED. Declined any

NOV -0-3 2017 ********** further diag

G** BROKEN DEF CLAMP. CK AND ADVISE. EXR EXHAUST REPAIR

The Terms and Conditions of this transaction are set forth in the Terms The Terms and Conditions of this transaction are set forth in the Terms and Conditions which may be viewed on the Web at www.westfaligmc.com ("Web Terms and Conditions"). The Web Terms and Conditions are incorporated by reference herein and are hereby made a part of the contractual relationship between Customer (you) and Dealer (us). If you do not have access to the Web, please ask our representative to print out a copy of the Web Terms and Conditions for your review <u>before</u> entering into this contractual relationship.

By signing this page, Customer hereby authorizes the repair work listed to be done (above) with the nocessary materials.

DEALER, GÉNÉRAL MANAGER OR AUTHORIZED PERSON

STATEMENT OF DISCLAIMER
The factory warranty constitutes all of the warranties with respect to the sale of this interface. The Saller hereby expressly disclaims all warranties other express or implied, including any implied warranty of merchantability or fitness for a pericular purpose. Saller neither assumes nor authorizes any other person to assume for it any liability in connection with the sale of this item/items. STATEMENT OF DISCLAIMER item/items.

CUSTOMER SIGNATURE

DESCRIPTION TOTALS LABOR AMOUNT PARTS AMOUNT GAS, OIL, LUBE SUBLET AMOUNT MISC. CHARGES TOTAL CHARGES LESS INSURANCE SALES TAX PLEASE PAY THIS AMOUNT

PO. BOX 418050 KANSASCI

CUSTOMER COPY

Westfall Volvo & GMC Truck Center Westfall-O'Dell Truck Sa 757226 Westfall Freightliner Truck Center CUSTOMER #: 8166820417 Westfall Lsuzu Heavy Duty Service & Sales Karsas Parts & Service 4001 N.E. RANDOLPH RD. K.C., MD. 64161 (816) 455-7262 P.O. BOX 418000 EANGAS CITY, MO 64141 INVOICE 6608 Kew Drive VSAS CITY, KS 66111 (913) 647-9100 CONCRETE WORKS GMC 305 NW 83RD ST PAGE 5 mensi @ KANSAS CITY, NO 64118 HOME: 816-682-0417 CONT: 816-682-0417 MICKY 344 MCKOWN SERVICE ADVISOR: BUS LICENSE CELL: MILEAGE IN/ OUT TAG VIN COLOR MAKE/MODEL <u>258977/258977 | T302MM</u> 1M2AX04Y38M003278 WHITE 08|| MACK GU713 PAYMENT RATE INV. DATE PO NO. PROD. DATE WARR. EXP. **DEL DATE** PROMISED CASH 310CT17 17SEP07 DI 40 310CT17 R.O. OPENED OPTIONS: DLR:30200 READY 09:43 11JUL17 11:28 310CT17 TOTAL NET LINE OPCODE TECH TYPE HOURS LIST 0.00 0.00 41B9CPHDM 19.43 19.43 1 20974254 STUB 23.84 46.06 23.03 20974250 HEX. SOCKET SCREW 28.26 65.49 TOTAL LINE G: 65.49 PARTS: LABOR: 0.00 0.00 OTHER: 258977 4139 CHECKED FOR BROKEN DPF MOUNTING BRACKET. FOUND SPACER AND BOLT MISSING. DID NOT HAVE NEW CLAMP IN STOCK. ORDERED CLAMP. TAKING PARTS AND WILL INSTALL HIMSELF 225.00 SHOP SUPPLIES OUR GOAL IS TO REPAIR YOUR VEHICLE RIGHT THE IF WE DID NOT, PLEASE ACCEPT OUR THE R FIRST TIME. APOLOGY AND LET US KNOW SO WE CAN BETTER SERVICE YOU AND YOUR VEHICLE'S NEEDS. THANK YOU FOR YOUR BUSINESS!!!!!! REMIT PAYMENTS TO: P.O. BOX 418050 KANSAS CITY, MO 64141 MON 03 PO BOX-MEGS KANSAS CITY, MU 64147 TOTALS DESCRIPTION The Terms and Conditions of this transaction are set forth in the Terms and Conditions which may be viewed on the Web at www.westfallgmc.com ("Web Terms and Conditions"). The Web Terms and Conditions are incorporated by reference herein and are hereby made and Conditions are incorporated by reference herein and are hereby made and conditions are incorporated by reference herein and are hereby made and conditions are incorporated by reference herein and are hereby made and conditions in the contractual relationship. STATEMENT OF DISCLAIMER The factory warranty constitutes all of the warranties with respect to the sale of this itemutems. The Soller hardby expressly disclaims all warranties other express or implied, including any implied warranty of merchantability or fatness for a particular purpose. Seller neither assumes nor outhorizes any other person to assume for it any liability in connection with the sale of this itemittems. 7587.00 The factory warranty constitutes all LABOR AMOUNT 25817.05 PARTS AMOUNT 0.00 GAS, OIL, LUBE 0.00

CUSTOMER COPY

CUSTOMER SIGNATURE

By signing this page | Quatomer hereby authorizes the repair work listed to be done (above) with the necessary materials.

DEALER, GENERAL MANAGER OR AUTHORIZED PERSON

(SIGNED)

225.00

2141.96

35771.01

0.00

33629.05

SUBLET AMOUNT

MISC. CHARGES TOTAL CHARGES

LESS INSURANCE

PLEASE PAY THIS AMOUNT

SALES TAX





Overhaul Extended Warranty Registration Form

Mack MP Engines

Mack Trucks Inc. offers an extended (purchased) coverage plan to purchasers of an engine overhaul or remanufactured engine when installed at the dealership. This plan is intended to provide the truck owner with additional coverage from failures that may occur after the Standard Parts Warranty has expired and until the date of expiration of this Purchased Coverage. Extended (purchased) coverage plan is applicable only to vehicles that are operated exclusively in the United States and Canada. Purchased coverage consideration can only be given if the deficiency is brought to the attention of an authorized Mack Trucks dealer upon discovery and the engine must be made available, in a timely fashion during the coverage period, for repair.

*Please submit this form within 60 days of Repair Order close date. Dealership is subject to monetary penalty if not submitted within the 60 day period.
monetary penalty if not subfinited within the so day pass
eService Case Number 1-8758534591
Dealer Code D295 Dealer Name WESTFALL MACK
Dealer Code D295 Dealer Name WESTFALL MACK
Customer Information
Name CONCRETE WORKS
Address 305 NW 83RD ST
Address 6/118
City KANSAS CITY State MO ZIP 64118
Customer Vehicle
VIN_1M2AX04Y38M003278
Chassis Model GU Chassis Serial 003278
Engine Model MP7 Engine Serial 89034711
New Engine Serial (Level 4 & 5) LEVEL 5
Repair Order Information
RO No. 757226 RO Open Date 11/31/17
Mileage at Overhaul 258977 Overhaul Level LEVEL 5
Mileage Covers Expires 608977 Date Coverage Expires 10/31/2020

Pre-Overhaul Engine Condition Checklist

The following systems and components must be inspected and performing to specifications. Place a check beside appropriate area where leaking, worn or non-performing components are found. All parts that are found not to be performing to specifications must be repaired or replaced prior to the engine being accepted into the Mack Overhaul Program for coverage. These systems and components are not among the parts covered under the Mack Overhaul Warranty.

0	Radiator & Cooling System Air Intake System & Piping Hoses & Clamps ECUs Sensors & Wiring	Exhaust SystemCharge Air Cooler SAir CompressorClutch Adjustment	
	The following components must be insponent component listed that fails to meet specimust be replaced. Components that do disqualify the engine from being covere appropriate Mack Technical Service Info	ifications. Components th not meet specifications ar d under the Mack Overhal	at fail to meet specifications nd are not replaced will ul Program. Refer to
Exte	Crankshaft Camshaft Turbocharger Valve Cover Stainless Steel Injector Cup	Oil Pan Oil Pump Intake Manifold Exhaust Manifold Rocker Assembly Oil Filter housing	Coolant Pump Conical Injectors (US'07 & US '10) Cylinder Head Belt Tensioner Timing Gears For all US07 engines the Double Idler Gear must be replaced at time of overhaul to receive Extended Warranty

Available Three Year / 350,000 Miles* (563,270 km) Extended Coverage When a contorming engine overhaul is performed or a remanufactured basic engine is installed by an authorized dealer, the customer has the option to purchase additional warranty coverage (no additional charge for level 3, 4, & 5).

The cost of the additional coverage varies depending on the level of the overhaul package purchased by the customer. The level is determined by the parts that must be purchased at time of installation, as described below.

Extended Warranty is fully transferable from truck owner to truck owner, and must have registration updated.

Note: Although levels 3, 4,& 5 do not have additional cost for the extended coverage, the warranty still needs to be registered with Mack.

Cost and Components required for 3 Year Extended Coverage

All required parts must be installed at time of overhaul

Level 1 (BASIC) \$750 Extended Warranty Cost (Canadian cost varies with exchange rate)

- Mack Genuine In-frame or Loaded Cylinder Overhaul Kit
- Mack Genuine Oil Pump
- Mack Premium Engine Oil
- Mack Premium Coolant
- Mack Genuine Filters (oil, fuel, coolant)
- Double Idler Gear (US07 Engines Only)

Level 2 (PLUS) \$450 Extended Warranty Cost (Canadian cost varies with exchange rate)

- Components listed in Level 1
- REMACK Cylinder Head

Level 3 (PREMIUM) No Additional Cost for Extended Warranty

- Componets Listed in Levels 1 & 2
- REMACK Injectors (Qty 6)
- REMACK Turbo Kit

Level 4 (REMACK BASIC 3/4 ENGINE) No Additional Cost for Extended Warranty

- REMACK Basic (3/4) Engine
- Mack Premium Engine Oil
- Mack Premium Coolant
- Mack Genuine Filters (oil, fuel, coolant)
- REMACK Turbo Kit

Level 5 (REMACK 7/8 ENGINE) No Additional Cost for Extended Warranty

- REMACK (7/8) Engine
- Mack Premium Engine Oil
- Mack Premium Coolant
- Mack Genuine Filters (oil, fuel, coolant)

For the Extended Warranty to be valid, all criteria, including required parts, has to be met. Any deviations to the warranty criteria, must be approved PRIOR to overhaul completion.

Warranty Coverage By	Basic	Plus	Premium	REMACK Basic 3/4 Engine	REMACK 7/8 Engine
Component Crankshaft Radions	Guard	Covered	Covered	Covered	Covered
Crankshaft Bearings	Covered	Covered	Covered	Covered	Covered
Connecting Rod Bearings	Covered	Covered	Covered	Covered	Covered
Pistons and Rings	Covered	Covered	Covered	Covered	Covered
Connecting Rod Caps	Covered	Covered	Covered	Covered	Covered
Cylinder Head Gasket	Covered	Covered	Covered	Covered	Covered
Engine Block Casting	Covered	Covered	Covered	Covered	Covered
Intake Manifold Casting	Covered	Covered	Covered	Covered	Covered
Exhaust Manifold Casting	Covered	Covered	Covered	Covered	Covered
Flywheel and Bolts	Covered		Covered	Covered	Covered
Flywheel Housing	Covered	Covered	Covered	Covered	Covered
Timing Gears	Covered	Covered			Covered
Camshaft	Covered	Covered	Covered	Covered	
Crankshaft	Covered	Covered	Covered	Covered	Covered
Main Caps and Boits	Covered	Covered	Covered	Covered	Covered
Thermostat Housing	Covered	Covered	Covered	Covered	Covered
Valve Cover	Covered	Covered	Covered	Covered	Covered
Crankshaft Dampener& Bolts	Covered	Covered	Covered	Covered	Covered
Oil Pan	Covered	Covered	Covered	Covered	Covered
Engine Oil Cooler	Covered	Covered	Covered	Covered	Covered
Oil Cooler Housing	Covered	Covered	Covered	Covered	Covered
Oil Pump	Covered	Covered	Covered	Covered	Covered
Cylinder Head Casting & Bolts		Covered	Covered	Covered	Covered
Rocker Arm Assemblies	F	Covered	Covered	Covered	Covered
Intake & Exhaust Valves	No and	Covered	Covered	Covered	Covered
Turbo & Mounting Bolts	'dre'		The last of the la	Covered	Covered
Injectors		4	2 year/unlimited miles	2 year/unlimited miles	2 year/unlimited miles
Reman Basic Engine	THE PARTY OF	72	THE TABLE	Covered	Covered
Camshaft	Covered	Covered	Covered	Covered	Covered
Accessory Drive (D12D)	105 (F) 17		S MAN	7 9 148	Covered
Air Compressor	and the second				2 year/unlimited miles
Fuel Pump			3		2 year/unlimited miles
Coolant Pump	Mark Con	e	- 1	Physical Property	2 year/unlimited miles
Sensors				7 19	2 year/unlimited miles
EGR Cooler			1	. V	2 year/unllmited miles
EGR Valves	7 7 5	-3		also.	2 year/unlimited miles
ECU		1		1	2 year/unlimited miles
PreHeater	Later to		water A Rapid		2 year/unlimited miles
Harness	100	Assess	E KIL	Sales in	2 year/unlimited miles

Used Truck Awaiting Sale

In the event the Engine involved is in a used truck awaiting sale by a used truck dealer when the repair is performed, this additional coverage begins on the date of sale or of lease/rental by the truck dealer to an end user of the truck, whichever occurs first.

Used truck awaiting sale in dealer's truck inventory must be sold within 12 months or 500 miles (805 kilometers), whichever occurs first, from the date of completion of repair. Trucks sold after 12 months or 500 miles (805 kilometers) will be solely covered from mileage and date of completion of repair

LIMITATIONS AND EXCLUSIONS TO THIS WARRANTY APPEAR ON THE FOLLOWING PAGES OF THIS CERTIFICATE. THESE LIMITATIONS AND EXCLUSIONS ARE IMPORTANT AND MUST BE READ AND UNDERSTOOD.

Excluded Components

The following components are not covered by the Extended Overhaul Warranty

EGR Components – cooler & pipes, control valves, exhaust gas pipes, hoses, clamps, fittings & tubes, mixing chamber, reed valve, temp sensors, cooler dampener and heat shields.

Engine Control Components – ECU, Engine wiring harnesses and sensors.

Preheater Components - Preheater element, gaskets and wiring harness.

Charge Air Components – Charge Air Cooler, piping, hoses and clamps. Exhaust Components – Muffler, piping and clamps.

Cooling System – Radiator, hoses, clamps, piping, fan & drive and belts. Aftertreatment components, DPF, SCR units sensors, wiring and control units

OWNER'S RESPONSIBILITIES

The owner must adhere to the preventive maintenance and inspection recommendations as outlined for the covered vehicle, and keep service records at the owner's place of business or at the servicing dealer. Only genuine Mack replacement parts, or their equivalent, must be used. The operator of the covered vehicle must use reasonable care to prevent further damage in case of a failure. Coverage consideration can only be given if the deficiency is brought to the attention of an authorized Mack Trucks dealer upon discovery and the vehicle must be made available, in a timely fashion during the recovery period, for repair. Supply repairing dealer with a copy of the maintenance log and/or furnish copies of backup documentation, if requested.

LIMITATIONS: Mack Truck's obligation is limited to, at its sole option, repair or replacement of parts which are acknowledged by it to be defective. In the case of acknowledged defective assemblies, exchange with factory rebuilt units may occur. The defective parts or assemblies replaced shall become the property of Mack Trucks. Warranty repairs performed by an authorized MackTrucks dealer in accordance with the terms of the warranty set forth herein are free of charge. Warranty repairs do not constitute an extension of the original warranty period for the engine or any part thereof. Warranty consideration can only be given if the deficiency is brought to the attention of an authorized Mack Trucks dealer upon discovery and the engine must be made available, in a timely fashion during the coverage period, for repair.

NO PAYMENT OR OTHER COMPENSATION WILL BE MADE FOR CONSEQUENTIAL, INDIRECT, INCIDENTAL EXPENSES OR DAMAGES OF ANY KIND.

Exclusions:

- 1.REPAIR: In the case of acknowledged defective Covered Parts, exchange with factory remanufactured parts may occur. Warranty repairs do not constitute an extension of any warranty period for any vehicle, component or part.
- 2. DAMAGES: Damages due to misapplication, misuse, accidents, negligence, improper operations, alterations, storage or transport, operation at excessive speeds, loading beyond the factory rated load capacity, failure to follow Mack Trucks' recommended inspection, maintenance, and service procedures, and improper or insufficient maintenance services are not covered.
- 3. PROGRESSIVE DAMAGE: Damages due to failure of operator to take reasonable precautions to mitigate damage are not covered. Damages to a Covered Part due to failure of non-covered part are not covered. Coverage is limited to failure of a Covered Part directly causing failure of a non-covered part, where reasonable precautions were taken to mitigate damages.

 A APPLICATION. To
- 4. APPLICATION: The selling dealer is responsible for designaling the correct application and/or specification for a vehicle sold to a customer. Damages due to misapplication, including but not limited to, fallures of component parts of vehicles being operated in excess of factory rated load capacities, or the use of a vehicle, component or part for a purpose for which it was not intended are not covered.
- 5. ALTERATIONS: Any vehicle, component or part repaired, altered, or inspected in any way, so as to adversely affect, in Mack Trucks' sole judgment, its stability, durability, or reliability, is not covered.
- 6. NON-ORIGINAL EQUIPMENT: Any part of the vehicle that fails, malfunctions, or does not perform as a result of improper conversion or installation of bodies or equipment by other manufacturers or suppliers is not covered.
- 7. MAINTENANCE AND PARTS CONSUMED: Maintenance and inspection requirements found in the Operator's Manuals and service manuals/instructions, including, but not limited to, engine tune-up, fuel system cleaning, replacement of lubricants and filter elements, adjustments of the engine injection pump/transmission/brakes/linkages, as well as diagnosis, test time and all other adjustments must be followed and are not covered. Parts which are normally consumed or worn out during the vehicle's normal service life and customarily replaced during usual maintenance service, including, but not limited to, mud flaps and brackets, brake linings, clutch brake, and clutch linings, are not covered.
- 8. PERFORMANCE COMPLAINTS: Performance complaints are not covered (including, but not limited to, low power and/or poor fuel economy). Coverage is limited to defects in material and workmanship of a Covered Part directly causing the performance issue.
- 9. WEAROUT: Mack Trucks does not cover normal wear of Covered Parts. Failures attributable to wear are excluded. For example and without limitation, the wear rate of parts in any engine or transmission, and especially those parts within the combustion area and clutch housing area, will vary depending upon operating conditions and environment. Conditions, such as load, trailer configuration, road speed and road conditions, as well as the quality of fuel, lubrication oil, and all filters bear a direct relationship to the wear rate and resulting life of parts. Depending upon the severity of these various conditions, parts wear and resulting failure could occur within the time limit of the coverage.
- 10. NON-GENUINE PARTS: Any failure of any vehicle, component or part caused by the use of parts and accessories, or major assemblies and exchange units, which do not meet factory standards is not covered.
- 11. ODOMETER READING: Any vehicle on which the actual mileage or hours cannot readily be determined, or on which the odometer, hour meter, or Electronic Control Unit has been disconnected, disabled, or altered, may not be covered by this warranty.
- 12. ACCESS TO INFORMATION: Owner must allow Mack Trucks full access to all data stored in all Electronic Control Modules; failure to do so may result in the loss of warranty coverage.
- 13. LABOR: Labor to remove and install a Covered Part is included only if a Mack Trucks authorized dealer originally installed the Covered Part. Labor for overtime and/or shift differential is not covered. Excessive labor for a warrantable repair due to the prior installation of equipment or body is not covered.
- 14. MISC. EXPENSE: Meals, lodging, communications charges, travel time and expense, loss of cargo, downtime, loss of profit/revenue, rental vehicles, driver's wages and other miscellaneous expenses are not covered. Shop supplies, lube oil, lubricants, sealers, anti-freeze, filter elements and labor performed by a non-approved location are not covered.
- 15. ADDITIONAL COMPONENTS: Components or parts that are not installed by Mack Trucks, including winches, power take-offs, dumper, mixer and refuse assemblies, hoists and bodies or other special equipment are not covered. During a warrantable repair, additional time to remove any customer installed components will not be covered under warranty. Mack Trucks' factory manufacturing records will be determinative as to factory installed components
- 16. TOWING: Unless expressly provided in this Warranty Certificate, expenses for towing or road service are not covered. Failures caused by improper towing technique Repair-Warranty consideration can only be given if the deficiency is brought to the attention of an authorized Mack Trucks dealer upon discovery and the truck must be made available, in a timely fashion during the warranty period, for repair. Failures resulting fom the user's unreasonable delay in making the truck available, after being notified of a potential problem, are not covered.
- 17. SUSPENSION PARTS: Suspension parts, including but not limited to rubber bushings, torque rod bushings, spring pins and bushings, and greased lubrication points that fall due to improper maintenance, abnormally severe service or abuse are not covered
- 18. CAB STRUCTURE AND CORROSION: Cab structural defects or cab corrosion that occurs in areas of the cab that previously were damaged, repaired, altered or modified are not covered. Cab corrosion where metal is perforated from the outside to the inside is not covered.
- 19. VENDOR ENGINES, ALLISON AUTOMATIC TRANSMISSIONS and ALTERNATE FUEL STORAGE AND DELIVERY SYSTEMS: Vendor engines, Allison automatic transmissions and alternate fuel (CNG/LNG/DME) fuel storage/delivery components used in Mack trucks are warranted by their respective manufacturers and not by Mack Trucks, Inc. Refer to the manufacturers' warranty statements.
- 20. OIL CONSUMPTION: Before a claim based upon excessive oil consumption will be considered, the owner must provide proof that all recommended maintenance has been performed and submit adequate documentation to show that oil consumption exceeds Mack Trucks' published standards. Under no circumstances will warranty pay for repairs related to excessive oil consumption after the earlier of 24 months, 250,000 miles, 402,000 kilometers, or 6,250 engine hours.

Date Code July 2017

- 21. ENVIRONMENTAL DAMAGE: Parts made out of cloth, leather, wood, rubber, synthetics, paint or chrome which have been affected by exposure to the elements or chemical influence including, but not limited to, road salt/chemicals, industrial fall-out or the use of improper cleaners, polishes and/or waxes are not covered.
- 22. ALIGNMENT: Alignment of axle(s), balance of tires, changing of axle camber, caster, toe and thrust angle are not covered.
- 23. GLASS: Glass breakage and scratches are not covered unless physical proof of manufacturing responsibility is established.
- 24. TIRES: Tires are not covered by this warrantly, but may be covered by separate warrantles given by their respective manufacturers.
- 25. CHANGES: Mack Trucks reserves the right to make any changes in design, or make additions to or upon its products, without incurring any obligations to install the same changes on vehicles previously built.