

2013 Vehicle Maintenance

ה

2013 Vehicle Maintenance		VIN #			
FL-7	Tires				
Date	Company Parts/Svcs Purchased From:	Part #Description	Work Performed	Hours	Cost
1/11/13	Shop Alan	Nut buster	Overall supply	\$ 7.28	\$ 7.28
1/14/13	Titan Machinery SHOP	Filters	84412164 Fuel, 84228510 Eng, 8605140 Air, 87712194 Cab	\$ 134.88	\$ 134.88
1/14/13	Extreme Truck outfitters	250 hour service	15W40 oil 4 gal, Grease 2	2603	\$ 44.72
1/15/13	Titan Machinery	8.602005,76048601,87105748	288271 Deflecta Shield Part Heat/Kit/Cable-replaced block heater and front wiper kit replaced engine coolant, 1/4 gal window wash, wiper?	\$ 348.71	\$ 348.71
1/18/13	Titan Machinery	Filters	76048930.00 Gas Strut in steering column replaced	\$ 205.11	\$ 205.11
1/24/13	Shop stock Bill not on VM	Filter	84491498 Hyd A, 87308945 HYD B	\$ 67.95	\$ 67.95
2/15/13	Stock Bill NAPA	32577 99002	Fender washer and 1/4-20 3/4 bolt	\$ 196.92	\$ 196.92
2/18/13	Western Petro	8226-0511 quick link	8 total	\$ 193.42	\$ 193.42
	Shop	Rando HD 32	5 5 gallon pails	\$ 25.25	\$ 25.25
		Oring	replaced o rings for hydraulic hoses	\$ 16.71	\$ 16.71
		oring 6v8400	o ring	\$ 353.41	\$ 353.41
		02382-120	GREASED	\$ 7.74	\$ 7.74
3/12/13	Wyoming Rigging	7/8 Shackle	Replaced missing shackle	\$ 0.00	\$ 0.00
4/20/13	Hose & Rubber Homax NAPA	200R /20-0REF O-ring	replaced o ring on hydraulic valve and line filled hydraulic tank 4 gallons hyd oil	1	\$ 2.91
	Snow Distributing	1055928-5	Cleaned hyd fittings		\$ 44.80
		4800 Brakleen	greased		\$ 2.09
		02382-120 Grease			\$ 7.74
5/1/13	HOMAX	1052955-1	15W40 oil	2819	\$ 35.68
	Snow Distributing	02383-1 Grease	250 hour service Greased		\$ 9.68
	Titan Machinery	84228510	oil filter		\$ 23.03
	NAPA	84309911	Separator		\$ 25.25
		94412164	Fuel filter		\$ 27.80
		7151051 Grease Zerk	replaced zerks 6		\$ 4.38
		94412164	replaced wash fluid		
5/31/13	Snow Distributing	02382-120	1/4 gallon		
6/1/13	Barnes	2523 Hairpin	Greased		\$ 7.75
6/7/13	Overall supply	212 nut loosener	replaced missing hairpin clip can nut and bolt loosener		\$ 0.47
6/25/13	Titan Machinery	check hydraulics			\$ 10.45
				2916	\$ 0.00

6/26/13	TDS	o ring	flat repair-replace bad o rings		\$ 114.45
8/13/13	Snow Distributing	02382-120 Grease	greased loader	2932	\$ 7.74
	Titan Machinery	8605139	replaced air filter (used)		
	Titan	84373506 light	replaced lft ST/T light		
8/22/13	2 way ratio	mic change		\$ 147.46	
9/9/13	Snow	Greased		\$ 89.25	
9/26/13	50/50 Homax	coolant 320055	added coolant	3015	\$ 7.74
	Sams club	M5702 glass cleaner		\$ 7.55	
	Homax	105255-1		\$ 2.10	
10/3/13	2 way ratio	mh-67 mic		\$ 9.13	
11/1/14		nut buster / coolant	1 each	\$ 78.85	
		15W40	4 gal		
		02382-120 greased	2 lbs		
11/18/13		clean n wipe			
12/1/13	Titan Machinery	32 oz howes			
			troubleshoot hydraulic problem-mechanic reports, no problem found in lift or tilt function of machine.	3259	
	Show Dist	02382-120 grease			
	NAPA	091847 brakleen	greased	3263	\$ 7.74
	Sams Club	washer fluid	repaired oil leak on cooling fan motor, cleaned battery terminal and cables	\$ 2.30	
12/18/14	motion and flow	6M148OMXS	tightened hose clamps on viper radiator hose coolant leak		
		LOHX6-S fitting	filled windshield washer reservoir	\$ 1.87	
	wheeler machinery	elbows and seals	replaced brown hydraulic fitting on implement lock cylinder	3268	\$ 20.40
				\$ 25.56	
				\$ 9.77	

2014 Vehicle Maintenance	VIN #				
FL-7	Tires				
Company Parts/Svcs					
DATE	Purchased From:	Part #/Description	WORK PERFORMED	HOURS	COST
1/21/14	Homax	15-40 Oil 1052955-1	200 Hour Service	22qt?	3392 \$ 37.52
	Titan Machinery	84228488 filter			\$ 23.86
		84348882 filter			\$ 29.54
		84412164 filter			\$ 27.79
	Snow Dist	02382-120 Grease	Greased Truck		\$ 7.74
	NAPA	08880 brakleen		1	\$ 2.62
	Barnes	BT45-co			\$ 0.84
	Same Club	Washer Flug	zipties 2		\$ 1.87
	Barnes	38216 cotter pin	1 gal		\$ 0.06
1/22/14	NAPA	RTA9200 paint	painted chains		\$ 11.95
		7308 Paint			\$ 11.95
	Clevis slip/grab hooks	7176780 safety hook	fabricate new tag line		\$ 14.60
1/30/14	HSC	8025-12	added power service to gelled fuel 2 qt		\$ 31.78
2/6/14	Fleet Pride				\$ 19.00
2/7/14			81216 red glad hand		
2/19/14	NAPA	Emblem 430			\$ 13.64
3/16/14	GSS	Wash	FL Wash and service/grease/look over		\$ 171.00
3/5/14	Snow Dist	02382-120 Grease	Greased equipment		\$ 7.74
	BARNES	33831 screw	repaired toolbox lid		\$ 0.42
		99002 Bolt	attached slow moving vehicle placard		\$ 0.18
		99740 washer			\$ 0.06
		32574 washer			\$ 0.34
		34272 Nyloc			\$ 0.04
3/25/14	Titan Machinery	Filters	84228488, 84348882, 84412164		\$ 81.18
4/1/14	Homax	1052955-1 15w40 oil	200HR service		\$ 37.76
	snow dist	02382-120 grease			\$ 7.74
	Titan Machinery	84228488 oil filter			\$ 23.86
		84348882 fuel filter			\$ 29.54
		84412164 fuel filter	repair front windshield wiper		\$ 27.79
	NAPA	715151 grease fitting	replaced broken grease fitting		\$ 0.73
4/2/14	Barnes	BT25-CO zip tie			\$ 0.36
4/9/14	snow dist	02382-120 grease	greased loader	3678	\$ 7.74
4/14/14	Barnes	KP86912 terminal	Fabricated new wiring harness and installed new switch for hood actuator		\$ 0.99
		KP81235 seal			\$ 0.51

		7352-1 body		\$ 1.41	
		23540 shrink tube		\$ 0.20	
		422288 blue wire		\$ 0.20	
		422295 yellow wire		\$ 0.20	
		23449 red wire		\$ 0.20	
	NAPA	CN27250 terminal		\$ 7.40	
	Peterbilt	P20-1178 connector		\$ 17.82	
	NAPA	16-091227B3GMN2D31 switch		\$ 64.55	
5/19/14	Titan Machinery	7704532 aluminum rivets		\$ 11.63	
		performed service hrs 2980?????????????	2980?	\$ 23.89	
		84348882 fuel filter		\$ 29.66	
		84412164 fuel filter		\$ 27.83	
	homax	1052955-1 15w40 oil		\$ 37.36	
		02382-120 grease		\$ 7.74	
5/30/14	NAPA	7651288 fiberglass	repainted hood	\$ 7.74	
		08011 adhesive		\$ 9.19	
		08101 adhesive		\$ 73.84	
		7651285 Resin		\$ 28.10	
	6/1/14	sutherland's	misc	\$ 15.72	
	6/2/14	Barnes	2506-2 hairpin clip	\$ 0.34	
	6/11/14	Snow Dist	02382-029 grease	greased 14 oz tube	\$ 4.68
6/19/14	Snow Dist	02382-120	greased loader	3946	\$ 3.87
6/20/14	Sams club	M5702	glass cleaner for loader		\$ 2.10
7/21/14	HOMAX	1052955-1 15w40 oil	200 Hour Service	4045	\$ 44.60
		Titan Machinery	84228488 OF		\$ 23.89
		84348882 FF		\$ 29.66	
		84412164 FF		\$ 27.83	
		Snow Dist	02382-120 Grease	\$ 7.74	
	VERNAL	8605139	replaced outer air filter		
		87712194	replaced cab filter	\$ 10.84	
8/19/14	Titan Machinery		repairs to hydraulic pump and engine	4112	\$ 2,938.59
9/1/14	Homax	3200.55 coolant	added coolant	\$ 7.12	
9/26/14	Homax	1052955-1 15w40 oil	200 hour service	4269	\$ 35.68
	Snow Dist	02382-120 grease		\$ 7.74	
	Titan Machinery	8422848 OF		\$ 23.89	
		84348882 FF		\$ 29.66	
		84412164 FF		\$ 27.83	
	Vernal	87712194 Filter	replaced cab filter	\$ 10.84	
	Homax	3200-55 coolant	added coolant	\$ 7.12	
10/2/14	Sams	959877 washer fluid	filled windshield washer res	\$ 1.97	

	Homax	3200.55 coolant	filled coolant overflow res	\$ 7.12
10/7/14	Sams Club	M5702	glass cleaner for forklift	\$ 2.10
11/5/14	R&B Tires	Fixed flat on M42 move		\$ 254.40
11/14/14	Titan Machin	BHC4DAW BATTERY	replaced batteries	4424 \$ 527.10
11/19/14	Titan Machinery	88412164 fuel filter	200 hour service	\$ 27.83
		88348882	fuel filter	\$ 29.66
	homax	84228488 oil filter		\$ 23.89
	snow dist	1052955-1 15w40 oil		\$ 35.68
	fleetpride	02382-120 grease		
	titan	413 hook	replaced cross chain hook on tire chain	\$ 3.65
11/26/14	504114393 intake	2854829 turbo	replaced intake and turbo charger	4424 \$ 1,473.43
		4899086 flangenut		inc
		4899087 o ring		inc
		87397416 belt	replaced serpentine belt	\$ 50.93
12/2/14	HSC	7124773 shackle	installed tire chains	\$ 99.56
12/8/14	titan	84322388 thermostat	changed thermostat	\$ 39.38
		87472435 motor	replaced electronic valve for heater	4489 \$ 186.90
		87691613 gasket		\$ 3.36









<u>2019 Vehicle Maintenance</u>	<u>VIN #N9F206566</u>	<u>start</u>	<u>end</u>		
FL-7	Tires				
<u>DATE</u>	<u>Purchased From:</u>	<u>Part #/Description</u>	<u>WORK PERFORMED</u>	<u>HOURS</u>	<u>COST</u>
1/28/2019	Fuel Filters oil filters hydro filters	Napa	Service greased	6835	\$174.30
2/27/2019	GCR	Tire	?not on log		\$885.16
3/14/2019	Midwest hose	Hydraulic 2SN06-2WB-04MP	? Not on log		\$ 53.74
8/29/2019	Titan Machine	Fuel cap			\$ 80.42
9/24/2019			Washed cleaned out and greased		\$14.53
10/8/2019			anti-freeze test -20 degrees		
10/9/20	horizon cable	screw pin anchor shackle	twisted eye/cordura eye		\$ 65.42

<b>2020 Vehicle Maintenance</b>	<b>VIN #N9F206566</b>	<b>start</b>
<b>FL-7 Tires</b>		<b>end</b>
<b>Company Parts/Svcs</b>		
<u>DATE</u>	<u>Purchased From:</u>	<u>Part #/Description</u>
9/11/20	NAPA	battery terminal repairs
9/23/20	napa	ignitino switch

<b>2021</b>	<b>Vehicle Maintenance</b>	<b>VIN #N9F206566</b>	<b>start</b>
<b>FL-7</b>	<b>Tires</b>		
			<b>end</b>
<b>Company Parts/Svcs</b>			
<b>DATE</b>	<b>Purchased From:</b>	<b>Part #/Description</b>	<b>WORK PERFORMED</b>
9/23/21	NAPA	Battery Charger	