| Hood Latch                 | 10/9/2021  | Replaced Both Hood Latches                               |
|----------------------------|------------|--|
| X/Y Shifter                | 10/10/2021 | Replaced X/Y Shifter                                     |
| Windshield Glass           | 10/19/2021 | Replaced Glass Windshield                                |
| Leaking Parking Valve      | 10/20/2021 | Replaced Parking Brake Valve Manifold                    |
| Replace Air Governor       | 11/24/2021 | Replace Air Governor                                     |
| Loose Steering Wheel       | 11/28/2021 | Replaced Steering Wheel & Hub                            |
| New Windshield Wipers      | 11/28/2021 | Replaced Both Windshield Wipers                          |
| Brake Knob Loose           | 11/28/2021 | Replaced Dash Brake Manifold                             |
| PM Service                 | 11/28/2021 | PM Service / Oil Change                                  |
| Grease Service             | 11/28/2021 | Greased All Grease Points                                |
| Air Filter Service         | 11/28/2021 | Replaced Cabin & Intake Air Filter                       |
| Cracked Dash / Destroyed   | 12/13/2021 | Replaced Entire Dash and all Components                  |
| HVAC not Blowing           | 12/23/2021 | Replaced Blower & Blower Motor                           |
| Headlights Not Working     | 12/23/2021 | Replaced Toggle Switch For Headlights                    |
| Headlights Not Working     | 12/23/2021 | Replaced Headlight On/Off Switch                         |
| Flasher Realy              | 12/23/2021 | Replaced Flasher Relay                                   |
| Guage Lights Dim           | 1/12/2022  | Replaced Bulbs in all Dash Guages                        |
| PM Service                 | 3/6/2022   | PM Service / Oil Change                                  |
| Grease Service             | 3/6/2022   | Greased All Grease Points                                |
| Air Filter Service         | 3/6/2022   | Replaced Cabin & Intake Air Filter                       |
| Power Steering Filter      | 3/30/2022  | Replaced Power Steering Filter                           |
| Power Steering System      | 3/30/2022  | Flushed & Replaced Power Steering Fluid                  |
| Water Pump Leaking         | 4/8/2022   | Replaced Water Pump                                      |
| Replace Waster Pump Hosesd | 4/8/2022   | Replaced Water Pump Hoses & Clamps                       |
| EGR Hoses Leaking          | 4/24/2022  | Replaced all EGR Hoses                                   |
| Stripped Wheel Stud        | 4/25/2022  | Replaced Stripped Wheel Stud & Lug Nut                   |
| Air Leak Behind Ash Tray   | 4/26/2022  | Replaced Air Switches on Manifold in Dash                |
| Damaged Quarter Fender     | 5/3/2022   | Replaced Both Quarter Fenders                            |
| Radiator Leaking           | 5/10/2022  | Replaced Radiator Drain Plug                             |
| Coolant Treatment          | 5/10/2022  | Flush Radiator, Changed Filter & Filled with New Coolant |
| Motor Belts                | 6/1/2022   | Replaced AC & Fan Hub Belts                              |
| PM Service                 | 6/22/2022  | PM Service / Oil Change                                  |
| Grease Service             | 6/22/2022  | Greased All Grease Points                                |
| Air Filter Service         | 6/22/2022  | Replaced Cabin & Intake Air Filter                       |
| AC Not Working             | 8/15/2022  | Replaced AC Compressor                                   |
| AC Not Working             | 8/15/2022  | Replaced AC Condensor                                    |
| AC Not Working             | 8/15/2022  | Replaced AC Line   |
| AC Not Working             | 8/15/2022  | Charged AC System with New Freon, Inspected for Leaks    |
| Trailer Lights Flickering  | 7/18/2022  | Replaced Trailer Cable Plug                              |
| Flickiering Tail Lights    | 9/1/2022   | Replaced Tail Light Harness & All Tail Lights            |
| Visor Clearance Lights Dim | 9/28/2022  | Replaced All 5 Clearance Lights w/LEDs                   |
| Battery Box Latch          | 10/3/2022  | Replaced Battery Box / Cover Latch                       |