# 2009 Western Star 4900 Hot Oiler, 5KKHALAV19PAB6866

Service performed every 500 hours w Shell Rotella T-6 oil. Fuel filters changed every 1000hrs.

## Major work performed since Jan 2018:

Nov 2019

- Replaced Roper Gear Pump
- Replaced Batteries

#### June 2019

- Burner igniters replaced

### March 2019

- Belly valve replaced

#### Jan 2019

- Replaced Burner fuel pump