



EQUIPMENT CONDITION REPORT

Equipment Type: Trailer
Unit Number: N/A
Year: 2014
Make: Monroe Motors
Model: Trailer 5CC
VIN/SN: 1W9H54628BH1571
Miles/Hrs.: n/a

Engine Year: _____
Engine Make: _____
Engine Model: _____
Engine SN: _____
Fuel Type: _____
Fuel Capacity: _____
Horse Power: _____

For Rolling Stock:

Transmission: _____
Auto / Standard: _____

Speeds: _____
Operational: ☐ Yes ☐ No

Mechanical Condition

- ☒ Very Good - Starts and operates with no known mechanical defects.
☐ Good - Starts and operates; Some parts may require repair or replacement soon.
☐ Fair - Starts and operates but some parts require repair or replacement.
☐ Poor - Will not start or operate and is in need of repair.
☐ Yes ☐ No Can the Equipment Be Repaired?

Describe Repairs:

- ☐ Yes ☒ No Equipment has keys
☐ Yes ☐ No Functioning Brake Lights, Head Lights and Turn Signals Not Applicable: ☐
☐ Yes ☒ No Functioning AC Not Applicable: ☐
☐ Yes ☒ No Functioning Heat Not Applicable: ☐
☐ Yes ☒ No Service / Repair Records Available
☐ Yes ☒ No Any Known Mechanical Issue

Details:

good working condition. The trailers driver's side back side light (not the break light)

Date Last Serviced: UNKNOWN

Tire / Track Condition: ☒ Very Good, ☐ Wear due to use, ☐ Damage, Needs Repair
Wheel/Sprocket Condition: ☒ Very Good, ☐ Wear due to use, ☐ Damage, Needs Repair

Attachments: ☒ Very Good, | | Wear due to use, | | Damage, Needs Repair
 Non-Standard Attachments: ☐ GPS | | Compressor | | Welder
 Other: _____
 Oil Leaks: | | Yes ☒ No Visible Leaks or Pooling
 Fuel Leaks: ☐ Yes ☒ No Visible Leaks or Pooling
 Cooling System Leaks: ☐ Yes ☒ No Visible Leaks or Pooling

Hydraulics	Not Applicable: <input checked="" type="checkbox"/> Pumps: <input type="checkbox"/> Operational <input type="checkbox"/> Wear due to use, Damage, Needs Repair Articulating Cylinders: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Wear due to use, Damage, Needs Repair Motors: <input checked="" type="checkbox"/> Operational Wear due to use, Damage, Needs Repair Leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Visible Leaks or Pooling
Interior Condition	<input checked="" type="checkbox"/> Very Good - No visible signs of damage. Good - Damage is limited to normal wear and minor scratches. Fair - Interior is heavily worn. Poor - Interior has severe damage and/or tears beyond normal wear.
Exterior Condition	<input checked="" type="checkbox"/> Very Good - Well maintained Good - Minor dings and scratches Fair - Visible dents and scratches Poor - Major body damage.
Safety	Mirrors: <input checked="" type="checkbox"/> Very Good, Wear due to use, Damage, Needs Repair Horn: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Non-Operational Seat Belts: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Wear due to use, Damage, Needs Repair Travel Alarm: <input checked="" type="checkbox"/> Operational Non-Operational Warning Lights: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Non-Operational Gauges: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Non-Operational Safety Manual: Yes <input checked="" type="checkbox"/> No Operation Manual: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No
Equipment Location	Contact: <u>Joe Cappy</u> Phone: <u>N/A</u> Email: <u>N/A</u> Company Name: <u>Union Beverage Lot</u> Address: <u>600 N Union Avenue,</u> <u>Hillside</u> State: <u>NJ</u> Zip: <u>7205</u>

Equipment Logistics

Contact: Joe Cappy Phone: N/A
Email: N/A
Buyer Storage Rate: \$300 per month (this is the rate with the truck attached)
Will the Equipment Self Load: _____
Hours of Operation: 24/7 Saturday/Sunday Removal: ☒ Yes ☐ No
Removal Lead Time: None
Required Transport Equipment: N/A
Is Loading Assistance Available: NO Cost: N/A
Additional Removal Information: Lot is open 24/7 with guard and guard dog on site. Coordinate with Jo