



EQUIPMENT CONDITION REPORT

Equipment Type: Crane
Unit Number: _____
Year: 1974
Make: Grove
Model: RT-65S
VIN/SN: 30088
Miles/Hrs: N/A

Engine Year: _____
Engine Make: CAT
Engine Model: 3160
Engine SN: _____
Fuel Type: _____
Fuel Capacity: _____
Horse Power: _____

For Rolling Stock:

Transmission: _____
Auto / Standard: _____

Speeds: _____
Operational: ☐ Yes ☐ No

Mechanical Condition

- ☐ Very Good - Starts and operates with no known mechanical defects.
☒ Good - Starts and operates; Some parts may require repair or replacement soon.
☐ Fair - Starts and operates but some parts require repair or replacement.
☐ Poor - Will not start or operate and is in need of repair.
☐ Yes ☐ No Can the Equipment Be Repaired?

Describe Repairs: _____

- ☒ Yes ☐ No Equipment has keys
☐ Yes ☐ No Functioning Brake Lights, Head Lights and Turn Signals Not Applicable ☒
☐ Yes ☐ No Functioning AC Not Applicable: ☒
☐ Yes ☐ No Functioning Heat Not Applicable: ☒
☐ Yes ☒ No Service / Repair Records Available
☐ Yes ☒ No Any Known Mechanical Issue

Details: _____

Date Last Serviced: _____

Tire / Track Condition:	<input type="checkbox"/> Very Good,	<input checked="" type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
Wheel/Sprocket Condition:	<input type="checkbox"/> Very Good,	<input checked="" type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
Attachments:	<input type="checkbox"/> Very Good,	<input checked="" type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
Non-Standard Attachments:	<input type="checkbox"/> GPS	<input type="checkbox"/> Compressor	<input type="checkbox"/> Welder

Other: _____

Oil Leaks:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No Visible Leaks or Pooling
Fuel Leaks:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No Visible Leaks or Pooling
Cooling System Leaks:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No Visible Leaks or Pooling

Hydraulics	Not Applicable: <input type="checkbox"/>			
	Pumps:	<input checked="" type="checkbox"/> Operational	<input type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
	Articulating Cylinders:	<input checked="" type="checkbox"/> Operational	<input type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
	Motors:	<input checked="" type="checkbox"/> Operational	<input type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
	Leaks:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No Visible Leaks or Pooling	
Interior Condition	<input type="checkbox"/>	Very Good - No visible signs of damage.		
	<input type="checkbox"/>	Good - Damage is limited to normal wear and minor scratches.		
	<input checked="" type="checkbox"/>	Fair - Interior is heavily worn.		
	<input type="checkbox"/>	Poor - Interior has severe damage and/or tears beyond normal wear.		
Exterior Condition	<input type="checkbox"/>	Very Good - Well maintained		
	<input checked="" type="checkbox"/>	Good - Minor dings and scratches		
	<input type="checkbox"/>	Fair - Visible dents and scratches		
	<input type="checkbox"/>	Poor - Major body damage.		
Safety	Mirrors:	<input type="checkbox"/> Very Good,	<input type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
	Horn:	<input type="checkbox"/> Operational	<input type="checkbox"/> Non-Operational	
	Seat Belts:	<input checked="" type="checkbox"/> Operational	<input type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
	Travel Alarm:	<input checked="" type="checkbox"/> Operational	<input type="checkbox"/> Non-Operational	
	Warning Lights:	<input checked="" type="checkbox"/> Operational	<input type="checkbox"/> Non-Operational	
	Gauges:	<input checked="" type="checkbox"/> Operational	<input type="checkbox"/> Non-Operational	
	Safety Manual:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No		
Operation Manual:	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No			