



EQUIPMENT CONDITION REPORT

Equipment Type: Dump Truck
Unit Number: _____
Year: 1999
Make: Sterling
Model: L7501
VIN/SN: 2FZNRLBB7XAA78078
Miles/Hrs: 170838

Engine Year: _____
Engine Make: _____
Engine Model: _____
Engine SN: _____
Fuel Type: _____
Fuel Capacity: _____
Horse Power: _____

For Rolling Stock:

Transmission: Eaton Fuller
Auto / Standard: Standard

Speeds: _____
Operational: ☐ Yes ☐ No

Mechanical Condition

- ☐ Very Good - Starts and operates with no known mechanical defects.
☒ Good - Starts and operates; Some parts may require repair or replacement soon.
☐ Fair - Starts and operates but some parts require repair or replacement.
☐ Poor - Will not start or operate and is in need of repair.
☐ Yes ☐ No Can the Equipment Be Repaired?

Describe Repairs: _____

- ☒ Yes ☐ No Equipment has keys
☒ Yes ☐ No Functioning Brake Lights, Head Lights and Turn Signals Not Applicable ☐
☐ Yes ☐ No Functioning AC Not Applicable: ☐
☐ Yes ☐ No Functioning Heat Not Applicable: ☐
☐ Yes ☒ No Service / Repair Records Available
☐ Yes ☒ No Any Known Mechanical Issue

Details: _____

Date Last Serviced: _____

Tire / Track Condition:	<input type="checkbox"/> Very Good,	<input checked="" type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
Wheel/Sprocket Condition:	<input type="checkbox"/> Very Good,	<input checked="" type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
Attachments:	<input type="checkbox"/> Very Good,	<input checked="" type="checkbox"/> Wear due to use,	<input type="checkbox"/> Damage, Needs Repair
Non-Standard Attachments:	<input type="checkbox"/> GPS	<input type="checkbox"/> Compressor	<input type="checkbox"/> Welder

Other: _____

Oil Leaks:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No Visible Leaks or Pooling
Fuel Leaks:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No Visible Leaks or Pooling
Cooling System Leaks:	<input type="checkbox"/> Yes	<input checked="" type="checkbox"/> No Visible Leaks or Pooling

Hydraulics	Not Applicable: <input type="checkbox"/> Pumps: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Wear due to use, <input type="checkbox"/> Damage, Needs Repair Articulating Cylinders: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Wear due to use, <input type="checkbox"/> Damage, Needs Repair Motors: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Wear due to use, <input type="checkbox"/> Damage, Needs Repair Leaks: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Visible Leaks or Pooling
Interior Condition	<input type="checkbox"/> Very Good - No visible signs of damage. <input checked="" type="checkbox"/> Good - Damage is limited to normal wear and minor scratches. <input type="checkbox"/> Fair - Interior is heavily worn. <input type="checkbox"/> Poor - Interior has severe damage and/or tears beyond normal wear.
Exterior Condition	<input type="checkbox"/> Very Good - Well maintained <input checked="" type="checkbox"/> Good - Minor dings and scratches <input type="checkbox"/> Fair - Visible dents and scratches <input type="checkbox"/> Poor - Major body damage.
Safety	Mirrors: <input checked="" type="checkbox"/> Very Good, <input type="checkbox"/> Wear due to use, <input type="checkbox"/> Damage, Needs Repair Horn: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Non-Operational Seat Belts: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Wear due to use, <input type="checkbox"/> Damage, Needs Repair Travel Alarm: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Non-Operational Warning Lights: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Non-Operational Gauges: <input checked="" type="checkbox"/> Operational <input type="checkbox"/> Non-Operational Safety Manual: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No Operation Manual: <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No