

VIN: 3HSDJSJR3EN057242

## 2014 INTERNATIONAL PROSTAR

PROSTAR Specifications	
Mileage	476,946
Engine Hours	15885
Engine	International MaxxForce 13 450 HP
Engine Brake	Yes
Engine Serial	125HM2Y4 180351
Fuel	Diesel 2 Alum Tanks 240 Gal. Total
Exhaust	Horizontal
Transmission	Eaton Auto FM-15E310B-LAS 10 Spd
Rear	Meritor 2.47
Axles	Tandem 12,000 Front / 40,000 Rear
GVWR (lbs)	52,000
Frame Type	Steel
Suspension	Air Ride
Wheelbase	226"
Tire Size F	275/80/22
Tire Size R	275-80-22
Wheels	Aluminum
5th Wheel	Air Slide
A/C	Yes * Operational
Sleeper Size	73"
Dual Bunks	Yes
Interior Color	GRAY
Radio Config	AM/FM/CASS * Operational
Power Mirrors	Dual Power
Hi Back Seats	Dual
Pass Seat	Air Ride
Exterior Color	WHITE
Bumper	Plastic
Heated Mirrors	Yes
Fairings	Full
External Visor	Yes

Drive Options
Cruise Control, Power Steering

### Inspection Photos



### Notes / Description

--

## 2014 INTERNATIONAL PROSTAR

Brakes	
25	25
17	14
22	22
Additional Brake Detail	

Tires			
Front 275/80/22	Michelin 11 / 32 Aluminum	Michelin 9 / 32 Aluminum	Rear 275-80-22
Michelin 5 / 32 Aluminum	Michelin 8 / 32 Aluminum	Yokohama 16 / 32 Aluminum	Yokohama 17 / 32 Aluminum
Michelin 6 / 32 Aluminum	Michelin 9 / 32 Aluminum	Goodyear 15 / 32 Aluminum	Goodyear 3 / 32 Aluminum
Additional Tire Detail			

General Observations	
Oil Milky? No Oil Leaks? No Water Leaks? No Oil in Coolant? No Clutch Play? NA Starts? Yes Drives? Yes	
Safety / Operational Observations	
Lights Work? Yes - All Wipers Work? Yes Gauges Work? Yes - All City Horn Works? Yes Air Horn Works? Yes	
Diesel Particulate Filter (DPF): <b>PASS</b>	
Additional Observation Detail	

Wear and Tear Items	
Diagnostics	Active faults: 647-3   Inactive faults: 111-1, 1810-15, 94-0, 789-1, 1059-2
Bumper	Right side of plastic bumper is pushed in
Tires	6 below terms
Sleeper	Top mattress missing
Headache rack	Damaged at rear
Power steering	Appears to be leaking at gear box
Paint	Var
Interior	Soiled