



SERVICE REPORT

Date: 04-26-2019

Customer's Name: Manson Construction

Customer P.O. # _____

Job Location: Port Arthur

M/M/T: Manitowoc 2250

Hours: 9205

Equipment # 300471

Serial # 2251274

Trip Mileage _____

Describe Defects & Cause of Failure: Hydraulic leak on main tank due to bad gasket on float gasket.

Repairs Completed: Extend all available cylinders, remove float and reinstall with new float. Close up and retract cylinders

Qty	Part Number	Description	Ordered	Installed
1	A113700	Sender, 10-30 in		

Recommendations: _____

Technician: G. C. Broadway

Customer Name: _____

Customer Signature: [Signature]

Job Complete:

Yes ☒ No ☐

Labor: Reg _____

O.T. _____




PM Service Report

Job-Site/Customer Information

Date of PM	10-16-2019
Job#	41-01-207648
Customer Name	Bigge
Customer Location	Houston

Equipment Information

Equipment #:	300471
Make	Manitowoc
Model	2250
Serial #	2251274
Equipment Hours	9858
Hour Meter	

Type of Service

PM Type	500 Hr
	 29.589044, -95.423501
Repairs Completed:	Yes
Photos of New Filter w/Date	 
	10-16-2019 04:59 PM



Date Submitted: 10-18-2019 04:47 AM

Submitted By: vprum@bigge.com

Bigge Crane and Rigging PM Service Report



PM Service Report

Recommendations:	Perform 500 hr services
------------------	-------------------------

Parts Used/Ordered

Engine Oil	Installed
Gallons:	13
Filter Type	Fuel
Parts	Installed
Qty.	1
Part Number	Fs1041
Filter Type	Oil
Parts	Installed
Qty.	1
Part Number	Lf14000nn
Filter Type	Air
Parts	Installed
Qty.	1
Part Number	4272890

Acknowledgement:

Job Completed	Yes
Bigge Technician:	Vutha Prum
Acknowledgment	<p>I agree that the information in this PM Service report is accurate and true. By checking yes I agree that the type of service completed was done per the manufacturer's recommendations.</p> <p>Thank You</p>
Signature	
Customer Representative:	Bigge
Acknowledgment	<p>I agree that, to the best of my knowledge, the service performed was completed as indicated on this PM Service Report.</p> <p>Thank You</p>
Signature	



Date Submitted: 10-18-2019 04:47 AM

Submitted By: vprum@bigge.com

Bigge Crane and Rigging PM Service Report

PM Service Report

Form Locations

