



Established 1916  
**CRANE and RIGGING CO.**

14800 Jersey Shore Dr.  
Houston, TX 77047  
(713) 434-0995

### SERVICE REPORT

10-14-006569

Date: 3-1-16

Customer's Name: BIGGE (AMECO)

Customer P.O. # \_\_\_\_\_

Job Location: LEE STATION

M/M/T: Grove RTTDE

Hours: 551

Equipment # BE 7013

Serial # 235292

Trip Mileage 200

Describe Defects & Cause of Failure: \_\_\_\_\_

Repairs Completed: REPLACED VALVE AND DID THE  
SAME TEST AS LAST WEEK AND THERE WAS NO  
TELESCOPE DRIFT.  
I RETURNED CRANE TO LIFTING SERVICE AND  
CUSTOMER WILL SEE IF ANY PROBLEMS COME BACK

Qty	Part Number	Description	Ordered	Installed
1	80046493			

Recommendations: \_\_\_\_\_

Technician: Tom Alay

Customer Name: Jimmy Morse

Customer Signature: Jimmy Morse

Job Complete:

Yes ☒ No ☐

Labor: Reg \_\_\_\_\_

O.T. \_\_\_\_\_

Copies: White: Office

Pink: Customer

Yellow: Technician Copy

**H&E Equipment Services, Inc.**  
**585 Brookshire Rd**  
**Greer SC 29651**  
**Tel No. (866) 849-7719**  
**Fax No.**

**Regional Credit Office**  
**Phone (800)463-8197**  
**Fax (770)593-2593**

# Invoice Preview

<b>Bill-To-Party</b> BIGGE CRANE AND RIGGING COMPANY ACCOUNTS PAYABLE PO Box 1657 SAN LEANDRO CA 94577	<b>Information</b> <b>Invoice Preview No.</b> 70393664 <b>Order No.</b> 42109082 <b>Customer No.</b> 1014390 <b>PO No.</b> <small>Need po number</small> <b>PO date</b> <b>Currency</b> USD <b>Make</b> GV - GROVE <b>Model</b> RT770E <b>Serial No.</b> 235292 <b>Customer Eq No.</b> <b>H&amp;E Eq No.</b> 10207294 <b>Customer Contact</b> <b>Contact Phone</b> <b>Meter</b> 1876 *****
<b>Ship-To-Party</b> BIGGE CRANE AND RIGGING COMPANY Lee steam plant 201 lee steam plant rd belton SC 29627	
<b>Complaints</b>	
<b>Complaint Details</b>	
<b>Annual Inspection</b>	
<b>Causes</b>	
<b>Cause Details</b>	
<b>Corrections</b>	
<b>Correction Details</b>	

**H&E Equipment Services, Inc.**  
**585 Brookshire Rd**  
**Greer SC 29651**  
**Tel No. (866) 849-7719**  
**Fax No.**

**Regional Credit Office**  
**Phone (800)463-8197**  
**Fax (770)593-2593**

# Invoice Preview

Material	Description	Quantity	Unit Price	Amount
Truck Mileage				210.00
Environmental				12.00
Shop Supplies				24.00
	Miscellaneous Total			246.00
Service Labor				480.00
Subtotal				726.00
Tax				0.84
Total Amount				726.84
<b>Conditions</b> This is SAMPLE INVOICE only. Do not pay.				
Customer Signature _____ Date _____				
Title _____ PO Number _____				



Auburn, WA  
206-443-8500  
San Leandro, CA  
510-638-8100

Richmond, VA  
804-271-9356  
North SLC, UT  
801-292-2453

Houston, TX  
713-456-3086  
**TOLL FREE**  
**888-337-2444**

## SERVICE REPORT

DATE:

CUSTOMER Ameco		TRIP MILEAGE 12/14/2017		
CONTACT NAME & NO.				
ADDRESS				
MAKE	MODEL	SERIAL NUMBER	HOURS	UNIT NUMBER
Grove	RT 700E	235292	3601	BE7013

### SERVICE REQUESTED

The length cable was damaged and there was an intermittent two block fault.  
Replaced the length cable and checked the telescoped length, it is now correct for both the short and the long boom.  
Found a broken wire and rusted terminal block in the two block wiring junction box on the jib. Cleaned the contact block and rewired the junction box and there are no more LMI faults in the computer. Both the main and jib two block switches are working properly.  
The machine electrical system is flashing a warning light that is called "electronic diagnostics". The fuel gage is not working properly and that may be the cause of the error. Checking the wires showed no problems. The customer was using the crane at by this point

### REPAIRS MADE

and I did not get to connect my laptop to the crane. I did check to see if I had the correct IO files to get in to this cranes operating system. According to Crane Care I need IO file 3.06 and looking in my "conductor" files end at 2.05 I talked to Crane Care and they sent me the correct IOC files for this crane. I have arranged with the customer to go back to the job site next Tuesday and troubleshoot this error. That way I will be able to talk to the factory to get any additional information.

### COMMENTS

PART NUMBER	QNTY	DESCRIPTION	INSTALLED	ORDERED
		Tom Akey		

TECHNICIAN

CUSTOMER SIGNATURE






## PM Service Report-HSTX



### Job-Site/Customer Information

Date of PM	01-10-2019
Job#	41-01-206941
Customer Name	Westcon
Customer Location	Towanga Oklahoma

### Equipment Information

RT/AT/CD Equipment #	BE7013
Make	Grove
Model	RT770E
Serial #	235292
Equipment Hours	4879
Hour Meter	

### Type of Service

PM Type	500 Hr
	 35.836665, -98.262956
Photos of New Filter w/Date	
	01-10-2019 06:17 AM


### Parts Used/Ordered



## PM Service Report-HSTX

Parts	Installed
Qty.	1
Part Number	Af55015
Filter Type	Air
Parts	Installed
Qty.	1
Part Number	Af55309
Filter Type	Air
Parts	Installed
Qty.	1
Part Number	Lf3970
Filter Type	Oil
Parts	Installed
Qty.	1
Part Number	Fs1098
Filter Type	Fuel/Water Separator
Parts	Installed
Qty.	1
Part Number	Ff63009
Filter Type	Fuel/Water Separator

### Acknowledgement:

Job Completed	Yes
Bigge Technician:	Danielsweaza
Acknowledgment	I agree that the information in this PM Service report is accurate and true. By checking yes I agree that the type of service completed was done per the manufacturer's recommendations.  Thank You
Signature	
Customer Representative:	Justin Matkin
Acknowledgment	I agree that, to the best of my knowledge, the service performed was completed as indicated on this PM Service Report.  Thank You



Date Submitted: 01-10-2019 07:32 PM  
Submitted By: hstxinspections@bigge.com  
Bigge Crane and Rigging PM Service Report

## PM Service Report-HSTX

Signature

A handwritten signature in black ink, which appears to read "Justin Matto", is written over a light gray rectangular background.



Date Submitted: 01-10-2019 07:32 PM  
Submitted By: hstxinspections@bigge.com  
Bigge Crane and Rigging PM Service Report

## PM Service Report-HSTX

### Form Locations

