Wood Destroying Insect Inspection Report	Notice: Pless	ca road ime		- Jr LPS C (FILLORION	
Section I. General Information Inspection Company, Address & Phone	Company's Bual			er information on Date of Inspection		
Lewis Termite & Pest Control, Inc.) Voltabouring to comme	Сотралу'я Визілева Ціс. No.			>	
6168 Termite Lane			533	7-18-17		
Chincoteague, VA 23336-2608	Address of Prope	Address of Property Inspected				
757-336-3373	PRCITTE	Lucille Cobb Estate 6338 Church Street				
Chinacter				26		
Inspector's Name, Signature & Certification, Registration, or Lic. #	Lewis	-cayue	Structure(s) Ins			
	-	202840		•		
		898MD	Dwelli	ng		
Section II. Inspection Findings This report is indicative of the not to be construed as a guarantee or warranty against latent concealed.	a condition of the	above ide	ntified. structur	re(s) on the date	of inspection and is	
readily accessible areas of the structure(s) inspected: A. No Visible evidence of wood destroying insects was observed.	or totore intestat	lons or defe	cts. Based o	n a careful vist	ial inspection of the	
B. Visible evidence of wood destroying insects was observed as follow	ws;					
1. Live Insects (description & location);						
2 Daard Imports Installed						
2. Dead Insects, Insect parts, frass, shelter tubes, exit holes, or sta	alning (description	and locatio	n): previ	ous sion		
from Powder post heatles Inactive of the living room areas						
3. Visible damage from wood destroying insects was noted as follows:	3 at time lows (description :	- Of in	spectic			
		and reveles.	<i>j.</i>			
NOTE: This is not a structural damage report. If box B above is check damage, may be present. If any questions arise reporting demans indicate						
damage, may be present. If any questions arise regarding damage indicate a qualified structural professional to determine the extent of damage and the Yes No It appears that the structure(s) or a portion thereof may. The inspecting company can give no assurances with regard to work done by for information on treatment and any warranty or service agreement which makes.	have been previou	usly treated.	Visible evider	nce of possible pr	revious treatment:	
Section III. Recommendations		-		W	-	
No treatment recommended: (Explain if Box B in Section II is checked)						

D-AV BU ALL						
section IV. Obstructions and inaccessible Areas fie following areas of the structure(s) inspected were obstructed or inaccessible: Basement				The inspector may write out obstructions or use the following optional key: 1. Fixed ceiling 13. Only visual access		
Crawlspace 13					14. Cluttered condition15. Standing water	
Main Level 10			4. Flo	oor covering	Dense vegetation	
Attic Garage					17. Exterior siding18. Window well covers	
Exterior 13,17			7. Sto	ored items	19. Wood pile 20. Snow	
Porch	Porch			pliances	21. Unsafe conditions	
Addition	Addition			,	22. Rigid feam board 23. Synthetic stucco	
Other					24. Duct work, plumbing,	
Section V. Additional Comments and Attachments					and/or wining	
Section V. Additional Comments and Attachments (these a	are an integral par	t of the repo	ort)			
This home has had yearly pest con- for ants, crickets and spiders	trol trea	tments	by thi	s compan	Υ,	
						
attachments						
Signature of Seller(s) or Owner(e) if refinancing. Seller cknowledges that all information regarding W.D.I. infestation, damage, epair, and treatment history has been disclosed to the buyer.	Signature of Buyer. The undersigned hereby acknowledges receipt of a copy of both page 1 and page 2 of this report and understands the information reported.					
(X	×				